

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College: MIAMI DADE COLLEGE
Survey: Number 3 - Version 1
Survey Status: Active Approved



EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 1: Survey Details

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

College: MIAMI DADE COLLEGE
Survey: Number 3 - Version 1
Description: 2020 Educational Plant Survey Miami Dade College
Survey Open Date: 4/14/2020 2:05:29 PM
Board Approval Date: 6/17/2020
Survey Expiration Date: 6/30/2025
DVE768 Approval Date: 6/24/2020 8:00:00 PM
Contact Name: Eduardo Cepero
Contact Phone Number: 3052372585
Contact Email: ecepero2@mdc.edu

Survey Status	Status Time	User
Active Approved	8/31/2022 9:17:07 AM	Eduardo Cepero

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

KENDALL CAMPUS - The survey recommends more vocational student stations than allowed; survey recommendations for vocational student stations should be revised before submitting the survey.

KENDALL CAMPUS; Auxiliary Space: Auditorium / Exhibition - The square footage recommended exceeds the square footage allowed by SREF.

KENDALL CAMPUS; Auxiliary Space: Custodial - The square footage recommended exceeds the square footage allowed by SREF.

MEDICAL CAMPUS - The survey recommends more general classroom student stations than allowed; survey recommendations for general classroom student stations should be revised before submitting the survey.

MEDICAL CAMPUS; Auxiliary Space: Audiovisual - The square footage recommended exceeds the square footage allowed by SREF.

MEDICAL CAMPUS; Auxiliary Space: Office - The square footage recommended exceeds the square footage allowed by SREF.

MEDICAL CAMPUS; Auxiliary Space: Circulation - The square footage recommended exceeds the square footage allowed by SREF.

MEDICAL CAMPUS; Auxiliary Space: Mechanical / Sanitation - The square footage recommended exceeds the square footage allowed by SREF.

HOMESTEAD CAMPUS; Auxiliary Space: Library / Study - The square footage recommended exceeds the square footage allowed by SREF.

WEST CAMPUS - The survey recommends more general classroom student stations than allowed; survey recommendations for general classroom student stations should be revised before submitting the survey.

ENTREPRENEURIAL ED - The survey recommends more general classroom student stations than allowed; survey recommendations for general classroom student stations should be revised before submitting the survey.

ENTREPRENEURIAL ED; Auxiliary Space: Audiovisual - The square footage recommended exceeds the square footage allowed by SREF.

ENTREPRENEURIAL ED; Auxiliary Space: Support Services - The square footage recommended exceeds the square footage allowed by SREF.

Master Plan update on file: Yes

The following local governments have received a copy of the college's educational plant survey pursuant to Chapter 1013 Florida Statutes:

Miami Dade County

City of Miami

City of Homestead

City of Doral

City of Hialeah

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Survey Notes:

Miami Dade College.

Site Notes for: NORTH CAMPUS

Located on 245 acres in northern Miami-Dade County, this beautifully landscaped campus was the College's first. It was built in 1960, on land that once hosted a World War II Naval air station. The main academic buildings of the campus surround a serene lake and lush walking paths. The campus is a gateway for students wishing to upgrade skills and complete one-year certificate programs, prepare for licensing exams or start working on a bachelor's degree.

Site Notes for: KENDALL CAMPUS

The Kendall Campus, situated on a 185-acre tract of trees and lakes, opened in 1967. It is home to a wide variety of academic programs and specialized institutes. The campus features 13 buildings equipped with the latest technologies, a wellness center, athletic fields and an Olympic-sized pool. The campus offers a comprehensive range of learning opportunities. Kendall provides students with transfer programs designed to facilitate the move to four-year institutions, programs that enhance and modernize professional and technical skills, and preparatory programs for licensing or certification. The campus is the home of MDC athletics.

Site Notes for: WOLFSON CAMPUS

The Wolfson Campus opened in 1970 by holding classes in the storefronts of downtown Miami. With the completion of the campus' first permanent facility in 1973, Wolfson catalyzed a downtown renaissance by hosting all manner of civic and cultural discourse. It is the only comprehensive urban campus in the city. Located within the city's financial, governmental, technological and cultural hubs, the campus capitalizes on its unique geographic resource by offering programs in banking/financial services, business, computer technology, paralegal studies, architecture, economics, hospitality management, engineering, the arts, humanities and social sciences. Wolfson is credited with helping spark Miami's cultural rebirth.

Site Notes for: MEDICAL CAMPUS

In 1977, MDC opened its Medical Campus on 4.3 acres within the city's medical/civic center complex. Along with the University of Miami School of Medicine, Jackson Memorial Hospital and the Veterans Administration Hospital, the campus forms the backbone of Miami's health care community. The campus highlight is its new Center for Learning, Innovation and Simulation, a state-of-the-art facility designed to provide students with the training needed to excel in today's fast-changing health care industry. The campus offers specialty disciplines in nursing and allied health.

Site Notes for: HOMESTEAD CAMPUS

In 1990, Homestead became the College's fifth campus. It was opened in the historic downtown district of the City of Homestead with the mission to deliver a full range of higher education programs for the Homestead/Florida City communities. The campus also enhances the community's cultural and social footprint. It played an important role in the rebuilding effort after Hurricane Andrew.

Site Notes for: PADRON CAMPUS

Eduardo J. Padrón Campus (formerly Inter-American Campus) is located in the lively neighborhood of Little Havana. The campus is home of the School of Education, Dual Language Honors College, and the Translation and Interpretation Studies program. The campus offers comprehensive academic programs in business, accounting, computer information technology, transfer degrees, pre-nursing classes, and credit and non-credit opportunities to learn English or upgrade professional skills.

Site Notes for: HIALEAH CAMPUS

The Hialeah Campus became MDC's seventh campus in 2005, serving the Greater Hialeah-Miami Lakes area. Offered courses support careers in Computer Technology, Office Technology, Electronics and Early Childhood Development, among others. The campus houses a large and comprehensive English language training program for speakers of other languages in various instructional formats.

Site Notes for: WEST CAMPUS

The West Campus opened for classes on March 1, 2006 and became a designated campus of Miami Dade College in July 2017, with the approval of the Southern Association of Colleges and Schools Commission on Colleges. It serves one of the fastest-growing locales in Miami-Dade County, including Doral and surrounding areas. Academic classes and corporate training programs are offered at the campus, which promises to be the next exciting learning environment for the Greater Miami community.

Site Notes for: ENTREPRENEURIAL ED

The Carrie P. Meek Entrepreneurial Education Center (MEEC) is a major outreach center of the North Campus, founded in 1989. The Center offers a vast array of college credit and non-credit courses. There are opportunities to pursue certificate and vocational programs as well as take part in a variety of seminars, conferences and workshops. Students at the MEEC can obtain workforce and business skills training to enter the labor market or become successful entrepreneurs.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 2: Survey Cost Summary

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

RECOMMENDATIONS FOR EDUCATIONAL PLANTS

MIAMI DADE COLLEGE

Survey : 3 Version : 1

Date : 5/11/2023 12:42:59 PM

The educational plant survey is a systematic study of present educational and ancillary plants and the determination of future needs. The survey is not directly concerned with the instructional program but the relationship of educational plants to the instructional program is such that judgments regarding the instructional program are necessarily a part of an educational plant survey.

The construction, remodeling, and renovation of educational facilities is a major undertaking. The educational plant survey aids in formulating plans for housing the educational activities of students and staff of the community college for the next several years and the survey considers the local comprehensive plan in its forecast strategies. This plan represents a careful study of all available data regarding the status of educational and ancillary facilities in relation to capital outlay full-time equivalency (COFTE) student membership and the projected changes in COFTE student membership. The intent of this educational plant survey is to ensure the thoughtful, orderly development of a program for providing educational and ancillary plants to house the educational and academic support activities of the college.

The recommendations in this educational plant survey furnish the foundation for a five-year plan for educational plants adopted by the Board of Trustees in accordance with §1013.31, Florida Statutes. Similarly, the recommendations serve as the basis for the proposed building program with projects listed in the order of priority submitted pursuant to State Requirements for Educational Facilities §2.1(5).

Educational plant survey cost estimates are determined based on cost factors that are 31 months (January, the midway point of the five-year survey period) from the official beginning of the survey period, which is July 1 of the first full year of the survey. The cost per square foot for new construction, remodeling, and renovation is based on actual statewide average construction cost data with a cost index increase applied to use the mid-point of the survey costs for planning purposes. The cost estimate process applies uniformly to all surveys in all colleges so that consistent planning can be made on a statewide basis.

Cost estimates for educational plant survey recommendations provide a general idea of anticipated costs and should not be interpreted as accurate estimates for particular projects. When educational plant survey recommendations become specific projects, professionals who can estimate the actual project costs based on current construction information must prepare the estimates.

The following table is a summary of square foot rates and cost estimates for the community college educational plant survey recommendations:

Recommendation Category	Cost per Square Foot	Estimated Cost
New Construction	399.00	895,565,475.00
Remodeling	228.97	45,909,666.00
Renovation	75.05	390,046,974.00
Site Recommendations		207,723,271.00
Estimated Total Survey Recommendation Cost		1,539,245,386.00

In addition, the educational plant survey provides six standard recommendations for college-wide application, as needed. The standard survey recommendations address general categories of physical plant needs that are likely to occur over time. No cost estimates are included for the standard survey recommendations.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 3: Expenditures By Project Type

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

FUND EXPENDITURES BY PROJECT TYPE

Site : NORTH CAMPUS

Site Number : 1

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	14,726,372	37,552,248	13,253,735	65,532,355
Furniture And Equipment	2,601,704	1,986,705	0	6,626,867	1,472,637	12,687,913
Remodeling, Renovation, Maintenance And Repair	65,640,543	36,354,787	18,501,136	13,184,015	23,762,663	157,443,144
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	68,242,247	38,341,492	33,227,508	57,363,130	38,489,035	235,663,412

Site : KENDALL CAMPUS

Site Number : 2

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	22,052,570	56,234,055	19,847,313	98,133,938
Furniture And Equipment	738,000	738,000	0	9,923,656	2,205,257	13,604,913
Remodeling, Renovation, Maintenance And Repair	77,801,442	48,848,678	19,833,631	33,340,781	71,501,080	251,325,612
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	78,539,442	49,586,678	41,886,201	99,498,492	93,553,650	363,064,463

Site : WOLFSON CAMPUS

Site Number : 3

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	38,620,168	98,481,428	34,758,152	171,859,748

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Site : WOLFSON CAMPUS

Site Number : 3

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Furniture And Equipment	3,325,378	3,325,378	0	17,379,075	3,862,016	27,891,847
Remodeling, Renovation, Maintenance And Repair	60,611,104	43,144,465	25,291,641	26,101,792	88,573,490	243,722,492
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0

Grand Total : 63,936,482 46,469,843 63,911,809 141,962,295 127,193,658 443,474,087

Site : MEDICAL CAMPUS

Site Number : 4

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	0	40,230,356	50,000,000	90,230,356
Furniture And Equipment	1,536,234	1,536,234	0	0	0	3,072,468
Remodeling, Renovation, Maintenance And Repair	26,641,086	14,800,729	4,901,771	5,262,171	8,578,498	60,184,255
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0

Grand Total : 28,177,320 16,336,963 4,901,771 45,492,527 58,578,498 153,487,079

Site : HOMESTEAD CAMPUS

Site Number : 5

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	15,769,806	11,924,462	4,544,590	8,576,518	2,423,816	43,239,192
Furniture And Equipment	2,368,240	2,368,240	120,239	3,775,469	838,993	9,471,181
Remodeling, Renovation, Maintenance And Repair	14,587,335	11,867,988	5,117,057	7,997,828	9,685,177	49,255,385

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Site : HOMESTEAD CAMPUS

Site Number : 5

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	32,725,381	26,160,690	9,781,886	20,349,815	12,947,986	101,965,758

Site : PADRON CAMPUS

Site Number : 6

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	7,427,894	7,427,894	7,936,349	20,237,691	7,142,715	50,172,543
Furniture And Equipment	2,038,539	1,041,768	0	3,571,357	793,634	7,445,298
Remodeling, Renovation, Maintenance And Repair	18,384,985	3,581,773	7,876,857	3,910,082	5,111,372	38,865,069
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	27,851,418	12,051,435	15,813,206	27,719,130	13,047,721	96,482,910

Site : HIALEAH CAMPUS

Site Number : 7

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	17,424,250	44,431,839	15,681,825	77,537,914
Furniture And Equipment	0	0	0	7,840,912	1,742,425	9,583,337
Remodeling, Renovation, Maintenance And Repair	3,382,463	4,137,971	1,617,646	3,187,416	21,170,978	33,496,474
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	3,382,463	4,137,971	19,041,896	55,460,167	38,595,228	120,617,725

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Site : WEST CAMPUS

Site Number : 8

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	7,231,323	0	5,398,630	13,766,506	4,858,768	31,255,227
Furniture And Equipment	1,482,421	1,482,421	0	2,429,383	539,862	5,934,087
Remodeling, Renovation, Maintenance And Repair	4,901,365	11,238,016	1,855,621	2,790,480	1,707,803	22,493,285
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	13,615,109	12,720,437	7,254,251	18,986,369	7,106,433	59,682,599

Site : ENTREPRENEURIAL ED

Site Number : 10

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Planning	0	0	0	0	0	0
Land Acquisition	0	0	0	0	0	0
Building Construction	0	0	4,001,651	10,204,210	3,601,486	17,807,347
Furniture And Equipment	0	0	0	1,800,742	400,165	2,200,907
Remodeling, Renovation, Maintenance And Repair	1,615,907	220,414	233,985	619,752	12,118,578	14,808,636
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	1,615,907	220,414	4,235,636	12,624,704	16,120,229	34,816,890

Report Run : 5/11/2023 12:39:07 PM

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 4: Expenditures By Fund Source

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

FUND EXPENDITURES BY FUND SOURCE

Site : NORTH CAMPUS

Site Number : 1

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	32,285,162	8,075,566	12,049,740	11,427,022	22,005,669	85,843,159
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	14,726,372	44,179,115	14,726,373	73,631,860
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	35,957,085	30,265,926	6,451,396	1,756,993	1,756,993	76,188,393
Student Capital Fee	0	0	0	0	0	0
Grand Total :	68,242,247	38,341,492	33,227,508	57,363,130	38,489,035	235,663,412

Site : KENDALL CAMPUS

Site Number : 2

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	53,569,806	24,617,042	13,785,200	30,625,683	68,785,982	191,383,713
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	22,052,570	66,157,711	22,052,570	110,262,851

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	24,969,636	24,969,636	6,048,431	2,715,098	2,715,098	61,417,899
Student Capital Fee	0	0	0	0	0	0
Grand Total :	78,539,442	49,586,678	41,886,201	99,498,492	93,553,650	363,064,463

Site : WOLFSON CAMPUS

Site Number : 3

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	22,245,605	6,008,583	11,865,972	19,085,861	81,557,558	140,763,579
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	38,620,168	115,860,503	38,620,167	193,100,838
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	41,690,877	40,461,260	13,425,669	7,015,932	7,015,932	109,609,670
Student Capital Fee	0	0	0	0	0	0
Grand Total :	63,936,482	46,469,843	63,911,809	141,962,296	127,193,657	443,474,087

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Site : MEDICAL CAMPUS

Site Number : 4

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	12,859,821	2,268,704	3,323,222	3,683,621	6,999,950	29,135,318
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	0	40,230,356	50,000,000	90,230,356
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	15,317,499	14,068,259	1,578,549	1,578,549	1,578,549	34,121,405
Student Capital Fee	0	0	0	0	0	0
Grand Total :	28,177,320	16,336,963	4,901,771	45,492,526	58,578,499	153,487,079

Site : HOMESTEAD CAMPUS

Site Number : 5

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	4,706,453	2,951,678	3,083,330	6,821,411	8,508,760	26,071,632
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	4,544,590	8,506,644	3,262,808	16,314,042

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	28,018,928	27,054,356	2,153,966	1,176,417	1,176,417	59,580,084
Student Capital Fee	0	0	0	0	0	0
Grand Total :	32,725,381	30,006,034	9,781,886	16,504,472	12,947,985	101,965,758

Site : PADRON CAMPUS

Site Number : 6

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	4,653,001	2,026,377	6,321,461	2,354,686	3,555,976	18,911,501
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	7,936,349	23,809,048	7,936,349	39,681,746
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	23,198,417	10,025,058	1,555,396	1,555,396	1,555,396	37,889,663
Student Capital Fee	0	0	0	0	0	0
Grand Total :	27,851,418	12,051,435	15,813,206	27,719,130	13,047,721	96,482,910

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Site : HIALEAH CAMPUS

Site Number : 7

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	686,970	1,442,478	483,608	2,053,378	20,036,950	24,703,384
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	17,424,250	52,272,751	17,424,251	87,121,252
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	2,695,493	2,695,493	1,134,038	1,134,037	1,134,028	8,793,089
Student Capital Fee	0	0	0	0	0	0
Grand Total :	3,382,463	4,137,971	19,041,896	55,460,166	38,595,229	120,617,725

Site : WEST CAMPUS

Site Number : 8

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	1,457,905	563,233	1,750,621	2,685,480	1,602,802	8,060,041
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	5,398,630	16,195,889	5,398,631	26,993,150

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	12,157,204	12,157,204	105,000	105,000	105,000	24,629,408
Student Capital Fee	0	0	0	0	0	0
Grand Total :	13,615,109	12,720,437	7,254,251	18,986,369	7,106,433	59,682,599

Site : ENTREPRENEURIAL ED

Site Number : 10

Fund Name	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	5 Year Total
Revenue Flowthrough And Interest	0	0	0	0	0	0
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	1,615,907	220,414	233,985	619,752	12,118,578	14,808,636
Removal Of Asbestos	0	0	0	0	0	0
New Construction	0	0	4,001,651	12,004,952	4,001,651	20,008,254
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	0	0	0	0	0	0
Local Funds	0	0	0	0	0	0
Student Capital Fee	0	0	0	0	0	0
Grand Total :	1,615,907	220,414	4,235,636	12,624,704	16,120,229	34,816,890

Report Run : 5/11/2023 12:39:07 PM

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 5: Capital Outlay Bonds

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 6: COFTE Projections

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : NORTH CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	6,965	7,050	7,164	7,165	7,159	7,161
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	6,965	7,050	7,164	7,165	7,159	7,161
VOCATIONAL FTE						
Annual FTE:	1,744	1,671	1,689	1,690	1,692	1,688
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	1,744	1,671	1,689	1,690	1,692	1,688
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	8,709	8,721	8,853	8,855	8,851	8,849

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE**CAMPUS :** ENTREPRENEURIAL ED**SURVEY :** 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	349	354	355	356	355	380
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	349	354	355	356	355	380
VOCATIONAL FTE						
Annual FTE:	2	2	2	2	2	2
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	2	2	2	2	2	2
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	351	356	357	358	357	382

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : KENDALL CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	11,080	11,233	11,251	11,253	11,248	11,254
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	11,080	11,233	11,251	11,253	11,248	11,254
VOCATIONAL FTE						
Annual FTE:	426	367	371	369	371	366
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	426	367	371	369	371	366
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	11,506	11,600	11,622	11,622	11,619	11,620

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : WOLFSON CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	10,224	10,358	10,882	11,417	12,741	12,743
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	10,224	10,358	10,882	11,417	12,741	12,743
VOCATIONAL FTE						
Annual FTE:	1,215	1,086	1,161	1,227	1,410	1,395
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	1,215	1,086	1,161	1,227	1,410	1,395
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	11,439	11,444	12,043	12,644	14,151	14,138

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : MEDICAL CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	180	230	248	227	250	257
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	180	230	248	227	250	257
VOCATIONAL FTE						
Annual FTE:	1,510	1,916	1,899	1,914	1,900	1,933
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	1,510	1,916	1,899	1,914	1,900	1,933
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	1,690	2,146	2,147	2,141	2,150	2,190

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : HOMESTEAD CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	1,959	1,991	1,985	2,257	2,256	2,254
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	1,959	1,991	1,985	2,257	2,256	2,254
VOCATIONAL FTE						
Annual FTE:	261	223	226	255	256	254
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	261	223	226	255	256	254
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	2,220	2,214	2,211	2,512	2,512	2,508

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : PADRON CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	3,256	3,291	3,439	3,440	3,473	3,560
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	3,256	3,291	3,439	3,440	3,473	3,560
VOCATIONAL FTE						
Annual FTE:	74	65	85	84	88	101
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	74	65	85	84	88	101
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	3,330	3,356	3,524	3,524	3,561	3,661

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : HIALEAH CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	3,502	3,551	3,552	3,554	3,549	3,551
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	3,502	3,551	3,552	3,554	3,549	3,551
VOCATIONAL FTE						
Annual FTE:	41	35	36	35	35	34
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	41	35	36	35	35	34
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	3,543	3,586	3,588	3,589	3,584	3,585

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : WEST CAMPUS

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	2,321	2,440	2,442	2,443	2,442	2,445
+/- FTE :	0	0	0	0	0	0
Adjusted Annual FTE:	2,321	2,440	2,442	2,443	2,442	2,445
VOCATIONAL FTE						
Annual FTE:	13	23	24	22	23	23
+/- FTE:	0	0	0	0	0	0
Adjusted Annual FTE:	13	23	24	22	23	23
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	2,334	2,463	2,466	2,465	2,465	2,468

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COFTE REPORT

COLLEGE : MIAMI DADE COLLEGE

CAMPUS : College Wide

SURVEY : 3 **Version :** 1

ITEM	2019 - 2020	2020 - 2021	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025
NON-VOCATIONAL FTE						
Annual FTE :	39,836	40,498	41,318	42,112	43,473	43,605
+/- FTE :	18	19	19	20	19	19
Adjusted Annual FTE:	39,854	40,517	41,337	42,132	43,492	43,624
VOCATIONAL FTE						
Annual FTE:	5,286	5,388	5,493	5,598	5,777	5,796
+/- FTE:	103	88	90	90	89	88
Adjusted Annual FTE:	5,389	5,476	5,583	5,688	5,866	5,884
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	45,243	45,993	46,920	47,820	49,358	49,508

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 7: Summary of Satisfactory Student Stations

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 1
 Site Name : NORTH CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	8,849	7,161	1,688
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	4,425	1,790	844
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	4,428	1,787	847
Program Facilities List (Under)/Over	4	-3	3

INVENTORY :

Student Stations :

Existing	4,125	873	709
Remodeling	300	400	130
Renovation	0	0	0
Construction	0	517	5

SURVEY PLAN :

Total Student Stations Planned	4,425	1,790	844
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	8,850	7,160	1,688
2024 - 2025 Out Year CO-FTE	8,849	7,161	1,688
COFTE Survey Plan (Under)/Over	1	-1	0

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 2
 Site Name : KENDALL CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	11,620	11,254	366
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	5,810	2,814	183
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	5,811	2,804	181
Program Facilities List (Under)/Over	1	-10	-2

INVENTORY :

Student Stations :

Existing	4,969	1,528	248
Remodeling	0	30	0
Renovation	0	0	0
Construction	841	1,255	0

SURVEY PLAN :

Total Student Stations Planned	5,810	2,813	248
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	11,620	11,252	496
2024 - 2025 Out Year CO-FTE	11,620	11,254	366
COFTE Survey Plan (Under)/Over	0	-2	130

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 3
 Site Name : WOLFSON CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	14,138	12,743	1,395
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	7,069	3,186	698
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	7,070	3,186	698
Program Facilities List (Under)/Over	1	0	1

INVENTORY :

Student Stations :

Existing	3,907	845	198
Remodeling	0	0	20
Renovation	0	0	0
Construction	3,162	2,341	478

SURVEY PLAN :

Total Student Stations Planned	7,069	3,186	696
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	14,138	12,744	1,392
2024 - 2025 Out Year CO-FTE	14,138	12,743	1,395
COFTE Survey Plan (Under)/Over	0	1	-3

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 4
 Site Name : MEDICAL CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	2,190	257	1,933
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,095	64	967
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	1,104	66	965
Program Facilities List (Under)/Over	9	2	-2

INVENTORY :

Student Stations :

Existing	1,549	72	196
Remodeling	0	0	0
Renovation	0	0	0
Construction	0	0	720

SURVEY PLAN :

Total Student Stations Planned	1,549	72	916
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	3,098	288	1,832
2024 - 2025 Out Year CO-FTE	2,190	257	1,933
COFTE Survey Plan (Under)/Over	908	31	-101

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 5
 Site Name : HOMESTEAD CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	2,508	2,254	254
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,254	564	127
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	1,254	565	129
Program Facilities List (Under)/Over	0	2	2

INVENTORY :

Student Stations :

Existing	1,207	236	115
Remodeling	43	0	0
Renovation	0	0	0
Construction	0	325	12

SURVEY PLAN :

Total Student Stations Planned	1,250	561	127
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	2,500	2,244	254
2024 - 2025 Out Year CO-FTE	2,508	2,254	254
COFTE Survey Plan (Under)/Over	-8	-10	0

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 6
 Site Name : PADRON CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	3,661	3,560	101
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,831	890	51
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	1,833	890	52
Program Facilities List (Under)/Over	3	0	2

INVENTORY :

Student Stations :

Existing	1,750	503	20
Remodeling	80	386	30
Renovation	0	0	0
Construction	0	0	0

SURVEY PLAN :

Total Student Stations Planned	1,830	889	50
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	3,660	3,556	100
2024 - 2025 Out Year CO-FTE	3,661	3,560	101
COFTE Survey Plan (Under)/Over	-1	-4	-1

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 7
 Site Name : HIALEAH CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	3,585	3,551	34
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,793	888	17
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	1,794	885	17
Program Facilities List (Under)/Over	2	-3	0

INVENTORY :

Student Stations :

Existing	1,276	118	0
Remodeling	0	0	0
Renovation	0	0	0
Construction	516	769	17

SURVEY PLAN :

Total Student Stations Planned	1,792	887	17
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	3,584	3,548	34
2024 - 2025 Out Year CO-FTE	3,585	3,551	34
COFTE Survey Plan (Under)/Over	-1	-3	0

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 8
 Site Name : WEST CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	2,468	2,445	23
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,234	611	12
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	1,232	624	11
Program Facilities List (Under)/Over	-2	13	-1

INVENTORY :

Student Stations :

Existing	1,347	114	0
Remodeling	0	313	0
Renovation	0	0	0
Construction	0	183	17

SURVEY PLAN :

Total Student Stations Planned	1,347	610	17
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	2,694	2,440	34
2024 - 2025 Out Year CO-FTE	2,468	2,445	23
COFTE Survey Plan (Under)/Over	226	-5	11

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE Date : 5/11/2023 12:42:59 PM
 Site Number : 10
 Site Name : ENTREPRENEURIAL ED

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2024 - 2025 Out Year CO-FTE	382	380	2
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	191	95	1
Recommended Student Stations 2024 - 2025 Out Year CO-FTE	195	96	0
Program Facilities List (Under)/Over	4	1	-1

INVENTORY :

Student Stations :

Existing	305	32	0
Remodeling	0	0	0
Renovation	0	0	0
Construction	0	62	0

SURVEY PLAN :

Total Student Stations Planned	305	94	0
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	610	376	0
2024 - 2025 Out Year CO-FTE	382	380	2
COFTE Survey Plan (Under)/Over	228	-4	-2

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 8: Existing Satisfactory Student Stations By Space and Facility

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : NORTH CAMPUS

Site No : 1

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	PAUL R SCOTT HALL	Building	Permanent	Remodeling C	1536	75	50	1,661	199,144	205,868
2	MITCHELL WOLFSON	Building	Permanent	Remodeling C	0	58	236	294	136,605	164,998
3	MCARTHUR HALL	Building	Permanent	Remodeling C	567	0	341	908	104,375	127,999
4	LEROY COLLINS CENTER	Building	Permanent	Remodeling B	29	0	0	29	57,377	83,567
5	WILLIAM PAWLEY CT	Building	Permanent	Remodeling B	0	168	0	168	58,538	71,710
6	LEARNING CENTER	Building	Permanent	Remodeling B	0	0	0	0	11,892	14,000
7	GARTH C REEVES HALL	Building	Permanent	Remodeling C	903	123	0	1,026	74,235	77,766
8	SCHOOL JUSTICE/SAFE	Building	Permanent	Remodeling B	349	0	31	380	53,396	54,724
9	ENVIR SCIENCE/JUSTIC	Building	Permanent	Remodeling A	352	0	6	358	23,338	32,560
10	FIRE SCIENCE ACADEMY	Building	Permanent	Remodeling B	0	0	14	14	8,544	8,692
11	FIRE SCI BURN BLDG	Building	Permanent	Remodeling A	0	0	0	0	3,167	3,474
12	FIRE SCIENCE TOWER	Building	Permanent	Remodeling C	0	0	0	0	6,689	7,611
13	GREEN URBAN LIVING C	Building	Permanent	Remodeling C	40	0	0	40	7,247	7,250
14	JFK CENTER - GYM	Building	Permanent	Remodeling C	0	0	0	0	0	77,489
15	AQUATIC CENTER	Building	Permanent	Remodeling A	114	0	0	114	20,017	21,617
16	PRESCHOOL LAB	Building	Permanent	Remodeling A	0	0	0	0	19,160	20,311
17	DRIVING RANGE/TOWER	Building	Permanent	Remodeling C	0	0	0	0	1,178	1,249
18	FIRE ENGINE STORAGE	Building	Permanent	Remodeling B	0	0	0	0	1,521	1,612
19	COLLEGE SERVICES	Building	Permanent	Remodeling B	0	0	0	0	32,707	34,702
20	UTILITIES BUILDING	Building	Permanent	Remodeling C	0	0	21	21	7,513	7,856
21	RECEIVING BUILDING	Building	Permanent	Remodeling A	0	0	0	0	1,525	1,578
22	INFORMATION BOOTH	Building	Permanent	Remodeling B	0	0	0	0	37	242
23	CHEMICAL STORAGE	Building	Permanent	Remodeling C	0	0	0	0	122	129
24	MOTOR POOL BUILDING	Building	Permanent	Remodeling C	0	0	0	0	7,022	7,089
25	CHILLER (EAST BLDG 1	Building	Permanent	Remodeling C	0	0	0	0	3,735	3,844
26	FLAMMABLE STORAGE	Building	Permanent	Remodeling C	0	0	0	0	440	466

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : NORTH CAMPUS

Site No : 1

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
27	FERTILIZER STORAGE	Building	Permanent	Remodeling C	0	0	0	0	800	848
28	TENNIS PAVILION	Building	Permanent	Remodeling C	0	0	0	0	2,888	3,063
29	STORAGE	Building	Permanent	Remodeling C	0	0	0	0	1,740	1,844
30	GATE HOUSE	Building	Permanent	Remodeling C	0	0	0	0	140	148
31	DUGOUT 1_FIELD A	Building	Permanent	Remodeling C	0	0	0	0	400	424
32	DUGOUT 2_FIELD A	Building	Permanent	Remodeling C	0	0	0	0	400	424
33	FUNERAL SCIENCES	Building	Permanent	Remodeling C	0	0	10	10	3,623	4,042
34	VEHICLE STORAGE	Building	Permanent	Remodeling C	0	0	0	0	1,470	1,559
35	STORAGE	Building	Permanent	Remodeling C	0	0	0	0	800	848
36	SCIENCE COMPLEX	Building	Permanent	Remodeling A	235	449	0	684	92,590	100,170
37	CHILLER ANEX SCIENCE	Building	Permanent	Remodeling A	0	0	0	0	1,501	1,831
40	SWIM DIVE POOL	Outdoor Swimming Pool	Permanent	Remodeling C	0	0	0	0	0	11,280
41	BASEBALL FIELD A	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	211,300
42	BASEBALL FIELD B	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	99,225
43	BASEBALL FIELD C	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	57,800
44	ATHLETIC FIELD	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	904,923
45	TENNIS COURTS A	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	49,914
46	TENNIS COURTS B	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	49,914
48	HANDBALL COURTS	Athletic Area	Permanent	Remodeling C	0	0	0	0	0	1,600
50	PARKING LOT 1	Parking Area	Permanent	Remodeling C	0	0	0	0	0	63,300
51	PARKING LOT 2	Parking Area	Permanent	Remodeling C	0	0	0	0	0	158,400
52	PARKING LOT 3	Parking Area	Permanent	Remodeling C	0	0	0	0	0	121,600
53	PARKING LOT 4	Parking Area	Permanent	Remodeling C	0	0	0	0	0	163,400

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : NORTH CAMPUS

Site No : 1

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
54	PARKING LOT 5	Parking Area	Permanent	Remodeling C	0	0	0	0	0	24,000
55	PARKING LOT 6	Parking Area	Permanent	Remodeling C	0	0	0	0	0	117,800
56	PARKING LOT 7	Parking Area	Permanent	Remodeling C	0	0	0	0	0	88,000
57	PARKING LOT 8	Parking Area	Permanent	Remodeling C	0	0	0	0	0	59,400
58	PARKING LOT 9	Parking Area	Permanent	Remodeling C	0	0	0	0	0	47,400
59	PARKING LOT 10	Parking Area	Permanent	Remodeling C	0	0	0	0	0	73,300
60	PARKING LOT 11	Parking Area	Permanent	Remodeling C	0	0	0	0	0	126,000
61	PARKING LOT 12	Parking Area	Permanent	Remodeling C	0	0	0	0	0	9,600
62	PARKING LOT 13	Parking Area	Permanent	Remodeling C	0	0	0	0	0	249,600
63	PARKING LOT 14	Parking Area	Permanent	Remodeling C	0	0	0	0	0	28,900
64	PARKING LOT 15	Parking Area	Permanent	Remodeling C	0	0	0	0	0	205,200
65	PARKING LOT 16	Parking Area	Permanent	Remodeling C	0	0	0	0	0	56,000
66	PARKING LOT 17	Parking Area	Permanent	Remodeling C	0	0	0	0	0	70,250
67	PARKING LOT 18	Parking Area	Permanent	Remodeling C	0	0	0	0	0	140,000
68	PARKING LOT 19	Parking Area	Permanent	Remodeling C	0	0	0	0	0	234,100
69	PARKING LOT 20	Parking Area	Permanent	Remodeling C	0	0	0	0	0	205,450
70	PARKING LOT 21	Parking Area	Permanent	Remodeling C	0	0	0	0	0	3,886
901	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	9,600
902	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	825
903	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	360
904	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	960
905	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	576

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : NORTH CAMPUS

Site No : 1

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
906	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,344
907	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	9,136
908	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	7,776
909	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,089
910	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,128
911	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	766
912	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,136
913	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,089
914	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	768
915	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	6,768
916	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	384
917	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	384
918	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,728
1401	GREEN HOUSE 1	Building	Permanent	Remodeling A	0	0	0	0	1,419	1,476
1402	GREEN HOUSE 2	Building	Permanent	Remodeling A	0	0	0	0	1,419	1,476
1403	GREEN HOUSE 3	Building	Permanent	Remodeling A	0	0	0	0	537	569
1701	PALMETUM	Other	Permanent	Remodeling A	0	0	0	0	0	148,104
1702	CHICKEE HUT	Building	Permanent	Remodeling A	0	0	0	0	1,283	1,360
NORTH CAMPUS Totals :					4,125	873	709	5,707	950,534	4,984,948
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : KENDALL CAMPUS

Site No : 2

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	PETER MASIKO JR BLDG	Building	Permanent	Remodeling C	0	0	0	0	29,855	37,142
2	NILES TRAMMELL CT	Building	Permanent	Remodeling B	684	49	23	756	144,325	151,878
3	LEONARD A USINA HALL	Building	Permanent	Remodeling C	519	564	17	1,100	133,019	148,660
4	DANIEL K GILL BLDG	Building	Permanent	Remodeling A	714	0	29	743	42,322	44,614
5	PUBLIC SAFETY AND CO	Building	Permanent	Remodeling B	435	79	0	514	47,270	49,346
6	MC CARTHY HALL	Building	Permanent	Remodeling B	573	171	167	911	143,525	170,659
7	THEODORE R GIBSON CT	Building	Permanent	Remodeling B	158	0	0	158	129,259	142,857
8	MARIA HERNANDEZ CT	Building	Permanent	Remodeling B	157	183	12	352	87,230	88,055
9	JACK KASSEWITZ HALL	Building	Permanent	Remodeling B	648	0	0	648	87,724	89,431
10	CT FOR THE ARTS	Building	Permanent	Remodeling B	293	351	0	644	99,122	110,464
11	STUDENT UNION	Building	Permanent	Remodeling B	0	0	0	0	22,021	22,058
12	ARTS ANNEX	Building	Permanent	Remodeling B	0	101	0	101	16,980	17,651
14	CONFERENCE CENTER	Building	Permanent	Remodeling A	0	0	0	0	13,665	15,716
15	MBF GLOBAL BUSINESS	Building	Permanent	Remodeling A	755	0	0	755	122,022	141,326
18	BLDG L (DISTRICT OFF	Building (with parking)	Permanent	Remodeling A	0	0	0	0	281,504	317,239
20	MOTOR POOL	Building	Permanent	Remodeling A	0	0	0	0	2,968	3,338
21	GROUNDS MAINTENANCE	Building	Permanent	Remodeling C	0	0	0	0	3,318	3,450
22	CTR ENVIRONMENT	Building	Permanent	Remodeling C	0	0	0	0	5,922	5,923
23	INFORMATION BOOTH	Building	Permanent	Remodeling B	0	0	0	0	27	29
24	TENNIS PAVILION	Building	Permanent	Remodeling A	0	0	0	0	2,636	2,800
25	HANDBALL STORAGE 1	Building	Permanent	Remodeling A	0	0	0	0	306	324
26	HANDBALL STORAGE 2	Building	Permanent	Remodeling A	0	0	0	0	324	343
27	DUGOUT 1	Building	Permanent	Remodeling C	0	0	0	0	351	372
28	DUGOUT 2	Building	Permanent	Remodeling C	0	0	0	0	333	353
29	TICKET BOOTH	Building	Permanent	Remodeling B	0	0	0	0	173	184

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : KENDALL CAMPUS

Site No : 2

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
30	HORTICULTURE CENTER	Building	Permanent	Remodeling C	0	0	0	0	1,484	1,573
40	SWIM DIVE POOL	Outdoor Swimming Pool	Permanent	Remodeling C	0	0	0	0	0	15,580
41	BASEBALL FIELD	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	260,000
42	SOFTBALL FIELD	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	57,800
43	TRACK AND FIELD	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	188,000
44	TENNIS COURTS	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	104,050
45	HANDBALL COURTS	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	6,400
46	ATHLETIC FIELD	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	867,800
47	SOCCER FIELD	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	86,400
48	BASKETBALL COURT	Athletic Area	Permanent	Remodeling A	0	0	0	0	0	17,000
49	BALL FIELD RESTROOMS	Building	Permanent	Remodeling A	0	0	0	0	1,083	1,126
50	PARKING LOT 1	Parking Area	Permanent	Remodeling B	0	0	0	0	0	41,800
51	PARKING LOT 2	Parking Area	Permanent	Remodeling B	0	0	0	0	0	484,400
52	PARKING LOT 3	Parking Area	Permanent	Remodeling B	0	0	0	0	0	188,800
53	PARKING LOT 4	Parking Area	Permanent	Remodeling B	0	0	0	0	0	43,793
54	PARKING LOT 5	Parking Area	Permanent	Remodeling B	0	0	0	0	0	99,800
55	PARKING LOT 6	Parking Area	Permanent	Remodeling B	0	0	0	0	0	9,286
56	PARKING LOT 7	Parking Area	Permanent	Remodeling B	0	0	0	0	0	139,500
57	PARKING LOT 8	Parking Area	Permanent	Remodeling B	0	0	0	0	0	99,600
58	PARKING LOT 9	Parking Area	Permanent	Remodeling B	0	0	0	0	0	68,374
59	PARKING LOT 10	Parking Area	Permanent	Remodeling B	0	0	0	0	0	70,000
60	PARKING LOT 11	Parking Area	Permanent	Remodeling B	0	0	0	0	0	105,400

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : KENDALL CAMPUS

Site No : 2

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
61	PARKING LOT 12	Parking Area	Permanent	Remodeling B	0	0	0	0	0	145,700
62	PARKING LOT 13	Parking Area	Permanent	Remodeling B	0	0	0	0	0	32,300
63	PARKING LOT 14	Parking Area	Permanent	Remodeling B	0	0	0	0	0	8,400
64	PARKING LOT 15	Parking Area	Permanent	Remodeling B	0	0	0	0	0	14,236
65	PARKING LOT 16	Parking Area	Permanent	Remodeling B	0	0	0	0	0	66,432
70	STORAGE CONTAINER_BL	Other	Permanent	Satisfactory	0	0	0	0	0	170
71	STORAGE CONTAINER_BL	Other	Permanent	Satisfactory	0	0	0	0	0	170
72	STOR CONT LOT EAST G	Other	Permanent	Satisfactory	0	0	0	0	0	340
73	STOR CONT LOT EAST G	Other	Permanent	Satisfactory	0	0	0	0	0	340
74	STOR CONT LOT EAST G	Other	Permanent	Satisfactory	0	0	0	0	0	340
75	STOR CONT LOT EAST G	Other	Permanent	Satisfactory	0	0	0	0	0	340
76	STORAGE CONTAINER_SO	Other	Permanent	Satisfactory	0	0	0	0	0	170
77	STORAGE CONTAINER_SO	Other	Permanent	Satisfactory	0	0	0	0	0	170
78	STO CON LOT EAST MOT	Other	Permanent	Satisfactory	0	0	0	0	0	170
79	STOR CONT LOT EAST G	Other	Permanent	Satisfactory	0	0	0	0	0	340
80	STOR CONT N. GROUND	Other	Permanent	Satisfactory	0	0	0	0	0	340
81	STOR CONT EAST MOTOR	Other	Permanent	Satisfactory	0	0	0	0	0	340
82	STOR CONT EAST MOTOR	Other	Permanent	Satisfactory	0	0	0	0	0	340
83	STOR CONT BASEBALL	Other	Permanent	Satisfactory	0	0	0	0	0	360
301	PORTABLE_CHEM LAB	Building	Temporary	Remodeling A	0	15	0	15	819	868
302	PORTABLE_CHEM LAB SE	Building	Temporary	Remodeling A	0	0	0	0	819	868
303	PORTABLE_BIOLOGY LAB	Building	Temporary	Remodeling A	0	15	0	15	819	868

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : KENDALL CAMPUS

Site No : 2

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
901	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,702
902	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,892
903	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,008
904	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,008
905	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	6,266
906	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	744
907	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	528
908	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,172
909	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,328
910	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,458
911	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,500
912	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,600
913	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,164
914	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	888
915	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,320
916	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	420
917	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	5,808
918	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	1,464
919	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	444
920	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	732
921	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	2,328
922	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	576

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : KENDALL CAMPUS

Site No : 2

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
923	COVERED WALKWAY	Covered Walkway	Permanent	Remodeling B	0	0	0	0	0	576
2201	VISITOR PAVILION	Building	Permanent	Remodeling A	0	0	0	0	888	906
2202	PORTABLE CLASSROOM	Building	Temporary	Remodeling C	33	0	0	33	1,174	1,245
2203	ANIMAL HOUSING	Building	Permanent	Remodeling C	0	0	0	0	494	509
2204	STORAGE - ENVIRONMEN	Building	Permanent	Remodeling B	0	0	0	0	600	636
2205	ROOF COVERED TABLES	Building	Permanent	Remodeling C	0	0	0	0	871	897
2206	POTTING SHED - ENVIR	Building	Permanent	Remodeling C	0	0	0	0	322	332
2207	OPEN WOOD SHED 2	Building	Permanent	Remodeling C	0	0	0	0	446	459
2208	STORAGE - GARAGE ENV	Building	Permanent	Remodeling A	0	0	0	0	276	284
2209	ROOF COVERED TABLES	Building	Permanent	Remodeling C	0	0	0	0	446	459
2210	CHICKEE - BUTTERFLY	Building	Permanent	Remodeling B	0	0	0	0	601	619
3001	WOOD SHED - HORTICUL	Building	Permanent	Remodeling B	0	0	0	0	1,080	1,112
3002	SALES OFFICE HORTICU	Building	Permanent	Remodeling B	0	0	0	0	160	165
3003	ELECTRICAL/PUMP	Building	Permanent	Remodeling A	0	0	0	0	254	262
3004	SALES SHED- HORTICULT	Building	Permanent	Remodeling B	0	0	0	0	730	752
3005	GREENHOUSE	Building	Permanent	Remodeling A	0	0	0	0	2,059	2,121
3006	SAWTOOTH SHADEHOUSE	Building	Permanent	Remodeling B	0	0	0	0	2,684	2,765
3007	POTTING SHED	Building	Permanent	Remodeling C	0	0	0	0	4,273	4,401
3008	TALL SHADEHOUSE	Building	Permanent	Remodeling C	0	0	0	0	3,575	3,682
KENDALL CAMPUS Totals :					4,969	1,528	248	6,745	1,442,158	4,856,828
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : WOLFSON CAMPUS

Site No : 3

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	WOLFSON CAMPUS 1	Building	Permanent	Remodeling C	355	163	21	539	232,452	243,352
2	WOLFSON CAMPUS 2	Building	Permanent	Remodeling B	830	215	36	1,081	148,548	157,209
3	WOLFSON CAMPUS 3	Building	Permanent	Remodeling A	1135	75	4	1,214	207,927	227,387
4	NEW WORLD SCHOOL ART	Building	Permanent	Remodeling B	0	0	0	0	19,394	26,638
5	BONNIE P MCCABE HALL	Building	Permanent	Remodeling B	267	18	0	285	110,530	193,871
6	WOLFSON CAMPUS 6	Building	Permanent	Remodeling A	67	48	0	115	14,169	15,747
7	WOLFSON CAMPUS 7 ETC	Building (with parking)	Permanent	Remodeling A	268	0	55	323	799,213	850,280
8	WOLFSON CAMPUS 8	Building	Permanent	Remodeling A	985	326	0	1,311	115,359	121,824
9	CULINARY ARTS INSTIT	Building	Permanent	Remodeling A	0	0	82	82	32,022	34,824
10	FREEDOM TOWER	Building	Permanent	Remodeling C	0	0	0	0	85,435	92,012
11	WOLFSON CAMPUS 11	Building (with parking)	Permanent	Satisfactory	0	0	0	0	211,256	211,257
50	PARKING LOT 3	Parking Area	Permanent	Remodeling B	0	0	0	0	0	59,900
51	PARKING LOT 4	Parking Area	Permanent	Remodeling B	0	0	0	0	0	19,132
52	PARKING LOT 1	Parking Area	Permanent	Remodeling B	0	0	0	0	0	111,637
53	PARKING LOT 2	Parking Area	Permanent	Remodeling A	0	0	0	0	0	28,500
WOLFSON CAMPUS Totals :					3,907	845	198	4,950	1,976,305	2,393,570

Total UnSatisfactory NSF :

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : MEDICAL CAMPUS

Site No : 4

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	MEYERS HALL	Building	Permanent	Remodeling C	129	0	191	320	127,655	135,677
2	MEDICAL CT BLDG 2	Building	Permanent	Remodeling A	451	0	5	456	51,083	52,019
3	CLIS	Building	Permanent	Satisfactory	969	72	0	1,041	126,624	131,332
5	PARKING GARAGE	Building (with parking)	Permanent	Satisfactory	0	0	0	0	504,061	536,210
50	WEST PARKING LOT	Parking Area	Permanent	Remodeling C	0	0	0	0	0	195,584
51	EAST PARKING LOT	Parking Area	Permanent	Remodeling A	0	0	0	0	0	30,835
MEDICAL CAMPUS Totals :					1,549	72	196	1,817	809,423	1,081,657
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : HOMESTEAD CAMPUS

Site No : 5

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	ADMINISTRATION BLDG	Building	Permanent	Remodeling B	81	0	0	81	25,793	26,828
2	FACULTY/ADMIN BLDG	Building	Permanent	Remodeling A	0	0	0	0	25,118	27,679
4	TECHNOLOGY/INFO CT	Building	Permanent	Remodeling A	276	67	53	396	58,457	60,612
6	AVIATION TRAINING	Building	Permanent	Remodeling A	222	0	43	265	42,421	45,725
7	CLASSROOM/LAB BLDG	Building	Permanent	Remodeling A	628	139	19	786	49,889	54,042
8	PHYSICAL PLANT BLDG	Building	Permanent	Remodeling A	0	30	0	30	18,600	22,260
50	PARKING LOT	Parking Area	Permanent	Remodeling A	0	0	0	0	0	76,380
51	PARKING LOT	Parking Area	Permanent	Remodeling A	0	0	0	0	0	36,686
52	PARKING LOT	Parking Area	Permanent	Remodeling A	0	0	0	0	0	22,994
53	PARKING LOT	Parking Area	Permanent	Remodeling A	0	0	0	0	0	87,315
54	PARKING LOT	Parking Area	Permanent	Remodeling C	0	0	0	0	0	743
55	FUTURE PARKING LOT	Other	Permanent	Remodeling C	0	0	0	0	0	113,256
56	FUTURE PARKING LOT	Other	Permanent	Remodeling C	0	0	0	0	0	152,028
57	FUTURE PARKING LOT	Other	Permanent	Remodeling C	0	0	0	0	0	70,700
HOMESTEAD CAMPUS Totals :					1,207	236	115	1,558	220,278	797,248
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : PADRON CAMPUS

Site No : 6

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	ACADEMIC BUILDING	Building	Permanent	Remodeling A	336	307	0	643	76,789	98,553
2	CLASSROOM BUILDING	Building	Permanent	Remodeling A	0	0	0	0	2,241	2,357
3	INTERAMERICAN	Building	Permanent	Remodeling A	239	107	20	366	33,702	35,845
4	PARKING STRUCTURE	Building (with parking)	Permanent	Remodeling A	0	0	0	0	148,122	155,510
5	SERVICE BUILDING	Building	Permanent	Remodeling A	0	0	0	0	2,744	3,100
6	INTERAMERICAN PLAZA	Building (with parking)	Permanent	Remodeling C	1175	89	0	1,264	437,042	468,408
20	KOUBEK MANSION	Building	Permanent	Remodeling C	0	0	0	0	4,452	4,719
21	KOUBEK CLASSROOM	Building	Permanent	Remodeling C	0	0	0	0	7,401	7,845
22	KOUBEK AUDITORIUM	Building	Permanent	Remodeling C	0	0	0	0	6,873	7,285
23	KOUBEK GAZEBO	Building	Permanent	Remodeling C	0	0	0	0	113	120
50	PARKING LOT 1	Parking Area	Permanent	Remodeling A	0	0	0	0	0	124,684
60	KOUBEK PARKING (33)	Parking Area	Permanent	Remodeling C	0	0	0	0	0	18,668
PADRON CAMPUS Totals :					1,750	503	20	2,273	719,479	927,094
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : HIALEAH CAMPUS

Site No : 7

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	ACADEMIC BLDG	Building	Permanent	Remodeling A	590	0	0	590	54,388	57,232
2	BLDG_2000	Building	Permanent	Satisfactory	686	118	0	804	87,119	94,730
3	CENTRAL UTILITIES PL	Building	Permanent	Remodeling A	0	0	0	0	2,256	2,582
5	BUILDING 5000	Building (with parking)	Permanent	Remodeling A	0	0	0	0	374,697	400,014
50	PARKING LOT 1	Parking Area	Permanent	Remodeling A	0	0	0	0	0	6,079
52	PARKING LOT 3	Parking Area	Permanent	Remodeling A	0	0	0	0	0	7,291
53	PARKING LOT 4	Parking Area	Permanent	Remodeling A	0	0	0	0	0	25,747
54	PARKING LOT 5	Parking Area	Permanent	Remodeling A	0	0	0	0	0	0
HIALEAH CAMPUS Totals :					1,276	118	0	1,394	518,460	593,675

Total UnSatisfactory NSF :

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : WEST CAMPUS

Site No : 8

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	CENTRAL BUILDING	Building	Permanent	Remodeling C	862	0	0	862	150,917	155,121
2	NORTH WAREHOUSE	Building	Permanent	Remodeling C	485	114	0	599	102,447	103,983
3	PARKING GARAGE	Parking Garage	Permanent	Satisfactory	0	0	0	0	701,339	725,131
50	PARKING LOT 1	Parking Area	Permanent	Remodeling A	0	0	0	0	0	65,924
51	PARKING LOT 2	Parking Area	Permanent	Remodeling A	0	0	0	0	0	57,164
WEST CAMPUS Totals :					1,347	114	0	1,461	954,703	1,107,323

Total UnSatisfactory NSF :

Total UnSatisfactory Student Stations :

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : MIAMI DADE COLLEGE

Survey : 3 **Version :** 1

Site : ENTREPRENEURIAL ED

Site No : 10

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	MEEK ENTRPREUNEUR CT	Building	Permanent	Remodeling B	305	32	0	337	30,209	31,652
2	PARKING LOT 1	Parking Area	Permanent	Remodeling A	0	0	0	0	0	10,000
3	PARKING LOT 2	Parking Area	Permanent	Remodeling A	0	0	0	0	0	26,500
ENTREPRENEURIAL ED Totals :					305	32	0	337	30,209	68,152
Total UnSatisfactory NSF :										
Total UnSatisfactory Student Stations :										
College-wide Facility Totals :					20,435	4,321	1,486	26,242	7,621,549	16,810,495

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 9: Summary of Existing And Recommended Square Footage

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:42:59 PM

Site Number : 1

Admin Site : NO

Site Name : NORTH CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	119,925	109,383	-10,542	0	6,697	116,080
Non-Vocational Spaces	118,460	76,464	-41,996	18,261	22,600	117,325
Vocational Spaces	86,548	79,950	-6,598	480	12,030	92,460
Physical Education	54,245	11,633	-42,612	42,612	0	54,245
Subtotal	379,178	277,430	-101,748	61,353	41,327	380,110
Academic Support:						
Library	98,439	45,755	-52,684	52,684	-26,348	72,091
Audiovisual	16,247	6,354	-9,893	9,892	0	16,246
Auditorium/Exhibition	30,547	20,287	-10,260	10,260	-5,398	25,149
Student Services	66,368	22,928	-43,440	43,440	0	66,368
Subtotal	211,600	95,324	-116,276	116,276	-31,746	179,854
Institutional Support:						
Office	110,613	137,292	26,680	0	0	137,292
Support Services	35,070	70,201	35,131	0	0	70,201
Custodial Services	9,734	4,334	-5,400	5,400	0	9,734
Sanitation:						
*Student Restrooms	13,274	4,870	-8,403	0	0	4,870
*Staff/Public Restrooms	2,212	793	-1,419	0	0	793
Subtotal	170,902	217,490	46,588	5,400	0	222,890
*HVAC /Mech/Sanitation	45,701	79,101	33,400	0	0	79,101
Circulation	274,509	286,838	-12,329	0	-15,814	271,024
Total Net Square Feet	1,081,890	956,183	-184,968	183,029	-6,233	1,132,979

Leased / Rented NSF not in Survey : 77,488

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 2

Admin Site : NO

Site Name : KENDALL CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	156,450	133,024	-23,426	23,575	0	156,599
Non-Vocational Spaces	157,981	103,431	-54,550	33,300	909	137,640
Vocational Spaces	15,484	40,909	25,425	0	0	40,909
Physical Education	68,100	53,943	-14,157	14,157	0	68,100
Subtotal	398,015	331,307	-66,708	71,032	909	403,248
Academic Support:						
Library	128,920	42,934	-85,986	85,986	0	128,920
Audiovisual	16,496	9,259	-7,237	5,245	0	14,504
Auditorium/Exhibition	38,860	25,736	-13,124	15,107	-1,769	39,074
Student Services	87,150	37,949	-49,201	49,201	0	87,150
Subtotal	271,426	115,878	-155,548	155,539	-1,769	269,648
Institutional Support:						
Office	145,250	183,167	37,917	0	0	183,167
Support Services	40,735	279,203	238,468	0	-950	278,253
Custodial Services	12,782	6,310	-6,472	6,565	0	12,875
Sanitation:						
*Student Restrooms	17,430	9,737	-7,693	0	0	9,737
*Staff/Public Restrooms	2,905	1,585	-1,320	0	0	1,585
Subtotal	219,102	480,002	260,900	6,565	-950	485,617
*HVAC /Mech/Sanitation	53,313	86,820	33,507	0	0	86,820
Circulation	320,231	436,776	-116,545	0	0	436,776
Total Net Square Feet	1,262,085	1,450,783	96,684	233,136	-1,810	1,682,109

Leased / Rented NSF not in Survey : 0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 3

Admin Site : YES

Site Name : WOLFSON CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	191,900	102,714	-89,186	88,575	-1,660	189,629
Non-Vocational Spaces	186,679	73,149	-113,530	114,465	-2,407	185,207
Vocational Spaces	74,487	21,348	-53,139	43,490	3,715	68,553
Physical Education	80,690	2,458	-78,232	78,232	0	80,690
Subtotal	533,756	199,669	-334,087	324,762	-352	524,079
Academic Support:						
Library	156,618	37,165	-119,453	119,453	0	156,618
Audiovisual	22,653	1,989	-20,664	20,664	0	22,653
Auditorium/Exhibition	46,414	32,966	-13,448	11,948	1,500	46,414
Student Services	106,035	18,766	-87,269	87,269	0	106,035
Subtotal	331,720	90,886	-240,834	239,334	1,500	331,720
Institutional Support:						
Office	325,249	163,797	-161,452	9,500	-130	173,167
Support Services	59,536	975,053	915,517	0	-3,554	971,499
Custodial Services	15,552	7,287	-8,265	8,309	-44	15,552
Sanitation:						
*Student Restrooms	21,207	6,701	-14,506	0	0	6,701
*Staff/Public Restrooms	3,535	1,091	-2,444	0	0	1,091
Subtotal	425,079	1,153,929	728,850	17,809	-3,728	1,168,010
*HVAC /Mech/Sanitation	77,433	109,579	32,146	0	-345	109,234
Circulation	465,116	429,892	35,224	0	475	430,367
Total Net Square Feet	1,833,104	1,983,955	249,340	581,905	-2,450	2,563,410

Leased / Rented NSF not in Survey : 72,545

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 4

Admin Site : NO

Site Name : MEDICAL CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	29,325	42,197	12,872	0	-318	41,879
Non-Vocational Spaces	4,905	34,369	29,464	0	-1,327	33,042
Vocational Spaces	107,917	33,362	-74,555	52,350	0	85,712
Physical Education	20,950	0	-20,950	20,950	0	20,950
Subtotal	163,097	109,928	-53,169	73,300	-1,645	181,583
Academic Support:						
Library	25,190	13,871	-11,319	9,177	0	23,048
Audiovisual	7,107	1,200	-5,907	5,517	1,500	8,217
Auditorium/Exhibition	10,570	0	-10,570	10,570	0	10,570
Student Services	16,425	3,556	-12,869	4,425	0	7,981
Subtotal	59,292	18,627	-40,665	29,689	1,500	49,816
Institutional Support:						
Office	27,375	41,262	13,887	0	5,456	46,718
Support Services	12,488	518,294	505,806	0	-354	517,940
Custodial Services	2,409	1,561	-848	466	0	2,027
Sanitation:						
*Student Restrooms	3,285	2,664	-621	0	430	3,094
*Staff/Public Restrooms	548	434	-114	0	75	509
Subtotal	46,105	564,215	518,110	466	5,607	570,288
*HVAC /Mech/Sanitation	16,110	26,298	10,188	4,237	-26	30,509
Circulation	96,765	86,702	10,063	43,121	-817	129,006
Total Net Square Feet	381,369	805,770	582,182	150,813	4,619	961,202

Leased / Rented NSF not in Survey : 0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 5

Admin Site : NO

Site Name : HOMESTEAD CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	33,825	32,726	-1,099	0	1,240	33,966
Non-Vocational Spaces	36,125	13,914	-22,211	17,375	0	31,289
Vocational Spaces	15,063	16,127	1,064	2,525	-2,941	15,711
Physical Education	22,540	0	-22,540	17,540	0	17,540
Subtotal	107,553	62,767	-44,786	37,440	-1,701	98,506
Academic Support:						
Library	28,688	12,236	-16,452	18,886	0	31,122
Audiovisual	4,251	0	-4,251	4,250	0	4,250
Auditorium/Exhibition	11,524	330	-11,194	11,194	0	11,524
Student Services	18,810	6,763	-12,047	12,047	0	18,810
Subtotal	63,273	19,329	-43,944	46,377	0	65,706
Institutional Support:						
Office	31,350	35,772	4,422	0	0	35,772
Support Services	10,109	3,738	-6,371	6,370	0	10,108
Custodial Services	2,759	790	-1,969	1,969	-30	2,729
Sanitation:						
*Student Restrooms	3,762	0	-3,762	0	0	0
*Staff/Public Restrooms	627	0	-627	0	0	0
Subtotal	48,607	40,300	-8,307	8,339	-30	48,609
*HVAC /Mech/Sanitation	13,166	20,647	7,481	0	0	20,647
Circulation	79,083	77,121	1,962	0	0	77,121
Total Net Square Feet	311,682	220,164	-120,004	92,156	-1,731	310,589

Leased / Rented NSF not in Survey : 0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 6

Admin Site : NO

Site Name : PADRON CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	48,750	46,269	-2,481	0	-107	46,162
Non-Vocational Spaces	35,975	18,225	-17,750	0	20,530	38,755
Vocational Spaces	4,526	1,365	-3,161	0	2,515	3,880
Physical Education	28,305	0	-28,305	28,305	0	28,305
Subtotal	117,556	65,859	-51,697	28,305	22,938	117,102
Academic Support:						
Library	41,371	12,853	-28,518	28,518	0	41,371
Audiovisual	4,463	1,020	-3,443	3,442	0	4,462
Auditorium/Exhibition	14,983	4,210	-10,773	6,773	4,000	14,983
Student Services	27,458	14,614	-12,844	1,187	11,657	27,458
Subtotal	88,274	32,697	-55,577	39,920	15,657	88,274
Institutional Support:						
Office	45,763	36,436	-9,327	0	9,107	45,543
Support Services	12,580	358,587	346,007	0	-255	358,332
Custodial Services	4,027	1,415	-2,612	2,814	-202	4,027
Sanitation:						
*Student Restrooms	5,492	3,946	-1,546	0	0	3,946
*Staff/Public Restrooms	915	642	-273	0	0	642
Subtotal	68,776	401,026	332,250	2,814	8,650	412,490
*HVAC /Mech/Sanitation	16,476	28,371	11,895	0	-2,507	25,864
Circulation	98,968	196,112	-97,144	0	-58,708	137,404
Total Net Square Feet	390,050	724,065	317,407	71,039	-13,970	781,134

Leased / Rented NSF not in Survey : 21,195

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 7

Admin Site : NO

Site Name : HIALEAH CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	48,300	34,126	-14,174	14,475	0	48,601
Non-Vocational Spaces	41,425	7,852	-33,573	35,905	0	43,757
Vocational Spaces	884	0	-884	884	0	884
Physical Education	27,925	0	-27,925	27,925	0	27,925
Subtotal	118,534	41,978	-76,556	79,189	0	121,167
Academic Support:						
Library	40,535	13,091	-27,444	27,444	0	40,535
Audiovisual	4,530	573	-3,957	3,957	0	4,530
Auditorium/Exhibition	14,755	7,407	-7,348	7,348	0	14,755
Student Services	26,888	3,122	-23,766	23,766	0	26,888
Subtotal	86,708	24,193	-62,515	62,515	0	86,708
Institutional Support:						
Office	44,813	22,120	-22,693	22,692	0	44,812
Support Services	12,503	345,938	333,435	0	0	345,938
Custodial Services	3,944	1,808	-2,136	2,136	0	3,944
Sanitation:						
*Student Restrooms	5,378	3,498	-1,880	0	0	3,498
*Staff/Public Restrooms	896	569	-327	0	0	569
Subtotal	67,532	373,933	306,401	24,828	0	398,761
*HVAC /Mech/Sanitation	16,366	14,291	-2,075	6,130	0	20,421
Circulation	98,308	68,128	30,180	16,856	0	84,984
Total Net Square Feet	387,449	522,523	221,441	189,518	0	712,041

Leased / Rented NSF not in Survey : 0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 8

Admin Site : NO

Site Name : WEST CAMPUS

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	32,900	35,159	2,259	0	0	35,159
Non-Vocational Spaces	35,435	9,528	-25,907	8,260	17,215	35,003
Vocational Spaces	3,481	0	-3,481	4,507	0	4,507
Physical Education	22,340	3,169	-19,171	19,171	0	22,340
Subtotal	94,156	47,856	-46,300	31,938	17,215	97,009
Academic Support:						
Library	28,248	15,794	-12,454	2,454	10,000	28,248
Audiovisual	3,591	1,533	-2,058	1,251	0	2,784
Auditorium/Exhibition	11,404	6,692	-4,712	4,712	0	11,404
Student Services	18,510	8,662	-9,848	8,848	1,000	18,510
Subtotal	61,753	32,681	-29,072	17,265	11,000	60,946
Institutional Support:						
Office	30,850	32,281	1,431	0	0	32,281
Support Services	9,338	558,594	549,256	0	-21,655	536,939
Custodial Services	2,715	885	-1,830	1,330	500	2,715
Sanitation:						
*Student Restrooms	3,702	4,440	738	0	0	4,440
*Staff/Public Restrooms	617	723	106	0	0	723
Subtotal	47,222	596,923	549,701	1,330	-21,155	577,098
*HVAC /Mech/Sanitation	12,188	23,094	10,906	0	-266	22,828
Circulation	73,208	259,174	-185,966	0	-39,337	219,837
Total Net Square Feet	288,527	959,728	650,216	50,533	-32,543	977,718

Leased / Rented NSF not in Survey : 0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 1

College Name : MIAMI DADE COLLEGE

Date : 5/11/2023 12:43:00 PM

Site Number : 10

Admin Site : NO

Site Name : ENTREPRENEURIAL ED

SPACE CATEGORY	2024 - 2025 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	5,250	7,725	2,475	0	-1,523	6,202
Non-Vocational Spaces	4,320	1,863	-2,457	2,790	0	4,653
Vocational Spaces	0	39	39	0	0	39
Physical Education	10,000	0	-10,000	10,000	0	10,000
Subtotal	19,570	9,627	-9,943	12,790	-1,523	20,894
Academic Support:						
Library	5,920	686	-5,234	0	1,523	2,209
Audiovisual	479	0	-479	494	0	494
Auditorium/Exhibition	5,000	0	-5,000	10,000	0	10,000
Student Services	2,865	0	-2,865	2,865	0	2,865
Subtotal	14,264	686	-13,578	13,359	1,523	15,568
Institutional Support:						
Office	4,775	5,232	457	0	0	5,232
Support Services	1,930	0	-1,930	1,946	0	1,946
Custodial Services	420	178	-242	0	0	178
Sanitation:						
*Student Restrooms	573	0	-573	0	0	0
*Staff/Public Restrooms	96	0	-96	0	0	0
Subtotal	7,794	5,410	-2,384	1,946	0	7,356
*HVAC /Mech/Sanitation	2,498	2,366	-132	0	0	2,366
Circulation	15,003	12,120	2,883	0	0	12,120
Total Net Square Feet	59,128	30,209	-34,889	28,095	0	58,304

Leased / Rented NSF not in Survey : 143

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Total NSF for all Sites : 5,409,950

Leased / Rented NSF not in Survey : 171,371

* : In College Surveys, New Construction for Restroom space is included in HVAC/Mech/Sanitation.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 10: Facility Lists

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: NORTH CAMPUS

Site No: 1

Stations Allowed

Current Stations

Classroom FTE: 8,849

4,424

4,428

Non-Voc FTE: 7,161

1,790

1,787

Vocational FTE: 1,688

844

847

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	36	25	900	123	110,700	4,428
	Storage, Material			75	123	9,225	0
				975	246	119,925	4,428
1.12.1002X	Art	18	50	900	4	3,600	72
	Kiln			60	4	240	0
	Storage, Material			200	4	800	0
		1,160	12	4,640	72		
1.12.10041	Music(Choral or Band)	35	35	1,225	7	8,575	245
	Ensemble			300	7	2,100	0
	Practice, Music 3@60sf			180	7	1,260	0
	Reference			150	7	1,050	0
	Storage, Instrument			400	7	2,800	0
	Storage, Robe			60	7	420	0
	Storage, Uniform			60	7	420	0
		2,375	49	16,625	245		
1.13.11XXX	Foreign Languages	34	40	1,360	3	4,080	102
	Storage, Material			100	3	300	0
		1,460	6	4,380	102		
1.16.17XXX	Mathematics	29	25	725	1	725	29
	Storage, Material			75	1	75	0
		800	2	800	29		
1.17.03XXX	Area Studies	33	55	1,815	4	7,260	132
	Storage, Material			75	4	300	0
		1,890	8	7,560	132		
1.31.1XXXX	Adult General & Preparatory	50	47	2,350	4	9,400	200
	Conference			300	4	1,200	0
	Storage, Material			300	4	1,200	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: NORTH CAMPUS

Site No: 1

Stations Allowed Current Stations

Classroom FTE: 8,849	4,424	4,428
Non-Voc FTE: 7,161	1,790	1,787
Vocational FTE: 1,688	844	847

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Testing			150	4	600	0
				3,100	16	12,400	200
1.32.1XXXX	Adult General & Preparatory	50	47	2,350	4	9,400	200
	Conference			600	4	2,400	0
	Storage, Material			350	4	1,400	0
	Testing			900	4	3,600	0
				4,200	16	16,800	200
1.32.3XXXX	Adult General & Preparatory	35	47	1,645	5	8,225	175
	Conference			600	5	3,000	0
	Storage, Material			900	5	4,500	0
				3,145	15	15,725	175
1.23.04021	Physical Therapy Assistant	20	80	1,600	1	1,600	20
	Hydrotherapy			550	1	550	0
	Lockers, Showers, & Toilets - Faculty			120	1	120	0
	Lockers, Showers, & Toilets - Student			225	1	225	0
	Storage, Material			250	1	250	0
	Toilet, Patient			75	1	75	0
				2,820	6	2,820	20
1.26.1011X	Arch. Design & Const Tech.	25	66	1,650	2	3,300	50
	Classroom,Related Instruct.			525	2	1,050	0
	Shower, Emergency			25	2	50	0
	Storage, Material			500	2	1,000	0
	Storage, Project			400	2	800	0
	Storage, Tool			200	2	400	0
				3,300	12	6,600	50
1.26.1506X	Computer Electronics	25	76	1,900	3	5,700	75

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: NORTH CAMPUS

Site No: 1

Stations Allowed

Current Stations

Classroom FTE: 8,849

4,424

4,428

Non-Voc FTE: 7,161

1,790

1,787

Vocational FTE: 1,688

844

847

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Classroom,Related Instruct.			525	3	1,575	0
	Storage, Material			250	3	750	0
	Storage, Project			200	3	600	0
	Storage, Tool			100	3	300	0
				2,975	15	8,925	75
1.26.13XXX	Drafting & Design Technology	25	76	1,900	3	5,700	75
	Reproduction			200	3	600	0
	Storage, Material			250	3	750	0
	Storage, Project			200	3	600	0
				2,550	12	7,650	75
1.26.2508X	Engineering Model Making	25	119	2,975	2	5,950	50
	Storage, Material			300	2	600	0
	Storage, Project			200	2	400	0
	Storage, Tool			150	2	300	0
				3,625	8	7,250	50
1.26.19002	Graphic Design Technology	30	57	1,710	2	3,420	60
	Art Production			800	2	1,600	0
	Classroom,Related Instruct.			525	2	1,050	0
	Photography Lab			500	2	1,000	0
	Storage, Material			250	2	500	0
	Storage, Project			200	2	400	0
				3,985	12	7,970	60
1.26.9906X	Manufacturing Technology	25	142	3,550	2	7,100	50
	Storage, Material			500	2	1,000	0
	Storage, Tool			200	2	400	0
				4,250	6	8,500	50
1.26.9908X	Television Production Tech.	50	27	1,350	4	5,400	200
	Conference			200	4	800	0
	Distribution & Control			450	4	1,800	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: NORTH CAMPUS

Site No: 1

Stations Allowed

Current Stations

Classroom FTE: 8,849

4,424

4,428

Non-Voc FTE: 7,161

1,790

1,787

Vocational FTE: 1,688

844

847

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Production Control			175	4	700	0
	Program Control			175	4	700	0
	Prop Production & Storage			600	4	2,400	0
	Studio			1,200	4	4,800	0
				4,150	28	16,600	200
1.27.01XXX	Fire Science Technology	14	100	1,400	1	1,400	14
	Classroom,Related Instruct.			525	1	525	0
	Storage, Flammable			70	1	70	0
	Storage, Material			500	1	500	0
				2,495	4	2,495	14
1.11.0401X	Biology, General	25	55	1,375	7	9,625	175
				1,375	7	9,625	175
1.11.0411X	Microbiology	26	55	1,430	1	1,430	26
				1,430	1	1,430	26
1.11.0412X	Anatomy	26	55	1,430	3	4,290	78
				1,430	3	4,290	78
1.11.1902X	Physics, General	24	55	1,320	4	5,280	96
				1,320	4	5,280	96
1.11.1905X	Chemistry, General	26	55	1,430	5	7,150	130
				1,430	5	7,150	130
1.11.1907X	Organic Chemistry	19	55	1,045	2	2,090	38
				1,045	2	2,090	38
1.11.1917X	Earth Sciences, General	23	55	1,265	1	1,265	23
				1,265	1	1,265	23

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: NORTH CAMPUS

Site No: 1

Stations Allowed

Current Stations

Classroom FTE: 8,849

4,424

4,428

Non-Voc FTE: 7,161

1,790

1,787

Vocational FTE: 1,688

844

847

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.12.1007X	Dramatic Arts	20	40	800	1	800	20
				800	1	800	20
1.12.1011X	Photography	23	50	1,150	2	2,300	46
				1,150	2	2,300	46
1.22.1800X	Recreation and Tourism	4	240	960	1	960	4
				960	1	960	4
1.25.0303X	General Office Clerks	24	52	1,248	1	1,248	24
				1,248	1	1,248	24
1.25.08XXX	Supervisory and Administrative Management (General Business, etc.)	40	52	2,080	4	8,320	160
				2,080	4	8,320	160
1.27.0201X	Law Enforcement, General	11	96	1,056	5	5,280	55
				1,056	5	5,280	55
1.27.1004X	Environmental Science	10	93	930	1	930	10
				930	1	930	10
NORTH CAMPUS		Totals :		66,774	511	318,633	7,062

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: KENDALL CAMPUS

Site No: 2

Stations Allowed

Current Stations

Classroom FTE: 11,620

5,810

5,811

Non-Voc FTE: 11,254

2,813

2,804

Vocational FTE: 366

183

181

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	39	25	975	149	145,275	5,811
	Storage, Material			75	149	11,175	0
				1,050	298	156,450	5,811
1.11.04XXX	Biological Sciences	21	55	1,155	7	8,085	147
	Storage, Material			150	7	1,050	0
	Storage, Project			275	7	1,925	0
		1,580	21	11,060	147		
1.12.1002X	Art	40	50	2,000	9	18,000	360
	Kiln			60	9	540	0
	Storage, Material			200	9	1,800	0
		2,260	27	20,340	360		
1.12.10041	Music(Choral or Band)	25	35	875	14	12,250	350
	Ensemble			300	14	4,200	0
	Practice, Music 3@60sf			180	14	2,520	0
	Reference			150	14	2,100	0
	Storage, Instrument			400	14	5,600	0
	Storage, Robe			60	14	840	0
	Storage, Uniform			60	14	840	0
		2,025	98	28,350	350		
1.13.11XXX	Foreign Languages	22	40	880	7	6,160	154
	Storage, Material			100	7	700	0
		980	14	6,860	154		
1.15.05XXX	Business & Management	45	45	2,025	7	14,175	315
	Storage, Material			100	7	700	0
		2,125	14	14,875	315		
1.31.1XXXX	Adult General & Preparatory	17	47	799	1	799	17
	Conference			300	1	300	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: KENDALL CAMPUS

Site No: 2

Stations Allowed

Current Stations

Classroom FTE: 11,620

5,810

5,811

Non-Voc FTE: 11,254

2,813

2,804

Vocational FTE: 366

183

181

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Storage, Material			300	1	300	0
	Testing			150	1	150	0
				1,549	4	1,549	17
1.32.3XXXX	Adult General & Preparatory	31	47	1,457	1	1,457	31
	Conference			600	1	600	0
	Storage, Material			900	1	900	0
				2,957	3	2,957	31
1.26.13XXX	Drafting & Design Technology	20	76	1,520	2	3,040	40
	Reproduction			200	2	400	0
	Storage, Material			250	2	500	0
	Storage, Project			200	2	400	0
				2,170	8	4,340	40
1.26.19002	Graphic Design Technology	12	57	684	1	684	12
	Art Production			800	1	800	0
	Classroom,Related Instruct.			525	1	525	0
	Photography Lab			500	1	500	0
	Storage, Material			250	1	250	0
	Storage, Project			200	1	200	0
				2,959	6	2,959	12
1.11.0410X	Physiology, Human and Animal	20	55	1,100	3	3,300	60
				1,100	3	3,300	60
1.11.0411X	Microbiology	23	55	1,265	2	2,530	46
				1,265	2	2,530	46
1.11.0412X	Anatomy	17	55	935	3	2,805	51
				935	3	2,805	51

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: KENDALL CAMPUS

Site No: 2

Stations Allowed

Current Stations

Classroom FTE: 11,620

5,810

5,811

Non-Voc FTE: 11,254

2,813

2,804

Vocational FTE: 366

183

181

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.11.1902X	Physics, General	20	55	1,100	4	4,400	80
				1,100	4	4,400	80
1.11.1905X	Chemistry, General	18	55	990	8	7,920	144
				990	8	7,920	144
1.11.1906X	Inorganic Chemistry	24	55	1,320	3	3,960	72
				1,320	3	3,960	72
1.11.1907X	Organic Chemistry	26	55	1,430	2	2,860	52
				1,430	2	2,860	52
1.12.1008X	Dance	48	40	1,920	1	1,920	48
				1,920	1	1,920	48
1.12.1011X	Photography	13	50	650	2	1,300	26
				650	2	1,300	26
1.14.0807X	Adult and Continuing Education, General	35	45	1,575	20	31,500	700
				1,575	20	31,500	700
1.14.0815X	Speech Correction	8	45	360	1	360	8
				360	1	360	8
1.15.0502X	Accounting	25	45	1,125	2	2,250	50
				1,125	2	2,250	50
1.18.0602X	Journalism	21	45	945	1	945	21
				945	1	945	21

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: KENDALL CAMPUS

Site No: 2

Stations Allowed

Current Stations

Classroom FTE: 11,620

5,810

5,811

Non-Voc FTE: 11,254

2,813

2,804

Vocational FTE: 366

183

181

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.18.0605X	Communications Media	36	45	1,620	2	3,240	72
				1,620	2	3,240	72
1.25.0303X	General Office Clerks	30	52	1,560	1	1,560	30
				1,560	1	1,560	30
1.25.08XXX	Supervisory and Administrative Management (General Business, etc.)	25	52	1,300	2	2,600	50
				1,300	2	2,600	50
1.26.0701X	Interior Decorating	7	119	833	1	833	7
				833	1	833	7
1.26.15060	Computer Electronics	21	76	1,596	2	3,192	42
				1,596	2	3,192	42
KENDALL CAMPUS Totals :				41,279	553	327,215	8,796

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	35	25	875	202	176,750	7,070
	Storage, Material			75	202	15,150	0
				950	404	191,900	7,070
1.11.02XXX	Architectural & Environmental Design	22	55	1,210	2	2,420	44
	Storage, Material			100	2	200	0
	Storage, Project			200	2	400	0
				1,510	6	3,020	44
1.11.04XXX	Biological Sciences	30	55	1,650	10	16,500	300
	Storage, Material			150	10	1,500	0
	Storage, Project			275	10	2,750	0
				2,075	30	20,750	300
1.11.19XXX	Physical Sciences	25	55	1,375	4	5,500	100
	Storage, Material			150	4	600	0
	Storage, Project			200	4	800	0
				1,725	12	6,900	100
1.12.1002X	Art	20	50	1,000	10	10,000	200
	Kiln			60	10	600	0
	Storage, Material			200	10	2,000	0
				1,260	30	12,600	200
1.12.10041	Music(Choral or Band)	25	35	875	10	8,750	250
	Ensemble			300	10	3,000	0
	Practice, Music 3@60sf			180	10	1,800	0
	Reference			150	10	1,500	0
	Storage, Instrument			400	10	4,000	0
	Storage, Robe			60	10	600	0
	Storage, Uniform			60	10	600	0
				2,025	70	20,250	250

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.12.10XXX	Other Arts	50	40	2,000	3	6,000	150
	Storage, Material			100	3	300	0
				2,100	6	6,300	150
1.13.11XXX	Foreign Languages	40	40	1,600	3	4,800	120
	Storage, Material			100	3	300	0
				1,700	6	5,100	120
1.14.08XXX	Education	40	45	1,800	3	5,400	120
	Storage, Material			100	3	300	0
				1,900	6	5,700	120
1.15.05XXX	Business & Management	25	45	1,125	10	11,250	250
	Storage, Material			100	10	1,000	0
				1,225	20	12,250	250
1.16.07XXX	Computer & Information Systems	25	45	1,125	10	11,250	250
	Storage, Material			100	10	1,000	0
				1,225	20	12,250	250
1.17.03XXX	Area Studies	50	55	2,750	3	8,250	150
	Storage, Material			75	3	225	0
				2,825	6	8,475	150
1.18.49XXX	Interdisciplinary	40	55	2,200	5	11,000	200
	Storage, Material			100	5	500	0
				2,300	10	11,500	200
1.31.1XXXX	Adult General & Preparatory	40	47	1,880	5	9,400	200
	Conference			300	5	1,500	0
	Storage, Material			300	5	1,500	0
	Testing			150	5	750	0
				2,630	20	13,150	200

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.31.2XXXX	Adult General & Preparatory	50	47	2,350	2	4,700	100
	Laser Alignment Tunnel			300	2	600	0
	Storage, Material			250	2	500	0
	Testing			300	2	600	0
				3,200	8	6,400	100
1.32.3XXXX	Adult General & Preparatory	31	47	1,457	2	2,914	62
	Conference			600	2	1,200	0
	Storage, Material			900	2	1,800	0
	2,957	6	5,914	62			
1.22.XXXXX	Hotel-Motel I	20	43	860	2	1,720	40
	Storage, Material			150	2	300	0
	1,010	4	2,020	40			
1.22.XXXXX	Management & Supervision	25	27	675	2	1,350	50
	Storage, Material			150	2	300	0
	825	4	1,650	50			
1.24.0202X	Apparel Manufacturing	20	95	1,900	5	9,500	100
	Storage, Material			350	5	1,750	0
	Storage, Project			150	5	750	0
	Textiles			60	5	300	0
	2,460	20	12,300	100			
1.24.02021	Clothing Production & Management	25	90	2,250	4	9,000	100
	Fitting			50	4	200	0
	Laundry			50	4	200	0
	Storage, Material			250	4	1,000	0
	Storage, Project			100	4	400	0
	Textiles			60	4	240	0
	2,760	24	11,040	100			

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.24.0203X	Food Production & Management	10	95	950	5	4,750	50
	Dining Room			550	5	2,750	0
	Freezer, Walk-in			90	5	450	0
	Garbage, Refrigerated			30	5	150	0
	Laundry			50	5	250	0
	Lockers, Showers, & Toilets - Student			225	5	1,125	0
	Refrigerator, Walk-in			100	5	500	0
	Storage, Dry Foods			200	5	1,000	0
	Storage, Material			150	5	750	0
						2,345	45
1.25.02XXX	Business Data Processing	25	63	1,575	4	6,300	100
	Classroom,Related Instruct.			525	4	2,100	0
	Storage, Material			100	4	400	0
			2,200	12	8,800	100	
1.26.1011X	Arch. Design & Const Tech.	15	66	990	1	990	15
	Classroom,Related Instruct.			525	1	525	0
	Shower, Emergency			25	1	25	0
	Storage, Material			500	1	500	0
	Storage, Project			400	1	400	0
	Storage, Tool			200	1	200	0
			2,640	6	2,640	15	
1.26.29XXX	Commercial Foods & Culinary Art	10	95	950	2	1,900	20
	Classroom,Related Instruct.			525	2	1,050	0
	Dining Room			1,000	2	2,000	0
	Freezer, Walk-in			90	2	180	0
	Garbage, Refrigerated			30	2	60	0
	Lockers, Showers, & Toilets - Faculty			120	2	240	0
	Lockers, Showers, & Toilets - Student			225	2	450	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Refrigerator, Walk-in			135	2	270	0
	Serving Line			90	2	180	0
	Storage, Dry Foods			200	2	400	0
				3,365	20	6,730	20
1.26.1506X	Computer Electronics	12	76	912	1	912	12
	Classroom,Related Instruct.			525	1	525	0
	Storage, Material			250	1	250	0
	Storage, Project			200	1	200	0
	Storage, Tool			100	1	100	0
				1,987	5	1,987	12
1.11.0401X	Biology, General	23	55	1,265	1	1,265	23
				1,265	1	1,265	23
1.11.0412X	Anatomy	28	55	1,540	1	1,540	28
				1,540	1	1,540	28
1.11.1905X	Chemistry, General	21	55	1,155	1	1,155	21
				1,155	1	1,155	21
1.12.1008X	Dance	25	40	1,000	10	10,000	250
				1,000	10	10,000	250
1.13.1507X	Creative Writing	31	25	775	1	775	31
				775	1	775	31
1.13.1508X	Teaching English as a Foreign Language	58	25	1,450	1	1,450	58
				1,450	1	1,450	58
1.16.0701X	Computer and Information Science, General	29	45	1,305	2	2,610	58
				1,305	2	2,610	58

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WOLFSON CAMPUS

Site No: 3

Stations Allowed

Current Stations

Classroom FTE: 14,138

7,069

7,070

Non-Voc FTE: 12,743

3,185

3,186

Vocational FTE: 1,395

697

698

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.16.1701X	Mathematics, General	31	25	775	1	775	31
				775	1	775	31
1.18.0601X	Communications, General	35	45	1,575	2	3,150	70
				1,575	2	3,150	70
1.18.1303X	Clothing and Textiles	40	80	3,200	3	9,600	120
				3,200	3	9,600	120
1.21.0104X	Farm Business Management (Agri-Business)	53	128	6,784	1	6,784	53
				6,784	1	6,784	53
1.25.08XXX	Supervisory and Administrative Management (General Business, etc.)	13	52	676	3	2,028	39
				676	3	2,028	39
1.25.0804X	Data Methods and Systems Procedures Analysts	25	52	1,300	4	5,200	100
				1,300	4	5,200	100
1.26.1501X	Communications	19	57	1,083	1	1,083	19
				1,083	1	1,083	19
WOLFSON CAMPUS Totals :				75,082	832	448,766	10,954

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: MEDICAL CAMPUS

Site No: 4

Stations Allowed

Current Stations

Classroom FTE: 2,190

1,095

1,104

Non-Voc FTE: 257

64

66

Vocational FTE: 1,933

966

965

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	48	25	1,200	23	27,600	1,104
	Storage, Material			75	23	1,725	0
				1,275	46	29,325	1,104
1.11.04XXX	Biological Sciences	22	55	1,210	3	3,630	66
	Storage, Material			150	3	450	0
	Storage, Project			275	3	825	0
		1,635	9	4,905	66		
1.23.0103X	Dental Laboratory Technology	40	50	2,000	1	2,000	40
	Ceramics			180	1	180	0
	Lockers, Showers, & Toilets - Faculty			120	1	120	0
	Lockers, Showers, & Toilets - Student			225	1	225	0
	Storage, Material			150	1	150	0
	Technical Laboratory			900	1	900	0
		3,575	6	3,575	40		
1.23.0907X	Emergency Medical Tech.	12	88	1,056	2	2,112	24
	Classroom,Related Instruct.			525	2	1,050	0
	Storage, Material			500	2	1,000	0
	Telemetry Operations			1,000	2	2,000	0
		3,081	8	6,162	24		
1.23.9901X	Health Care Management	50	80	4,000	2	8,000	100
	Storage, Material			350	2	700	0
		4,350	4	8,700	100		
1.23.0405X	Massage Therapy	30	63	1,890	2	3,780	60
	Classroom,Related Instruct.			525	2	1,050	0
	Lockers, Showers, & Toilets - Faculty			120	2	240	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: MEDICAL CAMPUS

Site No: 4

Stations Allowed

Current Stations

Classroom FTE: 2,190	1,095	1,104
Non-Voc FTE: 257	64	66
Vocational FTE: 1,933	966	965

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Lockers, Showers, & Toilets - Student			225	2	450	0
	Sauna			70	2	140	0
	Steam			80	2	160	0
	Storage, Material			600	2	1,200	0
	Toilet, Patient			75	2	150	0
				3,585	16	7,170	60
1.23.0205X	Medical Laboratory Assisting	20	63	1,260	2	2,520	40
	Storage, Material			150	2	300	0
				1,410	4	2,820	40
1.23.0503X	Nuclear Medical Technology	10	80	800	1	800	10
	Classroom,Related Instruct.			525	1	525	0
	Darkroom			350	1	350	0
	Storage, Material			400	1	400	0
	Technical Laboratory			900	1	900	0
				2,975	5	2,975	10
1.23.0301X	Nursing (RN)	20	158	3,160	4	12,640	80
	Classroom,Related Instruct.			525	4	2,100	0
	Locker, Faculty			90	4	360	0
	Locker, Student			350	4	1,400	0
	Reference			350	4	1,400	0
	Storage, Material			400	4	1,600	0
				4,875	24	19,500	80
1.23.0502X	Radiation Therapy Technician	20	80	1,600	1	1,600	20
	Classroom,Related Instruct.			525	1	525	0
	Darkroom			350	1	350	0
	Storage, Material			500	1	500	0
	Technical Laboratory			900	1	900	0
				3,875	5	3,875	20

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: MEDICAL CAMPUS

Site No: 4

Stations Allowed

Current Stations

Classroom FTE: 2,190	1,095	1,104
Non-Voc FTE: 257	64	66
Vocational FTE: 1,933	966	965

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.23.09031	Respiratory Therapist	21	80	1,680	1	1,680	21
	Classroom,Related Instruct.			525	1	525	0
	Maintenance			200	1	200	0
	Storage, Material			400	1	400	0
					2,805	4	2,805
1.23.0912X	Veterinary Technology	15	100	1,500	1	1,500	15
	Animal shelter			1,000	1	1,000	0
	Classroom,Related Instruct.			525	1	525	0
	Darkroom			200	1	200	0
	Isolation			50	1	50	0
	Lockers, Showers, & Toilets - Faculty			120	1	120	0
	Lockers, Showers, & Toilets - Student			225	1	225	0
	Scrub Area			100	1	100	0
	Sterilization			80	1	80	0
	Surgical Operations			1,200	1	1,200	0
	X-ray			135	1	135	0
				5,135	11	5,135	15
1.23.01XXX	Dental Assisting	50	71	3,550	6	21,300	300
				3,550	6	21,300	300
1.23.0202X	Histology	20	91	1,820	1	1,820	20
				1,820	1	1,820	20
1.23.0203X	Medical Laboratory Assisting	16	63	1,008	3	3,024	48
				1,008	3	3,024	48
1.23.0204X	Hematology	21	91	1,911	1	1,911	21
				1,911	1	1,911	21

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: MEDICAL CAMPUS

Site No: 4

Stations Allowed

Current Stations

Classroom FTE: 2,190

1,095

1,104

Non-Voc FTE: 257

64

66

Vocational FTE: 1,933

966

965

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.23.03XXX	Nursing	4	158	632	9	5,688	36
				632	9	5,688	36
1.23.0402X	Physical Therapy	46	80	3,680	1	3,680	46
				3,680	1	3,680	46
1.23.04050	Massage Therapy	14	63	882	1	882	14
				882	1	882	14
1.23.05040	Diagnostic Medical Sonography	21	80	1,680	1	1,680	21
				1,680	1	1,680	21
1.23.06XXX	Ophthalmic	10	79	790	4	3,160	40
				790	4	3,160	40
1.23.0904X	Medical Assistant (Assistant in Physician's Office)	9	95	855	1	855	9
				855	1	855	9
MEDICAL CAMPUS Totals :				55,384	170	140,947	2,135

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: HOMESTEAD CAMPUS

Site No: 5

Stations Allowed

Current Stations

Classroom FTE: 2,508	1,254	1,254
Non-Voc FTE: 2,254	563	565
Vocational FTE: 254	127	129

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	38	25	950	33	31,350	1,254
	Storage, Material			75	33	2,475	0
				1,025	66	33,825	1,254
1.31.2XXXX	Adult General & Preparatory	45	47	2,115	1	2,115	45
	Laser Alignment Tunnel			300	1	300	0
	Storage, Material			250	1	250	0
	Testing			300	1	300	0
				2,965	4	2,965	45
1.32.3XXXX	Adult General & Preparatory	40	47	1,880	2	3,760	80
	Conference			600	2	1,200	0
	Storage, Material			900	2	1,800	0
				3,380	6	6,760	80
1.26.0404X	Aircraft Piloting & Navigation	43	72	3,096	3	9,288	129
	Classroom,Related Instruct.			525	3	1,575	0
	Flight Simulator			450	3	1,350	0
	Meteorology			350	3	1,050	0
	Storage, Material			600	3	1,800	0
				5,021	15	15,063	129
1.11.0112X	Agriculture Business	25	55	1,375	4	5,500	100
				1,375	4	5,500	100
1.11.0401X	Biology, General	25	55	1,375	4	5,500	100
				1,375	4	5,500	100
1.11.1203X	Nursing (Four Year Programs)	20	80	1,600	4	6,400	80
				1,600	4	6,400	80
1.14.0801X	Education, General	25	45	1,125	4	4,500	100
				1,125	4	4,500	100

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: HOMESTEAD CAMPUS

Site No: 5

Stations Allowed

Current Stations

Classroom FTE: 2,508

1,254

1,254

Non-Voc FTE: 2,254

563

565

Vocational FTE: 254

127

129

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.16.0701X	Computer and Information Science, General	30	45	1,350	2	2,700	60
				1,350	2	2,700	60
	HOMESTEAD CAMPUS Totals :			19,216	109	83,213	1,948

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: PADRON CAMPUS

Site No: 6

Stations Allowed

Current Stations

Classroom FTE: 3,661

1,830

1,833

Non-Voc FTE: 3,560

890

890

Vocational FTE: 101

50

52

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	47	25	1,175	39	45,825	1,833
	Storage, Material			75	39	2,925	0
				1,250	78	48,750	1,833
1.15.05XXX	Business & Management	25	45	1,125	3	3,375	75
	Storage, Material			100	3	300	0
				1,225	6	3,675	75
1.16.07XXX	Computer & Information Systems	25	45	1,125	4	4,500	100
	Storage, Material			100	4	400	0
				1,225	8	4,900	100
1.16.17XXX	Mathematics	30	25	750	3	2,250	90
	Storage, Material			75	3	225	0
				825	6	2,475	90
1.25.02XXX	Business Data Processing	26	63	1,638	2	3,276	52
	Classroom,Related Instruct.			525	2	1,050	0
	Storage, Material			100	2	200	0
	2,263	6	4,526	52			
1.11.0401X	Biology, General	20	55	1,100	4	4,400	80
				1,100	4	4,400	80
1.11.1902X	Physics, General	20	55	1,100	3	3,300	60
				1,100	3	3,300	60
1.11.1905X	Chemistry, General	20	55	1,100	4	4,400	80
				1,100	4	4,400	80
1.13.1508X	Teaching English as a Foreign Language	45	25	1,125	7	7,875	315
				1,125	7	7,875	315

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: PADRON CAMPUS

Site No: 6

Stations Allowed

Current Stations

Classroom FTE: 3,661	1,830	1,833
Non-Voc FTE: 3,560	890	890
Vocational FTE: 101	50	52

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.18.4901X	General Liberal Arts and Sciences	30	55	1,650	3	4,950	90
				1,650	3	4,950	90
	PADRON CAMPUS	Totals :		12,863	125	89,251	2,775

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3

Version: 1

Site: HIALEAH CAMPUS

Site No: 7

Stations Allowed

Current Stations

Classroom FTE: 3,585

1,792

1,794

Non-Voc FTE: 3,551

887

885

Vocational FTE: 34

17

17

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	39	25	975	46	44,850	1,794
	Storage, Material			75	46	3,450	0
				1,050	92	48,300	1,794
1.14.0801X	Education, General	40	45	1,800	6	10,800	240
				1,800	6	10,800	240
1.14.0807X	Adult and Continuing Education, General	35	45	1,575	7	11,025	245
				1,575	7	11,025	245
1.15.0501X	Business and Commerce, General	40	45	1,800	6	10,800	240
				1,800	6	10,800	240
1.18.4901X	General Liberal Arts and Sciences	40	55	2,200	4	8,800	160
				2,200	4	8,800	160
1.25.08XXX	Supervisory and Administrative Management (General Business, etc.)	17	52	884	1	884	17
				884	1	884	17
HIALEAH CAMPUS		Totals :		9,309	116	90,609	2,696

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WEST CAMPUS

Site No: 8

Stations Allowed Current Stations

Classroom FTE: 2,468	1,234	1,232
Non-Voc FTE: 2,445	611	624
Vocational FTE: 23	11	11

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	44	25	1,100	28	30,800	1,232
	Storage, Material			75	28	2,100	0
				1,175	56	32,900	1,232
1.12.10XXX	Other Arts	50	40	2,000	2	4,000	100
	Storage, Material			100	2	200	0
				2,100	4	4,200	100
1.15.05XXX	Business & Management	50	45	2,250	3	6,750	150
	Storage, Material			100	3	300	0
				2,350	6	7,050	150
1.16.07XXX	Computer & Information Systems	25	45	1,125	1	1,125	25
	Storage, Material			100	1	100	0
				1,225	2	1,225	25
1.18.13XXX	Home Economics	15	80	1,200	1	1,200	15
	Storage, Material			150	1	150	0
	Storage, Project			150	1	150	0
				1,500	3	1,500	15
1.31.2XXXX	Adult General & Preparatory	40	47	1,880	1	1,880	40
	Laser Alignment Tunnel			300	1	300	0
	Storage, Material			250	1	250	0
	Testing			300	1	300	0
				2,730	4	2,730	40
1.32.1XXXX	Adult General & Preparatory	40	47	1,880	1	1,880	40
	Conference			600	1	600	0
	Storage, Material			350	1	350	0
	Testing			900	1	900	0
				3,730	4	3,730	40

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: WEST CAMPUS

Site No: 8

Stations Allowed

Current Stations

Classroom FTE: 2,468

1,234

1,232

Non-Voc FTE: 2,445

611

624

Vocational FTE: 23

11

11

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.32.3XXXX	Adult General & Preparatory	40	47	1,880	1	1,880	40
	Conference			600	1	600	0
	Storage, Material			900	1	900	0
				3,380	3	3,380	40
1.26.03021	Automotive Mechanics	11	171	1,881	1	1,881	11
	Classroom,Related Instruct.			525	1	525	0
	Storage, Flammable			175	1	175	0
	Storage, Material			250	1	250	0
	Storage, Project			200	1	200	0
	Storage, Tool			200	1	200	0
				3,231	6	3,231	11
1.11.0206X	City, Community and Regional Planning	13	55	715	1	715	13
				715	1	715	13
1.14.0838X	Business, Commerce and Distributive Education	42	45	1,890	1	1,890	42
				1,890	1	1,890	42
1.15.0501X	Business and Commerce, General	42	45	1,890	1	1,890	42
				1,890	1	1,890	42
1.15.0510X	Transportation and Public Utilities	21	45	945	1	945	21
				945	1	945	21
1.18.4901X	General Liberal Arts and Sciences	48	55	2,640	2	5,280	96
				2,640	2	5,280	96
WEST CAMPUS		Totals :		29,501	94	70,666	1,867

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

PROGRAM FACILITES LIST

College : MIAMI DADE COLLEGE

OUT Year: 5 - 6

Survey : 3 **Version:** 1

Site: ENTREPRENEURIAL ED

Site No: 10

Stations Allowed

Current Stations

Classroom FTE: 382

191

195

Non-Voc FTE: 380

95

96

Vocational FTE: 2

1

0

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
1.XX.XXXXX	Classroom	39	25	975	5	4,875	195
	Storage, Material			75	5	375	0
				1,050	10	5,250	195
1.14.0801X	Education, General	32	45	1,440	3	4,320	96
				1,440	3	4,320	96
ENTREPRENEURIAL ED Totals :				2,490	13	9,570	291
Report Totals :				311,898	2,523	1,578,870	38,524

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Section 11: Recommendation Details

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

COLLEGE WIDE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATED COST
SR.01	Correct deficiencies relating to safety to life, health, and sanitation as identified in the comprehensive Safety Inspection Report pursuant to §4.4(1) and §5(1) SREF.	15,000,000
SR.02	Necessary modifications for the physically disabled in existing buildings recommended for continued use as provided for in §255.21 F.S.	15,000,000
SR.03	Replacement of roofs at existing facilities as provided in §1.2(55) SREF and §423.12 Florida Building Code.	6,000,000
SR.04	Replace or purchase of equipment for existing facilities pursuant to §1.2(55) SREF.	31,673,675
SR.05	Provide for sanitation facilities for students, staff, and the public pursuant to §5(1) SREF and §423.2 Florida Building Code.	15,000,000
SR.06	Provide for custodial facilities pursuant to §423.20 Florida Building Code.	250,000
Total :		82,923,675

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 1
Site Name: NORTH CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
1.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	14,640,587
1.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	30,099,306
1.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	4,727,818
1.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	10,000,000
1.005	Renovate all athletic facilities to include but not limited to fields, courts, pools, spectator areas and seating, lighting, flooring, fencing and ancillary facilities.	1,000,000
NORTH CAMPUS Total :		60,467,711

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.006	New Construction: Adding Non-Vocational Labs (517 SS), (18261 NSF), (25938 GSF); Area Studies (18261 NSF)	10,348,863
1.007	New Construction: Adding Custodial (5400 NSF)	3,060,330
1.008	New Construction: Adding Student Services (43440 NSF)	24,619,098
1.009	New Construction: Adding Auditorium / Exhibition (10260 NSF)	5,814,627
1.010	New Construction: Adding Audiovisual (7827 NSF)	4,435,683

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.011	New Construction: Adding Library / Study (52684 NSF)	29,857,968
1.012	New Construction: Adding Audiovisual (2065 NSF), Physical Education (42612 NSF)	25,320,141
1.013	New Construction: Adding Vocational Labs (5 SS), (480 NSF), (682 GSF); Law Enforcement, General (480 NSF)	271,719
1.014	Remodeling Building Number - 2, Building Name - MITCHELL WOLFSON : Adding Classrooms (300 SS), (8400 NSF), (11931 GSF); Non-Vocational Labs (400 SS), (22600 NSF), (32101 GSF); Classroom (8400 NSF, 300 SSC), Area Studies (22600 NSF, 400 SSC) and Removing (0 SS), (36642 NSF) Room 210100 (24945 NSF), Room 215800 (2699 NSF), Room 215100 (2699 NSF), Room 225013 (1403 NSF), Room 22002W (4896 NSF)	7,310,079
1.015	Remodeling Building Number - 1, Building Name - PAUL R SCOTT HALL : Adding Vocational Labs (130 SS), (12030 NSF), (17087 GSF); Computer Electronics (12030 NSF, 130 SSC) and Removing (36 SS), (12621 NSF) Room 112200 (895 NSF), Room 116004 (808 NSF), Room 120900 (5169 NSF), Room 121700 (5749 NSF)	5,000,000
1.016	Renovating Building Number - 1401, Building Name - GREEN HOUSE 1 (0 SS), (1419 NSF) Apply Other to Room 1401A (1419 NSF) Renovation Description:	188,727
1.017	Renovating Building Number - 1, Building Name - PAUL R SCOTT HALL (0 SS), (88 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 110405 (88 NSF) Renovation Description:	8,869,928
1.018	Renovating Building Number - 2, Building Name - MITCHELL WOLFSON (294 SS), (136605 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 210100 (24945 NSF), Room 212800 (199 NSF), Room 215800 (2699 NSF), Room 222104 (139 NSF), Room 225014 (41 NSF), Room 225631 (151 NSF), Room 210011 (28 NSF), Room 212701 (177 NSF), Room 215100 (2699 NSF), Room 222100 (137 NSF), Room 225009 (84 NSF), Room 225627 (108 NSF), Room 2M4200 (114 NSF), Room 210092 (71 NSF), Room 212704 (152 NSF), Room 215400 (20 NSF), Room 222103 (133 NSF), Room 225013 (1403 NSF), Room 225630 (148 NSF), Room 210008 (77 NSF), Room 212602 (86 NSF), Room 214900 (420 NSF), Room 221603 (99 NSF), Room 225005 (129 NSF), Room 225623 (110 NSF), Room 2M3800 (116 NSF), Room 210101 (406 NSF), Room 213100 (1623 NSF), Room 215900 (412 NSF), Room 222105 (51 NSF), Room 225015 (96 NSF), Room 225632 (27 NSF), Room 210103 (203 NSF), Room 213102 (49 NSF), Room 216000 (395 NSF), Room 222200 (2772 NSF), Room 225017 (96 NSF), Room 225634 (194 NSF), Room 210200 (102 NSF), Room 213104 (71 NSF), Room 216200 (163 NSF), Room 222300 (1305 NSF), Room 225019 (50 NSF), Room 225636 (115 NSF), Room 210012 (28 NSF), Room 212702 (128 NSF), Room 215200 (17 NSF), Room 222101 (99 NSF), Room 225010 (111 NSF), Room 225628 (94 NSF), Room 2M4300 (484 NSF), Room 210212 (187 NSF), Room 213607 (38 NSF), Room 22002W (4896 NSF), Room 223505 (79 NSF), Room 225534 (140 NSF), Room 226003 (106 NSF), Room 210005 (185 NSF), Room 212401 (213 NSF), Room 214601 (469 NSF), Room 221600 (242 NSF), Room 225002 (599 NSF), Room 225620 (107 NSF), Room 2M3300 (707 NSF), Room 210207 (324 NSF), Room 213602 (149 NSF), Room 220006 (241 NSF), Room 223500 (86 NSF), Room 225026 (45 NSF), Room 225802 (194 NSF), Room 211701 (85 NSF), Room 214003 (122 NSF), Room 220600 (1297 NSF), Room 223516 (83 NSF), Room 225611 (118 NSF), Room 2M0010 (28 NSF), Room 210006 (222 NSF), Room 212600 (138 NSF), Room 214603 (179 NSF), Room 221601 (100 NSF), Room 225003 (133 NSF), Room 225621 (106 NSF), Room 2M3500 (133 NSF), Room 212101 (606 NSF), Room 214006 (105 NSF), Room 220900 (1511 NSF), Room 223520 (151 NSF), Room 225614 (110 NSF), Room 2M0092 (67 NSF), Room 210213 (187 NSF), Room 213700 (123 NSF), Room 220091 (71 NSF), Room 223506 (186 NSF), Room 225600 (894 NSF), Room 226004 (189 NSF), Room 210901 (53 NSF), Room 213706 (38 NSF), Room 220300 (188 NSF), Room 223512 (78 NSF), Room 225607 (101 NSF), Room 226101 (698 NSF), Room 210214 (229 NSF), Room 213701 (120 NSF), Room 220092 (72 NSF), Room 223507 (16 NSF), Room 225602 (93 NSF), Room 226005 (222 NSF), Room 210900 (137 NSF), Room 213705 (356 NSF), Room 220202 (30 NSF), Room 223511 (12 NSF), Room 225606 (91 NSF), Room 226100 (1578 NSF), Room 210203 (37 NSF), Room 213400 (510 NSF), Room 220002 (213 NSF), Room 222700 (295 NSF), Room 225022 (37 NSF), Room 225639 (120 NSF), Room 210007 (170 NSF), Room 212601 (85 NSF), Room 214700 (2699 NSF), Room 221602 (97 NSF), Room 225004 (226 NSF), Room 225622 (107 NSF), Room 2M3700 (116 NSF), Room 211700 (222 NSF), Room 214002 (621 NSF), Room 220500 (1298 NSF), Room 223515 (80 NSF), Room 225610 (216	8,235,626

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NSF), Room 2M0009 (28 NSF), Room 210004 (127 NSF), Room 212400 (1103 NSF), Room 214600 (358 NSF), Room 221500 (59 NSF), Room 225001 (802 NSF), Room 225619 (101 NSF), Room 2M3201 (111 NSF), Room 210000 (4744 NSF), Room 212102 (56 NSF), Room 214007 (157 NSF), Room 221000 (755 NSF), Room 223521 (134 NSF), Room 225615 (183 NSF), Room 2M0096 (10 NSF), Room 211800 (1349 NSF), Room 214004 (244 NSF), Room 220700 (1142 NSF), Room 223518 (69 NSF), Room 225612 (118 NSF), Room 2M0011 (30 NSF), Room 210202 (162 NSF), Room 213200 (48 NSF), Room 220001 (640 NSF), Room 222500 (1322 NSF), Room 225021 (91 NSF), Room 225638 (108 NSF), Room 210002 (178 NSF), Room 212300 (131 NSF), Room 214009 (108 NSF), Room 221200 (48 NSF), Room 224700 (163 NSF), Room 225617 (108 NSF), Room 2M3100 (41 NSF), Room 212100 (484 NSF), Room 214005 (33 NSF), Room 220800 (1191 NSF), Room 223519 (123 NSF), Room 225613 (68 NSF), Room 2M0012 (29 NSF), Room 211201 (53 NSF), Room 214001 (431 NSF), Room 220400 (1301 NSF), Room 223514 (74 NSF), Room 225609 (108 NSF), Room 2M0004 (117 NSF), Room 211200 (163 NSF), Room 214000 (796 NSF), Room 220301 (56 NSF), Room 223513 (97 NSF), Room 225608 (84 NSF), Room 226102 (375 NSF), Room 210003 (178 NSF), Room 212301 (70 NSF), Room 214010 (60 NSF), Room 221400 (52 NSF), Room 225000 (953 NSF), Room 225618 (153 NSF), Room 2M3200 (171 NSF), Room 210211 (237 NSF), Room 213606 (45 NSF), Room 22002E (1507 NSF), Room 223504 (87 NSF), Room 225200 (536 NSF), Room 226002 (114 NSF), Room 210401 (23 NSF), Room 213702 (151 NSF), Room 220100 (11241 NSF), Room 223508 (126 NSF), Room 225603 (110 NSF), Room 226006 (870 NSF), Room 210209 (13 NSF), Room 213604 (371 NSF), Room 22001E (554 NSF), Room 223502 (81 NSF), Room 225028 (183 NSF), Room 226000 (282 NSF), Room 210204 (77 NSF), Room 213406 (25 NSF), Room 220003 (198 NSF), Room 223300 (63 NSF), Room 225023 (102 NSF), Room 225640 (112 NSF), Room 210001 (695 NSF), Room 212200 (102 NSF), Room 214008 (90 NSF), Room 221100 (660 NSF), Room 223522 (348 NSF), Room 225616 (180 NSF), Room 2M3000 (99 NSF), Room 210206 (3181 NSF), Room 213601 (150 NSF), Room 220005 (178 NSF), Room 223302 (188 NSF), Room 225025 (107 NSF), Room 225801 (69 NSF), Room 210201 (245 NSF), Room 213105 (40 NSF), Room 216300 (269 NSF), Room 222400 (1305 NSF), Room 225020 (86 NSF), Room 225637 (130 NSF), Room 210205 (76 NSF), Room 213600 (1258 NSF), Room 220004 (117 NSF), Room 223301 (174 NSF), Room 225024 (23 NSF), Room 225800 (235 NSF), Room 210208 (1055 NSF), Room 213603 (135 NSF), Room 220007 (232 NSF), Room 223501 (257 NSF), Room 225027 (136 NSF), Room 225803 (331 NSF), Room 210102 (434 NSF), Room 213101 (371 NSF), Room 215901 (34 NSF), Room 222106 (116 NSF), Room 225016 (24 NSF), Room 225633 (98 NSF), Room 21000E (3525 NSF), Room 212603 (90 NSF), Room 214901 (63 NSF), Room 221700 (102 NSF), Room 225006 (142 NSF), Room 225624 (248 NSF), Room 2M3900 (306 NSF), Room 21000W (374 NSF), Room 212604 (92 NSF), Room 214902 (63 NSF), Room 221800 (1265 NSF), Room 225007 (68 NSF), Room 225625 (115 NSF), Room 2M4000 (341 NSF), Room 210091 (69 NSF), Room 212703 (152 NSF), Room 215300 (19 NSF), Room 222102 (236 NSF), Room 225011 (148 NSF), Room 225629 (112 NSF), Room 210210 (13 NSF), Room 213605 (37 NSF), Room 22001W (433 NSF), Room 223503 (85 NSF), Room 225029 (39 NSF), Room 226001 (220 NSF), Room 210600 (224 NSF), Room 213703 (94 NSF), Room 220200 (170 NSF), Room 223509 (119 NSF), Room 225604 (98 NSF), Room 226007 (265 NSF), Room 210010 (29 NSF), Room 212700 (781 NSF), Room 214903 (26 NSF), Room 222000 (189 NSF), Room 225008 (156 NSF), Room 225626 (114 NSF), Room 2M4100 (117 NSF), Room 210601 (66 NSF), Room 213704 (179 NSF), Room 220201 (56 NSF), Room 223510 (181 NSF), Room 225605 (106 NSF), Room 226008 (153 NSF), Room 210104 (231 NSF), Room 213103 (60 NSF), Room 216100 (268 NSF), Room 222201 (1213 NSF), Room 225018 (165 NSF), Room 225635 (16 NSF) Renovation Description:

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.019	Renovating Building Number - 3, Building Name - MCARTHUR HALL (908 SS), (104375 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 310700 (905 NSF), Room 313301 (332 NSF), Room 321302 (378 NSF), Room 32490B (1967 NSF), Room 310701 (33 NSF), Room 313302 (126 NSF), Room 321400 (1424 NSF), Room 32490C (1463 NSF), Room 310500 (92 NSF), Room 313003 (130 NSF), Room 321201 (85 NSF), Room 324700 (251 NSF), Room 310800 (603 NSF), Room 313500 (1757 NSF), Room 321401 (113 NSF), Room 32490D (1463 NSF), Room 310801 (43 NSF), Room 313600 (266 NSF), Room 321402 (282 NSF), Room 330100 (1133 NSF), Room 310904 (100 NSF), Room 313901 (87 NSF), Room 321700 (228 NSF), Room 311200 (606 NSF), Room 314600 (58 NSF), Room 322102 (53 NSF), Room 310601 (114 NSF), Room 313300 (1737 NSF), Room 321301 (161 NSF), Room 32490A (1967 NSF), Room 310900 (1506 NSF), Room 313700 (218 NSF), Room 321403 (146 NSF), Room 330200 (965 NSF), Room 312100 (677 NSF), Room 32000C (867 NSF), Room 323101 (139 NSF), Room 311901 (34 NSF), Room 320003 (756 NSF), Room 323100 (1647 NSF), Room 310200 (125 NSF), Room 312802 (144 NSF), Room 320800 (1482 NSF), Room 324200 (175 NSF), Room 310902 (64 NSF), Room 313800 (25 NSF), Room 321600 (263 NSF), Room 330400 (965 NSF), Room 310001 (785 NSF), Room 312102 (751 NSF), Room 32001N (1602 NSF), Room 323400 (220 NSF), Room 31003W (1677 NSF), Room 312402 (32 NSF), Room 320500 (273 NSF), Room 324000 (550 NSF), Room 310201 (103 NSF), Room 312803 (23 NSF), Room 320900 (635 NSF), Room 324300 (248 NSF), Room 310102 (22 NSF), Room 312801 (94 NSF), Room 320701 (245 NSF), Room 324100 (175 NSF), Room 311700 (473 NSF), Room 320001 (783 NSF), Room 322800 (633 NSF), Room 311600 (650 NSF), Room 320000 (3183 NSF), Room 322702 (325 NSF), Room 311900 (226 NSF), Room 320002 (756 NSF), Room 323000 (635 NSF), Room 310300 (1753 NSF), Room 313000 (355 NSF), Room 321000 (1499 NSF), Room 324400 (142 NSF), Room 310100 (727 NSF), Room 312700 (1990 NSF), Room 320600 (1486 NSF), Room 32401S (1335 NSF), Room 31002W (533 NSF), Room 312401 (16 NSF), Room 320400 (1489 NSF), Room 323900 (912 NSF), Room 31001N (1646 NSF), Room 312301 (101 NSF), Room 320200 (995 NSF), Room 323700 (155 NSF), Room 310400 (208 NSF), Room 313001 (128 NSF), Room 321100 (635 NSF), Room 324500 (316 NSF), Room 310003 (489 NSF), Room 312200 (213 NSF), Room 32002N (477 NSF), Room 323500 (25 NSF), Room 311101 (29 NSF), Room 314500 (159 NSF), Room 322101 (54 NSF), Room 310905 (110 NSF), Room 314000 (950 NSF), Room 321701 (55 NSF), Room 311300 (1088 NSF), Room 314701 (40 NSF), Room 322200 (592 NSF), Room 310401 (48 NSF), Room 313002 (37 NSF), Room 321200 (2038 NSF), Room 324600 (146 NSF), Room 311100 (952 NSF), Room 314400 (101 NSF), Room 322100 (1134 NSF), Room 311301 (29 NSF), Room 314702 (65 NSF), Room 322300 (980 NSF), Room 310903 (85 NSF), Room 313900 (466 NSF), Room 321601 (34 NSF), Room 311201 (43 NSF), Room 314700 (280 NSF), Room 322110 (1177 NSF), Room 310600 (269 NSF), Room 313200 (1299 NSF), Room 321300 (1460 NSF), Room 324800 (499 NSF), Room 310901 (78 NSF), Room 313701 (25 NSF), Room 321500 (537 NSF), Room 330300 (965 NSF), Room 310101 (23 NSF), Room 312800 (1039 NSF), Room 320700 (1147 NSF), Room 32401W (1256 NSF), Room 311500 (295 NSF), Room 315200 (157 NSF), Room 322700 (1640 NSF), Room 310002 (489 NSF), Room 312103 (627 NSF), Room 32001S (1651 NSF), Room 323401 (23 NSF), Room 310091 (70 NSF), Room 312500 (2024 NSF), Room 320501 (46 NSF), Room 32401N (580 NSF), Room 31002N (477 NSF), Room 312400 (1003 NSF), Room 320301 (55 NSF), Room 323800 (768 NSF), Room 311400 (650 NSF), Room 314703 (65 NSF), Room 322500 (982 NSF), Room 311501 (89 NSF), Room 315300 (103 NSF), Room 322701 (180 NSF), Room 310000 (2853 NSF), Room 312101 (787 NSF), Room 32000W (2097 NSF), Room 323200 (763 NSF), Room 31001W (306 NSF), Room 312302 (101 NSF), Room 320300 (250 NSF), Room 323701 (44 NSF), Room 31000C (713 NSF), Room 312201 (55 NSF), Room 320091 (71 NSF), Room 323600 (218 NSF), Room 311000 (650 NSF), Room 314100 (479 NSF), Room 321800 (39 NSF), Room 31000S (2089 NSF), Room 312300 (33 NSF), Room 320100 (632 NSF), Room 323601 (53 NSF) Renovation Description:	10,342,836

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.020	Renovating Building Number - 4, Building Name - LEROY COLLINS CENTER (29 SS), (57377 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 410100 (6062 NSF), Room 42001C (210 NSF), Room 410101 (240 NSF), Room 42001S (289 NSF), Room 410091 (47 NSF), Room 42000W (1172 NSF), Room 410102 (123 NSF), Room 42002C (616 NSF), Room 410200 (422 NSF), Room 42002S (947 NSF), Room 410201 (72 NSF), Room 42003S (141 NSF), Room 410400 (5641 NSF), Room 420301 (36 NSF), Room 410303 (48 NSF), Room 420300 (235 NSF), Room 410006 (14 NSF), Room 42000N (2949 NSF), Room 410004 (197 NSF), Room 420004 (272 NSF), Room 410600 (862 NSF), Room 420400 (554 NSF), Room 411005 (84 NSF), Room 420803 (245 NSF), Room 411003 (123 NSF), Room 420801 (168 NSF), Room 410005 (14 NSF), Room 42000E (584 NSF), Room 411006 (84 NSF), Room 420804 (127 NSF), Room 411602 (173 NSF), Room 421100 (303 NSF), Room 410800 (37 NSF), Room 420601 (30 NSF), Room 411601 (100 NSF), Room 421000 (311 NSF), Room 411200 (1002 NSF), Room 420808 (243 NSF), Room 410500 (1872 NSF), Room 420302 (83 NSF), Room 410302 (83 NSF), Room 420201 (35 NSF), Room 410900 (37 NSF), Room 420602 (56 NSF), Room 04000R (1 NSF), Room 412500 (64 NSF), Room 4M0101 (297 NSF), Room 410601 (420 NSF), Room 420401 (31 NSF), Room 411004 (84 NSF), Room 420802 (176 NSF), Room 411301 (59 NSF), Room 420900 (880 NSF), Room 411000 (1023 NSF), Room 420700 (1990 NSF), Room 411001 (155 NSF), Room 420701 (952 NSF), Room 411300 (1536 NSF), Room 420809 (123 NSF), Room 410301 (62 NSF), Room 420200 (252 NSF), Room 411302 (58 NSF), Room 420901 (67 NSF), Room 410000 (9542 NSF), Room 420000 (476 NSF), Room 4M0102 (275 NSF), Room 410300 (411 NSF), Room 420100 (880 NSF), Room 410602 (289 NSF), Room 420402 (13 NSF), Room 411600 (595 NSF), Room 420902 (112 NSF), Room 411100 (601 NSF), Room 420805 (126 NSF), Room 410700 (37 NSF), Room 420600 (1334 NSF), Room 411700 (1215 NSF), Room 421200 (726 NSF), Room 410002 (288 NSF), Room 420002 (292 NSF), Room 410003 (95 NSF), Room 420003 (161 NSF), Room 410001 (184 NSF), Room 420001 (181 NSF), Room 411002 (407 NSF), Room 420800 (732 NSF), Room 412100 (123 NSF), Room 4M0100 (390 NSF), Room 411101 (417 NSF), Room 420806 (125 NSF), Room 411102 (64 NSF), Room 420807 (125 NSF), Room 410501 (401 NSF), Room 420303 (48 NSF), Room 410202 (65 NSF), Room 420091 (47 NSF), Room 410603 (254 NSF), Room 420500 (1173 NSF) Renovation Description:	3,614,601

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.021	Renovating Building Number - 5, Building Name - WILLIAM PAWLEY CT (168 SS), (58538 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 510004 (150 NSF), Room 512700 (348 NSF), Room 521600 (206 NSF), Room 523301 (730 NSF), Room 510007 (231 NSF), Room 512800 (109 NSF), Room 521700 (286 NSF), Room 523500 (255 NSF), Room 51000W (811 NSF), Room 513102 (31 NSF), Room 522201 (87 NSF), Room 510010 (60 NSF), Room 513200 (41 NSF), Room 522202 (106 NSF), Room 510008 (45 NSF), Room 512900 (225 NSF), Room 521900 (166 NSF), Room 523501 (141 NSF), Room 51000E (819 NSF), Room 513100 (41 NSF), Room 522101 (315 NSF), Room 523600 (218 NSF), Room 51000N (2342 NSF), Room 513101 (69 NSF), Room 522200 (1641 NSF), Room 523700 (97 NSF), Room 510091 (45 NSF), Room 513202 (31 NSF), Room 522301 (57 NSF), Room 510200 (594 NSF), Room 513700 (224 NSF), Room 522401 (78 NSF), Room 510011 (20 NSF), Room 513201 (69 NSF), Room 522300 (1795 NSF), Room 510009 (58 NSF), Room 513000 (225 NSF), Room 522100 (275 NSF), Room 523502 (412 NSF), Room 510001 (297 NSF), Room 512302 (159 NSF), Room 521300 (250 NSF), Room 523100 (183 NSF), Room 511100 (52 NSF), Room 520006 (57 NSF), Room 522411 (78 NSF), Room 511700 (154 NSF), Room 520013 (43 NSF), Room 522606 (87 NSF), Room 512100 (2957 NSF), Room 520400 (1058 NSF), Room 522611 (80 NSF), Room 511602 (47 NSF), Room 520012 (37 NSF), Room 522605 (87 NSF), Room 512102 (33 NSF), Room 520501 (55 NSF), Room 522613 (120 NSF), Room 512103 (39 NSF), Room 520700 (104 NSF), Room 522614 (80 NSF), Room 510000 (5767 NSF), Room 512301 (146 NSF), Room 521200 (73 NSF), Room 523000 (61 NSF), Room 510900 (250 NSF), Room 520004 (144 NSF), Room 522409 (159 NSF), Room 511300 (243 NSF), Room 520008 (46 NSF), Room 522412 (78 NSF), Room 512104 (39 NSF), Room 520701 (26 NSF), Room 522615 (93 NSF), Room 512101 (33 NSF), Room 520500 (198 NSF), Room 522612 (80 NSF), Room 512202 (159 NSF), Room 521100 (224 NSF), Room 522802 (81 NSF), Room 510700 (978 NSF), Room 520001 (407 NSF), Room 522406 (80 NSF), Room 512200 (882 NSF), Room 521000 (122 NSF), Room 522800 (197 NSF), Room 511800 (686 NSF), Room 520100 (290 NSF), Room 522608 (85 NSF), Room 510100 (212 NSF), Room 513600 (91 NSF), Room 522400 (317 NSF), Room 511301 (65 NSF), Room 52000E (1251 NSF), Room 522600 (163 NSF), Room 511701 (46 NSF), Room 520091 (45 NSF), Room 522607 (86 NSF), Room 511601 (118 NSF), Room 520011 (71 NSF), Room 522604 (82 NSF), Room 512201 (149 NSF), Room 521001 (25 NSF), Room 522801 (82 NSF), Room 512106 (2719 NSF), Room 520900 (1344 NSF), Room 522700 (182 NSF), Room 512105 (641 NSF), Room 520800 (306 NSF), Room 522616 (46 NSF), Room 05000R (1 NSF), Room 512300 (881 NSF), Room 521101 (70 NSF), Room 522900 (209 NSF), Room 510800 (72 NSF), Room 520003 (138 NSF), Room 522408 (81 NSF), Room 511900 (209 NSF), Room 520200 (209 NSF), Room 522609 (100 NSF), Room 510701 (143 NSF), Room 520002 (410 NSF), Room 522407 (80 NSF), Room 511302 (23 NSF), Room 52000N (1903 NSF), Room 522601 (378 NSF), Room 512000 (1107 NSF), Room 520300 (679 NSF), Room 522610 (115 NSF), Room 510600 (430 NSF), Room 513801 (124 NSF), Room 522403 (229 NSF), Room 510201 (85 NSF), Room 513800 (1770 NSF), Room 522402 (78 NSF), Room 510002 (297 NSF), Room 512400 (481 NSF), Room 521400 (1124 NSF), Room 523200 (133 NSF), Room 510602 (219 NSF), Room 520000 (834 NSF), Room 522405 (81 NSF), Room 510003 (142 NSF), Room 512500 (1039 NSF), Room 521500 (681 NSF), Room 523300 (522 NSF), Room 511600 (1874 NSF), Room 52000W (1272 NSF), Room 522603 (169 NSF), Room 510601 (288 NSF), Room 513802 (152 NSF), Room 522404 (158 NSF), Room 510901 (85 NSF), Room 520005 (56 NSF), Room 522410 (229 NSF) Renovation Description:	6,768,777
1.022	Renovating Building Number - 6, Building Name - LEARNING CENTER (0 SS), (11892 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 611100 (162 NSF), Room 611200 (168 NSF), Room 611400 (130 NSF), Room 611800 (96 NSF), Room 612100 (85 NSF), Room 611900 (203 NSF), Room 611500 (135 NSF), Room 611000 (170 NSF), Room 612600 (135 NSF), Room 612700 (130 NSF), Room 612400 (232 NSF), Room 611700 (133 NSF), Room 613500 (609 NSF), Room 612000 (63 NSF), Room 613600 (605 NSF), Room 613700 (610 NSF), Room 611600 (135 NSF), Room 610900 (170 NSF), Room 610100 (170 NSF), Room 06000R (1 NSF), Room 61000E (645 NSF), Room 610300 (170 NSF), Room 61000S (1196 NSF), Room 613400 (485 NSF), Room 61000W (647 NSF), Room 610400 (170 NSF), Room 610600 (168 NSF), Room 613300 (691 NSF), Room 61000N (819 NSF), Room 610500 (162 NSF), Room 610700 (169 NSF), Room 610200 (162 NSF), Room 613200 (957 NSF), Room 613000 (159 NSF), Room 611300 (170 NSF), Room 612800 (167 NSF), Room 612500 (135 NSF), Room 610800 (162 NSF), Room 613100 (166 NSF), Room 612200 (190 NSF), Room 612900 (160 NSF) Renovation Description:	1,838,678

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.023	Renovating Building Number - 7, Building Name - GARTH C REEVES HALL (1026 SS), (74235 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 710301 (44 NSF), Room 721700 (904 NSF), Room 732211 (233 NSF), Room 710100 (70 NSF), Room 721400 (731 NSF), Room 732208 (900 NSF), Room 710500 (730 NSF), Room 721900 (731 NSF), Room 732400 (201 NSF), Room 710400 (719 NSF), Room 721800 (737 NSF), Room 732300 (316 NSF), Room 710700 (902 NSF), Room 722100 (231 NSF), Room 732402 (16 NSF), Room 710200 (187 NSF), Room 721500 (279 NSF), Room 732209 (293 NSF), Room 710800 (902 NSF), Room 722101 (43 NSF), Room 732500 (731 NSF), Room 711200 (572 NSF), Room 73000S (918 NSF), Room 732701 (162 NSF), Room 710900 (742 NSF), Room 730001 (473 NSF), Room 732600 (572 NSF), Room 711201 (33 NSF), Room 73000W (1396 NSF), Room 732800 (102 NSF), Room 710300 (279 NSF), Room 721600 (904 NSF), Room 732210 (441 NSF), Room 72000W (1282 NSF), Room 730900 (160 NSF), Room 734200 (286 NSF), Room 711400 (731 NSF), Room 730100 (231 NSF), Room 733000 (282 NSF), Room 710002 (443 NSF), Room 720800 (902 NSF), Room 732201 (164 NSF), Room 72002N (1414 NSF), Room 731200 (167 NSF), Room 734500 (355 NSF), Room 71000S (1523 NSF), Room 721100 (718 NSF), Room 732204 (193 NSF), Room 72000E (1298 NSF), Room 730800 (181 NSF), Room 734100 (180 NSF), Room 71001S (1552 NSF), Room 721201 (33 NSF), Room 732206 (167 NSF), Room 711800 (737 NSF), Room 730300 (279 NSF), Room 733400 (270 NSF), Room 720100 (70 NSF), Room 731500 (270 NSF), Room 734503 (439 NSF), Room 720200 (187 NSF), Room 731600 (166 NSF), Room 734504 (299 NSF), Room 72002S (1445 NSF), Room 731300 (167 NSF), Room 734501 (316 NSF), Room 70000R (1 NSF), Room 720500 (727 NSF), Room 732000 (181 NSF), Room 734700 (920 NSF), Room 72001N (680 NSF), Room 731000 (169 NSF), Room 734300 (182 NSF), Room 712000 (719 NSF), Room 730400 (390 NSF), Room 733600 (167 NSF), Room 711600 (904 NSF), Room 730200 (152 NSF), Room 733200 (105 NSF), Room 720091 (44 NSF), Room 731400 (167 NSF), Room 734502 (295 NSF), Room 720301 (44 NSF), Room 731800 (181 NSF), Room 734601 (100 NSF), Room 71001N (1550 NSF), Room 721200 (572 NSF), Room 732205 (271 NSF), Room 720400 (719 NSF), Room 731900 (282 NSF), Room 734602 (15 NSF), Room 72001S (794 NSF), Room 731100 (270 NSF), Room 734400 (101 NSF), Room 710600 (744 NSF), Room 722000 (719 NSF), Room 732401 (100 NSF), Room 711300 (719 NSF), Room 730091 (46 NSF), Room 732900 (182 NSF), Room 711700 (904 NSF), Room 730201 (31 NSF), Room 733300 (167 NSF), Room 720002 (443 NSF), Room 730700 (286 NSF), Room 734000 (105 NSF), Room 71000E (1430 NSF), Room 720900 (742 NSF), Room 732202 (279 NSF), Room 710001 (475 NSF), Room 720700 (902 NSF), Room 732200 (357 NSF), Room 734800 (1165 NSF), Room 71000N (1501 NSF), Room 721000 (724 NSF), Room 732203 (192 NSF), Room 712101 (43 NSF), Room 730500 (104 NSF), Room 733800 (270 NSF), Room 710000 (7352 NSF), Room 720600 (744 NSF), Room 732100 (102 NSF), Room 734701 (411 NSF), Room 712100 (231 NSF), Room 730401 (311 NSF), Room 733700 (169 NSF), Room 711900 (731 NSF), Room 730301 (44 NSF), Room 733500 (169 NSF), Room 710091 (44 NSF), Room 721300 (719 NSF), Room 732207 (221 NSF), Room 711500 (737 NSF), Room 730101 (43 NSF), Room 733100 (180 NSF), Room 720001 (478 NSF), Room 730600 (183 NSF), Room 733900 (170 NSF), Room 711000 (730 NSF), Room 730002 (435 NSF), Room 732601 (33 NSF), Room 711100 (718 NSF), Room 73000E (1292 NSF), Room 732700 (212 NSF), Room 720300 (279 NSF), Room 731700 (104 NSF), Room 734600 (202 NSF)	3,885,213

Renovation Description:

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.024	Renovating Building Number - 8, Building Name - SCHOOL JUSTICE/SAFE (380 SS), (53396 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 810500 (155 NSF), Room 820600 (211 NSF), Room 832400 (337 NSF), Room 810900 (84 NSF), Room 820900 (112 NSF), Room 832600 (214 NSF), Room 810901 (184 NSF), Room 821000 (169 NSF), Room 832700 (356 NSF), Room 811101 (177 NSF), Room 821102 (115 NSF), Room 833000 (195 NSF), Room 811301 (78 NSF), Room 821200 (174 NSF), Room 833300 (1836 NSF), Room 811200 (176 NSF), Room 821103 (44 NSF), Room 833100 (192 NSF), Room 811600 (1005 NSF), Room 822100 (258 NSF), Room 833500 (222 NSF), Room 811000 (325 NSF), Room 821100 (1397 NSF), Room 832800 (195 NSF), Room 810800 (168 NSF), Room 820800 (62 NSF), Room 832500 (160 NSF), Room 820104 (74 NSF), Room 830800 (135 NSF), Room 834800 (581 NSF), Room 82001S (362 NSF), Room 83001W (805 NSF), Room 834002 (172 NSF), Room 811400 (160 NSF), Room 821300 (110 NSF), Room 833400 (124 NSF), Room 82000W (1170 NSF), Room 83000S (929 NSF), Room 834000 (79 NSF), Room 820105 (104 NSF), Room 830900 (151 NSF), Room 834900 (431 NSF), Room 811800 (976 NSF), Room 822103 (433 NSF), Room 833700 (640 NSF), Room 810100 (637 NSF), Room 820207 (330 NSF), Room 831900 (98 NSF), Room 835400 (130 NSF), Room 820102 (193 NSF), Room 830600 (123 NSF), Room 834601 (48 NSF), Room 810001 (440 NSF), Room 820202 (193 NSF), Room 831400 (98 NSF), Room 835100 (146 NSF), Room 810000 (1739 NSF), Room 820201 (291 NSF), Room 831300 (98 NSF), Room 835003 (127 NSF), Room 820103 (417 NSF), Room 830700 (135 NSF), Room 834602 (66 NSF), Room 810200 (1005 NSF), Room 820302 (379 NSF), Room 832100 (192 NSF), Room 835402 (119 NSF), Room 811900 (768 NSF), Room 822104 (54 NSF), Room 833800 (66 NSF), Room 820002 (426 NSF), Room 83000N (1001 NSF), Room 833900 (136 NSF), Room 810101 (91 NSF), Room 820300 (4587 NSF), Room 832000 (182 NSF), Room 835401 (254 NSF), Room 820101 (193 NSF), Room 830300 (198 NSF), Room 834600 (136 NSF), Room 820106 (183 NSF), Room 831000 (358 NSF), Room 835000 (175 NSF), Room 810400 (1049 NSF), Room 820500 (885 NSF), Room 832300 (136 NSF), Room 811700 (924 NSF), Room 822101 (49 NSF), Room 833600 (281 NSF), Room 811500 (1048 NSF), Room 821400 (159 NSF), Room 833401 (173 NSF), Room 810700 (111 NSF), Room 820700 (156 NSF), Room 832402 (203 NSF), Room 811100 (84 NSF), Room 821101 (65 NSF), Room 832900 (195 NSF), Room 810300 (2004 NSF), Room 820400 (331 NSF), Room 832200 (139 NSF), Room 840003 (12 NSF), Room 81000S (752 NSF), Room 820205 (194 NSF), Room 831700 (98 NSF), Room 835202 (169 NSF), Room 820091 (48 NSF), Room 830101 (42 NSF), Room 834300 (103 NSF), Room 810002 (423 NSF), Room 820203 (195 NSF), Room 831500 (106 NSF), Room 835200 (282 NSF), Room 82002S (738 NSF), Room 830100 (179 NSF), Room 834200 (156 NSF), Room 81000N (787 NSF), Room 820204 (195 NSF), Room 831600 (106 NSF), Room 835201 (168 NSF), Room 82002N (777 NSF), Room 830091 (52 NSF), Room 834100 (202 NSF), Room 810091 (48 NSF), Room 820206 (291 NSF), Room 831800 (98 NSF), Room 835300 (124 NSF), Room 811701 (67 NSF), Room 822102 (29 NSF), Room 833601 (149 NSF), Room 820001 (437 NSF), Room 830002 (441 NSF), Room 833802 (127 NSF), Room 820107 (183 NSF), Room 831100 (381 NSF), Room 835001 (196 NSF), Room 82001N (421 NSF), Room 83001E (831 NSF), Room 834001 (115 NSF), Room 811300 (33 NSF), Room 821104 (356 NSF), Room 833200 (129 NSF), Room 810600 (62 NSF), Room 820601 (213 NSF), Room 832401 (737 NSF), Room 820100 (361 NSF), Room 830102 (59 NSF), Room 834500 (126 NSF), Room 80000R (1 NSF), Room 820200 (201 NSF), Room 831200 (97 NSF), Room 835002 (133 NSF), Room 812000 (767 NSF), Room 830001 (424 NSF), Room 833801 (134 NSF)	4,369,570

Renovation Description:

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.025	Renovating Building Number - 9, Building Name - ENVIR SCIENCE/JUSTIC (358 SS), (23338 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 910201 (78 NSF), Room 910600 (1431 NSF), Room 910800 (613 NSF), Room 911101 (37 NSF), Room 910400 (240 NSF), Room 910300 (50 NSF), Room 911100 (391 NSF), Room 910701 (131 NSF), Room 910900 (298 NSF), Room 910500 (1439 NSF), Room 911500 (202 NSF), Room 920001 (368 NSF), Room 920100 (88 NSF), Room 920201 (70 NSF), Room 910801 (94 NSF), Room 910091 (80 NSF), Room 921100 (150 NSF), Room 92000N (1304 NSF), Room 910200 (315 NSF), Room 911300 (145 NSF), Room 912200 (174 NSF), Room 920002 (226 NSF), Room 920300 (307 NSF), Room 911900 (69 NSF), Room 920000 (812 NSF), Room 040 (1 NSF), Room 920400 (93 NSF), Room 920200 (311 NSF), Room 911801 (89 NSF), Room 910000 (1768 NSF), Room 920500 (53 NSF), Room 91000W (922 NSF), Room 921000 (1118 NSF), Room 911600 (148 NSF), Room 920301 (70 NSF), Room 912000 (138 NSF), Room 920091 (80 NSF), Room 911200 (145 NSF), Room 910101 (78 NSF), Room 911800 (870 NSF), Room 911501 (107 NSF), Room 911000 (215 NSF), Room 910001 (157 NSF), Room 920600 (127 NSF), Room 91110N (398 NSF), Room 910100 (319 NSF), Room 91000S (157 NSF), Room 920900 (1105 NSF), Room 910002 (226 NSF), Room 920700 (1139 NSF), Room 910700 (1432 NSF), Room 911700 (148 NSF), Room 91000N (1209 NSF), Room 920800 (1118 NSF), Room 912100 (340 NSF), Room 911400 (145 NSF) Renovation Description:	330,904
1.026	Renovating Building Number - 10, Building Name - FIRE SCIENCE ACADEMY (14 SS), (8544 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 010301 (153 NSF), Room 010104 (35 NSF), Room 010303 (118 NSF), Room 010100 (1612 NSF), Room 010102 (165 NSF), Room 010107 (258 NSF), Room 010401 (25 NSF), Room 010502 (33 NSF), Room 010600 (1440 NSF), Room 010302 (70 NSF), Room 010504 (167 NSF), Room 010503 (149 NSF), Room 010500 (158 NSF), Room 010402 (88 NSF), Room 010403 (75 NSF), Room 00100R (1 NSF), Room 010501 (25 NSF), Room 010103 (170 NSF), Room 010400 (161 NSF), Room 010601 (190 NSF), Room 010300 (1442 NSF), Room 010200 (225 NSF), Room 010101 (145 NSF), Room 01000S (1639 NSF) Renovation Description:	1,251,433
1.027	Renovating Building Number - 11, Building Name - FIRE SCI BURN BLDG (0 SS), (3167 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room K10300 (74 NSF), Room K10400 (32 NSF), Room K10700 (315 NSF), Room K10500 (63 NSF), Room K10800 (92 NSF), Room K10900 (139 NSF), Room K10600 (306 NSF), Room K20000 (968 NSF), Room K10100 (293 NSF), Room K2000N (94 NSF), Room K20100 (277 NSF), Room 01100R (1 NSF), Room K20200 (226 NSF), Room K20300 (61 NSF), Room K10200 (73 NSF), Room K10001 (153 NSF) Renovation Description:	2,239
1.028	Renovating Building Number - 12, Building Name - FIRE SCIENCE TOWER (0 SS), (6689 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 024200 (108 NSF), Room 025100 (70 NSF), Room 025300 (104 NSF), Room 024600 (16 NSF), Room 025402 (33 NSF), Room 025400 (247 NSF), Room 024800 (174 NSF), Room 021000 (344 NSF), Room 027400 (345 NSF), Room 026100 (70 NSF), Room 020100 (45 NSF), Room 027300 (129 NSF), Room 021801 (173 NSF), Room 021700 (42 NSF), Room 026600 (16 NSF), Room 022300 (106 NSF), Room 021400 (347 NSF), Room 025600 (16 NSF), Room 022100 (65 NSF), Room 021600 (17 NSF), Room 023200 (108 NSF), Room 023800 (178 NSF), Room 023400 (341 NSF), Room 022200 (109 NSF), Room 01200R (1 NSF), Room 027200 (108 NSF), Room 023101 (238 NSF), Room 021200 (126 NSF), Room 026400 (347 NSF), Room 021300 (84 NSF), Room 026200 (108 NSF), Room 023600 (16 NSF), Room 022600 (16 NSF), Room 021800 (173 NSF), Room 025200 (108 NSF), Room 026300 (104 NSF), Room 021100 (48 NSF), Room 027600 (16 NSF), Room 024100 (70 NSF), Room 022400 (341 NSF), Room 024300 (106 NSF), Room 024400 (345 NSF), Room 025401 (100 NSF), Room 027100 (47 NSF), Room 023300 (106 NSF), Room 023100 (66 NSF), Room 021900 (31 NSF), Room 022800 (351 NSF), Room 022000 (168 NSF), Room 023801 (211 NSF), Room 024700 (21 NSF), Room 021500 (30 NSF) Renovation Description:	508,363

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.029	Renovating Building Number - 13, Building Name - GREEN URBAN LIVING C (40 SS), (7247 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 030200 (255 NSF), Room 030600 (147 NSF), Room 030800 (253 NSF), Room 030700 (48 NSF), Room 031102 (204 NSF), Room 031500 (1009 NSF), Room 031300 (523 NSF), Room 031401 (48 NSF), Room 031103 (23 NSF), Room 030900 (256 NSF), Room 031101 (967 NSF), Room 030400 (234 NSF), Room 030801 (83 NSF), Room 031600 (50 NSF), Room 031200 (280 NSF), Room 031400 (1262 NSF), Room 030100 (126 NSF), Room 030901 (75 NSF), Room 030300 (55 NSF), Room 01300R (1 NSF), Room 030500 (163 NSF), Room 031000 (208 NSF), Room 031100 (977 NSF) Renovation Description:	943,532
1.030	Renovating Building Number - 15, Building Name - AQUATIC CENTER (114 SS), (20017 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 050800 (640 NSF), Room 051300 (1602 NSF), Room 052000 (177 NSF), Room 050900 (58 NSF), Room 051600 (355 NSF), Room B51400 (715 NSF), Room 052200 (1434 NSF), Room 052300 (175 NSF), Room 052400 (143 NSF), Room B51700 (705 NSF), Room 052600 (35 NSF), Room B51800 (705 NSF), Room 052100 (4427 NSF), Room B51500 (715 NSF), Room 050700 (184 NSF), Room 050103 (367 NSF), Room 050600 (140 NSF), Room 05002C (1341 NSF), Room 050201 (409 NSF), Room 050400 (266 NSF), Room 050202 (405 NSF), Room 051900 (177 NSF), Room 05000G (1 NSF), Room 050104 (36 NSF), Room 050101 (359 NSF), Room 05001C (1202 NSF), Room 050102 (462 NSF), Room 050100 (290 NSF), Room 050203 (367 NSF), Room 051301 (394 NSF), Room 050200 (291 NSF), Room 05000R (1 NSF), Room 051200 (58 NSF), Room 050300 (1381 NSF) Renovation Description:	1,705,525
1.031	Renovating Building Number - 16, Building Name - PRESCHOOL LAB (0 SS), (19160 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 060600 (221 NSF), Room 061000 (225 NSF), Room 060902 (49 NSF), Room 060800 (39 NSF), Room 060500 (318 NSF), Room 060700 (221 NSF), Room 060900 (330 NSF), Room 061900 (463 NSF), Room 062100 (326 NSF), Room 061800 (80 NSF), Room 060200 (565 NSF), Room 063401 (266 NSF), Room 062401 (48 NSF), Room 060102 (122 NSF), Room 063200 (131 NSF), Room 062300 (109 NSF), Room 061901 (51 NSF), Room 061601 (38 NSF), Room 062400 (1068 NSF), Room 060100 (208 NSF), Room 063100 (1053 NSF), Room 061201 (51 NSF), Room 06001E (768 NSF), Room 062501 (83 NSF), Room 061600 (423 NSF), Room 061200 (444 NSF), Room 061100 (53 NSF), Room 062200 (1061 NSF), Room 061500 (425 NSF), Room 06001W (748 NSF), Room 062700 (66 NSF), Room 06003S (209 NSF), Room 063000 (108 NSF), Room 060104 (75 NSF), Room 063400 (1417 NSF), Room 01600R (1 NSF), Room 062500 (427 NSF), Room 060300 (293 NSF), Room 063500 (1059 NSF), Room 060101 (126 NSF), Room 063101 (48 NSF), Room 060901 (50 NSF), Room 061401 (51 NSF), Room 06002S (753 NSF), Room 062900 (1060 NSF), Room 060401 (145 NSF), Room 061001 (57 NSF), Room 060400 (269 NSF), Room 063600 (229 NSF), Room 062201 (48 NSF), Room 06001S (178 NSF), Room 062600 (55 NSF), Room 062000 (116 NSF), Room 061701 (51 NSF), Room 061501 (38 NSF), Room 061300 (81 NSF), Room 061400 (453 NSF), Room 06002W (270 NSF), Room 062901 (48 NSF), Room 06002E (272 NSF), Room 062800 (336 NSF), Room 060103 (197 NSF), Room 063300 (137 NSF), Room 061700 (450 NSF) Renovation Description:	481,444
1.032	Renovating Building Number - 17, Building Name - DRIVING RANGE/TOWER (0 SS), (1178 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 001701 (364 NSF), Room 001704 (642 NSF), Room 001703 (6 NSF), Room 001702 (166 NSF) Renovation Description:	171,092
1.033	Renovating Building Number - 18, Building Name - FIRE ENGINE STORAGE (0 SS), (1521 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 001801 (1521 NSF) Renovation Description:	210,990

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.034	Renovating Building Number - 19, Building Name - COLLEGE SERVICES (0 SS), (32707 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 090100 (9203 NSF), Room 090200 (158 NSF), Room 090400 (204 NSF), Room 090005 (43 NSF), Room 092501 (2355 NSF), Room 090201 (149 NSF), Room 090008 (17 NSF), Room 092800 (102 NSF), Room 090404 (142 NSF), Room 090202 (739 NSF), Room 090701 (40 NSF), Room 090601 (28 NSF), Room 090801 (68 NSF), Room 090007 (43 NSF), Room 092700 (220 NSF), Room 090006 (43 NSF), Room 092600 (220 NSF), Room 091800 (820 NSF), Room 091702 (56 NSF), Room 091600 (581 NSF), Room 091001 (78 NSF), Room 091701 (149 NSF), Room 091200 (126 NSF), Room 091505 (77 NSF), Room 091700 (3989 NSF), Room 091300 (175 NSF), Room 091100 (177 NSF), Room 090900 (25 NSF), Room 092000 (351 NSF), Room 091900 (612 NSF), Room 091000 (71 NSF), Room 090003 (43 NSF), Room 092400 (244 NSF), Room 092100 (604 NSF), Room 090004 (43 NSF), Room 092500 (152 NSF), Room 090001 (319 NSF), Room 092200 (166 NSF), Room 090800 (280 NSF), Room 090501 (113 NSF), Room 090401 (122 NSF), Room 090500 (1295 NSF), Room 090700 (151 NSF), Room 091500 (5519 NSF), Room 090002 (296 NSF), Room 092300 (163 NSF), Room 090402 (143 NSF), Room 090405 (21 NSF), Room 091503 (72 NSF), Room 091502 (569 NSF), Room 091504 (63 NSF), Room 091501 (134 NSF), Room 090600 (491 NSF), Room 090300 (307 NSF), Room 091400 (233 NSF), Room 090403 (103 NSF) Renovation Description:	2,496,858
1.035	Renovating Building Number - 20, Building Name - UTILITIES BUILDING (21 SS), (7513 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 720003 (193 NSF), Room 723001 (187 NSF), Room 72003N (763 NSF), Room 713300 (481 NSF), Room 71003N (741 NSF), Room 710003 (188 NSF), Room 723000 (187 NSF), Room 723200 (387 NSF), Room 723100 (1091 NSF), Room 713200 (481 NSF), Room 723300 (956 NSF), Room 713000 (1857 NSF), Room 02000R (1 NSF) Renovation Description:	1,054,211
1.036	Renovating Building Number - 21, Building Name - RECEIVING BUILDING (0 SS), (1525 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002103 (470 NSF), Room 002104 (363 NSF), Room 002102 (141 NSF), Room 002101 (551 NSF) Renovation Description:	150,728
1.037	Renovating Building Number - 22, Building Name - INFORMATION BOOTH (0 SS), (37 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002201 (37 NSF) Renovation Description:	40,678
1.038	Renovating Building Number - 24, Building Name - MOTOR POOL BUILDING (0 SS), (7022 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002403 (148 NSF), Room 002406 (212 NSF), Room 002410 (200 NSF), Room 002402 (164 NSF), Room 002407 (104 NSF), Room 002405 (1397 NSF), Room 002408 (914 NSF), Room 002404 (323 NSF), Room 002401 (3502 NSF), Room 002411 (58 NSF) Renovation Description:	875,017
1.039	Renovating Building Number - 25, Building Name - CHILLER (EAST BLDG 1 (0 SS), (3735 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002502 (904 NSF), Room 002501 (1761 NSF), Room 002500 (1070 NSF) Renovation Description:	2,108,481
1.040	Renovating Building Number - 26, Building Name - FLAMMABLE STORAGE (0 SS), (440 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002602 (220 NSF), Room 002601 (220 NSF) Renovation Description:	58,839

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.041	Renovating Building Number - 27, Building Name - FERTILIZER STORAGE (0 SS), (800 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002701 (800 NSF) Renovation Description:	65,084
1.042	Renovating Building Number - 28, Building Name - TENNIS PAVILION (0 SS), (2888 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002804 (97 NSF), Room 002803 (104 NSF), Room 002802 (123 NSF), Room 002805 (2349 NSF), Room 002801 (215 NSF) Renovation Description:	328,243
1.043	Renovating Building Number - 29, Building Name - STORAGE (0 SS), (1740 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002903 (70 NSF), Room 002904 (70 NSF), Room 002902 (800 NSF), Room 002901 (800 NSF) Renovation Description:	138,900
1.044	Renovating Building Number - 30, Building Name - GATE HOUSE (0 SS), (140 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003002 (20 NSF), Room 003003 (20 NSF), Room 003001 (100 NSF) Renovation Description:	78,578
1.045	Renovating Building Number - 31, Building Name - DUGOUT 1_FIELD A (0 SS), (400 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003101 (400 NSF) Renovation Description:	73,797
1.046	Renovating Building Number - 32, Building Name - DUGOUT 2_FIELD A (0 SS), (400 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003201 (400 NSF) Renovation Description:	73,797
1.047	Renovating Building Number - 33, Building Name - FUNERAL SCIENCES (10 SS), (3623 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Retrofit for Technology, Other to Room 314214 (31 NSF), Room 314300 (133 NSF), Room 314210 (73 NSF), Room 314215 (73 NSF), Room 314211 (97 NSF), Room 314303 (58 NSF), Room 314213 (75 NSF), Room 3M0100 (280 NSF), Room 314305 (51 NSF), Room 314301 (44 NSF), Room 314304 (769 NSF), Room 314212 (726 NSF), Room 314302 (143 NSF), Room 314206 (24 NSF), Room 314209 (418 NSF), Room 314204 (38 NSF), Room 314201 (93 NSF), Room 314207 (86 NSF), Room 314208 (50 NSF), Room 314203 (70 NSF), Room 314200 (161 NSF), Room 314202 (82 NSF), Room 314205 (48 NSF) Renovation Description:	529,128
1.048	Renovating Building Number - 34, Building Name - VEHICLE STORAGE (0 SS), (1470 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003401 (270 NSF), Room 003400 (1200 NSF) Renovation Description:	305,663
1.049	Renovating Building Number - 35, Building Name - STORAGE (0 SS), (800 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003500 (800 NSF) Renovation Description:	31,462

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.050	Renovating Building Number - 36, Building Name - SCIENCE COMPLEX (684 SS), (92590 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room A10002 (404 NSF), Room A12600 (85 NSF), Room A30001 (278 NSF), Room A32300 (146 NSF), Room A37100 (324 NSF), Room A1002N (230 NSF), Room A20002 (422 NSF), Room A3001N (382 NSF), Room A32800 (127 NSF), Room A40004 (110 NSF), Room A1001N (345 NSF), Room A12900 (29 NSF), Room A3001C (477 NSF), Room A32600 (126 NSF), Room A40000 (1810 NSF), Room A10400 (1386 NSF), Room A2003N (341 NSF), Room A3004S (302 NSF), Room A33900 (139 NSF), Room A1004S (1014 NSF), Room A2001N (327 NSF), Room A3002E (803 NSF), Room A33200 (127 NSF), Room A40300 (414 NSF), Room A10001 (295 NSF), Room A12500 (208 NSF), Room A22201 (36 NSF), Room A32204 (335 NSF), Room A37000 (36 NSF), Room A10091 (100 NSF), Room A2001S (249 NSF), Room A3002N (256 NSF), Room A33300 (188 NSF), Room A40400 (89 NSF), Room A1003S (1294 NSF), Room A2001E (1432 NSF), Room A3002C (343 NSF), Room A33100 (146 NSF), Room A40200 (415 NSF), Room A1001S (2789 NSF), Room A20001 (305 NSF), Room A3001E (1745 NSF), Room A32700 (147 NSF), Room A40002 (421 NSF), Room A11700 (793 NSF), Room A21400 (1431 NSF), Room A31800 (200 NSF), Room A36100 (126 NSF), Room A11200 (128 NSF), Room A20303 (71 NSF), Room A30700 (353 NSF), Room A35000 (135 NSF), Room A11600 (1370 NSF), Room A21000 (324 NSF), Room A31400 (507 NSF), Room A35700 (127 NSF), Room A11900 (253 NSF), Room A21600 (88 NSF), Room A32000 (124 NSF), Room A36300 (129 NSF), Room A11500 (409 NSF), Room A20900 (43 NSF), Room A31300 (616 NSF), Room A35600 (131 NSF), Room A11901 (70 NSF), Room A21700 (263 NSF), Room A3200A (87 NSF), Room A36400 (131 NSF), Room A11603 (47 NSF), Room A21300 (991 NSF), Room A31700 (263 NSF), Room A36000 (131 NSF), Room A10100 (418 NSF), Room A2002N (289 NSF), Room A3003C (478 NSF), Room A33600 (127 NSF), Room A10800 (86 NSF), Room A20200 (1430 NSF), Room A30400 (352 NSF), Room A34600 (135 NSF), Room A11601 (21 NSF), Room A21100 (1462 NSF), Room A31500 (1467 NSF), Room A35800 (132 NSF), Room A10502 (47 NSF), Room A20091 (103 NSF), Room A30093 (78 NSF), Room A34200 (613 NSF), Room A12100 (191 NSF), Room A21900 (200 NSF), Room A32200 (627 NSF), Room A36600 (131 NSF), Room A11800 (793 NSF), Room A21500 (1460 NSF), Room A31900 (116 NSF), Room A36200 (133 NSF), Room A10500 (1305 NSF), Room A2003S (322 NSF), Room A30091 (99 NSF), Room A34000 (129 NSF), Room A12200 (88 NSF), Room A22000 (116 NSF), Room A32201 (370 NSF), Room A36700 (43 NSF), Room A12300 (263 NSF), Room A22100 (133 NSF), Room A32202 (168 NSF), Room A36800 (152 NSF), Room A11401 (18 NSF), Room A20600 (164 NSF), Room A31000 (1495 NSF), Room A35300 (127 NSF), Room A1001E (1413 NSF), Room A12800 (29 NSF), Room A30003 (120 NSF), Room A32500 (192 NSF), Room A37300 (89 NSF), Room A11402 (28 NSF), Room A20700 (89 NSF), Room A31100 (1462 NSF), Room A35400 (135 NSF), Room A10092 (75 NSF), Room A2001W (1142 NSF), Room A3002S (502 NSF), Room A33400 (127 NSF), Room A40401 (77 NSF), Room A10300 (796 NSF), Room A2003C (410 NSF), Room A3003S (426 NSF), Room A33800 (127 NSF), Room A10000 (8402 NSF), Room A12400 (124 NSF), Room A22200 (576 NSF), Room A32203 (255 NSF), Room A36900 (170 NSF), Room A10900 (301 NSF), Room A20300 (1195 NSF), Room A30500 (1295 NSF), Room A34700 (127 NSF), Room A11400 (1383 NSF), Room A20500 (1452 NSF), Room A30900 (1048 NSF), Room A35200 (134 NSF), Room A11100 (182 NSF), Room A20302 (255 NSF), Room A30600 (378 NSF), Room A34900 (127 NSF), Room A10003 (271 NSF), Room A12700 (150 NSF), Room A30002 (421 NSF), Room A32400 (128 NSF), Room A37200 (26 NSF), Room A11300 (141 NSF), Room A20400 (1432 NSF), Room A30800 (1068 NSF), Room A35100 (127 NSF), Room A11000 (84 NSF), Room A20301 (163 NSF), Room A30501 (289 NSF), Room A34800 (139 NSF), Room A10700 (139 NSF), Room A20093 (77 NSF), Room A30200 (1068 NSF), Room A34400 (451 NSF), Room A10701 (64 NSF), Room A20100 (1461 NSF), Room A30300 (382 NSF), Room A34500 (130 NSF), Room A10501 (315 NSF), Room A2004S (401 NSF), Room A30092 (76 NSF), Room A34100 (106 NSF), Room A11403 (46 NSF), Room A20800 (170 NSF), Room A31200 (508 NSF), Room A35500 (127 NSF), Room A11602 (27 NSF), Room A21200 (1429 NSF), Room A31600 (1505 NSF), Room A35900 (127 NSF), Room A10200 (793 NSF), Room A2002S (737 NSF), Room A3003N (314 NSF), Room A33700 (119 NSF), Room A10093 (75 NSF), Room A2002C (413 NSF), Room A3002W (681 NSF), Room A33500 (147 NSF), Room A1003N (307 NSF), Room A2001C (413 NSF), Room A3001W (1027 NSF), Room A33000 (127 NSF), Room A40100 (89 NSF), Room A1002S (602 NSF), Room A20003 (290 NSF), Room A3001S (355 NSF), Room A32900 (187 NSF), Room A40091 (102 NSF), Room A12000 (113 NSF), Room A21800 (124 NSF), Room A32100 (133 NSF), Room A36500 (164 NSF), Room A10600 (149 NSF), Room A20092 (77 NSF), Room A30100 (1059 NSF), Room A34300 (103 NSF) Renovation Description:	2,148,533

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.051	Renovating Building Number - 37, Building Name - CHILLER ANEX SCIENCE (0 SS), (1501 NSF) Apply Painting, Electrical, Plumbing, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 003702 (1404 NSF), Room 003701 (97 NSF) Renovation Description:	176,562
1.052	Renovating Building Number - 1401, Building Name - GREEN HOUSE 1 (0 SS), (1419 NSF) Apply Other to Room 1401A (1419 NSF) Renovation Description:	188,727
1.053	Renovating Building Number - 1402, Building Name - GREEN HOUSE 2 (0 SS), (1419 NSF) Apply Other to Room 140200 (1419 NSF) Renovation Description:	45,921
1.054	Renovating Building Number - 1403, Building Name - GREEN HOUSE 3 (0 SS), (537 NSF) Apply Other to Room 1403A (537 NSF) Renovation Description:	45,921
1.055	Renovating Building Number - 1702, Building Name - CHICKEE HUT (0 SS), (1283 NSF) Apply Other to Room 170200 (1283 NSF) Renovation Description:	42,700
NORTH CAMPUS		Total : 180,815,814

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 2
Site Name: KENDALL CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
2.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	11,368,671
2.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	35,842,411
2.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	4,727,818
2.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	10,000,000
2.005	Renovate all athletic facilities to include but not limited to fields, courts, pools, spectator areas and seating, lighting, flooring, fencing and ancillary facilities.	1,000,000
KENDALL CAMPUS		Total : 62,938,900

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.006	New Construction: Adding Classrooms (841 SS), (23575 NSF), (33486 GSF); Non-Vocational Labs (1255 SS), (33300 NSF), (47298 GSF); Classroom (23575 NSF), Art (13600 NSF), Photography (6000 NSF), Foreign Languages (2700 NSF), Communications Media (11000 NSF)	32,233,215

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.007	New Construction: Adding Physical Education (14157 NSF), Custodial (6565 NSF)	11,743,767
2.008	New Construction: Adding Student Services (49201 NSF)	27,884,115
2.009	New Construction: Adding Auditorium / Exhibition (15107 NSF)	8,561,343
2.010	New Construction: Adding Audiovisual (5245 NSF)	2,972,151
2.011	New Construction: Adding Library / Study (85986 NSF)	48,731,466
2.012	Remodeling Building Number - 12, Building Name - ARTS ANNEX : Adding Non-Vocational Labs (30 SS), (1660 NSF), (2358 GSF); Art (1660 NSF, 30 SSC) and Removing (0 SS), (3470 NSF) Room N10802 (751 NSF), Room N20000 (950 NSF), Room N10100 (1769 NSF)	692,265
2.013	Renovating Building Number - 1, Building Name - PETER MASIKO JR BLDG (0 SS), (29855 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100105 (2098 NSF), Room 113100 (215 NSF), Room 100104 (2300 NSF), Room 113000 (212 NSF), Room 100102 (2089 NSF), Room 112700 (597 NSF), Room 100091 (46 NSF), Room 112500 (500 NSF), Room 100601 (34 NSF), Room 113600 (170 NSF), Room 100900 (1130 NSF), Room 113800 (571 NSF), Room 101001 (113 NSF), Room 113802 (16 NSF), Room 100600 (97 NSF), Room 113500 (398 NSF), Room 100011 (173 NSF), Room 112300 (107 NSF), Room 100500 (53 NSF), Room 113400 (418 NSF), Room 110009 (118 NSF), Room 114000 (196 NSF), Room 110102 (141 NSF), Room 101002 (115 NSF), Room 113803 (16 NSF), Room 110010 (118 NSF), Room 114100 (169 NSF), Room 110800 (127 NSF), Room 110901 (21 NSF), Room 110600 (47 NSF), Room 100004 (99 NSF), Room 111400 (330 NSF), Room 100007 (48 NSF), Room 111900 (212 NSF), Room 110011 (302 NSF), Room 114200 (169 NSF), Room 100008 (45 NSF), Room 112000 (541 NSF), Room 101000 (902 NSF), Room 113801 (16 NSF), Room 110900 (148 NSF), Room 100001 (99 NSF), Room 111100 (117 NSF), Room 110500 (157 NSF), Room 01000R (1 NSF), Room 111000 (721 NSF), Room 100602 (431 NSF), Room 113700 (196 NSF), Room 110700 (997 NSF), Room 110801 (21 NSF), Room 100200 (833 NSF), Room 113200 (215 NSF), Room 110200 (396 NSF), Room 100003 (99 NSF), Room 111300 (189 NSF), Room 110201 (144 NSF), Room 100009 (186 NSF), Room 112200 (69 NSF), Room 100103 (777 NSF), Room 112900 (131 NSF), Room 100005 (88 NSF), Room 111500 (152 NSF), Room 100010 (186 NSF), Room 112201 (9 NSF), Room 100300 (61 NSF), Room 113300 (212 NSF), Room 100002 (99 NSF), Room 111200 (151 NSF), Room 110400 (125 NSF), Room 100101 (2301 NSF), Room 112600 (207 NSF), Room 110000 (3441 NSF), Room 113900 (197 NSF), Room 110100 (420 NSF), Room 114500 (44 NSF), Room 110202 (128 NSF), Room 110091 (44 NSF), Room 114400 (44 NSF), Room 110300 (344 NSF), Room 110101 (144 NSF), Room 114600 (44 NSF), Room 100006 (88 NSF), Room 111800 (330 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$1,422,596 in deficiencies (Year 1) and \$1,587,373 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$1,422,596 in deficiencies (Year 1) and \$1,587,373 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	3,009,969
2.014	Renovating Building Number - 2, Building Name - NILES TRAMMELL CT (756 SS), (144325 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 211902 (301 NSF), Room 215600 (178 NSF), Room 220407 (112 NSF), Room 222003 (112 NSF), Room 227003 (28 NSF), Room 211900 (1070 NSF), Room 215401 (23 NSF), Room 220405 (113 NSF), Room 222001 (112 NSF), Room 227001 (27 NSF), Room 210000 (39139 NSF), Room 212106 (181 NSF), Room 220003 (76 NSF), Room 220701 (118 NSF), Room 223200 (136 NSF), Room 2M0201 (106 NSF), Room 211905 (60 NSF), Room 216000 (153 NSF), Room 220600 (524 NSF), Room 222006 (112 NSF), Room 2M0001 (19 NSF), Room 210010 (30 NSF), Room 212700 (110 NSF), Room 22002S (405 NSF), Room 220903 (116 NSF), Room 224200 (899 NSF), Room 210011 (105 NSF), Room 212800 (574 NSF), Room 22002W (1065 NSF), Room 220904 (203 NSF), Room 224300 (298 NSF), Room 210009 (89 NSF), Room 212600 (134 NSF), Room 22002N (556 NSF), Room 220902 (124 NSF), Room 223600 (1163 NSF), Room 210700 (262 NSF), Room 213600 (700 NSF), Room 220102 (55 NSF), Room 221300 (302 NSF), Room 224700 (65 NSF), Room 212104 (96 NSF), Room 220001 (228 NSF), Room 220606 (322 NSF), Room 223001 (12283 NSF), Room 2M0100 (444 NSF), Room 210900 (208 NSF), Room 213800 (71 NSF), Room 220201 (112 NSF), Room 221500 (103 NSF), Room 224900 (59 NSF), Room 210008 (83 NSF), Room 212500 (185 NSF), Room 22001W (640 NSF), Room 220901 (148 NSF), Room 223505 (158 NSF), Room 210600 (211 NSF), Room 213500 (1439 NSF), Room 220101 (55 NSF), Room 221200 (129 NSF), Room 224602 (95 NSF), Room 211700 (9048 NSF), Room 214300 (574 NSF), Room 220208 (112 NSF), Room 221804 (112 NSF), Room 226100 (164 NSF), Room	18,864,316

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

211200 (210 NSF), Room 214101 (353 NSF), Room 220204 (112 NSF), Room 221800 (254 NSF), Room 225200 (607 NSF), Room 211300 (198 NSF), Room 214102 (574 NSF), Room 220205 (112 NSF), Room 221801 (112 NSF), Room 225300 (590 NSF), Room 210013 (12 NSF), Room 212900 (574 NSF), Room 22003N (1754 NSF), Room 221000 (510 NSF), Room 224400 (152 NSF), Room 211100 (1957 NSF), Room 214100 (1353 NSF), Room 220203 (112 NSF), Room 221700 (578 NSF), Room 225100 (19 NSF), Room 211701 (1093 NSF), Room 214400 (574 NSF), Room 220300 (169 NSF), Room 221805 (112 NSF), Room 226400 (219 NSF), Room 210800 (1957 NSF), Room 213700 (102 NSF), Room 220200 (254 NSF), Room 221400 (80 NSF), Room 224800 (64 NSF), Room 210500 (1957 NSF), Room 213400 (590 NSF), Room 220100 (485 NSF), Room 221103 (203 NSF), Room 224601 (111 NSF), Room 211400 (1957 NSF), Room 214103 (180 NSF), Room 220206 (112 NSF), Room 221802 (112 NSF), Room 225900 (295 NSF), Room 212000 (590 NSF), Room 216001 (40 NSF), Room 220601 (236 NSF), Room 222007 (112 NSF), Room 2M0002 (15 NSF), Room 210007 (204 NSF), Room 212113 (544 NSF), Room 22001S (192 NSF), Room 220900 (350 NSF), Room 223504 (173 NSF), Room 211800 (698 NSF), Room 214500 (574 NSF), Room 220400 (255 NSF), Room 221806 (112 NSF), Room 226401 (24 NSF), Room 210003 (78 NSF), Room 212109 (127 NSF), Room 220006 (204 NSF), Room 220704 (121 NSF), Room 223500 (331 NSF), Room 2M0500 (208 NSF), Room 211805 (143 NSF), Room 215400 (198 NSF), Room 220404 (113 NSF), Room 222000 (254 NSF), Room 227000 (203 NSF), Room 210092 (28 NSF), Room 213100 (574 NSF), Room 22003W (1258 NSF), Room 221100 (365 NSF), Room 224501 (103 NSF), Room 212103 (95 NSF), Room 216201 (24 NSF), Room 220605 (320 NSF), Room 223000 (9962 NSF), Room 2M0010 (53 NSF), Room 211000 (209 NSF), Room 214000 (419 NSF), Room 220202 (112 NSF), Room 221600 (58 NSF), Room 225000 (56 NSF), Room 211903 (128 NSF), Room 215601 (23 NSF), Room 220408 (112 NSF), Room 222004 (112 NSF), Room 227200 (174 NSF), Room 211801 (282 NSF), Room 214600 (574 NSF), Room 220401 (112 NSF), Room 221807 (112 NSF), Room 226403 (30 NSF), Room 210004 (77 NSF), Room 212110 (126 NSF), Room 220007 (204 NSF), Room 220707 (302 NSF), Room 223501 (158 NSF), Room 212100 (277 NSF), Room 216002 (49 NSF), Room 220602 (418 NSF), Room 222008 (112 NSF), Room 2M0003 (14 NSF), Room 211803 (142 NSF), Room 214700 (574 NSF), Room 220402 (112 NSF), Room 221808 (112 NSF), Room 226500 (177 NSF), Room 211904 (107 NSF), Room 215602 (60 NSF), Room 220500 (167 NSF), Room 222005 (112 NSF), Room 227201 (36 NSF), Room 210091 (54 NSF), Room 213000 (574 NSF), Room 22003S (1759 NSF), Room 221001 (264 NSF), Room 224500 (1598 NSF), Room 212102 (96 NSF), Room 216200 (238 NSF), Room 220604 (161 NSF), Room 222900 (153 NSF), Room 2M0009 (89 NSF), Room 211804 (142 NSF), Room 214800 (574 NSF), Room 220403 (112 NSF), Room 221900 (169 NSF), Room 226501 (24 NSF), Room 212101 (174 NSF), Room 216003 (40 NSF), Room 220603 (192 NSF), Room 222100 (169 NSF), Room 2M0008 (89 NSF), Room 210100 (211 NSF), Room 213200 (1149 NSF), Room 220091 (54 NSF), Room 221101 (181 NSF), Room 224502 (32 NSF), Room 02000R (1 NSF), Room 212105 (96 NSF), Room 220002 (76 NSF), Room 220700 (1505 NSF), Room 223100 (185 NSF), Room 2M0200 (198 NSF), Room 210006 (204 NSF), Room 212112 (752 NSF), Room 22001N (192 NSF), Room 220800 (831 NSF), Room 223503 (156 NSF), Room 210002 (77 NSF), Room 212108 (126 NSF), Room 220005 (76 NSF), Room 220703 (142 NSF), Room 223400 (574 NSF), Room 2M0400 (208 NSF), Room 210005 (77 NSF), Room 212111 (127 NSF), Room 22000E (2171 NSF), Room 220708 (521 NSF), Room 223502 (172 NSF), Room 210001 (241 NSF), Room 212107 (127 NSF), Room 220004 (76 NSF), Room 220702 (114 NSF), Room 223300 (110 NSF), Room 2M0300 (236 NSF), Room 211901 (342 NSF), Room 215402 (68 NSF), Room 220406 (112 NSF), Room 222002 (112 NSF), Room 227002 (31 NSF), Room 210400 (215 NSF), Room 213300 (1148 NSF), Room 220092 (28 NSF), Room 221102 (138 NSF), Room 224600 (319 NSF), Room 211500 (942 NSF), Room 214104 (182 NSF), Room 220207 (112 NSF), Room 221803 (112 NSF), Room 226000 (262 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$3,821,033 in deficiencies (Year 1) and \$1,587,373 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

Facilities condition assessment performed February 2020 identified \$3,821,033 in deficiencies (Year 1) and \$1,587,373 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

2.015	Renovating Building Number - 3, Building Name - LEONARD A USINA HALL (1100 SS), (133019 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 310100 (1390 NSF), Room 318500 (952 NSF), Room 320201 (163 NSF), Room 324505 (87 NSF), Room 326517 (144 NSF), Room 330004 (111 NSF), Room 332800 (786 NSF), Room 31003W (642 NSF), Room 318200 (135 NSF), Room 320092 (82 NSF), Room 324502 (88 NSF), Room 326514 (77 NSF), Room 330001 (111 NSF), Room 332500 (810 NSF), Room 310200 (163 NSF), Room 318700 (528 NSF), Room 320203 (196 NSF), Room 324507 (88 NSF), Room 326519 (86 NSF), Room 330006 (246 NSF), Room 332901 (22 NSF), Room 310201 (114 NSF), Room 318800 (154 NSF), Room 320204 (121 NSF), Room 324508 (88 NSF), Room 326600 (171 NSF), Room 330007 (260 NSF), Room 332902 (44 NSF), Room 310092 (82 NSF), Room 318400 (17 NSF), Room 320200 (1829 NSF), Room 320204 (88 NSF), Room 326516 (91 NSF), Room 330003 (110 NSF), Room 332700 (812 NSF), Room 310002 (81 NSF), Room 312605 (50 NSF), Room 320013 (51 NSF), Room 321217 (146 NSF), Room 325700 (940 NSF), Room 329107 (88 NSF), Room 330900 (812 NSF), Room 334900 (103 NSF), Room 312601 (148 NSF), Room 320008 (282 NSF), Room 321213 (77 NSF), Room 325300 (209 NSF), Room 329103 (88 NSF), Room 330402 (45 NSF),	28,886,306
-------	---	------------

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Room 334402 (120 NSF), Room 310101 (68 NSF), Room 318600 (248 NSF), Room 320202 (218 NSF), Room 324506 (87 NSF), Room 326518 (143 NSF), Room 330005 (260 NSF), Room 332900 (232 NSF), Room 310800 (95 NSF), Room 319101 (1223 NSF), Room 321201 (116 NSF), Room 324515 (87 NSF), Room 327500 (147 NSF), Room 33002N (283 NSF), Room 333601 (52 NSF), Room 31002W (260 NSF), Room 317600 (226 NSF), Room 32003N (562 NSF), Room 322203 (595 NSF), Room 326510 (117 NSF), Room 329400 (168 NSF), Room 332200 (244 NSF), Room 310008 (282 NSF), Room 315400 (92 NSF), Room 32001N (712 NSF), Room 321800 (1101 NSF), Room 326501 (116 NSF), Room 329113 (77 NSF), Room 331400 (247 NSF), Room 30000R (1 NSF), Room 312603 (654 NSF), Room 320011 (95 NSF), Room 321215 (81 NSF), Room 325500 (940 NSF), Room 329105 (87 NSF), Room 330700 (811 NSF), Room 334700 (296 NSF), Room 310009 (109 NSF), Room 315900 (167 NSF), Room 32001S (704 NSF), Room 321900 (180 NSF), Room 326502 (88 NSF), Room 329114 (77 NSF), Room 331500 (105 NSF), Room 31001N (2898 NSF), Room 316100 (933 NSF), Room 320020 (78 NSF), Room 322001 (90 NSF), Room 326504 (88 NSF), Room 329116 (90 NSF), Room 331701 (133 NSF), Room 31002N (262 NSF), Room 316500 (1008 NSF), Room 32002W (394 NSF), Room 322201 (148 NSF), Room 326508 (88 NSF), Room 329200 (171 NSF), Room 332000 (811 NSF), Room 31001E (1893 NSF), Room 316000 (15 NSF), Room 32001W (705 NSF), Room 322000 (1294 NSF), Room 326503 (88 NSF), Room 329115 (87 NSF), Room 331700 (447 NSF), Room 310003 (83 NSF), Room 312700 (47 NSF), Room 320014 (50 NSF), Room 321218 (147 NSF), Room 325800 (209 NSF), Room 329108 (88 NSF), Room 331000 (809 NSF), Room 312000 (217 NSF), Room 319200 (164 NSF), Room 321205 (87 NSF), Room 324519 (86 NSF), Room 328100 (938 NSF), Room 33003N (201 NSF), Room 333900 (232 NSF), Room 310005 (282 NSF), Room 315200 (1100 NSF), Room 320016 (51 NSF), Room 321300 (171 NSF), Room 326000 (639 NSF), Room 329110 (117 NSF), Room 331101 (21 NSF), Room 310500 (133 NSF), Room 319002 (1189 NSF), Room 320600 (501 NSF), Room 324512 (87 NSF), Room 326901 (18 NSF), Room 33001S (1338 NSF), Room 333400 (732 NSF), Room 312602 (587 NSF), Room 320010 (45 NSF), Room 321214 (72 NSF), Room 325400 (164 NSF), Room 329104 (88 NSF), Room 330600 (1230 NSF), Room 334600 (384 NSF), Room 310006 (282 NSF), Room 315300 (1387 NSF), Room 320017 (51 NSF), Room 321400 (335 NSF), Room 326100 (1018 NSF), Room 329111 (90 NSF), Room 331102 (45 NSF), Room 31001W (1893 NSF), Room 316300 (753 NSF), Room 32002N (397 NSF), Room 322100 (17 NSF), Room 326506 (87 NSF), Room 329118 (148 NSF), Room 331800 (881 NSF), Room 312400 (97 NSF), Room 320005 (282 NSF), Room 321210 (118 NSF), Room 325100 (1018 NSF), Room 329100 (333 NSF), Room 330200 (810 NSF), Room 334302 (195 NSF), Room 310004 (81 NSF), Room 315100 (523 NSF), Room 320015 (50 NSF), Room 321219 (85 NSF), Room 325900 (157 NSF), Room 329109 (88 NSF), Room 331100 (233 NSF), Room 310202 (23 NSF), Room 318900 (1098 NSF), Room 320300 (18 NSF), Room 324509 (88 NSF), Room 326700 (168 NSF), Room 330008 (246 NSF), Room 333000 (113 NSF), Room 31003E (485 NSF), Room 317800 (804 NSF), Room 32003S (637 NSF), Room 322300 (151 NSF), Room 326511 (89 NSF), Room 329500 (126 NSF), Room 332201 (53 NSF), Room 31001S (1899 NSF), Room 316200 (205 NSF), Room 32002E (413 NSF), Room 322004 (70 NSF), Room 326505 (87 NSF), Room 329117 (143 NSF), Room 331702 (160 NSF), Room 310007 (282 NSF), Room 315301 (315 NSF), Room 32001E (705 NSF), Room 321600 (144 NSF), Room 326500 (332 NSF), Room 329112 (87 NSF), Room 331200 (113 NSF), Room 31002S (271 NSF), Room 316700 (523 NSF), Room 32003E (546 NSF), Room 322202 (576 NSF), Room 326509 (88 NSF), Room 329300 (168 NSF), Room 332100 (813 NSF), Room 312301 (1003 NSF), Room 320004 (105 NSF), Room 321209 (88 NSF), Room 324900 (145 NSF), Room 328500 (1043 NSF), Room 330100 (1281 NSF), Room 334301 (184 NSF), Room 312300 (1347 NSF), Room 320003 (106 NSF), Room 321208 (88 NSF), Room 324800 (168 NSF), Room 328400 (160 NSF), Room 330091 (76 NSF), Room 334300 (245 NSF), Room 312500 (17 NSF), Room 320006 (282 NSF), Room 321211 (91 NSF), Room 325200 (393 NSF), Room 329101 (116 NSF), Room 330300 (813 NSF), Room 334400 (203 NSF), Room 310901 (70 NSF), Room 319103 (1209 NSF), Room 321203 (88 NSF), Room 324517 (146 NSF), Room 327900 (957 NSF), Room 33002W (411 NSF), Room 333800 (736 NSF), Room 310600 (17 NSF), Room 319003 (1190 NSF), Room 320700 (1072 NSF), Room 324513 (77 NSF), Room 327100 (167 NSF), Room 33001W (1625 NSF), Room 333500 (294 NSF), Room 312600 (1454 NSF), Room 320007 (281 NSF), Room 321212 (87 NSF), Room 325201 (219 NSF), Room 329102 (88 NSF), Room 330400 (242 NSF), Room 334401 (168 NSF), Room 312100 (113 NSF), Room 320001 (106 NSF), Room 321206 (87 NSF), Room 324600 (171 NSF), Room 328200 (588 NSF), Room 33003S (200 NSF), Room 334000 (295 NSF), Room 310001 (80 NSF), Room 312604 (64 NSF), Room 320012 (52 NSF), Room 321216 (85 NSF), Room 325600 (15 NSF), Room 329106 (87 NSF), Room 330800 (1281 NSF), Room 334800 (728 NSF), Room 310700 (1265 NSF), Room 319004 (1157 NSF), Room 321200 (350 NSF), Room 324514 (77 NSF), Room 327300 (752 NSF), Room 33002E (421 NSF), Room 333600 (203 NSF), Room 312200 (166 NSF), Room 320002 (106 NSF), Room 321207 (88 NSF), Room 324700 (168 NSF), Room 328300 (189 NSF), Room 33003W (336 NSF), Room 334200 (294 NSF), Room 31003N (616 NSF), Room 317900 (575 NSF), Room 32003W (641 NSF), Room 324500 (331 NSF), Room 326512 (87 NSF), Room 329501 (17 NSF), Room 332202 (44 NSF), Room 310400 (746 NSF), Room 319001 (1195 NSF), Room 320500 (168 NSF), Room 324511 (89 NSF), Room 326900 (127 NSF), Room 33001N (1249 NSF), Room 333300 (812 NSF), Room 310300 (261 NSF), Room 319000 (610 NSF), Room 320400 (1234 NSF), Room 324510 (117 NSF), Room 326800 (168 NSF), Room 33001E (1718 NSF), Room 333200 (1230 NSF), Room 31003S (537 NSF), Room 318000 (78 NSF), Room 320091 (48 NSF), Room 324501 (116 NSF), Room 326513 (77 NSF), Room 330000 (3841

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NSF), Room 332400 (1231 NSF), Room 310900 (1464 NSF), Room 319102 (1165 NSF), Room 321202 (88 NSF), Room 324516 (91 NSF), Room 327600 (563 NSF), Room 33002S (283 NSF), Room 333602 (164 NSF), Room 310091 (84 NSF), Room 318300 (1016 NSF), Room 320100 (544 NSF), Room 324503 (88 NSF), Room 326515 (87 NSF), Room 330002 (111 NSF), Room 332600 (1280 NSF), Room 310902 (169 NSF), Room 319104 (1165 NSF), Room 321204 (88 NSF), Room 324518 (144 NSF), Room 328000 (17 NSF), Room 33003E (336 NSF), Room 333801 (128 NSF), Room 31002E (284 NSF), Room 316400 (61 NSF), Room 32002S (385 NSF), Room 322200 (1619 NSF), Room 326507 (88 NSF), Room 329119 (85 NSF), Room 331900 (1281 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$4,199,737 in deficiencies (Year 1) and \$24,686,569 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

Facilities condition assessment performed February 2020 identified \$4,199,737 in deficiencies (Year 1) and \$24,686,569 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

2.016 Renovating Building Number - 4, Building Name - DANIEL K GILL BLDG (743 SS), (42322 NSF) 4,892,537

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 410200 (853 NSF), Room 430200 (853 NSF), Room 410500 (843 NSF), Room 430500 (843 NSF), Room 411100 (38 NSF), Room 431100 (38 NSF), Room 411000 (121 NSF), Room 431000 (121 NSF), Room 410700 (852 NSF), Room 430700 (852 NSF), Room 410600 (852 NSF), Room 430600 (852 NSF), Room 411400 (271 NSF), Room 431400 (271 NSF), Room 420092 (42 NSF), Room 421100 (38 NSF), Room 420500 (843 NSF), Room 420800 (843 NSF), Room 410300 (853 NSF), Room 430300 (853 NSF), Room 420900 (271 NSF), Room 421000 (121 NSF), Room 41000N (293 NSF), Room 43000N (323 NSF), Room 410002 (344 NSF), Room 430002 (160 NSF), Room 410092 (42 NSF), Room 430092 (42 NSF), Room 42000E (1762 NSF), Room 420091 (42 NSF), Room 410091 (42 NSF), Room 430091 (42 NSF), Room 420300 (853 NSF), Room 410100 (844 NSF), Room 430100 (844 NSF), Room 41000E (1686 NSF), Room 43000E (1967 NSF), Room 420400 (844 NSF), Room 420200 (853 NSF), Room 421400 (271 NSF), Room 410001 (182 NSF), Room 430001 (160 NSF), Room 420600 (852 NSF), Room 420700 (852 NSF), Room 421300 (121 NSF), Room 42000N (320 NSF), Room 421200 (79 NSF), Room 41000C (1272 NSF), Room 43000C (883 NSF), Room 41000S (372 NSF), Room 43000S (324 NSF), Room 411500 (165 NSF), Room 431500 (59 NSF), Room 420002 (344 NSF), Room 440100 (1104 NSF), Room 42000C (909 NSF), Room 420100 (844 NSF), Room 411300 (121 NSF), Room 431300 (121 NSF), Room 42000W (1762 NSF), Room 411200 (191 NSF), Room 431200 (79 NSF), Room 421500 (59 NSF), Room 420001 (344 NSF), Room 440002 (182 NSF), Room 42000S (320 NSF), Room 410400 (844 NSF), Room 430400 (844 NSF), Room 410800 (843 NSF), Room 430800 (843 NSF), Room 410900 (271 NSF), Room 430900 (271 NSF), Room 41000W (1632 NSF), Room 43000W (1975 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$168,101 in deficiencies (Year 1) and \$4,724,436 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

Facilities condition assessment performed February 2020 identified \$168,101 in deficiencies (Year 1) and \$4,724,436 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.017	Renovating Building Number - 5, Building Name - PUBLIC SAFETY AND CO (514 SS), (47270 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 511702 (97 NSF), Room 520500 (758 NSF), Room 511800 (174 NSF), Room 520600 (260 NSF), Room 511700 (744 NSF), Room 520300 (758 NSF), Room 511500 (507 NSF), Room 520100 (1165 NSF), Room 511900 (170 NSF), Room 520601 (33 NSF), Room 510003 (227 NSF), Room 512702 (116 NSF), Room 521305 (109 NSF), Room 511501 (146 NSF), Room 520200 (758 NSF), Room 51002S (144 NSF), Room 513001 (140 NSF), Room 521314 (224 NSF), Room 51003S (216 NSF), Room 513003 (134 NSF), Room 521400 (712 NSF), Room 510091 (35 NSF), Room 513005 (137 NSF), Room 521600 (712 NSF), Room 512400 (345 NSF), Room 521300 (1096 NSF), Room 510001 (248 NSF), Room 512700 (1014 NSF), Room 521303 (83 NSF), Room 512000 (279 NSF), Room 520700 (84 NSF), Room 512500 (417 NSF), Room 521301 (210 NSF), Room 510900 (251 NSF), Room 52002E (78 NSF), Room 523200 (1159 NSF), Room 512200 (261 NSF), Room 521100 (699 NSF), Room 511000 (250 NSF), Room 52002N (457 NSF), Room 523300 (135 NSF), Room 510700 (70 NSF), Room 52001E (613 NSF), Room 522900 (42 NSF), Room 510500 (676 NSF), Room 520002 (95 NSF), Room 522500 (242 NSF), Room 510301 (111 NSF), Room 513200 (276 NSF), Room 522300 (262 NSF), Room 511200 (602 NSF), Room 52003N (477 NSF), Room 523500 (1159 NSF), Room 510800 (146 NSF), Room 52001N (625 NSF), Room 523000 (696 NSF), Room 510400 (356 NSF), Room 520001 (139 NSF), Room 522400 (87 NSF), Room 510101 (169 NSF), Room 521307 (132 NSF), Room 521800 (626 NSF), Room 51002C (177 NSF), Room 512900 (166 NSF), Room 521312 (96 NSF), Room 512100 (174 NSF), Room 521000 (17 NSF), Room 510200 (891 NSF), Room 513009 (133 NSF), Room 522000 (101 NSF), Room 511100 (601 NSF), Room 52002S (433 NSF), Room 523400 (199 NSF), Room 510801 (95 NSF), Room 52001S (655 NSF), Room 523100 (1502 NSF), Room 51004E (138 NSF), Room 513004 (134 NSF), Room 521500 (712 NSF), Room 511701 (100 NSF), Room 520400 (758 NSF), Room 510601 (30 NSF), Room 520004 (95 NSF), Room 522600 (84 NSF), Room 51001C (815 NSF), Room 512705 (154 NSF), Room 521310 (324 NSF), Room 510002 (247 NSF), Room 512701 (212 NSF), Room 521304 (84 NSF), Room 51000N (1321 NSF), Room 512704 (192 NSF), Room 521309 (90 NSF), Room 510004 (247 NSF), Room 512703 (116 NSF), Room 521306 (109 NSF), Room 51001E (2056 NSF), Room 512800 (327 NSF), Room 521311 (74 NSF), Room 510100 (192 NSF), Room 513006 (90 NSF), Room 521700 (712 NSF), Room 512300 (260 NSF), Room 521200 (1128 NSF), Room 50000R (1 NSF), Room 512600 (1009 NSF), Room 521302 (83 NSF), Room 51003E (293 NSF), Room 513002 (162 NSF), Room 521315 (113 NSF), Room 51002E (357 NSF), Room 513000 (994 NSF), Room 521313 (95 NSF), Room 510102 (160 NSF), Room 513008 (201 NSF), Room 521900 (208 NSF), Room 510201 (86 NSF), Room 513010 (118 NSF), Room 522100 (138 NSF), Room 510600 (871 NSF), Room 520003 (139 NSF), Room 522501 (33 NSF), Room 510300 (110 NSF), Room 513100 (340 NSF), Room 522200 (107 NSF), Room 511400 (732 NSF), Room 520091 (35 NSF), Room 511300 (92 NSF), Room 52003S (481 NSF), Room 523600 (1128 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$202,037 in deficiencies (Year 1) and \$5,362,596 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$202,037 in deficiencies (Year 1) and \$5,362,596 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	5,564,633
2.018	Renovating Building Number - 6, Building Name - MC CARTHY HALL (911 SS), (143525 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 600021 (65 NSF), Room 610300 (775 NSF), Room 615800 (127 NSF), Room 620608 (86 NSF), Room 621916 (78 NSF), Room 625400 (370 NSF), Room 630608 (86 NSF), Room 631908 (74 NSF), Room 632412 (146 NSF), Room 600093 (60 NSF), Room 610501 (22 NSF), Room 616100 (66 NSF), Room 620612 (73 NSF), Room 621920 (83 NSF), Room 625700 (562 NSF), Room 630611 (113 NSF), Room 631911 (83 NSF), Room 632600 (231 NSF), Room 600101 (36 NSF), Room 610601 (22 NSF), Room 616300 (99 NSF), Room 620614 (65 NSF), Room 621922 (85 NSF), Room 630001 (410 NSF), Room 630617 (81 NSF), Room 631913 (83 NSF), Room 632800 (92 NSF), Room 600019 (90 NSF), Room 610100 (608 NSF), Room 615600 (103 NSF), Room 620606 (83 NSF), Room 621914 (65 NSF), Room 625200 (538 NSF), Room 630606 (83 NSF), Room 631906 (83 NSF), Room 632410 (139 NSF), Room 600901 (105 NSF), Room 611202 (111 NSF), Room 620002 (410 NSF), Room 620621 (85 NSF), Room 621929 (92 NSF), Room 630008 (238 NSF), Room 630623 (80 NSF), Room 631923 (59 NSF), Room 633100 (792 NSF), Room 600200 (1686 NSF), Room 610700 (501 NSF), Room 616400 (101 NSF), Room 620615 (79 NSF), Room 621923 (83 NSF), Room 630002 (410 NSF), Room 630618 (82 NSF), Room 631914 (85 NSF), Room 632900 (126 NSF), Room 610006 (222 NSF), Room 612002 (94 NSF), Room 62001S (326 NSF), Room 620700 (273 NSF), Room 622001 (136 NSF), Room 63002W (328 NSF), Room 630631 (83 NSF), Room 631931 (60 NSF), Room 633900 (233 NSF), Room 600012 (99 NSF), Room	20,437,855

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

61003N (484 NSF), Room 615100 (103 NSF), Room 620600 (176 NSF), Room 621908 (85 NSF), Room 625000 (240 NSF), Room 630601 (82 NSF), Room 631901 (80 NSF), Room 632405 (65 NSF), Room 61001N (768 NSF), Room 612009 (317 NSF), Room 62003N (698 NSF), Room 621300 (255 NSF), Room 623000 (696 NSF), Room 63004W (282 NSF), Room 630900 (84 NSF), Room 631938 (71 NSF), Room 634800 (533 NSF), Room 610005 (222 NSF), Room 612001 (755 NSF), Room 62001N (349 NSF), Room 620630 (894 NSF), Room 622000 (136 NSF), Room 63002S (817 NSF), Room 630630 (83 NSF), Room 631930 (59 NSF), Room 633801 (23 NSF), Room 61001S (769 NSF), Room 612100 (214 NSF), Room 62003S (725 NSF), Room 621301 (22 NSF), Room 623200 (1108 NSF), Room 63005E (233 NSF), Room 630901 (9 NSF), Room 631939 (38 NSF), Room 635000 (606 NSF), Room 600092 (60 NSF), Room 610500 (251 NSF), Room 616000 (127 NSF), Room 620610 (85 NSF), Room 621919 (82 NSF), Room 625600 (537 NSF), Room 630610 (85 NSF), Room 631910 (80 NSF), Room 632502 (365 NSF), Room 610021 (43 NSF), Room 612201 (45 NSF), Room 62004N (371 NSF), Room 621401 (22 NSF), Room 623600 (533 NSF), Room 630092 (67 NSF), Room 631101 (19 NSF), Room 631941 (2013 NSF), Room 635500 (2429 NSF), Room 600001 (92 NSF), Room 610026 (62 NSF), Room 612600 (1966 NSF), Room 620093 (63 NSF), Room 621900 (286 NSF), Room 624100 (569 NSF), Room 630098 (5 NSF), Room 631300 (167 NSF), Room 632100 (232 NSF), Room 636000 (1374 NSF), Room 610000 (1333 NSF), Room 611500 (1525 NSF), Room 620006 (225 NSF), Room 620624 (86 NSF), Room 621932 (13 NSF), Room 63001S (362 NSF), Room 630626 (74 NSF), Room 631926 (59 NSF), Room 633500 (571 NSF), Room 600003 (268 NSF), Room 610028 (35 NSF), Room 612800 (116 NSF), Room 620097 (5 NSF), Room 621902 (78 NSF), Room 624300 (570 NSF), Room 630200 (1230 NSF), Room 631500 (1086 NSF), Room 632200 (145 NSF), Room 636100 (165 NSF), Room 610017 (158 NSF), Room 612007 (108 NSF), Room 62002W (443 NSF), Room 621103 (19 NSF), Room 622600 (185 NSF), Room 63004N (438 NSF), Room 630636 (116 NSF), Room 631936 (40 NSF), Room 634500 (572 NSF), Room 600004 (110 NSF), Room 61002E (855 NSF), Room 613400 (723 NSF), Room 620098 (5 NSF), Room 621903 (79 NSF), Room 624400 (533 NSF), Room 630300 (134 NSF), Room 631600 (33 NSF), Room 632201 (357 NSF), Room 636200 (62 NSF), Room 60000E (2226 NSF), Room 61002S (1413 NSF), Room 615002 (356 NSF), Room 620300 (108 NSF), Room 621905 (67 NSF), Room 624600 (534 NSF), Room 630401 (9 NSF), Room 631701 (387 NSF), Room 632402 (692 NSF), Room 640100 (3245 NSF), Room 610008 (222 NSF), Room 612004 (108 NSF), Room 62002E (441 NSF), Room 621100 (206 NSF), Room 622400 (840 NSF), Room 63003N (765 NSF), Room 630633 (83 NSF), Room 631933 (59 NSF), Room 634000 (651 NSF), Room 600002 (103 NSF), Room 610027 (35 NSF), Room 612700 (116 NSF), Room 620096 (5 NSF), Room 621901 (80 NSF), Room 624200 (534 NSF), Room 630100 (1730 NSF), Room 631400 (146 NSF), Room 632101 (23 NSF), Room 636001 (337 NSF), Room 600010 (80 NSF), Room 61002W (526 NSF), Room 615003 (147 NSF), Room 620400 (775 NSF), Room 621906 (83 NSF), Room 624700 (569 NSF), Room 630500 (44 NSF), Room 631800 (231 NSF), Room 632403 (60 NSF), Room 640200 (152 NSF), Room 610023 (43 NSF), Room 612203 (73 NSF), Room 620091 (67 NSF), Room 621700 (775 NSF), Room 623800 (464 NSF), Room 630096 (5 NSF), Room 631103 (19 NSF), Room 632000 (250 NSF), Room 635800 (1107 NSF), Room 610014 (270 NSF), Room 612006 (317 NSF), Room 62002S (747 NSF), Room 621102 (13 NSF), Room 622501 (111 NSF), Room 63003W (331 NSF), Room 630635 (113 NSF), Room 631935 (59 NSF), Room 634300 (1103 NSF), Room 600011 (107 NSF), Room 61003E (588 NSF), Room 615004 (133 NSF), Room 620500 (273 NSF), Room 621907 (83 NSF), Room 624800 (533 NSF), Room 630600 (289 NSF), Room 631900 (300 NSF), Room 632404 (43 NSF), Room 610024 (43 NSF), Room 612400 (214 NSF), Room 620092 (63 NSF), Room 621800 (273 NSF), Room 624000 (696 NSF), Room 630097 (5 NSF), Room 631200 (151 NSF), Room 632001 (23 NSF), Room 635900 (1244 NSF), Room 610013 (270 NSF), Room 612005 (317 NSF), Room 62002N (721 NSF), Room 621101 (19 NSF), Room 622500 (162 NSF), Room 63003S (677 NSF), Room 630634 (85 NSF), Room 631934 (59 NSF), Room 634200 (1105 NSF), Room 600900 (182 NSF), Room 611200 (162 NSF), Room 620001 (410 NSF), Room 620620 (83 NSF), Room 621928 (65 NSF), Room 630007 (221 NSF), Room 630622 (80 NSF), Room 631918 (73 NSF), Room 633000 (651 NSF), Room 61001E (691 NSF), Room 612008 (317 NSF), Room 62003E (443 NSF), Room 621200 (840 NSF), Room 622601 (78 NSF), Room 63004S (502 NSF), Room 630640 (1526 NSF), Room 631937 (161 NSF), Room 634600 (1105 NSF), Room 601000 (279 NSF), Room 611300 (186 NSF), Room 620004 (410 NSF), Room 620622 (85 NSF), Room 621930 (824 NSF), Room 63001E (329 NSF), Room 630624 (80 NSF), Room 631924 (59 NSF), Room 633200 (1104 NSF), Room 610004 (198 NSF), Room 612000 (5355 NSF), Room 62001E (648 NSF), Room 620628 (73 NSF), Room 621935 (83 NSF), Room 63002N (686 NSF), Room 630629 (83 NSF), Room 631929 (59 NSF), Room 633800 (251 NSF), Room 600009 (27 NSF), Room 61002N (1601 NSF), Room 615001 (274 NSF), Room 620100 (608 NSF), Room 621904 (68 NSF), Room 624500 (518 NSF), Room 630400 (723 NSF), Room 631700 (1024 NSF), Room 632300 (105 NSF), Room 640097 (13 NSF), Room 610001 (201 NSF), Room 611501 (24 NSF), Room 620007 (225 NSF), Room 620626 (65 NSF), Room 621933 (19 NSF), Room 63001W (328 NSF), Room 630627 (82 NSF), Room 631927 (59 NSF), Room 633600 (533 NSF), Room 600018 (124 NSF), Room 610093 (63 NSF), Room 615500 (100 NSF), Room 620605 (81 NSF), Room 621913 (71 NSF), Room 625100 (562 NSF), Room 630605 (81 NSF), Room 631905 (81 NSF), Room 632409 (143 NSF), Room 601200 (504 NSF), Room 611301 (77 NSF), Room 620005 (225 NSF), Room 620623 (83 NSF), Room 621931 (19 NSF), Room 63001N (500 NSF), Room 630625 (80 NSF), Room 631925 (71 NSF), Room 633400 (533 NSF), Room 61001W (998 NSF), Room 612200 (384 NSF), Room 62003W (460 NSF), Room 621400 (241 NSF), Room

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

623400 (1093 NSF), Room 630091 (71 NSF), Room 631100 (126 NSF), Room 631940 (56 NSF), Room 635200 (538 NSF), Room 600300 (2702 NSF), Room 610800 (93 NSF), Room 616500 (101 NSF), Room 620616 (78 NSF), Room 621924 (86 NSF), Room 630004 (410 NSF), Room 630619 (73 NSF), Room 631915 (83 NSF), Room 632901 (19 NSF), Room 600100 (3127 NSF), Room 610600 (241 NSF), Room 616200 (102 NSF), Room 620613 (71 NSF), Room 621921 (81 NSF), Room 625800 (533 NSF), Room 630612 (116 NSF), Room 631912 (83 NSF), Room 632700 (151 NSF), Room 600400 (2095 NSF), Room 610900 (762 NSF), Room 616600 (99 NSF), Room 620617 (117 NSF), Room 621926 (73 NSF), Room 630005 (238 NSF), Room 630620 (78 NSF), Room 631916 (86 NSF), Room 632902 (13 NSF), Room 600016 (65 NSF), Room 610091 (67 NSF), Room 615300 (100 NSF), Room 620602 (78 NSF), Room 621910 (86 NSF), Room 625002 (233 NSF), Room 630603 (82 NSF), Room 631903 (73 NSF), Room 632407 (66 NSF), Room 610022 (43 NSF), Room 612202 (75 NSF), Room 62004S (395 NSF), Room 621500 (614 NSF), Room 623700 (963 NSF), Room 630093 (72 NSF), Room 631102 (13 NSF), Room 631942 (135 NSF), Room 635600 (1092 NSF), Room 610007 (222 NSF), Room 612003 (94 NSF), Room 62001W (687 NSF), Room 620900 (92 NSF), Room 622100 (232 NSF), Room 63003E (386 NSF), Room 630632 (86 NSF), Room 631932 (59 NSF), Room 633901 (23 NSF), Room 610002 (196 NSF), Room 611502 (25 NSF), Room 620008 (225 NSF), Room 620627 (71 NSF), Room 621934 (68 NSF), Room 63002E (345 NSF), Room 630628 (83 NSF), Room 631928 (73 NSF), Room 633700 (1637 NSF), Room 600800 (279 NSF), Room 611100 (840 NSF), Room 616700 (102 NSF), Room 620619 (83 NSF), Room 621927 (71 NSF), Room 630006 (237 NSF), Room 630621 (80 NSF), Room 631917 (135 NSF), Room 632903 (19 NSF), Room 600020 (124 NSF), Room 610200 (108 NSF), Room 615700 (73 NSF), Room 620607 (81 NSF), Room 621915 (79 NSF), Room 625300 (505 NSF), Room 630607 (82 NSF), Room 631907 (82 NSF), Room 632411 (139 NSF), Room 600015 (66 NSF), Room 61003S (510 NSF), Room 615200 (100 NSF), Room 620601 (80 NSF), Room 621909 (83 NSF), Room 625001 (450 NSF), Room 630602 (81 NSF), Room 631902 (78 NSF), Room 632406 (930 NSF), Room 600091 (63 NSF), Room 610400 (840 NSF), Room 615900 (271 NSF), Room 620609 (83 NSF), Room 621917 (80 NSF), Room 625500 (360 NSF), Room 630609 (83 NSF), Room 631909 (80 NSF), Room 632501 (201 NSF), Room 600017 (82 NSF), Room 610092 (63 NSF), Room 615400 (100 NSF), Room 620603 (79 NSF), Room 621912 (73 NSF), Room 625003 (47 NSF), Room 630604 (83 NSF), Room 631904 (82 NSF), Room 632408 (145 NSF) Renovation

Description: Facilities condition assessment performed February 2020 identified \$8,521,380 in deficiencies (Year 1) and \$11,916,475 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

Facilities condition assessment performed February 2020 identified \$8,521,380 in deficiencies (Year 1) and \$11,916,475 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NUMBER	DESCRIPTION	ESTIMATED COST
2.019	Renovating Building Number - 7, Building Name - THEODORE R GIBSON CT (158 SS), (129259 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room G10004 (396 NSF), Room G11500 (347 NSF), Room G13502 (47 NSF), Room G21500 (206 NSF), Room G31801 (39 NSF), Room G00102 (100 NSF), Room G11100 (804 NSF), Room G13405 (384 NSF), Room G21000 (20262 NSF), Room G31714 (184 NSF), Room G00100 (1122 NSF), Room G11003 (152 NSF), Room G13403 (332 NSF), Room G20800 (2853 NSF), Room G31712 (89 NSF), Room G10002 (304 NSF), Room G11300 (623 NSF), Room G13500 (277 NSF), Room G21300 (205 NSF), Room G31722 (12 NSF), Room G10011 (494 NSF), Room G11900 (745 NSF), Room G13703 (267 NSF), Room G22100 (438 NSF), Room G32803 (27 NSF), Room G1001E (932 NSF), Room G12800 (856 NSF), Room G13906 (62 NSF), Room G30200 (708 NSF), Room GM0800 (106 NSF), Room G10003 (355 NSF), Room G11400 (227 NSF), Room G13501 (74 NSF), Room G21301 (40 NSF), Room G31800 (401 NSF), Room G10012 (300 NSF), Room G12000 (561 NSF), Room G13704 (247 NSF), Room G22200 (449 NSF), Room G32804 (64 NSF), Room G10401 (111 NSF), Room G13101 (134 NSF), Room G20025 (165 NSF), Room G31702 (211 NSF), Room G10014 (501 NSF), Room G12200 (678 NSF), Room G13900 (3723 NSF), Room G3000S (2222 NSF), Room GM0002 (426 NSF), Room G10301 (111 NSF), Room G13003 (67 NSF), Room G10023 (90 NSF), Room G31600 (496 NSF), Room G10091 (42 NSF), Room G12906 (164 NSF), Room G2000N (6073 NSF), Room G31200 (5738 NSF), Room G10800 (191 NSF), Room G13203 (19 NSF), Room G20200 (206 NSF), Room G31706 (92 NSF), Room G1003E (476 NSF), Room G12905 (102 NSF), Room G20004 (386 NSF), Room G31100 (774 NSF), Room G10022 (30 NSF), Room G12901 (125 NSF), Room G14101 (18 NSF), Room G30601 (81 NSF), Room G10900 (99 NSF), Room G13204 (34 NSF), Room G20201 (40 NSF), Room G31707 (186 NSF), Room G1002E (631 NSF), Room G12903 (262 NSF), Room G20002 (386 NSF), Room G30800 (57 NSF), Room G10200 (225 NSF), Room G13001 (101 NSF), Room G20021 (91 NSF), Room G31400 (233 NSF), Room G1000 (2770 NSF), Room G13400 (1357 NSF), Room G20401 (40 NSF), Room G31709 (89 NSF), Room G11001 (195 NSF), Room G13401 (46 NSF), Room G20500 (14 NSF), Room G31710 (177 NSF), Room G10020 (225 NSF), Room G12802 (40 NSF), Room G14001 (13 NSF), Room G30301 (95 NSF), Room G10008 (560 NSF), Room G11702 (73 NSF), Room G13601 (42 NSF), Room G21801 (60 NSF), Room G32300 (710 NSF), Room G0000R (1 NSF), Room G11002 (96 NSF), Room G13402 (57 NSF), Room G20600 (153 NSF), Room G31711 (178 NSF), Room G1000N (3333 NSF), Room G11800 (245 NSF), Room G13701 (56 NSF), Room G21900 (472 NSF), Room G32801 (33 NSF), Room G10300 (661 NSF), Room G13002 (52 NSF), Room G20022 (91 NSF), Room G31500 (233 NSF), Room G10023 (589 NSF), Room G12902 (208 NSF), Room G20001 (386 NSF), Room G30700 (205 NSF), Room G10500 (224 NSF), Room G13200 (131 NSF), Room G20026 (167 NSF), Room G31703 (280 NSF), Room G10600 (2267 NSF), Room G13201 (84 NSF), Room G20091 (44 NSF), Room G31704 (92 NSF), Room G1002S (494 NSF), Room G12904 (248 NSF), Room G20003 (378 NSF), Room G31000 (142 NSF), Room G10001 (390 NSF), Room G11200 (525 NSF), Room G13406 (235 NSF), Room G21200 (151 NSF), Room G31721 (991 NSF), Room G10015 (505 NSF), Room G12300 (678 NSF), Room G13901 (186 NSF), Room G30027 (26 NSF), Room GM0003 (428 NSF), Room G10006 (453 NSF), Room G11700 (557 NSF), Room G13504 (32 NSF), Room G21700 (151 NSF), Room G32100 (61 NSF), Room G10017 (712 NSF), Room G12500 (561 NSF), Room G13903 (111 NSF), Room G30029 (32 NSF), Room GM0500 (138 NSF), Room G10021 (33 NSF), Room G12900 (750 NSF), Room G14100 (113 NSF), Room G30600 (492 NSF), Room G1001S (528 NSF), Room G12801 (438 NSF), Room G14000 (111 NSF), Room G30300 (3541 NSF), Room G10009 (254 NSF), Room G11703 (95 NSF), Room G13700 (2062 NSF), Room G21802 (59 NSF), Room G32800 (204 NSF), Room G10700 (196 NSF), Room G13202 (19 NSF), Room G20100 (153 NSF), Room G31705 (188 NSF), Room G10007 (494 NSF), Room G11701 (131 NSF), Room G13600 (1038 NSF), Room G21800 (1337 NSF), Room G32200 (117 NSF), Room G10005 (494 NSF), Room G11600 (291 NSF), Room G13503 (83 NSF), Room G21501 (40 NSF), Room G32000 (60 NSF), Room G10100 (1871 NSF), Room G13000 (310 NSF), Room G2000S (5996 NSF), Room G31300 (720 NSF), Room G00101 (48 NSF), Room G11004 (478 NSF), Room G13404 (399 NSF), Room G20900 (2475 NSF), Room G31713 (89 NSF), Room G10016 (300 NSF), Room G12400 (340 NSF), Room G13902 (72 NSF), Room G30028 (26 NSF), Room GM0004 (397 NSF), Room G10019 (233 NSF), Room G12700 (583 NSF), Room G13905 (204 NSF), Room G30100 (5273 NSF), Room GM0700 (107 NSF), Room G10400 (660 NSF), Room G13100 (477 NSF), Room G20024 (91 NSF), Room G31701 (191 NSF), Room G10013 (254 NSF), Room G12100 (339 NSF), Room G13800 (137 NSF), Room G3000N (2168 NSF), Room GM0001 (408 NSF), Room G10010 (494 NSF), Room G11801 (832 NSF), Room G13702 (206 NSF), Room G22000 (510 NSF), Room G32802 (25 NSF), Room G10018 (681 NSF), Room G12600 (446 NSF), Room G13904 (73 NSF), Room G30091 (40 NSF), Room GM0600 (107 NSF), Room G10901 (297 NSF), Room G13300 (367 NSF), Room G20400 (205 NSF), Room G31708 (92 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$10,228,108 in deficiencies (Year 1) and \$15,566,771 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	25,794,879

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
	Facilities condition assessment performed February 2020 identified \$10,228,108 in deficiencies (Year 1) and \$15,566,771 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	
2.020	<p>Renovating Building Number - 8, Building Name - MARIA HERNANDEZ CT (352 SS), (87230 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 810013 (107 NSF), Room 811900 (219 NSF), Room 821100 (67 NSF), Room 823900 (63 NSF), Room 81001C (1585 NSF), Room 812000 (204 NSF), Room 821200 (389 NSF), Room 824000 (136 NSF), Room 81000E (610 NSF), Room 811702 (165 NSF), Room 820802 (238 NSF), Room 823600 (137 NSF), Room 81001S (2163 NSF), Room 812200 (1890 NSF), Room 821301 (116 NSF), Room 824200 (194 NSF), Room 81002C (462 NSF), Room 812202 (117 NSF), Room 821303 (106 NSF), Room 824400 (136 NSF), Room 81002N (1383 NSF), Room 812203 (73 NSF), Room 821304 (106 NSF), Room 824500 (136 NSF), Room 810091 (56 NSF), Room 812502 (26 NSF), Room 821504 (215 NSF), Room 824900 (769 NSF), Room 810011 (40 NSF), Room 811800 (225 NSF), Room 821000 (192 NSF), Room 823800 (136 NSF), Room 810201 (26 NSF), Room 812901 (32 NSF), Room 821507 (31 NSF), Room 825200 (62 NSF), Room 810409 (113 NSF), Room 82000N (849 NSF), Room 821906 (93 NSF), Room 8M0301 (180 NSF), Room 81003N (836 NSF), Room 812401 (26 NSF), Room 821501 (145 NSF), Room 824700 (1371 NSF), Room 810501 (1462 NSF), Room 82000W (944 NSF), Room 821908 (146 NSF), Room 81001N (1110 NSF), Room 812100 (258 NSF), Room 821300 (204 NSF), Room 824100 (137 NSF), Room 810406 (435 NSF), Room 820004 (338 NSF), Room 821903 (96 NSF), Room 8M0101 (119 NSF), Room 810003 (215 NSF), Room 811301 (107 NSF), Room 820300 (186 NSF), Room 822900 (60 NSF), Room 810500 (2543 NSF), Room 82000S (752 NSF), Room 821907 (93 NSF), Room 8M0400 (139 NSF), Room 810000 (1854 NSF), Room 811100 (417 NSF), Room 820103 (183 NSF), Room 822600 (137 NSF), Room 80000R (2194 NSF), Room 810900 (460 NSF), Room 820102 (126 NSF), Room 822500 (64 NSF), Room 810401 (113 NSF), Room 813100 (147 NSF), Room 821700 (628 NSF), Room 825400 (240 NSF), Room 810403 (71 NSF), Room 820000 (3298 NSF), Room 821900 (156 NSF), Room 825402 (26 NSF), Room 810005 (92 NSF), Room 811400 (267 NSF), Room 820600 (228 NSF), Room 823100 (60 NSF), Room 810601 (135 NSF), Room 820091 (56 NSF), Room 822200 (206 NSF), Room 81001W (500 NSF), Room 812201 (119 NSF), Room 821302 (114 NSF), Room 824300 (137 NSF), Room 810007 (197 NSF), Room 811600 (346 NSF), Room 820700 (257 NSF), Room 823300 (61 NSF), Room 810602 (174 NSF), Room 820100 (1584 NSF), Room 822300 (136 NSF), Room 810200 (6465 NSF), Room 812900 (45 NSF), Room 821506 (69 NSF), Room 825100 (507 NSF), Room 810600 (7312 NSF), Room 82002E (619 NSF), Room 822100 (295 NSF), Room 81002S (558 NSF), Room 812300 (62 NSF), Room 821400 (84 NSF), Room 824600 (768 NSF), Room 810407 (68 NSF), Room 820008 (176 NSF), Room 821904 (91 NSF), Room 8M0200 (114 NSF), Room 810400 (1185 NSF), Room 813001 (36 NSF), Room 821601 (133 NSF), Room 825301 (26 NSF), Room 810402 (646 NSF), Room 813200 (259 NSF), Room 821701 (172 NSF), Room 825401 (32 NSF), Room 810300 (2322 NSF), Room 813000 (47 NSF), Room 821600 (761 NSF), Room 825300 (196 NSF), Room 81003W (2614 NSF), Room 812500 (366 NSF), Room 821502 (250 NSF), Room 824701 (277 NSF), Room 810008 (60 NSF), Room 811700 (1737 NSF), Room 820800 (132 NSF), Room 823400 (137 NSF), Room 81004N (279 NSF), Room 812501 (35 NSF), Room 821503 (124 NSF), Room 824800 (759 NSF), Room 810006 (183 NSF), Room 811500 (352 NSF), Room 820601 (72 NSF), Room 823200 (136 NSF), Room 81002W (888 NSF), Room 812400 (356 NSF), Room 821500 (284 NSF), Room 824601 (116 NSF), Room 810001 (2342 NSF), Room 811200 (449 NSF), Room 820104 (182 NSF), Room 822700 (60 NSF), Room 810404 (68 NSF), Room 820002 (148 NSF), Room 821901 (99 NSF), Room 826500 (60 NSF), Room 810405 (729 NSF), Room 820003 (342 NSF), Room 821902 (96 NSF), Room 8M0100 (133 NSF), Room 810100 (1149 NSF), Room 812600 (106 NSF), Room 821505 (256 NSF), Room 825000 (500 NSF), Room 810408 (62 NSF), Room 82000C (1073 NSF), Room 821905 (140 NSF), Room 8M0300 (233 NSF), Room 810002 (192 NSF), Room 811300 (670 NSF), Room 820200 (201 NSF), Room 822800 (137 NSF), Room 810502 (133 NSF), Room 82001E (2323 NSF), Room 822000 (475 NSF), Room 810010 (40 NSF), Room 811703 (122 NSF), Room 820900 (117 NSF), Room 823700 (61 NSF), Room 810009 (281 NSF), Room 811701 (167 NSF), Room 820801 (156 NSF), Room 823500 (61 NSF), Room 810605 (44 NSF), Room 820101 (141 NSF), Room 822400 (136 NSF), Room 810004 (212 NSF), Room 811302 (159 NSF), Room 820500 (482 NSF), Room 823000 (136 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$7,690,511 in deficiencies (Year 1) and \$5,479,964 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$7,690,511 in deficiencies (Year 1) and \$5,479,964 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	13,170,475

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.021	Renovating Building Number - 9, Building Name - JACK KASSEWITZ HALL (648 SS), (87724 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 911900 (901 NSF), Room 920400 (901 NSF), Room 913601 (44 NSF), Room 920700 (900 NSF), Room 914300 (145 NSF), Room 921000 (381 NSF), Room 914400 (74 NSF), Room 921001 (15 NSF), Room 910005 (1898 NSF), Room 915400 (97 NSF), Room 922000 (901 NSF), Room 91001W (2439 NSF), Room 915900 (443 NSF), Room 923900 (67 NSF), Room 913800 (1060 NSF), Room 920900 (301 NSF), Room 91002E (3250 NSF), Room 916000 (1263 NSF), Room 924000 (271 NSF), Room 910003 (303 NSF), Room 915200 (972 NSF), Room 921800 (901 NSF), Room 911200 (321 NSF), Room 92000E (756 NSF), Room 925400 (7144 NSF), Room 911401 (36 NSF), Room 92002S (1633 NSF), Room 91002W (1673 NSF), Room 917100 (1562 NSF), Room 924200 (67 NSF), Room 913700 (174 NSF), Room 920800 (900 NSF), Room 911500 (898 NSF), Room 920091 (87 NSF), Room 91001N (311 NSF), Room 915702 (210 NSF), Room 923601 (44 NSF), Room 914800 (197 NSF), Room 921400 (303 NSF), Room 914200 (275 NSF), Room 920902 (23 NSF), Room 910300 (1802 NSF), Room 917301 (286 NSF), Room 924700 (121 NSF), Room 911100 (65 NSF), Room 92000C (1128 NSF), Room 925301 (1680 NSF), Room 910002 (317 NSF), Room 915000 (158 NSF), Room 921600 (898 NSF), Room 911400 (302 NSF), Room 92001S (1633 NSF), Room 910700 (900 NSF), Room 920001 (580 NSF), Room 924900 (69 NSF), Room 910900 (735 NSF), Room 920003 (292 NSF), Room 925100 (34 NSF), Room 91001S (2386 NSF), Room 915800 (268 NSF), Room 923800 (76 NSF), Room 911000 (43 NSF), Room 920004 (299 NSF), Room 925300 (7132 NSF), Room 910800 (900 NSF), Room 920002 (461 NSF), Room 925000 (119 NSF), Room 91003N (931 NSF), Room 917200 (228 NSF), Room 924500 (12 NSF), Room 911800 (901 NSF), Room 920300 (450 NSF), Room 91002S (3007 NSF), Room 917000 (340 NSF), Room 924002 (6 NSF), Room 914601 (15 NSF), Room 921201 (35 NSF), Room 910091 (87 NSF), Room 917300 (575 NSF), Room 924600 (96 NSF), Room 910500 (901 NSF), Room 920000 (1370 NSF), Room 924701 (60 NSF), Room 910001 (474 NSF), Room 914900 (249 NSF), Room 921500 (898 NSF), Room 910006 (800 NSF), Room 915500 (100 NSF), Room 923400 (174 NSF), Room 911201 (35 NSF), Room 92000N (252 NSF), Room 925401 (1670 NSF), Room 912000 (901 NSF), Room 920500 (451 NSF), Room 91002N (1132 NSF), Room 916001 (58 NSF), Room 924001 (6 NSF), Room 910000 (1451 NSF), Room 914801 (250 NSF), Room 921402 (36 NSF), Room 91000C (1155 NSF), Room 915700 (238 NSF), Room 923401 (44 NSF), Room 910004 (293 NSF), Room 915300 (505 NSF), Room 921900 (901 NSF), Room 91001E (1167 NSF), Room 915701 (130 NSF), Room 923600 (172 NSF), Room 914600 (206 NSF), Room 921200 (321 NSF), Room 911300 (29 NSF), Room 92000W (750 NSF), Room 930100 (105 NSF), Room 914700 (4277 NSF), Room 921301 (65 NSF), Room 914701 (95 NSF), Room 921302 (29 NSF), Room 913600 (172 NSF), Room 920600 (450 NSF), Room 914100 (445 NSF), Room 920901 (50 NSF), Room 911600 (898 NSF), Room 920200 (451 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$4,385,581 in deficiencies (Year 1) and \$5,170,105 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$4,385,581 in deficiencies (Year 1) and \$5,170,105 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	9,555,686

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.022	Renovating Building Number - 10, Building Name - CT FOR THE ARTS (644 SS), (99122 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room M10006 (115 NSF), Room M12003 (26 NSF), Room M21400 (127 NSF), Room M3003C (463 NSF), Room M33600 (943 NSF), Room M1000N (548 NSF), Room M12200 (108 NSF), Room M21500 (123 NSF), Room M30091 (62 NSF), Room M33800 (357 NSF), Room M1000E (912 NSF), Room M12100 (55 NSF), Room M21401 (126 NSF), Room M3004C (1086 NSF), Room M33700 (945 NSF), Room M10091 (62 NSF), Room M12301 (315 NSF), Room M21700 (113 NSF), Room M30100 (1417 NSF), Room M33802 (99 NSF), Room M10092 (67 NSF), Room M12302 (411 NSF), Room M21800 (129 NSF), Room M30101 (218 NSF), Room M33803 (74 NSF), Room M10100 (697 NSF), Room M12303 (58 NSF), Room M21900 (146 NSF), Room M30200 (122 NSF), Room M33804 (141 NSF), Room M1000S (544 NSF), Room M12300 (2482 NSF), Room M21600 (120 NSF), Room M30092 (67 NSF), Room M33801 (636 NSF), Room M10101 (114 NSF), Room M12304 (101 NSF), Room M22000 (685 NSF), Room M30300 (119 NSF), Room M33805 (609 NSF), Room M10103 (78 NSF), Room M12306 (116 NSF), Room M22101 (155 NSF), Room M30500 (122 NSF), Room M10200 (81 NSF), Room M12400 (94 NSF), Room M22200 (320 NSF), Room M30600 (243 NSF), Room M10302 (130 NSF), Room M20001 (293 NSF), Room M22400 (121 NSF), Room M30900 (111 NSF), Room M10300 (193 NSF), Room M12500 (127 NSF), Room M22201 (46 NSF), Room M30700 (128 NSF), Room M10500 (50 NSF), Room M20003 (270 NSF), Room M22600 (956 NSF), Room M31100 (116 NSF), Room M10400 (55 NSF), Room M20002 (357 NSF), Room M22500 (957 NSF), Room M31000 (187 NSF), Room M10600 (88 NSF), Room M20004 (357 NSF), Room M22700 (229 NSF), Room M31200 (116 NSF), Room M10700 (527 NSF), Room M20005 (170 NSF), Room M22800 (565 NSF), Room M31300 (126 NSF), Room M10800 (112 NSF), Room M2000E (336 NSF), Room M23000 (388 NSF), Room M31500 (123 NSF), Room M10701 (60 NSF), Room M20006 (115 NSF), Room M22900 (69 NSF), Room M31400 (127 NSF), Room M10900 (733 NSF), Room M2000N (169 NSF), Room M23100 (287 NSF), Room M31600 (125 NSF), Room M10901 (48 NSF), Room M2000W (235 NSF), Room M23101 (32 NSF), Room M31700 (118 NSF), Room M11100 (404 NSF), Room M2002C (1755 NSF), Room M23300 (1791 NSF), Room M31900 (129 NSF), Room M11102 (45 NSF), Room M2004C (968 NSF), Room M23302 (124 NSF), Room M32100 (557 NSF), Room M11200 (437 NSF), Room M2005C (490 NSF), Room M23303 (144 NSF), Room M32200 (320 NSF), Room M11201 (44 NSF), Room M20091 (62 NSF), Room M23304 (301 NSF), Room M32201 (46 NSF), Room M11300 (3657 NSF), Room M20092 (67 NSF), Room M23400 (2190 NSF), Room M32300 (397 NSF), Room M11301 (184 NSF), Room M20100 (1053 NSF), Room M23401 (137 NSF), Room M32400 (122 NSF), Room M11101 (43 NSF), Room M2003C (411 NSF), Room M23301 (138 NSF), Room M32000 (656 NSF), Room M11302 (619 NSF), Room M20101 (97 NSF), Room M23500 (946 NSF), Room M32500 (1726 NSF), Room M11303 (90 NSF), Room M20102 (99 NSF), Room M23600 (941 NSF), Room M32501 (145 NSF), Room M11304 (85 NSF), Room M20103 (319 NSF), Room M23700 (941 NSF), Room M32502 (95 NSF), Room M11400 (529 NSF), Room M20104 (111 NSF), Room M23800 (946 NSF), Room M32600 (230 NSF), Room M11500 (232 NSF), Room M20105 (98 NSF), Room M23900 (943 NSF), Room M32700 (563 NSF), Room M11700 (474 NSF), Room M20201 (216 NSF), Room M24001 (58 NSF), Room M32900 (390 NSF), Room M11701 (69 NSF), Room M20300 (122 NSF), Room M24002 (94 NSF), Room M33000 (285 NSF), Room M11702 (70 NSF), Room M20400 (120 NSF), Room M24100 (588 NSF), Room M33001 (34 NSF), Room M11703 (75 NSF), Room M20500 (122 NSF), Room M30001 (284 NSF), Room M33100 (1663 NSF), Room M11800 (443 NSF), Room M20600 (122 NSF), Room M30002 (357 NSF), Room M33101 (120 NSF), Room 01000R (1 NSF), Room M11801 (47 NSF), Room M20700 (243 NSF), Room M30003 (270 NSF), Room M33200 (1926 NSF), Room M10001 (286 NSF), Room M11803 (68 NSF), Room M20900 (130 NSF), Room M3000E (316 NSF), Room M33300 (2016 NSF), Room M10000 (16380 NSF), Room M11802 (63 NSF), Room M20800 (128 NSF), Room M30004 (357 NSF), Room M33201 (117 NSF), Room M10002 (272 NSF), Room M11900 (382 NSF), Room M21000 (111 NSF), Room M3000N (170 NSF), Room M33301 (47 NSF), Room M10003 (194 NSF), Room M12000 (939 NSF), Room M21100 (187 NSF), Room M3000W (303 NSF), Room M33302 (106 NSF), Room M10102 (116 NSF), Room M12305 (105 NSF), Room M22100 (403 NSF), Room M30400 (122 NSF), Room M33900 (962 NSF), Room M11000 (3060 NSF), Room M2001C (1480 NSF), Room M23200 (955 NSF), Room M31800 (116 NSF), Room M10301 (70 NSF), Room M12600 (120 NSF), Room M22300 (397 NSF), Room M30800 (131 NSF), Room M10004 (225 NSF), Room M12001 (93 NSF), Room M21200 (116 NSF), Room M3001C (1222 NSF), Room M33400 (687 NSF), Room M11600 (524 NSF), Room M20200 (1419 NSF), Room M24000 (205 NSF), Room M32800 (68 NSF), Room M10005 (104 NSF), Room M12002 (42 NSF), Room M21300 (116 NSF), Room M3002C (2023 NSF), Room M33500 (946 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$188,281 in deficiencies (Year 1) and \$5,500,237 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	5,688,518

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
	Facilities condition assessment performed February 2020 identified \$188,281 in deficiencies (Year 1) and \$5,500,237 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	
2.023	<p>Renovating Building Number - 11, Building Name - STUDENT UNION (0 SS), (22021 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 010301 (15 NSF), Room 010400 (55 NSF), Room 010600 (77 NSF), Room 010700 (124 NSF), Room 01130A (18 NSF), Room 011401 (521 NSF), Room 010901 (26 NSF), Room 011300 (65 NSF), Room 011100 (113 NSF), Room 011400 (4006 NSF), Room 011601 (78 NSF), Room 012700 (1513 NSF), Room 012000 (109 NSF), Room 012200 (77 NSF), Room 010006 (386 NSF), Room 013100 (105 NSF), Room 01002N (1162 NSF), Room 010000 (557 NSF), Room 012600 (279 NSF), Room 01001W (662 NSF), Room 011801 (41 NSF), Room 01001N (243 NSF), Room 010500 (56 NSF), Room 010008 (206 NSF), Room 013300 (71 NSF), Room 010001 (386 NSF), Room 012700 (1513 NSF), Room 01001S (1319 NSF), Room 012100 (51 NSF), Room 010101 (67 NSF), Room 01001E (1745 NSF), Room 010800 (54 NSF), Room 010100 (1274 NSF), Room 012500 (155 NSF), Room 010102 (133 NSF), Room 010005 (255 NSF), Room 013000 (403 NSF), Room 010002 (274 NSF), Room 012701 (63 NSF), Room 011603 (19 NSF), Room 010300 (981 NSF), Room 011600 (135 NSF), Room 010900 (164 NSF), Room 012300 (89 NSF), Room 01000C (106 NSF), Room 013400 (29 NSF), Room 010007 (206 NSF), Room 013200 (518 NSF), Room 011800 (148 NSF), Room 010004 (269 NSF), Room 012900 (914 NSF), Room 011900 (20 NSF), Room 011000 (60 NSF), Room 010200 (508 NSF), Room 011200 (88 NSF), Room 01000R (1 NSF), Room 013500 (38 NSF), Room 010003 (271 NSF), Room 012800 (161 NSF), Room 01002W (552 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$2,150,880 in deficiencies (Year 1) and \$919,845 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	3,070,725
	Facilities condition assessment performed February 2020 identified \$2,150,880 in deficiencies (Year 1) and \$919,845 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	
2.024	<p>Renovating Building Number - 12, Building Name - ARTS ANNEX (101 SS), (16980 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room N10500 (56 NSF), Room N10700 (34 NSF), Room N10600 (50 NSF), Room N10800 (2460 NSF), Room N10401 (174 NSF), Room N10803 (672 NSF), Room N20100 (276 NSF), Room N10801 (209 NSF), Room N20300 (353 NSF), Room N10900 (164 NSF), Room N10402 (178 NSF), Room N10802 (751 NSF), Room N20000 (950 NSF), Room N20200 (275 NSF), Room N10100 (1769 NSF), Room N1002E (349 NSF), Room N10102 (59 NSF), Room N10103 (52 NSF), Room N10106 (49 NSF), Room N10105 (50 NSF), Room N10201 (423 NSF), Room N10200 (941 NSF), Room N10202 (276 NSF), Room N10302 (751 NSF), Room N10108 (751 NSF), Room N10303 (668 NSF), Room N0000R (1 NSF), Room N10107 (104 NSF), Room N1001E (205 NSF), Room N10301 (274 NSF), Room N10104 (100 NSF), Room N10400 (1088 NSF), Room N10101 (175 NSF), Room N10110 (110 NSF), Room N10109 (664 NSF), Room N10300 (1519 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$13,074 in deficiencies (Year 1) and \$1,232,356 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	1,245,430
	Facilities condition assessment performed February 2020 identified \$13,074 in deficiencies (Year 1) and \$1,232,356 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.025	<p>Renovating Building Number - 14, Building Name - CONFERENCE CENTER (0 SS), (13665 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room K41500 (108 NSF), Room K41400 (145 NSF), Room K41201 (69 NSF), Room K41700 (640 NSF), Room K41301 (443 NSF), Room K41302 (403 NSF), Room K42001 (224 NSF), Room K42000 (47 NSF), Room K41600 (708 NSF), Room K41900 (42 NSF), Room K42002 (261 NSF), Room K42101 (128 NSF), Room K42400 (359 NSF), Room K40002 (201 NSF), Room K41000 (615 NSF), Room K42091 (49 NSF), Room K40001 (197 NSF), Room K42200 (915 NSF), Room K41300 (1985 NSF), Room K41200 (238 NSF), Room K42700 (460 NSF), Room K4200C (616 NSF), Room K42600 (98 NSF), Room K4100C (1238 NSF), Room K42104 (115 NSF), Room K40091 (49 NSF), Room K42300 (548 NSF), Room K42103 (197 NSF), Room 04000R (1 NSF), Room K4100N (191 NSF), Room K41800 (61 NSF), Room K42501 (116 NSF), Room K41002 (71 NSF), Room K41100 (220 NSF), Room K42105 (122 NSF), Room K4200N (484 NSF), Room K42102 (101 NSF), Room K42500 (373 NSF), Room K42106 (23 NSF), Room K42100 (710 NSF), Room K41001 (94 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$36,128 in deficiencies (Year 1) and \$1,481,745 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$36,128 in deficiencies (Year 1) and \$1,481,745 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	1,517,873
2.026	<p>Renovating Building Number - 15, Building Name - MBF GLOBAL BUSINESS (755 SS), (122022 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room R10091 (202 NSF), Room R12701 (144 NSF), Room R21000 (109 NSF), Room R25301 (11 NSF), Room R32900 (131 NSF), Room R40094 (92 NSF), Room R44100 (131 NSF), Room R51800 (305 NSF), Room R10003 (374 NSF), Room R12505 (112 NSF), Room R20700 (322 NSF), Room R25200 (897 NSF), Room R32600 (131 NSF), Room R40091 (202 NSF), Room R43800 (148 NSF), Room R51500 (132 NSF), Room R1001N (1302 NSF), Room R12700 (110 NSF), Room R20900 (830 NSF), Room R25300 (897 NSF), Room R32800 (127 NSF), Room R40093 (90 NSF), Room R44000 (134 NSF), Room R51700 (931 NSF), Room R1011S (1059 NSF), Room R13500 (151 NSF), Room R22100 (156 NSF), Room R3001C (3694 NSF), Room R34100 (810 NSF), Room R40700 (283 NSF), Room R45000 (1082 NSF), Room R10800 (116 NSF), Room R14400 (129 NSF), Room R23000 (128 NSF), Room R30300 (131 NSF), Room R34900 (887 NSF), Room R41500 (131 NSF), Room R5001C (1426 NSF), Room R11000 (121 NSF), Room R14600 (129 NSF), Room R23200 (127 NSF), Room R30500 (237 NSF), Room R35000 (900 NSF), Room R41700 (258 NSF), Room R50091 (202 NSF), Room R12300 (119 NSF), Room R20092 (94 NSF), Room R24500 (371 NSF), Room R31800 (293 NSF), Room R40002 (315 NSF), Room R42900 (119 NSF), Room R50701 (79 NSF), Room R10300 (281 NSF), Room R13800 (155 NSF), Room R22400 (128 NSF), Room R30091 (202 NSF), Room R34400 (171 NSF), Room R41000 (518 NSF), Room R45200 (916 NSF), Room R10500 (120 NSF), Room R14100 (155 NSF), Room R22700 (127 NSF), Room R30094 (92 NSF), Room R34700 (978 NSF), Room R41201 (22 NSF), Room R45301 (11 NSF), Room R10201 (53 NSF), Room R13700 (155 NSF), Room R22300 (133 NSF), Room R3001S (2165 NSF), Room R34300 (155 NSF), Room R40900 (26 NSF), Room R45101 (11 NSF), Room R10301 (33 NSF), Room R13900 (129 NSF), Room R22500 (131 NSF), Room R30092 (91 NSF), Room R34500 (185 NSF), Room R41100 (293 NSF), Room R45201 (12 NSF), Room R10104 (209 NSF), Room R13100 (712 NSF), Room R21700 (130 NSF), Room R25701 (13 NSF), Room R33700 (192 NSF), Room R40304 (87 NSF), Room R44701 (11 NSF), Room R12502 (201 NSF), Room R20400 (130 NSF), Room R25001 (13 NSF), Room R32300 (148 NSF), Room R4002S (382 NSF), Room R43500 (119 NSF), Room R51300 (210 NSF), Room R10001 (287 NSF), Room R12503 (27 NSF), Room R20500 (130 NSF), Room R25100 (882 NSF), Room R32400 (127 NSF), Room R4003E (362 NSF), Room R43600 (125 NSF), Room R51301 (406 NSF), Room R12401 (72 NSF), Room R20100 (360 NSF), Room R24800 (343 NSF), Room R32000 (109 NSF), Room R4001E (747 NSF), Room R43200 (119 NSF), Room R51000 (179 NSF), Room R12301 (176 NSF), Room R20093 (83 NSF), Room R24600 (145 NSF), Room R31900 (282 NSF), Room R40003 (460 NSF), Room R43000 (125 NSF), Room R50800 (119 NSF), Room R12500 (895 NSF), Room R20200 (224 NSF), Room R24900 (856 NSF), Room R32100 (139 NSF), Room R4001S (1628 NSF), Room R43300 (125 NSF), Room R51100 (179 NSF), Room R12100 (125 NSF), Room R2001S (2724 NSF), Room R24300 (446 NSF), Room R31600 (700 NSF), Room R35501 (11 NSF), Room R42700 (385 NSF), Room R50600 (183 NSF), Room R10103 (184 NSF), Room R13000 (254 NSF), Room R21600 (122 NSF), Room R25700 (887 NSF), Room R33600 (128 NSF), Room R40303 (83 NSF), Room R44700 (916 NSF), Room R10102 (738 NSF), Room R12900 (741 NSF), Room R21500 (105 NSF), Room R25601 (11 NSF), Room R33500 (131 NSF), Room R40302 (137 NSF), Room R44601 (13 NSF), Room R11500 (148 NSF), Room R15100 (132 NSF), Room R23700 (126 NSF), Room R31000 (134 NSF), Room R35201 (11 NSF), Room</p>	3,050,371

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

R42200 (127 NSF), Room R5011W (180 NSF), Room R11600 (118 NSF), Room R20001 (399 NSF), Room R23800 (126 NSF), Room R31100 (117 NSF), Room R35300 (900 NSF), Room R42300 (307 NSF), Room R5012C (1792 NSF), Room R10400 (112 NSF), Room R14000 (129 NSF), Room R22600 (127 NSF), Room R30093 (88 NSF), Room R34600 (201 NSF), Room R41200 (293 NSF), Room R45300 (922 NSF), Room R10002 (113 NSF), Room R12504 (149 NSF), Room R20600 (169 NSF), Room R25101 (11 NSF), Room R32500 (128 NSF), Room R4003S (490 NSF), Room R43700 (139 NSF), Room R51400 (1310 NSF), Room R10101 (466 NSF), Room R12800 (992 NSF), Room R21400 (26 NSF), Room R25600 (884 NSF), Room R33400 (127 NSF), Room R40301 (120 NSF), Room R44600 (932 NSF), Room R12000 (122 NSF), Room R2001E (693 NSF), Room R24200 (145 NSF), Room R31500 (202 NSF), Room R35500 (894 NSF), Room R42601 (102 NSF), Room R50500 (85 NSF), Room R10100 (783 NSF), Room R12705 (81 NSF), Room R21301 (22 NSF), Room R25501 (12 NSF), Room R33300 (127 NSF), Room R40300 (1823 NSF), Room R44500 (96 NSF), Room R60100 (2664 NSF), Room R11100 (175 NSF), Room R14700 (155 NSF), Room R23300 (127 NSF), Room R30600 (196 NSF), Room R35001 (11 NSF), Room R41800 (128 NSF), Room R50092 (91 NSF), Room R11800 (322 NSF), Room R20003 (428 NSF), Room R24000 (124 NSF), Room R31300 (101 NSF), Room R35400 (889 NSF), Room R42500 (279 NSF), Room R50300 (1310 NSF), Room R10700 (133 NSF), Room R14300 (129 NSF), Room R22900 (128 NSF), Room R30200 (134 NSF), Room R34801 (13 NSF), Room R41400 (128 NSF), Room R50003 (460 NSF), Room R10900 (181 NSF), Room R14500 (155 NSF), Room R23100 (131 NSF), Room R30400 (148 NSF), Room R34901 (11 NSF), Room R41600 (127 NSF), Room R5001E (681 NSF), Room R10107 (191 NSF), Room R13400 (160 NSF), Room R22000 (146 NSF), Room R30003 (417 NSF), Room R34000 (818 NSF), Room R40600 (116 NSF), Room R44900 (344 NSF), Room R10106 (122 NSF), Room R13300 (167 NSF), Room R21900 (279 NSF), Room R30002 (368 NSF), Room R33900 (362 NSF), Room R40500 (97 NSF), Room R44801 (120 NSF), Room R11200 (121 NSF), Room R14800 (149 NSF), Room R23400 (131 NSF), Room R30700 (121 NSF), Room R35100 (900 NSF), Room R41900 (128 NSF), Room R50093 (89 NSF), Room R12200 (122 NSF), Room R20091 (100 NSF), Room R24400 (898 NSF), Room R31700 (599 NSF), Room R40001 (410 NSF), Room R42800 (125 NSF), Room R50700 (144 NSF), Room R11900 (263 NSF), Room R2001C (3809 NSF), Room R24100 (132 NSF), Room R31400 (79 NSF), Room R35401 (11 NSF), Room R42600 (390 NSF), Room R50400 (85 NSF), Room R10600 (117 NSF), Room R14200 (155 NSF), Room R22800 (131 NSF), Room R30100 (197 NSF), Room R34800 (903 NSF), Room R41300 (127 NSF), Room R50001 (413 NSF), Room R1001C (3275 NSF), Room R12600 (231 NSF), Room R20800 (321 NSF), Room R25201 (11 NSF), Room R32700 (127 NSF), Room R40092 (89 NSF), Room R43900 (135 NSF), Room R51600 (1316 NSF), Room R10105 (121 NSF), Room R13200 (241 NSF), Room R21800 (166 NSF), Room R30001 (406 NSF), Room R33800 (209 NSF), Room R40400 (329 NSF), Room R44800 (1237 NSF), Room R11400 (208 NSF), Room R15000 (94 NSF), Room R23600 (192 NSF), Room R30900 (127 NSF), Room R35200 (900 NSF), Room R42100 (127 NSF), Room R50100 (1326 NSF), Room R10200 (275 NSF), Room R13600 (125 NSF), Room R22200 (140 NSF), Room R3001E (678 NSF), Room R34200 (792 NSF), Room R40800 (308 NSF), Room R45100 (928 NSF), Room R11300 (178 NSF), Room R14900 (374 NSF), Room R23500 (128 NSF), Room R30800 (163 NSF), Room R35101 (11 NSF), Room R42000 (131 NSF), Room R50094 (95 NSF), Room R10092 (99 NSF), Room R12702 (93 NSF), Room R21100 (178 NSF), Room R25400 (885 NSF), Room R33000 (128 NSF), Room R40100 (285 NSF), Room R44200 (335 NSF), Room R51900 (275 NSF), Room R10094 (97 NSF), Room R12704 (67 NSF), Room R21300 (292 NSF), Room R25500 (888 NSF), Room R33200 (131 NSF), Room R40201 (176 NSF), Room R44400 (138 NSF), Room R52000 (95 NSF), Room R10093 (97 NSF), Room R12703 (72 NSF), Room R21200 (293 NSF), Room R25401 (11 NSF), Room R33100 (128 NSF), Room R40200 (1428 NSF), Room R44300 (307 NSF), Room R51901 (33 NSF), Room R11700 (102 NSF), Room R20002 (227 NSF), Room R23900 (186 NSF), Room R31200 (26 NSF), Room R35301 (11 NSF), Room R42400 (247 NSF), Room R50200 (132 NSF), Room R12400 (119 NSF), Room R20094 (94 NSF), Room R24700 (261 NSF), Room R31901 (22 NSF), Room R4001C (4203 NSF), Room R43100 (125 NSF), Room R50900 (119 NSF), Room R12501 (211 NSF), Room R20300 (190 NSF), Room R25000 (877 NSF), Room R32200 (260 NSF), Room R4002E (323 NSF), Room R43400 (125 NSF), Room R51200 (119 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$3,050,371 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$3,050,371 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.027	<p>Renovating Building Number - 18, Building Name - BLDG L (DISTRICT OFF (0 SS), (281504 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room L10200 (212 NSF), Room L12500 (89 NSF), Room L15100 (876 NSF), Room L50000 (45194 NSF), Room L10600 (141 NSF), Room L12700 (251 NSF), Room L15400 (544 NSF), Room L50091 (77 NSF), Room L10900 (209 NSF), Room L13000 (211 NSF), Room L15403 (39 NSF), Room L11000 (256 NSF), Room L13100 (469 NSF), Room L15404 (102 NSF), Room L10300 (204 NSF), Room L12501 (49 NSF), Room L15200 (633 NSF), Room L50001 (287 NSF), Room L10400 (151 NSF), Room L12502 (49 NSF), Room L15201 (192 NSF), Room L50002 (287 NSF), Room L10800 (147 NSF), Room L12900 (222 NSF), Room L15402 (35 NSF), Room L50100 (159 NSF), Room L11808 (64 NSF), Room L14100 (183 NSF), Room L20004 (179 NSF), Room L11201 (110 NSF), Room L13300 (113 NSF), Room L15700 (828 NSF), Room L11600 (146 NSF), Room L1360E (177 NSF), Room L16400 (3692 NSF), Room L11806 (64 NSF), Room L1390B (122 NSF), Room L20002 (292 NSF), Room L11803 (66 NSF), Room L13800 (178 NSF), Room L20000 (55355 NSF), Room L10700 (142 NSF), Room L12800 (70 NSF), Room L15401 (105 NSF), Room L50092 (74 NSF), Room L10000 (352 NSF), Room L12100 (111 NSF), Room L15001 (158 NSF), Room L30100 (3631 NSF), Room L12001 (115 NSF), Room L15000 (373 NSF), Room L30092 (74 NSF), Room L11902 (112 NSF), Room L14800 (408 NSF), Room L30004 (179 NSF), Room L11203 (134 NSF), Room L13500 (185 NSF), Room L15702 (835 NSF), Room L1180S (481 NSF), Room L14300 (184 NSF), Room L20092 (74 NSF), Room L10091 (77 NSF), Room L12400 (71 NSF), Room L15006 (48 NSF), Room L40004 (176 NSF), Room L11100 (195 NSF), Room L1310C (495 NSF), Room L15500 (1770 NSF), Room L11807 (65 NSF), Room L14000 (139 NSF), Room L20003 (283 NSF), Room L11901 (116 NSF), Room L14700 (198 NSF), Room L30003 (283 NSF), Room L11302 (38 NSF), Room L13602 (51 NSF), Room L15900 (276 NSF), Room L11804 (65 NSF), Room L1390A (120 NSF), Room L20001 (293 NSF), Room L11700 (111 NSF), Room L1360N (284 NSF), Room L16401 (156 NSF), Room L10002 (225 NSF), Room L12200 (128 NSF), Room L15002 (43 NSF), Room L40000 (60868 NSF), Room L11810 (65 NSF), Room L14500 (273 NSF), Room L30001 (293 NSF), Room L11402 (116 NSF), Room L13604 (51 NSF), Room L16000 (278 NSF), Room L11801 (66 NSF), Room L1360S (241 NSF), Room L16500 (21 NSF), Room L11301 (37 NSF), Room L13601 (65 NSF), Room L15801 (434 NSF), Room L11403 (43 NSF), Room L13605 (50 NSF), Room L16100 (278 NSF), Room L11500 (83 NSF), Room L13606 (100 NSF), Room L16200 (219 NSF), Room L11400 (108 NSF), Room L13603 (51 NSF), Room L15901 (258 NSF), Room L10003 (189 NSF), Room L12300 (126 NSF), Room L15003 (43 NSF), Room L40001 (283 NSF), Room L11200 (138 NSF), Room L13200 (268 NSF), Room L15600 (700 NSF), Room L11900 (125 NSF), Room L14600 (198 NSF), Room L30002 (292 NSF), Room L11501 (62 NSF), Room L13607 (100 NSF), Room L16300 (834 NSF), Room L10092 (74 NSF), Room L12401 (112 NSF), Room L15007 (34 NSF), Room L40091 (77 NSF), Room L10500 (229 NSF), Room L12600 (34 NSF), Room L15300 (14 NSF), Room L50003 (287 NSF), Room L10100 (210 NSF), Room L12402 (122 NSF), Room L15032 (208 NSF), Room L40092 (74 NSF), Room L11802 (64 NSF), Room L13700 (148 NSF), Room L16600 (53 NSF), Room L12000 (115 NSF), Room L14900 (89 NSF), Room L30091 (77 NSF), Room L11202 (110 NSF), Room L13400 (279 NSF), Room L15701 (604 NSF), Room L11300 (99 NSF), Room L13600 (448 NSF), Room L15800 (1273 NSF), Room L1180N (511 NSF), Room L14200 (184 NSF), Room L20091 (77 NSF), Room L1180W (382 NSF), Room L14400 (187 NSF), Room L30000 (60867 NSF), Room L10005 (20011 NSF), Room L12302 (51 NSF), Room L15005 (43 NSF), Room L40003 (283 NSF), Room L10004 (183 NSF), Room L12301 (51 NSF), Room L15004 (43 NSF), Room L40002 (284 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$8,490 in deficiencies (Year 1) and \$453,501 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$8,490 in deficiencies (Year 1) and \$453,501 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	461,991
2.028	<p>Renovating Building Number - 20, Building Name - MOTOR POOL (0 SS), (2968 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002007 (26 NSF), Room 002006 (34 NSF), Room 002003 (662 NSF), Room 002008 (87 NSF), Room 002005 (38 NSF), Room 002009 (160 NSF), Room 002004 (204 NSF), Room 002002 (590 NSF), Room 002001 (1167 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$4,662 in deficiencies (Year 1) and \$52,346 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$4,662 in deficiencies (Year 1) and \$52,346 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	57,008

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.029	<p>Renovating Building Number - 21, Building Name - GROUNDS MAINTENANCE (0 SS), (3318 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 002111 (300 NSF), Room 002105 (31 NSF), Room 002101 (372 NSF), Room 002102 (185 NSF), Room 002109 (300 NSF), Room 002104 (133 NSF), Room 002106 (15 NSF), Room 002108 (154 NSF), Room 002107 (215 NSF), Room 002103 (188 NSF), Room 002110 (160 NSF), Room 002100 (1265 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$155,803 in deficiencies (Year 1) and \$91,538 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$155,803 in deficiencies (Year 1) and \$91,538 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	247,341
2.030	<p>Renovating Building Number - 22, Building Name - CTR ENVIRONMENT (0 SS), (5922 NSF) Apply Other to Room 002203 (1590 NSF), Room 002202 (3029 NSF), Room 002205 (329 NSF), Room 002204 (270 NSF), Room 002201 (704 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$566,692 in deficiencies (Year 1) and \$444,171 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$566,692 in deficiencies (Year 1) and \$444,171 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	1,010,863
2.031	<p>Renovating Building Number - 24, Building Name - TENNIS PAVILION (0 SS), (2636 NSF) Apply Other to Room 002402 (320 NSF), Room 002403 (314 NSF), Room 002401 (2002 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$21,966 in deficiencies (Year 1) and \$65,110 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$21,966 in deficiencies (Year 1) and \$65,110 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	87,076
2.032	<p>Renovating Building Number - 25, Building Name - HANDBALL STORAGE 1 (0 SS), (306 NSF) Apply Other to Room 002502 (108 NSF), Room 002503 (108 NSF), Room 002501 (90 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$19,891 in deficiencies (Year 1) and \$17,387 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$19,891 in deficiencies (Year 1) and \$17,387 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	37,278
2.033	<p>Renovating Building Number - 26, Building Name - HANDBALL STORAGE 2 (0 SS), (324 NSF) Apply Other to Room 002602 (108 NSF), Room 002603 (108 NSF), Room 002601 (108 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$19,891 in deficiencies (Year 1) and \$14,240 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$19,891 in deficiencies (Year 1) and \$14,240 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	34,131
2.034	<p>Renovating Building Number - 27, Building Name - DUGOUT 1 (0 SS), (351 NSF) Apply Other to Room 002701 (351 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$348 in deficiencies (Year 1) and \$7,729 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$348 in deficiencies (Year 1) and \$7,729 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	8,077
2.035	<p>Renovating Building Number - 28, Building Name - DUGOUT 2 (0 SS), (333 NSF) Apply Other to Room 002802 (40 NSF), Room 002801 (293 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$1,043 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$1,043 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	1,043

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.036	<p>Renovating Building Number - 29, Building Name - TICKET BOOTH (0 SS), (173 NSF) Apply Painting, Floor Cover, Plumbing, HVAC Systems, Retrofit for Technology, Other to Room 002901 (173 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$96,110 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$96,110 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	96,110
2.037	<p>Renovating Building Number - 30, Building Name - HORTICULTURE CENTER (0 SS), (1484 NSF) Apply Other to Room 003001 (520 NSF), Room 003002 (964 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$35,231 in deficiencies (Year 1) and \$86,771 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$35,231 in deficiencies (Year 1) and \$86,771 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	122,002
2.038	<p>Renovating Building Number - 49, Building Name - BALL FIELD RESTROOMS (0 SS), (1083 NSF) Apply Painting, Floor Cover, Plumbing, Lighting, Restrooms, HVAC Systems, Retrofit for Technology, Other to Room 004903 (308 NSF), Room 004902 (308 NSF), Room 004901 (308 NSF), Room 004900 (159 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$5,067 in deficiencies (Year 1) and \$62,690 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$5,067 in deficiencies (Year 1) and \$62,690 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	67,757
2.039	<p>Renovating Building Number - 301, Building Name - PORTABLE_CHEM LAB (15 SS), (819 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room T30100 (819 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$46,272 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$46,272 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	161,721
2.040	<p>Renovating Building Number - 302, Building Name - PORTABLE_CHEM LAB SE (0 SS), (819 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room T30200 (819 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$37,913 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$37,913 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	153,362
2.041	<p>Renovating Building Number - 303, Building Name - PORTABLE_BIOLOGY LAB (15 SS), (819 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room T30300 (819 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$45,533 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$45,533 in deficiencies (Year 1) and \$115,449 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	160,982
2.042	<p>Renovating Building Number - 2201, Building Name - VISITOR PAVILION (0 SS), (888 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 2201A2 (54 NSF), Room 220104 (351 NSF), Room 2201A1 (437 NSF), Room 220103 (46 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$7,136 in deficiencies (Year 1) and \$11,581 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$7,136 in deficiencies (Year 1) and \$11,581 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.</p>	18,717

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.043	Renovating Building Number - 2203, Building Name - ANIMAL HOUSING (0 SS), (494 NSF) Apply Other to Room 220302 (54 NSF), Room 220301 (440 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$25,265 in deficiencies (Year 1) and \$11,654 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$25,265 in deficiencies (Year 1) and \$11,654 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	36,919
2.044	Renovating Building Number - 2204, Building Name - STORAGE - ENVIRONMEN (0 SS), (600 NSF) Apply Other to Room 2204A2 (360 NSF), Room 2204A1 (240 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$15,549 in deficiencies (Year 1) and \$936 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$15,549 in deficiencies (Year 1) and \$936 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	16,485
2.045	Renovating Building Number - 2206, Building Name - POTTING SHED - ENVIR (0 SS), (322 NSF) Apply Other to Room 2206A (322 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$2,309 in deficiencies (Year 1) and \$0 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$2,309 in deficiencies (Year 1) and \$0 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	2,309
2.046	Renovating Building Number - 2208, Building Name - STORAGE - GARAGE ENV (0 SS), (276 NSF) Apply Other to Room 220801 (276 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$17,388 in deficiencies (Year 1) and \$6,630 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$17,388 in deficiencies (Year 1) and \$6,630 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	24,018
2.047	Renovating Building Number - 2209, Building Name - ROOF COVERED TABLES (0 SS), (446 NSF) Apply Other to Room 2209A (446 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$1 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$1 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	1
2.048	Renovating Building Number - 2210, Building Name - CHICKEE - BUTTERFLY (0 SS), (601 NSF) Apply Other to Room 2210A (601 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$19,740 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$19,740 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	19,740
2.049	Renovating Building Number - 3001, Building Name - WOOD SHED - HORTICUL (0 SS), (1080 NSF) Apply Other to Room 300101 (1080 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$741 in deficiencies (Year 1) and \$57,794 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$741 in deficiencies (Year 1) and \$57,794 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	58,535
2.050	Renovating Building Number - 3002, Building Name - SALES OFFICE HORTICU (0 SS), (160 NSF) Apply Other to Room 300201 (160 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$10,767 in deficiencies (Year 1) and \$16,829 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$10,767 in deficiencies (Year 1) and \$16,829 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	27,596

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
2.051	Renovating Building Number - 3003, Building Name - ELECTRICAL/PUMP (0 SS), (254 NSF) Apply Other to Room 300302 (127 NSF), Room 300301 (127 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$6,401 in deficiencies (Year 1) and \$67,479 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$6,401 in deficiencies (Year 1) and \$67,479 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	73,880
2.052	Renovating Building Number - 3004, Building Name - SALES SHED-HORTICULT (0 SS), (730 NSF) Apply Other to Room 300403 (306 NSF), Room 300402 (108 NSF), Room 300401 (316 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$35,977 in deficiencies (Year 1) and \$3,942 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years. Facilities condition assessment performed February 2020 identified \$35,977 in deficiencies (Year 1) and \$3,942 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over the next 5 years.	39,919
2.053	Renovating Building Number - 3005, Building Name - GREENHOUSE (0 SS), (2059 NSF) Apply Other to Room 300501 (2059 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$14,263 in deficiencies (Year 1) and \$366,648 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$14,263 in deficiencies (Year 1) and \$366,648 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	380,911
2.054	Renovating Building Number - 3006, Building Name - SAWTOOTH SHADEHOUSE (0 SS), (2684 NSF) Apply Other to Room 300601 (2684 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$300,982 in deficiencies (Year 1) and \$16,129 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$300,982 in deficiencies (Year 1) and \$16,129 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	317,021
2.055	Renovating Building Number - 3007, Building Name - POTTING SHED (0 SS), (4273 NSF) Apply Other to Room 300701 (4273 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$63,693 in deficiencies (Year 1) and \$178,979 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$63,693 in deficiencies (Year 1) and \$178,979 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	242,672
KENDALL CAMPUS		Total : 281,533,360

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 3
Site Name: WOLFSON CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
3.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	5,452,172
3.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	25,458,829
3.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	4,160,480

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
3.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	8,800,000
WOLFSON CAMPUS		
Total :		43,871,481

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
3.005	New Construction: Adding Non-Vocational Labs (2341 SS), (114465 NSF), (162587 GSF); Vocational Labs (198 SS), (11045 NSF), (15688 GSF); Area Studies (11300 NSF), Art (11840 NSF), Biological Sciences (12700 NSF), Biology, General (11000 NSF), Chemistry, General (11000 NSF), Communications, General (9000 NSF), Computer & Information Systems (11355 NSF), Clothing and Textiles (10000 NSF), Business Data Processing (11045 NSF), Business & Management (11470 NSF), Architectural & Environmental Design (8800 NSF), Anatomy (6000 NSF)	71,131,326
3.006	New Construction: Adding Vocational Labs (220 SS), (26810 NSF), (38080 GSF); Apparel Manufacturing (2460 NSF), Clothing Production & Manag. (10020 NSF), Commercial Foods & Culin. Art (14330 NSF)	15,193,920
3.007	New Construction: Adding Custodial (7243 NSF), Custodial (1066 NSF)	4,708,998
3.008	New Construction: Adding Student Services (87269 NSF)	49,458,444
3.009	New Construction: Adding Auditorium / Exhibition (8448 NSF), Physical Education (78232 NSF)	49,124,880
3.010	New Construction: Adding Audiovisual (9562 NSF), Audiovisual (11102 NSF)	11,711,049
3.011	New Construction: Adding Library / Study (119453 NSF)	67,698,729
3.012	New Construction: Adding Classrooms (2000 SS), (56000 NSF), (79542 GSF); Classroom (56000 NSF), Office (4500 NSF)	34,287,666
3.013	New Construction: Adding Classrooms (1162 SS), (32575 NSF), (46270 GSF); Vocational Labs (60 SS), (5635 NSF), (8004 GSF); Classroom (32575 NSF), Computer Electronics (5635 NSF), Office (5000 NSF), Auditorium / Exhibition (3500 NSF)	26,472,054
3.014	Remodeling Building Number - 3, Building Name - WOLFSON CAMPUS 3 : Adding Circulation (3500 NSF), (4971 GSF); Circulation (3500 NSF) and Removing (0 SS), (5372 NSF) Room 33003W (2945 NSF), Room 340500 (2427 NSF)	1,071,714
3.015	Remodeling Building Number - 2, Building Name - WOLFSON CAMPUS 2 : Adding Circulation (2500 NSF), (3551 GSF); Circulation (2500 NSF) and Removing (0 SS), (3554 NSF) Room 210600 (3554 NSF)	709,023
3.016	Remodeling Building Number - 6, Building Name - WOLFSON CAMPUS 6 : Adding Vocational Labs (20 SS), (3715 NSF), (5277 GSF); Auditorium/Exhibition (1500 NSF), (2131 GSF); Commercial Foods & Culin. Art (3715 NSF, 20 SSC), Auditorium / Exhibition (1500 NSF) and Removing (115 SS), (4739 NSF) Room 610300 (76 NSF), Room 610100 (105 NSF), Room 610101 (59 NSF), Room 610200 (181 NSF), Room 611500 (44 NSF), Room 640001 (122 NSF), Room 611000 (130 NSF), Room 640300 (361 NSF), Room 640000 (1924 NSF), Room 630800 (814 NSF), Room 630900 (846 NSF), Room 620091 (77 NSF)	1,040,392
3.017	Renovating Building Number - 1, Building Name - WOLFSON CAMPUS 1 (539 SS), (232452 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 10000W (1482 NSF), Room 107001 (513 NSF), Room 113001 (56 NSF), Room 117100 (229 NSF), Room 120500 (211 NSF), Room 126428 (50 NSF), Room 14003E (75 NSF), Room 144000 (910 NSF), Room 147504 (146 NSF), Room 151503 (194 NSF), Room 155602 (28 NSF), Room 166402 (53 NSF), Room 100010 (66 NSF), Room 107200 (421 NSF), Room 113002 (129 NSF), Room 117101 (26 NSF), Room 135003 (125 NSF), Room 126429 (368 NSF), Room 135004 (57 NSF), Room 14003N (255 NSF), Room 144001 (154 NSF), Room 147600 (71 NSF), Room 161800 (212 NSF), Room 155603 (153 NSF), Room 161801 (32 NSF), Room 166403 (87 NSF), Room 100400 (178 NSF), Room 110021 (62 NSF), Room 121600 (650 NSF), Room 118102 (118 NSF), Room 126100 (2924 NSF), Room 13000E (638 NSF), Room 136502 (268 NSF), Room 141000 (834 NSF), Room 151504 (120 NSF), Room 15000W (928 NSF), Room 153200 (106 NSF), Room 160002 (232 NSF), Room 163800 (165 NSF), Room 167602 (200 NSF), Room 115702 (23 NSF),	26,298,579

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Room 110023 (441 NSF), Room 115800 (896 NSF), Room 118104 (119 NSF), Room 126102 (166 NSF), Room 13000W (852 NSF), Room 145301 (171 NSF), Room 141100 (209 NSF), Room 145500 (144 NSF), Room 15001S (1505 NSF), Room 153400 (106 NSF), Room 160004 (222 NSF), Room 103001 (172 NSF), Room 170004 (216 NSF), Room 105803 (479 NSF), Room 110092 (69 NSF), Room 116003 (173 NSF), Room 120005 (229 NSF), Room 136504 (40 NSF), Room 130700 (153 NSF), Room 137200 (167 NSF), Room 142200 (135 NSF), Room 146600 (154 NSF), Room 150104 (65 NSF), Room 164000 (1272 NSF), Room 160100 (541 NSF), Room 164700 (193 NSF), Room 105001 (214 NSF), Room 110029 (85 NSF), Room 115901 (258 NSF), Room 126404 (187 NSF), Room 126108 (160 NSF), Room 130100 (600 NSF), Room 136705 (126 NSF), Room 141800 (213 NSF), Room 146100 (484 NSF), Room 154200 (160 NSF), Room 154001 (154 NSF), Room 16002E (154 NSF), Room 164100 (191 NSF), Room 170600 (251 NSF), Room 105100 (72 NSF), Room 118110 (112 NSF), Room 115902 (154 NSF), Room 118200 (42 NSF), Room 126200 (1199 NSF), Room 130101 (67 NSF), Room 136706 (201 NSF), Room 150091 (86 NSF), Room 146200 (152 NSF), Room 150092 (69 NSF), Room 154002 (169 NSF), Room 16002S (492 NSF), Room 164200 (157 NSF), Room 110030 (788 NSF), Room 105800 (473 NSF), Room 110032 (1066 NSF), Room 116000 (191 NSF), Room 120002 (231 NSF), Room 126202 (220 NSF), Room 141801 (30 NSF), Room 136901 (105 NSF), Room 141901 (134 NSF), Room 146301 (115 NSF), Room 150101 (634 NSF), Room 154004 (674 NSF), Room 170700 (932 NSF), Room 164400 (252 NSF), Room 175300 (484 NSF), Room 100021 (72 NSF), Room 110002 (231 NSF), Room 113005 (70 NSF), Room 130300 (100 NSF), Room 122000 (55 NSF), Room 126900 (122 NSF), Room 135802 (110 NSF), Room 140042 (369 NSF), Room 144200 (160 NSF), Room 16003S (491 NSF), Room 152000 (43 NSF), Room 156400 (665 NSF), Room 162200 (177 NSF), Room 166701 (222 NSF), Room 105600 (189 NSF), Room 118003 (67 NSF), Room 115903 (28 NSF), Room 120001 (204 NSF), Room 126201 (100 NSF), Room 130200 (157 NSF), Room 136900 (47 NSF), Room 147801 (74 NSF), Room 146300 (44 NSF), Room 150100 (524 NSF), Room 154003 (149 NSF), Room 16003E (73 NSF), Room 164300 (164 NSF), Room 110031 (841 NSF), Room 105804 (50 NSF), Room 110093 (60 NSF), Room 116004 (25 NSF), Room 120006 (432 NSF), Room 126406 (328 NSF), Room 141900 (43 NSF), Room 137201 (36 NSF), Room 142300 (104 NSF), Room 146700 (188 NSF), Room 150105 (66 NSF), Room 154300 (164 NSF), Room 170800 (656 NSF), Room 164800 (170 NSF), Room 103003 (129 NSF), Room 110025 (251 NSF), Room 115802 (10 NSF), Room 118106 (119 NSF), Room 130800 (48 NSF), Room 13002S (522 NSF), Room 136701 (383 NSF), Room 141300 (133 NSF), Room 145700 (144 NSF), Room 15002S (418 NSF), Room 160101 (600 NSF), Room 16000N (462 NSF), Room 164002 (168 NSF), Room 170046 (21 NSF), Room 100091 (80 NSF), Room 110006 (280 NSF), Room 126104 (59 NSF), Room 118008 (248 NSF), Room 123001 (893 NSF), Room 127200 (155 NSF), Room 136000 (646 NSF), Room 140092 (68 NSF), Room 153700 (160 NSF), Room 149000 (7057 NSF), Room 152500 (163 NSF), Room 156800 (636 NSF), Room 162800 (156 NSF), Room 167200 (223 NSF), Room 113201 (100 NSF), Room 110106 (46 NSF), Room 116500 (10 NSF), Room 120034 (97 NSF), Room 126413 (187 NSF), Room 131801 (32 NSF), Room 144501 (22 NSF), Room 143000 (102 NSF), Room 147201 (36 NSF), Room 150701 (76 NSF), Room 155000 (61 NSF), Room 160700 (151 NSF), Room 105906 (92 NSF), Room 105900 (75 NSF), Room 110100 (1144 NSF), Room 116400 (1243 NSF), Room 120007 (447 NSF), Room 126407 (67 NSF), Room 140004 (222 NSF), Room 137400 (218 NSF), Room 142400 (80 NSF), Room 146800 (352 NSF), Room 150200 (174 NSF), Room 154400 (252 NSF), Room 16540M (209 NSF), Room 164900 (183 NSF), Room 105802 (80 NSF), Room 110091 (78 NSF), Room 116002 (123 NSF), Room 120004 (221 NSF), Room 131000 (368 NSF), Room 130500 (5 NSF), Room 137101 (36 NSF), Room 142100 (132 NSF), Room 146500 (142 NSF), Room 150103 (65 NSF), Room 160102 (906 NSF), Room 160092 (68 NSF), Room 164600 (164 NSF), Room 105901 (271 NSF), Room 110101 (404 NSF), Room 116401 (161 NSF), Room 126204 (155 NSF), Room 126408 (100 NSF), Room 131001 (239 NSF), Room 137500 (621 NSF), Room 142500 (214 NSF), Room 146900 (443 NSF), Room 154100 (178 NSF), Room 154500 (172 NSF), Room 160200 (165 NSF), Room 165000 (61 NSF), Room 100019 (140 NSF), Room 110000 (14817 NSF), Room 120008 (258 NSF), Room 118001 (164 NSF), Room 121800 (206 NSF), Room 126430 (18 NSF), Room 135800 (1523 NSF), Room 14003S (163 NSF), Room 150300 (153 NSF), Room 147700 (107 NSF), Room 151800 (212 NSF), Room 155604 (153 NSF), Room 162000 (50 NSF), Room 166404 (114 NSF), Room 113003 (48 NSF), Room 110012 (467 NSF), Room 115700 (293 NSF), Room 118100 (116 NSF), Room 126000 (551 NSF), Room 130006 (255 NSF), Room 144002 (148 NSF), Room 140800 (162 NSF), Room 145200 (746 NSF), Room 150005 (221 NSF), Room 153000 (161 NSF), Room 157600 (977 NSF), Room 100202 (132 NSF), Room 167600 (1073 NSF), Room 100003 (195 NSF), Room 106101 (151 NSF), Room 111700 (343 NSF), Room 116800 (738 NSF), Room 136500 (2416 NSF), Room 126423 (314 NSF), Room 132200 (134 NSF), Room 14001N (728 NSF), Room 143400 (106 NSF), Room 147401 (225 NSF), Room 163600 (158 NSF), Room 155401 (19 NSF), Room 161100 (221 NSF), Room 166100 (653 NSF), Room 100101 (420 NSF), Room 11000A (2231 NSF), Room 120094 (42 NSF), Room 118013 (178 NSF), Room 125802 (155 NSF), Room 130003 (267 NSF), Room 136102 (451 NSF), Room 140300 (154 NSF), Room 151100 (275 NSF), Room 150002 (233 NSF), Room 152900 (65 NSF), Room 157201 (39 NSF), Room 163200 (106 NSF), Room 167402 (311 NSF), Room 115600 (615 NSF), Room 110027 (350 NSF), Room 115804 (116 NSF), Room 118108 (242 NSF), Room 126106 (59 NSF), Room 130092 (70 NSF), Room 144900 (211 NSF), Room 141500 (146 NSF), Room 145900 (316 NSF), Room 15003S (422 NSF), Room 153900 (166 NSF), Room 16001E (392 NSF), Room 104000 (740 NSF), Room 170200 (406 NSF), Room 105801 (279 NSF), Room 110033 (966 NSF), Room

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

116001 (130 NSF), Room 120003 (267 NSF), Room 136703 (26 NSF), Room 130400 (31 NSF), Room 137100 (167 NSF), Room 142000 (135 NSF), Room 146400 (144 NSF), Room 150102 (538 NSF), Room 164004 (308 NSF), Room 160091 (87 NSF), Room 164500 (172 NSF), Room 175400 (442 NSF), Room 105903 (129 NSF), Room 110103 (155 NSF), Room 126203 (82 NSF), Room 12000N (857 NSF), Room 126410 (85 NSF), Room 13160A (3417 NSF), Room 140001 (205 NSF), Room 142700 (165 NSF), Room 154005 (239 NSF), Room 150500 (166 NSF), Room 154700 (193 NSF), Room 160400 (175 NSF), Room 165300 (727 NSF), Room 105000 (206 NSF), Room 116403 (124 NSF), Room 115900 (154 NSF), Room 118109 (101 NSF), Room 126107 (103 NSF), Room 130094 (42 NSF), Room 136704 (184 NSF), Room 147000 (347 NSF), Room 146000 (682 NSF), Room 15004S (365 NSF), Room 154000 (906 NSF), Room 16001S (1944 NSF), Room 164005 (286 NSF), Room 110028 (348 NSF), Room 10000S (442 NSF), Room 107000 (309 NSF), Room 113000 (164 NSF), Room 117000 (143 NSF), Room 120400 (211 NSF), Room 141600 (246 NSF), Room 135002 (129 NSF), Room 14002S (514 NSF), Room 143900 (166 NSF), Room 147503 (404 NSF), Room 151502 (105 NSF), Room 170300 (225 NSF), Room 161503 (221 NSF), Room 166401 (91 NSF), Room 100093 (60 NSF), Room 110008 (86 NSF), Room 114001 (228 NSF), Room 126427 (1150 NSF), Room 125800 (1203 NSF), Room 130001 (251 NSF), Room 136100 (657 NSF), Room 140101 (149 NSF), Room 144700 (193 NSF), Room 155601 (91 NSF), Room 152700 (171 NSF), Room 156901 (115 NSF), Room 163000 (150 NSF), Room 167400 (159 NSF), Room 105904 (37 NSF), Room 118010 (545 NSF), Room 116404 (114 NSF), Room 12000S (1467 NSF), Room 126411 (37 NSF), Room 13160B (1553 NSF), Room 140002 (232 NSF), Room 149002 (476 NSF), Room 147100 (127 NSF), Room 150600 (158 NSF), Room 154800 (170 NSF), Room 160500 (166 NSF), Room 16530M (197 NSF), Room 110104 (181 NSF), Room 106200 (182 NSF), Room 111701 (22 NSF), Room 116801 (254 NSF), Room 120100 (470 NSF), Room 126424 (147 NSF), Room 142800 (155 NSF), Room 14001S (1400 NSF), Room 143600 (157 NSF), Room 147500 (134 NSF), Room 151102 (121 NSF), Room 155500 (1612 NSF), Room 100009 (40 NSF), Room 166200 (135 NSF), Room 100201 (215 NSF), Room 110011 (28 NSF), Room 115602 (351 NSF), Room 118015 (644 NSF), Room 132300 (87 NSF), Room 130005 (221 NSF), Room 136301 (70 NSF), Room 140600 (153 NSF), Room 145100 (61 NSF), Room 150004 (222 NSF), Room 161500 (595 NSF), Room 157500 (25 NSF), Room 163400 (106 NSF), Room 167500 (1186 NSF), Room 10000N (310 NSF), Room 106900 (202 NSF), Room 125900 (258 NSF), Room 116803 (128 NSF), Room 120300 (211 NSF), Room 126426 (587 NSF), Room 135001 (77 NSF), Room 14002N (186 NSF), Room 152902 (149 NSF), Room 147502 (520 NSF), Room 151501 (105 NSF), Room 155600 (228 NSF), Room 161502 (228 NSF), Room 166400 (1039 NSF), Room 112001 (119 NSF), Room 106800 (783 NSF), Room 112000 (44 NSF), Room 116802 (71 NSF), Room 120200 (211 NSF), Room 126425 (360 NSF), Room 143800 (164 NSF), Room 14002E (200 NSF), Room 143700 (160 NSF), Room 147501 (243 NSF), Room 151500 (232 NSF), Room 155501 (137 NSF), Room 10000E (532 NSF), Room 166300 (1312 NSF), Room 100047 (34 NSF), Room 110004 (318 NSF), Room 113101 (154 NSF), Room 118006 (205 NSF), Room 135000 (2078 NSF), Room 127100 (162 NSF), Room 135804 (111 NSF), Room 14005N (469 NSF), Room 144400 (252 NSF), Room 147901 (39 NSF), Room 161501 (143 NSF), Room 156600 (622 NSF), Room 162600 (171 NSF), Room 166900 (36 NSF), Room 100100 (3371 NSF), Room 110009 (72 NSF), Room 122100 (302 NSF), Room 118011 (823 NSF), Room 125801 (320 NSF), Room 130002 (253 NSF), Room 136101 (420 NSF), Room 140200 (144 NSF), Room 152200 (177 NSF), Room 150001 (233 NSF), Room 152800 (156 NSF), Room 157200 (223 NSF), Room 163100 (161 NSF), Room 167401 (151 NSF), Room 114002 (28 NSF), Room 110003 (267 NSF), Room 113100 (854 NSF), Room 118004 (83 NSF), Room 122001 (109 NSF), Room 126901 (104 NSF), Room 144800 (170 NSF), Room 14004N (99 NSF), Room 144300 (164 NSF), Room 147900 (996 NSF), Room 152001 (134 NSF), Room 156500 (684 NSF), Room 100022 (11 NSF), Room 166702 (668 NSF), Room 100048 (37 NSF), Room 110005 (50 NSF), Room 113200 (1195 NSF), Room 118007 (203 NSF), Room 135803 (173 NSF), Room 127101 (36 NSF), Room 135805 (164 NSF), Room 140091 (86 NSF), Room 144500 (178 NSF), Room 148000 (218 NSF), Room 162201 (23 NSF), Room 156700 (859 NSF), Room 162700 (171 NSF), Room 166901 (115 NSF), Room 100300 (747 NSF), Room 110013 (24 NSF), Room 123000 (5775 NSF), Room 118101 (50 NSF), Room 126001 (118 NSF), Room 130007 (258 NSF), Room 136501 (233 NSF), Room 140900 (179 NSF), Room 152201 (23 NSF), Room 15000N (511 NSF), Room 153100 (150 NSF), Room 160001 (232 NSF), Room 163700 (159 NSF), Room 167601 (30 NSF), Room 115701 (100 NSF), Room 110010 (66 NSF), Room 115601 (662 NSF), Room 118014 (160 NSF), Room 125803 (77 NSF), Room 130004 (221 NSF), Room 145300 (529 NSF), Room 140301 (174 NSF), Room 145000 (91 NSF), Room 150003 (267 NSF), Room 152901 (35 NSF), Room 157400 (677 NSF), Room 100200 (591 NSF), Room 167403 (202 NSF), Room 106000 (578 NSF), Room 110108 (18 NSF), Room 116601 (124 NSF), Room 120091 (80 NSF), Room 136300 (437 NSF), Room 132001 (108 NSF), Room 14000W (701 NSF), Room 143200 (106 NSF), Room 147301 (197 NSF), Room 150900 (179 NSF), Room 163300 (103 NSF), Room 160900 (179 NSF), Room 165900 (631 NSF), Room 103002 (225 NSF), Room 110024 (362 NSF), Room 115801 (118 NSF), Room 126421 (147 NSF), Room 126103 (106 NSF), Room 13001S (2215 NSF), Room 136700 (529 NSF), Room 141200 (125 NSF), Room 145600 (144 NSF), Room 155300 (1456 NSF), Room 153600 (157 NSF), Room 160005 (221 NSF), Room 164001 (154 NSF), Room 170045 (20 NSF), Room 106100 (118 NSF), Room 118105 (127 NSF), Room 116700 (179 NSF), Room 120092 (69 NSF), Room 126422 (231 NSF), Room 132100 (130 NSF), Room 14001E (320 NSF), Room 15002E (220 NSF), Room 147400 (227 NSF), Room 151000 (791 NSF), Room 155400 (1146 NSF), Room 161000 (569

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NSF), Room 166000 (631 NSF), Room 110109 (17 NSF), Room 110001 (231 NSF), Room 113004 (124 NSF), Room 118002 (119 NSF), Room 121801 (38 NSF), Room 126500 (247 NSF), Room 143300 (104 NSF), Room 140041 (417 NSF), Room 144100 (178 NSF), Room 147800 (279 NSF), Room 151801 (31 NSF), Room 155700 (664 NSF), Room 100020 (147 NSF), Room 166700 (1328 NSF), Room 100092 (69 NSF), Room 110007 (280 NSF), Room 114000 (591 NSF), Room 118009 (317 NSF), Room 135801 (181 NSF), Room 127201 (37 NSF), Room 136001 (414 NSF), Room 140100 (287 NSF), Room 144600 (484 NSF), Room 149001 (428 NSF), Room 162001 (134 NSF), Room 156900 (44 NSF), Room 162900 (250 NSF), Room 167201 (39 NSF), Room 105907 (115 NSF), Room 110107 (58 NSF), Room 124000 (1225 NSF), Room 120035 (79 NSF), Room 126420 (162 NSF), Room 132000 (55 NSF), Room 140005 (221 NSF), Room 143100 (154 NSF), Room 152600 (173 NSF), Room 150800 (162 NSF), Room 155200 (746 NSF), Room 160800 (162 NSF), Room 165800 (664 NSF), Room 105905 (68 NSF), Room 116600 (289 NSF), Room 116405 (114 NSF), Room 12000W (2840 NSF), Room 126412 (132 NSF), Room 131800 (234 NSF), Room 140003 (267 NSF), Room 147300 (219 NSF), Room 147200 (463 NSF), Room 150700 (126 NSF), Room 154900 (183 NSF), Room 160600 (214 NSF), Room 165400 (727 NSF), Room 110105 (118 NSF), Room 110102 (104 NSF), Room 116402 (104 NSF), Room 12000E (501 NSF), Room 126409 (100 NSF), Room 131601 (73 NSF), Room 142900 (256 NSF), Room 142600 (171 NSF), Room 146901 (367 NSF), Room 150400 (169 NSF), Room 154600 (164 NSF), Room 160300 (163 NSF), Room 105902 (21 NSF), Room 103004 (1328 NSF), Room 110026 (240 NSF), Room 115803 (61 NSF), Room 118107 (134 NSF), Room 126105 (103 NSF), Room 137600 (502 NSF), Room 136702 (293 NSF), Room 141400 (121 NSF), Room 145800 (163 NSF), Room 15003E (73 NSF), Room 153800 (164 NSF), Room 165200 (746 NSF), Room 164003 (149 NSF), Room 170100 (1041 NSF), Room 103000 (1955 NSF), Room 110022 (113 NSF), Room 115703 (136 NSF), Room 130091 (79 NSF), Room 126101 (1054 NSF), Room 13000N (1158 NSF), Room 136503 (98 NSF), Room 141001 (655 NSF), Room 145400 (147 NSF), Room 16000W (566 NSF), Room 15001E (333 NSF), Room 153300 (104 NSF), Room 160003 (267 NSF), Room 163900 (155 NSF), Room 170003 (251 NSF), Room 118103 (127 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$6,678,607 in deficiencies (Year 1) and \$19,619,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$6,678,607 in deficiencies (Year 1) and \$19,619,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

3.018 Renovating Building Number - 2, Building Name - WOLFSON CAMPUS 2 (1081 SS), (148548 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 210405 (326 NSF), Room 214011 (1194 NSF), Room 220500 (791 NSF), Room 230002 (376 NSF), Room 231700 (792 NSF), Room 210404 (997 NSF), Room 214010 (310 NSF), Room 220400 (791 NSF), Room 230001 (356 NSF), Room 231600 (792 NSF), Room 210412 (105 NSF), Room 216001 (329 NSF), Room 2211B (1222 NSF), Room 23001W (482 NSF), Room 232200 (1408 NSF), Room 210410 (128 NSF), Room 215002 (203 NSF), Room 221101 (137 NSF), Room 23001N (834 NSF), Room 232101 (196 NSF), Room 210409 (311 NSF), Room 215001 (248 NSF), Room 220900 (792 NSF), Room 23001E (324 NSF), Room 232100 (1175 NSF), Room 210004 (288 NSF), Room 210601 (190 NSF), Room 220001 (363 NSF), Room 221400 (791 NSF), Room 230091 (94 NSF), Room 232300 (967 NSF), Room 210003 (308 NSF), Room 210600 (3554 NSF), Room 220000 (631 NSF), Room 221300 (791 NSF), Room 23003N (460 NSF), Room 232204 (127 NSF), Room 21004W (153 NSF), Room 211601 (28 NSF), Room 220100 (6711 NSF), Room 222304 (185 NSF), Room 230204 (83 NSF), Room 240200 (1840 NSF), Room 210091 (93 NSF), Room 211700 (122 NSF), Room 220101 (426 NSF), Room 222305 (581 NSF), Room 230205 (428 NSF), Room 240201 (54 NSF), Room 210092 (75 NSF), Room 211800 (122 NSF), Room 220102 (183 NSF), Room 222400 (152 NSF), Room 230206 (232 NSF), Room 240300 (1991 NSF), Room 21003E (267 NSF), Room 211400 (153 NSF), Room 22003N (451 NSF), Room 222300 (1508 NSF), Room 230200 (166 NSF), Room 236101 (100 NSF), Room 210305 (145 NSF), Room 214004 (112 NSF), Room 220202 (66 NSF), Room 225004 (118 NSF), Room 231102 (135 NSF), Room 210100 (688 NSF), Room 211900 (400 NSF), Room 220103 (182 NSF), Room 222500 (31 NSF), Room 230300 (791 NSF), Room 2M0700 (734 NSF), Room 210407 (382 NSF), Room 214013 (119 NSF), Room 220700 (791 NSF), Room 230004 (309 NSF), Room 231900 (791 NSF), Room 210401 (344 NSF), Room 214007 (345 NSF), Room 220205 (151 NSF), Room 226003 (77 NSF), Room 231300 (792 NSF), Room 210306 (1479 NSF), Room 214005 (112 NSF), Room 220203 (66 NSF), Room 226001 (278 NSF), Room 231200 (1561 NSF), Room 210302 (410 NSF), Room 214001 (1684 NSF), Room 220110 (340 NSF), Room 225001 (271 NSF), Room 231000 (877 NSF), Room 210303 (154 NSF), Room 214002 (122 NSF), Room 220200 (572 NSF), Room 225002 (247 NSF), Room 231100 (1366 NSF), Room 210400 (213 NSF), Room 214006 (230 NSF), Room 220204 (66 NSF), Room 226002 (301 NSF), Room 231201 (151 NSF), Room 210403 (351 NSF), Room 214009 (5834 NSF), Room 220300 (791 NSF), Room 230000 (518 NSF), Room 231500 (792 NSF), Room 210301 (1368 NSF), Room 214000 (632 NSF), Room 220109 (386 NSF), Room 224500 (391 NSF), Room 230900 (792 NSF), Room 21000S (6650 NSF), Room 210801 (315 NSF), Room 22001N (831 NSF), Room 222100 (498 NSF), Room 230104 (103 NSF), Room 235002 (247 NSF), Room 210202 (28 NSF), Room 212100 (122 NSF), Room 220107 (776 NSF), Room 224004 (148 NSF), Room 230700 (791 NSF), Room 210200 (759 NSF), Room 211902 (104

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NSF), Room 220105 (115 NSF), Room 224002 (289 NSF), Room 230500 (791 NSF), Room 210005 (270 NSF), Room 210602 (192 NSF), Room 220002 (286 NSF), Room 221500 (791 NSF), Room 230092 (77 NSF), Room 234001 (246 NSF), Room 210201 (78 NSF), Room 212000 (519 NSF), Room 220106 (887 NSF), Room 224003 (148 NSF), Room 230600 (791 NSF), Room 210002 (291 NSF), Room 210415 (157 NSF), Room 216004 (44 NSF), Room 221202 (159 NSF), Room 23002S (1744 NSF), Room 232203 (45 NSF), Room 210000 (3102 NSF), Room 210413 (122 NSF), Room 216002 (305 NSF), Room 221200 (1516 NSF), Room 23002E (452 NSF), Room 232201 (140 NSF), Room 21002W (171 NSF), Room 211300 (190 NSF), Room 22002S (1753 NSF), Room 222201 (459 NSF), Room 23011B (89 NSF), Room 236100 (1483 NSF), Room 210006 (48 NSF), Room 210603 (333 NSF), Room 220003 (309 NSF), Room 221600 (791 NSF), Room 230100 (6878 NSF), Room 234002 (254 NSF), Room 210411 (105 NSF), Room 215003 (83 NSF), Room 2211A (1215 NSF), Room 23001S (857 NSF), Room 232102 (196 NSF), Room 210001 (134 NSF), Room 210414 (165 NSF), Room 216003 (77 NSF), Room 221201 (606 NSF), Room 23002N (1749 NSF), Room 232202 (101 NSF), Room 21004E (270 NSF), Room 211600 (171 NSF), Room 220092 (77 NSF), Room 222303 (126 NSF), Room 230203 (107 NSF), Room 240100 (1188 NSF), Room 210101 (41 NSF), Room 211901 (140 NSF), Room 220104 (229 NSF), Room 224001 (280 NSF), Room 230400 (791 NSF), Room 210304 (159 NSF), Room 214003 (110 NSF), Room 220201 (63 NSF), Room 225003 (118 NSF), Room 231101 (95 NSF), Room 21003W (138 NSF), Room 211501 (52 NSF), Room 220091 (95 NSF), Room 222302 (265 NSF), Room 230202 (98 NSF), Room 240005 (286 NSF), Room 21001W (3367 NSF), Room 211000 (115 NSF), Room 22001W (407 NSF), Room 222102 (132 NSF), Room 230106 (323 NSF), Room 236002 (301 NSF), Room 21002E (452 NSF), Room 211100 (115 NSF), Room 22002E (363 NSF), Room 222103 (131 NSF), Room 230107 (281 NSF), Room 236003 (77 NSF), Room 210007 (25 NSF), Room 210700 (357 NSF), Room 220004 (307 NSF), Room 221700 (791 NSF), Room 230101 (140 NSF), Room 234003 (70 NSF), Room 21002S (178 NSF), Room 211200 (115 NSF), Room 22002N (1768 NSF), Room 222200 (1418 NSF), Room 230108 (251 NSF), Room 236004 (21 NSF), Room 210008 (144 NSF), Room 210701 (147 NSF), Room 220005 (286 NSF), Room 221800 (791 NSF), Room 230102 (219 NSF), Room 234004 (70 NSF), Room 210406 (339 NSF), Room 214012 (263 NSF), Room 220600 (791 NSF), Room 230003 (288 NSF), Room 231800 (792 NSF), Room 210402 (352 NSF), Room 214008 (122 NSF), Room 220206 (152 NSF), Room 226004 (21 NSF), Room 231400 (792 NSF), Room 21001E (695 NSF), Room 210900 (115 NSF), Room 22001S (950 NSF), Room 222101 (131 NSF), Room 230105 (107 NSF), Room 236001 (279 NSF), Room 210408 (156 NSF), Room 214014 (114 NSF), Room 220800 (791 NSF), Room 230005 (286 NSF), Room 232000 (1148 NSF), Room 210009 (144 NSF), Room 210800 (245 NSF), Room 22001E (324 NSF), Room 221900 (791 NSF), Room 230103 (213 NSF), Room 235001 (271 NSF), Room 210300 (4463 NSF), Room 212200 (122 NSF), Room 220108 (642 NSF), Room 224005 (55 NSF), Room 230800 (791 NSF), Room 21003S (99 NSF), Room 211500 (255 NSF), Room 22003S (129 NSF), Room 222301 (148 NSF), Room 230201 (679 NSF), Room 240004 (312 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$822,647 in deficiencies (Year 1) and \$6,846,269 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$822,647 in deficiencies (Year 1) and \$6,846,269 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

3.019 Renovating Building Number - 3, Building Name - WOLFSON CAMPUS 3 (1214 SS), (207927 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 310401 (119 NSF), Room 311308 (124 NSF), Room 311702 (119 NSF), Room 320095 (81 NSF), Room 33000C (2399 NSF), Room 332000 (856 NSF), Room 342006 (209 NSF), Room 350614 (119 NSF), Room 360414 (238 NSF), Room 370201 (54 NSF), Room 370500 (187 NSF), Room 311312 (475 NSF), Room 311706 (118 NSF), Room 320201 (44 NSF), Room 33002W (2950 NSF), Room 332400 (858 NSF), Room 340411 (813 NSF), Room 342010 (75 NSF), Room 350618 (160 NSF), Room 360418 (238 NSF), Room 370402 (134 NSF), Room 380002 (174 NSF), Room 310405 (1707 NSF), Room 311310 (160 NSF), Room 311704 (26 NSF), Room 320101 (44 NSF), Room 33000S (868 NSF), Room 332200 (840 NSF), Room 340415 (970 NSF), Room 342008 (75 NSF), Room 350616 (133 NSF), Room 360416 (132 NSF), Room 370400 (357 NSF), Room 370600 (77 NSF), Room 310403 (161 NSF), Room 311401 (337 NSF), Room 311709 (128 NSF), Room 320500 (76 NSF), Room 330092 (67 NSF), Room 332700 (840 NSF), Room 340413 (367 NSF), Room 342013 (483 NSF), Room 350621 (168 NSF), Room 360421 (133 NSF), Room 370405 (134 NSF), Room 380100 (318 NSF), Room 310408 (216 NSF), Room 311408 (119 NSF), Room 311716 (276 NSF), Room 321001 (193 NSF), Room 330201 (44 NSF), Room 333301 (91 NSF), Room 340700 (77 NSF), Room 342700 (217 NSF), Room 350628 (121 NSF), Room 360428 (152 NSF), Room 370412 (262 NSF), Room 310406 (647 NSF), Room 310416 (189 NSF), Room 311707 (120 NSF), Room 320300 (104 NSF), Room 33003W (2945 NSF), Room 332500 (858 NSF), Room 340500 (2427 NSF), Room 341003 (127 NSF), Room 350619 (165 NSF), Room 360419 (132 NSF), Room 370403 (134 NSF), Room 380005 (218 NSF), Room 31000C (5786 NSF), Room 311313 (35 NSF), Room 311508 (123 NSF), Room 312301 (265 NSF), Room 322000 (948 NSF), Room 330900 (135 NSF), Room 340094 (73 NSF), Room 342011 (75 NSF), Room 350300 (99 NSF), Room 360101 (43 NSF), Room 360444 (132 NSF), Room 370428 (151 NSF), Room 31005S (284 NSF), Room 310812 (70 NSF), Room 311514 (118 NSF), Room

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

320006 (381 NSF), Room 322600 (881 NSF), Room 331200 (245 NSF), Room 340300 (99 NSF), Room 341805 (67 NSF), Room 350602 (133 NSF), Room 360402 (134 NSF), Room 360600 (77 NSF), Room 370434 (247 NSF), Room 31001W (635 NSF), Room 311100 (272 NSF), Room 311510 (166 NSF), Room 320002 (176 NSF), Room 322200 (856 NSF), Room 33090B (405 NSF), Room 340100 (329 NSF), Room 341811 (217 NSF), Room 350402 (6858 NSF), Room 360201 (54 NSF), Room 360446 (482 NSF), Room 370430 (167 NSF), Room 310404 (310 NSF), Room 31083A (152 NSF), Room 311705 (120 NSF), Room 320200 (335 NSF), Room 33001W (625 NSF), Room 332300 (857 NSF), Room 340414 (530 NSF), Room 341807 (67 NSF), Room 350617 (133 NSF), Room 360417 (132 NSF), Room 370401 (100 NSF), Room 380000 (317 NSF), Room 310095 (82 NSF), Room 311311 (407 NSF), Room 311519 (1074 NSF), Room 32001W (1537 NSF), Room 323001 (91 NSF), Room 331600 (215 NSF), Room 340404 (170 NSF), Room 342009 (75 NSF), Room 350607 (133 NSF), Room 360407 (132 NSF), Room 370092 (71 NSF), Room 370439 (132 NSF), Room 310411 (1274 NSF), Room 311301 (121 NSF), Room 311712 (117 NSF), Room 320701 (146 NSF), Room 330095 (81 NSF), Room 333000 (882 NSF), Room 340901 (151 NSF), Room 341901 (77 NSF), Room 350624 (128 NSF), Room 360424 (134 NSF), Room 370408 (119 NSF), Room 310094 (46 NSF), Room 311300 (466 NSF), Room 311404 (169 NSF), Room 32000S (805 NSF), Room 323000 (255 NSF), Room 331500 (889 NSF), Room 340403 (170 NSF), Room 341900 (1037 NSF), Room 342300 (855 NSF), Room 360406 (119 NSF), Room 370091 (73 NSF), Room 370438 (119 NSF), Room 310001 (1173 NSF), Room 310805 (120 NSF), Room 311518 (157 NSF), Room 311725 (1325 NSF), Room 321300 (124 NSF), Room 330500 (344 NSF), Room 34000S (1153 NSF), Room 341500 (856 NSF), Room 350606 (213 NSF), Room 36000C (868 NSF), Room 360437 (137 NSF), Room 370421 (133 NSF), Room 310201 (44 NSF), Room 311305 (132 NSF), Room 311501 (343 NSF), Room 320092 (71 NSF), Room 330006 (381 NSF), Room 331701 (91 NSF), Room 340408 (492 NSF), Room 342003 (209 NSF), Room 350093 (71 NSF), Room 360411 (132 NSF), Room 370100 (331 NSF), Room 370443 (118 NSF), Room 31004S (290 NSF), Room 311000 (219 NSF), Room 311602 (181 NSF), Room 320005 (196 NSF), Room 322500 (855 NSF), Room 331100 (479 NSF), Room 340201 (58 NSF), Room 341810 (217 NSF), Room 350611 (124 NSF), Room 360401 (81 NSF), Room 360501 (119 NSF), Room 370433 (132 NSF), Room 310003 (335 NSF), Room 310807 (120 NSF), Room 311513 (118 NSF), Room 311900 (256 NSF), Room 321500 (857 NSF), Room 330601 (91 NSF), Room 34002W (2999 NSF), Room 341700 (851 NSF), Room 350601 (133 NSF), Room 360092 (71 NSF), Room 360439 (132 NSF), Room 370423 (165 NSF), Room 310093 (46 NSF), Room 311201 (124 NSF), Room 311503 (119 NSF), Room 32000C (2028 NSF), Room 322900 (147 NSF), Room 331400 (957 NSF), Room 340402 (170 NSF), Room 341814 (464 NSF), Room 350095 (87 NSF), Room 360405 (134 NSF), Room 37000C (865 NSF), Room 370437 (137 NSF), Room 31003S (790 NSF), Room 310900 (218 NSF), Room 311517 (116 NSF), Room 320004 (465 NSF), Room 322400 (837 NSF), Room 331000 (77 NSF), Room 340200 (334 NSF), Room 341809 (250 NSF), Room 350605 (133 NSF), Room 360400 (394 NSF), Room 360500 (183 NSF), Room 370432 (132 NSF), Room 310407 (384 NSF), Room 311400 (310 NSF), Room 311512 (118 NSF), Room 320400 (77 NSF), Room 330091 (69 NSF), Room 332600 (856 NSF), Room 340600 (125 NSF), Room 342012 (89 NSF), Room 350600 (193 NSF), Room 360420 (148 NSF), Room 370404 (134 NSF), Room 380009 (145 NSF), Room 310004 (274 NSF), Room 310808 (163 NSF), Room 311708 (118 NSF), Room 312000 (634 NSF), Room 321600 (839 NSF), Room 330701 (96 NSF), Room 34003W (3006 NSF), Room 341801 (97 NSF), Room 350620 (167 NSF), Room 360093 (71 NSF), Room 360440 (119 NSF), Room 370424 (133 NSF), Room 310801 (483 NSF), Room 311414 (120 NSF), Room 311504 (120 NSF), Room 321102 (125 NSF), Room 330404 (19 NSF), Room 340007 (389 NSF), Room 341300 (124 NSF), Room 35000C (1664 NSF), Room 350100 (329 NSF), Room 360434 (132 NSF), Room 370418 (145 NSF), Room 310100 (331 NSF), Room 311302 (118 NSF), Room 311520 (873 NSF), Room 311722 (208 NSF), Room 323100 (110 NSF), Room 331601 (265 NSF), Room 340405 (170 NSF), Room 341902 (79 NSF), Room 350608 (133 NSF), Room 350800 (77 NSF), Room 370093 (71 NSF), Room 370440 (131 NSF), Room 31002S (824 NSF), Room 31083B (60 NSF), Room 311511 (118 NSF), Room 32002W (3049 NSF), Room 322300 (839 NSF), Room 33090C (139 NSF), Room 340101 (44 NSF), Room 341808 (79 NSF), Room 350500 (63 NSF), Room 360408 (119 NSF), Room 360447 (2443 NSF), Room 370431 (219 NSF), Room 310500 (153 NSF), Room 311410 (727 NSF), Room 311718 (237 NSF), Room 320003 (319 NSF), Room 330400 (283 NSF), Room 333500 (114 NSF), Room 341005 (1073 NSF), Room 342801 (87 NSF), Room 350630 (297 NSF), Room 360300 (103 NSF), Room 370414 (132 NSF), Room 310006 (343 NSF), Room 310810 (143 NSF), Room 311506 (116 NSF), Room 312200 (292 NSF), Room 321003 (232 NSF), Room 330703 (97 NSF), Room 340092 (71 NSF), Room 341803 (79 NSF), Room 350200 (341 NSF), Room 360095 (80 NSF), Room 360430 (163 NSF), Room 370426 (151 NSF), Room 310008 (343 NSF), Room 310811 (140 NSF), Room 311507 (116 NSF), Room 312300 (342 NSF), Room 321800 (857 NSF), Room 330800 (451 NSF), Room 340093 (71 NSF), Room 341804 (67 NSF), Room 350201 (53 NSF), Room 360100 (331 NSF), Room 360442 (119 NSF), Room 370427 (152 NSF), Room 310413 (125 NSF), Room 311405 (113 NSF), Room 311713 (120 NSF), Room 320800 (1092 NSF), Room 321900 (857 NSF), Room 333100 (106 NSF), Room 341000 (787 NSF), Room 342400 (882 NSF), Room 350625 (128 NSF), Room 360425 (131 NSF), Room 360443 (132 NSF), Room 310005 (197 NSF), Room 310809 (71 NSF), Room 311505 (83 NSF), Room 312100 (379 NSF), Room 321700 (844 NSF), Room 330100 (329 NSF), Room 340091 (73 NSF), Room 341802 (92 NSF), Room 350101 (44 NSF), Room 360094 (73 NSF), Room 360441 (131 NSF), Room 370409 (120 NSF), Room 310200 (335 NSF), Room 311304 (165 NSF), Room 311601

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

(141 NSF), Room 320091 (73 NSF), Room 330005 (196 NSF), Room 330702 (97 NSF), Room 340407 (896 NSF), Room 342002 (107 NSF), Room 350610 (69 NSF), Room 360410 (119 NSF), Room 370095 (80 NSF), Room 370425 (187 NSF), Room 310415 (119 NSF), Room 311407 (113 NSF), Room 311715 (169 NSF), Room 321000 (7526 NSF), Room 330200 (335 NSF), Room 331700 (274 NSF), Room 341002 (76 NSF), Room 342600 (108 NSF), Room 350627 (139 NSF), Room 360427 (151 NSF), Room 370411 (132 NSF), Room 370442 (132 NSF), Room 311500 (613 NSF), Room 311724 (508 NSF), Room 321201 (87 NSF), Room 330406 (66 NSF), Room 34000C (2648 NSF), Room 333300 (273 NSF), Room 350092 (71 NSF), Room 360005 (195 NSF), Room 360436 (123 NSF), Room 370420 (135 NSF), Room 310409 (502 NSF), Room 310804 (303 NSF), Room 311710 (118 NSF), Room 320600 (415 NSF), Room 330093 (67 NSF), Room 332800 (837 NSF), Room 340800 (279 NSF), Room 341400 (875 NSF), Room 350622 (119 NSF), Room 360422 (72 NSF), Room 370406 (119 NSF), Room 380200 (103 NSF), Room 310092 (46 NSF), Room 311402 (1400 NSF), Room 311516 (202 NSF), Room 320008 (379 NSF), Room 322800 (105 NSF), Room 331300 (957 NSF), Room 340401 (172 NSF), Room 342100 (849 NSF), Room 350604 (213 NSF), Room 360404 (134 NSF), Room 370005 (215 NSF), Room 370436 (119 NSF), Room 310410 (1243 NSF), Room 311200 (382 NSF), Room 311711 (115 NSF), Room 320700 (448 NSF), Room 330094 (69 NSF), Room 332900 (855 NSF), Room 340900 (500 NSF), Room 341813 (214 NSF), Room 350623 (222 NSF), Room 360423 (133 NSF), Room 370407 (131 NSF), Room 380300 (93 NSF), Room 31001S (1165 NSF), Room 311403 (242 NSF), Room 311509 (135 NSF), Room 320001 (1128 NSF), Room 322100 (858 NSF), Room 33090A (444 NSF), Room 340095 (87 NSF), Room 342200 (841 NSF), Room 350400 (250 NSF), Room 360200 (335 NSF), Room 360445 (118 NSF), Room 370429 (163 NSF), Room 310700 (224 NSF), Room 310813 (460 NSF), Room 311720 (50 NSF), Room 321100 (1321 NSF), Room 330402 (296 NSF), Room 340005 (196 NSF), Room 341101 (135 NSF), Room 341806 (67 NSF), Room 350700 (202 NSF), Room 360432 (219 NSF), Room 370416 (263 NSF), Room 310600 (97 NSF), Room 311411 (274 NSF), Room 311412 (163 NSF), Room 321004 (1006 NSF), Room 330401 (90 NSF), Room 340002 (168 NSF), Room 341100 (394 NSF), Room 342900 (110 NSF), Room 350002 (168 NSF), Room 360431 (167 NSF), Room 370415 (132 NSF), Room 310101 (207 NSF), Room 311303 (257 NSF), Room 311600 (207 NSF), Room 311719 (118 NSF), Room 330002 (188 NSF), Room 331602 (135 NSF), Room 340406 (239 NSF), Room 342001 (112 NSF), Room 350609 (135 NSF), Room 350631 (1531 NSF), Room 370094 (73 NSF), Room 370441 (132 NSF), Room 310400 (255 NSF), Room 311307 (124 NSF), Room 311701 (119 NSF), Room 32003W (3027 NSF), Room 330008 (379 NSF), Room 331900 (881 NSF), Room 340410 (741 NSF), Room 342005 (209 NSF), Room 350613 (130 NSF), Room 360409 (120 NSF), Room 370200 (335 NSF), Room 370445 (2520 NSF), Room 310800 (224 NSF), Room 311413 (120 NSF), Room 311721 (107 NSF), Room 320094 (72 NSF), Room 330403 (21 NSF), Room 340006 (491 NSF), Room 341200 (274 NSF), Room 350005 (196 NSF), Room 350701 (117 NSF), Room 360413 (132 NSF), Room 370417 (132 NSF), Room 310402 (119 NSF), Room 311309 (124 NSF), Room 311703 (119 NSF), Room 320100 (330 NSF), Room 321101 (159 NSF), Room 332100 (839 NSF), Room 340412 (874 NSF), Room 342007 (89 NSF), Room 350615 (132 NSF), Room 360415 (132 NSF), Room 360433 (132 NSF), Room 370501 (119 NSF), Room 310002 (186 NSF), Room 310806 (120 NSF), Room 311502 (313 NSF), Room 311800 (195 NSF), Room 33000E (369 NSF), Room 330600 (710 NSF), Room 34001W (626 NSF), Room 341600 (839 NSF), Room 350094 (73 NSF), Room 360091 (73 NSF), Room 370300 (103 NSF), Room 370422 (105 NSF), Room 310414 (119 NSF), Room 311406 (225 NSF), Room 311714 (118 NSF), Room 320900 (1086 NSF), Room 321400 (858 NSF), Room 333200 (216 NSF), Room 341001 (1226 NSF), Room 342500 (114 NSF), Room 350626 (63 NSF), Room 360426 (121 NSF), Room 360438 (123 NSF), Room 310802 (363 NSF), Room 311415 (780 NSF), Room 311723 (149 NSF), Room 321200 (274 NSF), Room 330405 (235 NSF), Room 330101 (43 NSF), Room 341301 (87 NSF), Room 350091 (73 NSF), Room 360002 (174 NSF), Room 360435 (92 NSF), Room 370419 (132 NSF), Room 370410 (119 NSF), Room 311409 (240 NSF), Room 311717 (117 NSF), Room 321002 (194 NSF), Room 330300 (110 NSF), Room 333400 (124 NSF), Room 340008 (338 NSF), Room 342800 (252 NSF), Room 350629 (121 NSF), Room 360429 (151 NSF), Room 370413 (132 NSF), Room 310300 (100 NSF), Room 310417 (1058 NSF), Room 311700 (253 NSF), Room 320093 (71 NSF), Room 330007 (372 NSF), Room 331800 (124 NSF), Room 340409 (210 NSF), Room 341004 (181 NSF), Room 350612 (120 NSF), Room 360412 (119 NSF), Room 370101 (43 NSF), Room 370444 (389 NSF), Room 310091 (46 NSF), Room 311306 (124 NSF), Room 311515 (118 NSF), Room 320007 (372 NSF), Room 322700 (111 NSF), Room 331201 (88 NSF), Room 340400 (350 NSF), Room 342004 (209 NSF), Room 341812 (217 NSF), Room 350603 (133 NSF), Room 360403 (134 NSF), Room 370002 (174 NSF), Room 370435 (92 NSF), Room 311101 (87 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$2,080,135 in deficiencies (Year 1) and \$5,017,377 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$2,080,135 in deficiencies (Year 1) and \$5,017,377 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
3.020	<p>Renovating Building Number - 4, Building Name - NEW WORLD SCHOOL ART (0 SS), (19394 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 42002E (161 NSF), Room 420001 (241 NSF), Room 430092 (82 NSF), Room 420100 (356 NSF), Room 430700 (113 NSF), Room 420301 (79 NSF), Room 430500 (193 NSF), Room 42000W (454 NSF), Room 42001E (686 NSF), Room 430201 (39 NSF), Room 420002 (171 NSF), Room 430100 (86 NSF), Room 410200 (1275 NSF), Room 420701 (22 NSF), Room 430800 (74 NSF), Room 420091 (82 NSF), Room 410002 (231 NSF), Room 420307 (79 NSF), Room 431100 (87 NSF), Room 410202 (170 NSF), Room 410091 (82 NSF), Room 431400 (21 NSF), Room 430701 (24 NSF), Room 410300 (170 NSF), Room 421800 (141 NSF), Room 410204 (293 NSF), Room 420304 (79 NSF), Room 430901 (57 NSF), Room 43000N (567 NSF), Room 410700 (129 NSF), Room 430001 (237 NSF), Room 420305 (79 NSF), Room 41000N (263 NSF), Room 420309 (168 NSF), Room 410209 (283 NSF), Room 421600 (123 NSF), Room 410500 (165 NSF), Room 422000 (59 NSF), Room 421200 (125 NSF), Room 411000 (536 NSF), Room 411100 (492 NSF), Room 430091 (82 NSF), Room 410206 (299 NSF), Room 410800 (133 NSF), Room 430902 (29 NSF), Room 42000S (385 NSF), Room 420600 (27 NSF), Room 440100 (884 NSF), Room 410211 (102 NSF), Room 421700 (130 NSF), Room 410900 (136 NSF), Room 43000E (303 NSF), Room 410205 (74 NSF), Room 421201 (243 NSF), Room 410208 (315 NSF), Room 421500 (216 NSF), Room 430002 (169 NSF), Room 410101 (120 NSF), Room 420303 (79 NSF), Room 430900 (502 NSF), Room 41000E (155 NSF), Room 420308 (79 NSF), Room 410100 (443 NSF), Room 420501 (24 NSF), Room 430600 (27 NSF), Room 410600 (225 NSF), Room 422001 (45 NSF), Room 420302 (79 NSF), Room 410201 (170 NSF), Room 420800 (29 NSF), Room 420310 (138 NSF), Room 431301 (578 NSF), Room 411002 (279 NSF), Room 43002S (567 NSF), Room 431200 (241 NSF), Room 420092 (82 NSF), Room 410203 (113 NSF), Room 421100 (60 NSF), Room 410001 (213 NSF), Room 420306 (79 NSF), Room 430801 (22 NSF), Room 41000W (387 NSF), Room 421900 (240 NSF), Room 410102 (109 NSF), Room 420700 (74 NSF), Room 410207 (205 NSF), Room 411001 (123 NSF), Room 43001S (540 NSF), Room 42000N (343 NSF), Room 410092 (82 NSF), Room 420500 (114 NSF), Room 431401 (246 NSF), Room 431000 (116 NSF), Room 410400 (165 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$250,367 in deficiencies (Year 1) and \$1,929,375 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$250,367 in deficiencies (Year 1) and \$1,929,375 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p>	2,179,742
3.021	<p>Renovating Building Number - 5, Building Name - BONNIE P MCCABE HALL (285 SS), (110530 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 500300 (3320 NSF), Room 510100 (2088 NSF), Room 520200 (525 NSF), Room 530093 (83 NSF), Room 54002S (163 NSF), Room 542500 (117 NSF), Room 571801 (72 NSF), Room 50002W (271 NSF), Room 51002W (230 NSF), Room 520093 (83 NSF), Room 551001 (136 NSF), Room 560111 (160 NSF), Room 562000 (456 NSF), Room 580402 (38 NSF), Room 551300 (634 NSF), Room 57001N (396 NSF), Room 520201 (66 NSF), Room 530094 (177 NSF), Room 54002W (482 NSF), Room 542501 (76 NSF), Room 53000S (860 NSF), Room 540003 (192 NSF), Room 571900 (84 NSF), Room 500003 (186 NSF), Room 510008 (27 NSF), Room 52000N (868 NSF), Room 590108 (510 NSF), Room 500301 (502 NSF), Room 550601 (72 NSF), Room 560105 (73 NSF), Room 58010M (554 NSF), Room 590102 (138 NSF), Room 551400 (269 NSF), Room 57001S (421 NSF), Room 53002W (496 NSF), Room 54001W (384 NSF), Room 542200 (453 NSF), Room 551202 (12 NSF), Room 522701 (81 NSF), Room 532600 (81 NSF), Room 580602 (141 NSF), Room 50001N (420 NSF), Room 51000E (286 NSF), Room 52001W (629 NSF), Room 5000S (1122 NSF), Room 510093 (83 NSF), Room 550700 (643 NSF), Room 560107 (123 NSF), Room 571000 (106 NSF), Room 580201 (72 NSF), Room 570003 (201 NSF), Room 571600 (150 NSF), Room 512201 (379 NSF), Room 522300 (154 NSF), Room 541400 (199 NSF), Room 550200 (139 NSF), Room 530001 (190 NSF), Room 532701 (81 NSF), Room 580091 (75 NSF), Room 590091 (75 NSF), Room 521600 (583 NSF), Room 531300 (29 NSF), Room 590104 (186 NSF), Room 510001 (124 NSF), Room 560509 (152 NSF), Room 572208 (137 NSF), Room 581003 (54 NSF), Room 592100 (140 NSF), Room 560094 (175 NSF), Room 560801 (51 NSF), Room 520094 (174 NSF), Room 53001N (1037 NSF), Room 54001E (264 NSF), Room 551100 (582 NSF), Room 550101 (170 NSF), Room 560000 (529 NSF), Room 580500 (247 NSF), Room 590109 (130 NSF), Room 512100 (356 NSF), Room 522101 (121 NSF), Room 50003W (211 NSF), Room 51003N (229 NSF), Room 560092 (73 NSF), Room 560700 (516 NSF), Room 58001C (1128 NSF), Room 59001W (206 NSF), Room 560112 (276 NSF), Room 570000 (472 NSF), Room 522600 (81 NSF), Room 532500 (117 NSF), Room 550500 (133 NSF), Room 580100 (284 NSF), Room 541301 (164 NSF), Room 550110 (266 NSF), Room 522100 (373 NSF), Room 550109 (198 NSF), Room 560091 (75 NSF), Room 560600 (86 NSF), Room 500001 (241 NSF), Room 520003 (194 NSF), Room 510002 (325 NSF), Room 520000 (282</p>	17,564,752

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

NSF), Room 522400 (42 NSF), Room 532100 (511 NSF), Room 590100 (290 NSF), Room 512001 (60 NSF), Room 560100 (1952 NSF), Room 560900 (29 NSF), Room 580092 (73 NSF), Room 590092 (73 NSF), Room 58000W (552 NSF), Room 59000S (943 NSF), Room 550108 (196 NSF), Room 56002W (752 NSF), Room 560517 (81 NSF), Room 580003 (203 NSF), Room 541500 (28 NSF), Room 550201 (72 NSF), Room 550103 (181 NSF), Room 560002 (328 NSF), Room 572210 (117 NSF), Room 590000 (497 NSF), Room 512000 (96 NSF), Room 522001 (67 NSF), Room 512200 (183 NSF), Room 522200 (432 NSF), Room 531901 (135 NSF), Room 550111 (220 NSF), Room 59000N (1038 NSF), Room 511600 (53 NSF), Room 58002C (331 NSF), Room 59002W (914 NSF), Room 501600 (230 NSF), Room 521201 (799 NSF), Room 5J0100 (290 NSF), Room 510000 (1053 NSF), Room 552301 (51 NSF), Room 570103 (186 NSF), Room 572204 (125 NSF), Room 580905 (28 NSF), Room 560093 (71 NSF), Room 560800 (344 NSF), Room 510007 (83 NSF), Room 52000E (472 NSF), Room 522700 (116 NSF), Room 532501 (73 NSF), Room 540500 (37 NSF), Room 550092 (73 NSF), Room 590101 (200 NSF), Room 521200 (100 NSF), Room 550091 (67 NSF), Room 552300 (344 NSF), Room 591700 (155 NSF), Room 500002 (211 NSF), Room 580904 (54 NSF), Room 591600 (492 NSF), Room 50002E (268 NSF), Room 51001N (124 NSF), Room 550600 (135 NSF), Room 560104 (156 NSF), Room 540001 (191 NSF), Room 550900 (453 NSF), Room 560109 (72 NSF), Room 571200 (344 NSF), Room 570102 (148 NSF), Room 572203 (140 NSF), Room 502200 (180 NSF), Room 521601 (64 NSF), Room 540900 (175 NSF), Room 550102 (185 NSF), Room 520091 (80 NSF), Room 530003 (196 NSF), Room 581004 (28 NSF), Room 592101 (72 NSF), Room 521800 (553 NSF), Room 541001 (51 NSF), Room 580400 (134 NSF), Room 590106 (135 NSF), Room 572211 (137 NSF), Room 590001 (182 NSF), Room 5J0200 (129 NSF), Room 521801 (63 NSF), Room 560001 (182 NSF), Room 572209 (134 NSF), Room 580000 (446 NSF), Room 590002 (327 NSF), Room 5J0300 (701 NSF), Room 501101 (76 NSF), Room 550104 (182 NSF), Room 560003 (198 NSF), Room 552100 (175 NSF), Room 560500 (1563 NSF), Room 570093 (71 NSF), Room 572105 (142 NSF), Room 550105 (232 NSF), Room 56000C (992 NSF), Room 510600 (54 NSF), Room 55000W (280 NSF), Room 552200 (185 NSF), Room 560501 (303 NSF), Room 510501 (77 NSF), Room 55000E (484 NSF), Room 580901 (28 NSF), Room 501400 (80 NSF), Room 510800 (368 NSF), Room 55002N (373 NSF), Room 580900 (45 NSF), Room 501200 (799 NSF), Room 572202 (7 NSF), Room 580903 (79 NSF), Room 591501 (142 NSF), Room 511900 (45 NSF), Room 570094 (175 NSF), Room 572200 (212 NSF), Room 56002N (286 NSF), Room 560516 (723 NSF), Room 580002 (291 NSF), Room 59000E (358 NSF), Room 552202 (158 NSF), Room 570101 (145 NSF), Room 52002W (494 NSF), Room 530002 (277 NSF), Room 540000 (457 NSF), Room 550800 (202 NSF), Room 522000 (526 NSF), Room 550107 (186 NSF), Room 580300 (84 NSF), Room 590105 (138 NSF), Room 501300 (79 NSF), Room 510700 (212 NSF), Room 50001W (256 NSF), Room 510011 (186 NSF), Room 570100 (285 NSF), Room 572201 (106 NSF), Room 580902 (217 NSF), Room 521500 (501 NSF), Room 560108 (75 NSF), Room 571100 (29 NSF), Room 550100 (2251 NSF), Room 552600 (299 NSF), Room 570200 (549 NSF), Room 572207 (119 NSF), Room 55001N (701 NSF), Room 552201 (131 NSF), Room 550106 (427 NSF), Room 56001W (478 NSF), Room 560514 (96 NSF), Room 580001 (182 NSF), Room 531200 (202 NSF), Room 540601 (77 NSF), Room 54003S (171 NSF), Room 542600 (79 NSF), Room 551401 (1486 NSF), Room 560120 (114 NSF), Room 581002 (79 NSF), Room 592000 (84 NSF), Room 580704 (392 NSF), Room 590900 (546 NSF), Room 500800 (793 NSF), Room 510301 (81 NSF), Room 590003 (203 NSF), Room 520300 (124 NSF), Room 551800 (137 NSF), Room 560400 (134 NSF), Room 57002W (671 NSF), Room 572102 (176 NSF), Room 57001W (336 NSF), Room 572000 (140 NSF), Room 510094 (175 NSF), Room 530091 (80 NSF), Room 54002E (264 NSF), Room 542300 (203 NSF), Room 540094 (173 NSF), Room 550001 (191 NSF), Room 571700 (38 NSF), Room 510003 (193 NSF), Room 520001 (186 NSF), Room 522500 (117 NSF), Room 580802 (87 NSF), Room 500100 (560 NSF), Room 560101 (180 NSF), Room 561000 (106 NSF), Room 580093 (71 NSF), Room 590093 (71 NSF), Room 551203 (136 NSF), Room 57000C (185 NSF), Room 530092 (76 NSF), Room 54002N (278 NSF), Room 542400 (38 NSF), Room 551204 (139 NSF), Room 532200 (140 NSF), Room 550300 (174 NSF), Room 580701 (74 NSF), Room 500600 (171 NSF), Room 520401 (68 NSF), Room 540092 (73 NSF), Room 500200 (932 NSF), Room 5100N2 (781 NSF), Room 560201 (72 NSF), Room 57002N (649 NSF), Room 572100 (96 NSF), Room 591000 (31 NSF), Room 57001E (383 NSF), Room 571800 (134 NSF), Room 53001W (534 NSF), Room 54001N (708 NSF), Room 551200 (890 NSF), Room 560113 (166 NSF), Room 542701 (63 NSF), Room 551600 (120 NSF), Room 500094 (178 NSF), Room 510092 (76 NSF), Room 53002N (191 NSF), Room 54001S (687 NSF), Room 500091 (264 NSF), Room 510091 (80 NSF), Room 570002 (333 NSF), Room 571500 (512 NSF), Room 580601 (96 NSF), Room 501000 (93 NSF), Room 570001 (182 NSF), Room 571401 (138 NSF), Room 550002 (333 NSF), Room 551900 (139 NSF), Room 560401 (72 NSF), Room 570091 (75 NSF), Room 542104 (136 NSF), Room 551201 (217 NSF), Room 520400 (551 NSF), Room 540091 (67 NSF), Room 542700 (116 NSF), Room 551500 (121 NSF), Room 510400 (81 NSF), Room 520700 (53 NSF), Room 572001 (72 NSF), Room 580705 (265 NSF), Room 590901 (106 NSF), Room 500700 (765 NSF), Room 572103 (120 NSF), Room 500500 (93 NSF), Room 550000 (625 NSF), Room 551700 (134 NSF), Room 560300 (84 NSF), Room 57002S (427 NSF), Room 560200 (140 NSF), Room 591002E (146 NSF), Room 50002N (792 NSF), Room 51001W (760 NSF), Room 520092 (76 NSF), Room 53000E (443 NSF), Room 510300 (116 NSF), Room 540093 (70 NSF), Room 560110 (153 NSF), Room 561900 (343 NSF), Room 580401 (72 NSF), Room 590107 (154 NSF), Room 572101 (93 NSF), Room 591100 (341 NSF), Room 540600 (916 NSF), Room 550094 (176 NSF), Room 552500 (105 NSF), Room 570105 (181 NSF), Room 540002 (269 NSF), Room

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

551000 (337 NSF), Room 591901 (72 NSF), Room 501100 (695 NSF), Room 510500 (120 NSF), Room 550003 (235 NSF), Room 511100 (1185 NSF), Room 521400 (422 NSF), Room 570092 (73 NSF), Room 572104 (17 NSF), Room 511000 (643 NSF), Room 521300 (31 NSF), Room 572206 (132 NSF), Room 581001 (217 NSF), Room 570104 (436 NSF), Room 572205 (143 NSF), Room 581000 (57 NSF), Room 591900 (134 NSF), Room 552000 (225 NSF), Room 560402 (38 NSF), Room 52000S (730 NSF), Room 530000 (274 NSF), Room 532700 (116 NSF), Room 550602 (42 NSF), Room 550093 (72 NSF), Room 552400 (29 NSF), Room 590103 (265 NSF), Room 510004 (23 NSF), Room 520002 (419 NSF), Room 522501 (74 NSF), Room 500013 (306 NSF), Room 510009 (137 NSF), Room 532400 (37 NSF), Room 550400 (84 NSF), Room 580094 (176 NSF), Room 590094 (176 NSF), Room 560106 (125 NSF), Room 580200 (140 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$7,742,458 in deficiencies (Year 1) and \$9,822,294 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$7,742,458 in deficiencies (Year 1) and \$9,822,294 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

3.022 Renovating Building Number - 6, Building Name - WOLFSON CAMPUS 6 (115 SS), (14169 NSF) 671,074

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 610700 (110 NSF), Room 610300 (76 NSF), Room 640091 (65 NSF), Room 610100 (105 NSF), Room 640003 (163 NSF), Room 610101 (59 NSF), Room 611500 (44 NSF), Room 620601 (111 NSF), Room 630400 (100 NSF), Room 630091 (77 NSF), Room 640004 (161 NSF), Room 610200 (181 NSF), Room 64000E (417 NSF), Room 611100 (541 NSF), Room 611200 (121 NSF), Room 630200 (81 NSF), Room 630003 (171 NSF), Room 63000S (266 NSF), Room 620003 (153 NSF), Room 62000S (284 NSF), Room 611300 (39 NSF), Room 610000 (218 NSF), Room 610004 (161 NSF), Room 640001 (122 NSF), Room 611000 (130 NSF), Room 611400 (39 NSF), Room 610091 (79 NSF), Room 640002 (222 NSF), Room 620100 (77 NSF), Room 620500 (83 NSF), Room 620004 (160 NSF), Room 630100 (77 NSF), Room 620002 (71 NSF), Room 63000N (687 NSF), Room 630600 (55 NSF), Room 610800 (135 NSF), Room 610400 (158 NSF), Room 640100 (55 NSF), Room 610600 (158 NSF), Room 640300 (361 NSF), Room 60000R (1 NSF), Room 630500 (112 NSF), Room 620400 (52 NSF), Room 620200 (81 NSF), Room 610003 (129 NSF), Room 640000 (1924 NSF), Room 630401 (83 NSF), Room 630004 (160 NSF), Room 620001 (70 NSF), Room 610900 (50 NSF), Room 630900 (846 NSF), Room 620300 (77 NSF), Room 610500 (82 NSF), Room 640200 (95 NSF), Room 630300 (52 NSF), Room 620600 (465 NSF), Room 620091 (77 NSF), Room 62000W (351 NSF), Room 610001 (40 NSF), Room 630800 (814 NSF), Room 62000N (296 NSF), Room 610002 (39 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$455,862 in deficiencies (Year 1) and \$215,212 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$455,862 in deficiencies (Year 1) and \$215,212 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

3.023 Renovating Building Number - 7, Building Name - WOLFSON CAMPUS 7 ETC (323 SS), (799213 NSF) 949,158

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 7A0005 (207 NSF), Room 7A3500 (634 NSF), Room 7A8200 (299 NSF), Room 7E0005 (207 NSF), Room 7H0094 (83 NSF), Room 7L0003 (266 NSF), Room 7K0092 (84 NSF), Room 7A0004 (199 NSF), Room 7K0400 (341 NSF), Room 7A3100 (167 NSF), Room 7A3000 (353 NSF), Room 7A7300 (270 NSF), Room 7D0095 (90 NSF), Room 7G0300 (835 NSF), Room 7A0092 (84 NSF), Room 7A3800 (672 NSF), Room 7A3400 (527 NSF), Room 7A8100 (237 NSF), Room 7E0004 (199 NSF), Room 7H0093 (84 NSF), Room 7A0094 (83 NSF), Room 7A4000 (427 NSF), Room 7A7400 (4109 NSF), Room 7D0096 (92 NSF), Room 7H0000 (67745 NSF), Room 7K0093 (84 NSF), Room 7A0600 (802 NSF), Room 7A5200 (129 NSF), Room 7B0003 (186 NSF), Room 7E0092 (84 NSF), Room 7H0100 (253 NSF), Room 7L0091 (84 NSF), Room 7A4900 (28 NSF), Room 7B0300 (475 NSF), Room 7B0005 (207 NSF), Room 7E0094 (83 NSF), Room 7H0300 (836 NSF), Room 7L0093 (84 NSF), Room 7A5700 (168 NSF), Room 7C0092 (84 NSF), Room 7C0003 (186 NSF), Room 7F0092 (84 NSF), Room 7I0100 (253 NSF), Room 7A041N (1102 NSF), Room 7B0095 (90 NSF), Room 7E0300 (834 NSF), Room 7F0004 (199 NSF), Room 7I0094 (83 NSF), Room 7M0400 (182 NSF), Room 7A0903 (599 NSF), Room 7C0200 (117 NSF), Room 7G0004 (199 NSF), Room 7F0100 (253 NSF), Room 7J0003 (186 NSF), Room 7A0200 (117 NSF), Room 7A4400 (33 NSF), Room 7G0000 (68525 NSF), Room 7J0091 (84 NSF), Room 7I0005 (207 NSF), Room 7L0200 (117 NSF), Room 7A1801 (337 NSF), Room 7A6300 (280 NSF), Room 7J0092 (84 NSF), Room 7A2600 (518 NSF), Room 7J0094 (83 NSF), Room 7A1700 (1272 NSF), Room 7A6000 (118 NSF), Room 7C0095 (49 NSF), Room 7A2800 (1969 NSF), Room 7A7100 (30 NSF), Room 7A1701 (392 NSF), Room 7A6100 (118 NSF), Room 7C0096 (50 NSF), Room 7G0001 (179 NSF), Room 7A5100 (122 NSF), Room 7C0001 (179 NSF), Room 7A7000 (241 NSF), Room 7D0092 (84 NSF), Room 7G0096 (92 NSF), Room 7K0004 (199 NSF), Room 7C0093 (84 NSF), Room 7F0200 (117 NSF), Room 7D0093 (84 NSF), Room 7G0100 (253 NSF), Room 7K0005 (207 NSF), Room 7A0500 (420 NSF), Room 7G0005 (207 NSF), Room 7J0095 (90 NSF), Room 7F0091 (84 NSF), Room 7I0096 (92 NSF), Room 7A1000 (115 NSF), Room 7A5800 (118 NSF), Room 7K0003 (598 NSF), Room 7A0100 (258

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NSF), Room 7J0004 (199 NSF), Room 7A1900 (1124 NSF), Room 7A6301 (25 NSF), Room 7C0300 (835 NSF), Room 7L0096 (92 NSF), Room 7A1800 (966 NSF), Room 7A2500 (270 NSF), Room 7A6900 (29 NSF), Room 7D0091 (84 NSF), Room 7G0095 (90 NSF), Room 7A0091 (84 NSF), Room 7A3700 (412 NSF), Room 7A4200 (36 NSF), Room 7B0093 (84 NSF), Room 7E0100 (253 NSF), Room 7I0003 (186 NSF), Room 7A2000 (30 NSF), Room 7A6400 (798 NSF), Room 7A6200 (118 NSF), Room 7C0100 (253 NSF), Room 7G0003 (186 NSF), Room 7J0093 (84 NSF), Room 7A5400 (114 NSF), Room 7C0005 (207 NSF), Room 7B0001 (236 NSF), Room 7E0091 (84 NSF), Room 7H0096 (52 NSF), Room 7L0005 (207 NSF), Room 7D0001 (179 NSF), Room 7G0091 (84 NSF), Room 7D0000 (67600 NSF), Room 7G0006 (5950 NSF), Room 7J0096 (92 NSF), Room 7A0800 (95 NSF), Room 7E0096 (92 NSF), Room 7I0001 (179 NSF), Room 7F0094 (83 NSF), Room 7I0300 (835 NSF), Room 7A2100 (29 NSF), Room 7A6500 (951 NSF), Room 7F0096 (92 NSF), Room 7J0001 (179 NSF), Room 7J0100 (253 NSF), Room 7A0096 (92 NSF), Room 7A4100 (36 NSF), Room 7B0092 (84 NSF), Room 7J0300 (836 NSF), Room 7A0000 (19517 NSF), Room 7L0095 (90 NSF), Room 7A0902 (596 NSF), Room 7A5600 (122 NSF), Room 7C0091 (84 NSF), Room 7K0096 (92 NSF), Room 7A0002 (14750 NSF), Room 7A2300 (30 NSF), Room 7A6700 (523 NSF), Room 7D0004 (199 NSF), Room 7G0093 (84 NSF), Room 7K0200 (117 NSF), Room 7A0300 (2176 NSF), Room 7A3103 (54 NSF), Room 7A7700 (992 NSF), Room 7D0300 (835 NSF), Room 7H0004 (199 NSF), Room 7L0400 (341 NSF), Room 7A0700 (893 NSF), Room 7A3200 (618 NSF), Room 7A7900 (143 NSF), Room 7E0001 (179 NSF), Room 7H0091 (84 NSF), Room 7A041S (1042 NSF), Room 7A5000 (130 NSF), Room 7A4600 (106 NSF), Room 7B0096 (92 NSF), Room 7F0000 (67798 NSF), Room 7I0091 (84 NSF), Room 7A3900 (612 NSF), Room 7B0004 (199 NSF), Room 7A5300 (129 NSF), Room 7C0004 (155 NSF), Room 7F0093 (84 NSF), Room 7I0200 (117 NSF), Room 7A3600 (293 NSF), Room 7B0000 (58941 NSF), Room 7C0000 (65660 NSF), Room 7F0005 (207 NSF), Room 7I0095 (90 NSF), Room 7A0093 (84 NSF), Room 7A5500 (119 NSF), Room 7C0006 (6162 NSF), Room 7E0093 (84 NSF), Room 7H0200 (117 NSF), Room 7L0092 (84 NSF), Room 7A0006 (7884 NSF), Room 7D0200 (117 NSF), Room 7H0003 (186 NSF), Room 7E0006 (5173 NSF), Room 7H0095 (90 NSF), Room 7L0004 (199 NSF), Room 7A0900 (2987 NSF), Room 7E0095 (90 NSF), Room 7I0000 (67520 NSF), Room 7F0095 (90 NSF), Room 7J0000 (67744 NSF), Room 7A3102 (433 NSF), Room 7A7600 (986 NSF), Room 7E0200 (117 NSF), Room 7I0004 (199 NSF), Room 7K0095 (90 NSF), Room 7A0095 (90 NSF), Room 7A4001 (65 NSF), Room 7B0091 (84 NSF), Room 7F0300 (835 NSF), Room 7J0005 (207 NSF), Room 7L0094 (83 NSF), Room 7A0101 (428 NSF), Room 7A4300 (36 NSF), Room 7B0094 (83 NSF), Room 7K0000 (67072 NSF), Room 7A2200 (242 NSF), Room 7L0100 (576 NSF), Room 7A1200 (43 NSF), Room 7A5900 (118 NSF), Room 7C0094 (83 NSF), Room 7A040S (608 NSF), Room 7A4801 (866 NSF), Room 7A2400 (19 NSF), Room 7A6800 (30 NSF), Room 7D0005 (207 NSF), Room 7G0094 (83 NSF), Room 7A2900 (136 NSF), Room 7A7200 (19 NSF), Room 7A6600 (491 NSF), Room 7D0003 (186 NSF), Room 7G0092 (84 NSF), Room 7J0200 (117 NSF), Room 7A7500 (562 NSF), Room 7D0100 (253 NSF), Room 7B0200 (117 NSF), Room 7F0003 (186 NSF), Room 7I0093 (84 NSF), Room 7M0100 (805 NSF), Room 7A8000 (136 NSF), Room 7E0003 (186 NSF), Room 7D0094 (83 NSF), Room 7G0200 (117 NSF), Room 7K0091 (84 NSF), Room 7A3101 (394 NSF), Room 7A780E (677 NSF), Room 7E0000 (67636 NSF), Room 7H0001 (179 NSF), Room 7K0094 (83 NSF), Room 7A0003 (186 NSF), Room 7A3300 (586 NSF), Room 7B0100 (238 NSF), Room 7F0001 (179 NSF), Room 7H0092 (84 NSF), Room 7K0300 (1021 NSF), Room 7A0001 (182 NSF), Room 7A3104 (54 NSF), Room 7I0092 (84 NSF), Room 7M0005 (199 NSF), Room 7H0005 (207 NSF), Room 7K0100 (244 NSF), Room 7A040N (2463 NSF), Room 7A4800 (628 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$39,186 in deficiencies (Year 1) and \$909,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$39,186 in deficiencies (Year 1) and \$909,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

3.024	Renovating Building Number - 8, Building Name - WOLFSON CAMPUS 8 (1311 SS), (115359 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 810004 (179 NSF), Room 820400 (51 NSF), Room 831901 (156 NSF), Room 850101 (152 NSF), Room 860102 (122 NSF), Room 8M0401 (182 NSF), Room 860501 (85 NSF), Room 8M1100 (101 NSF), Room 860700 (158 NSF), Room 810600 (1450 NSF), Room 810100 (1160 NSF), Room 821100 (953 NSF), Room 84000N (784 NSF), Room 850400 (391 NSF), Room 81000N (653 NSF), Room 820600 (139 NSF), Room 810703 (54 NSF), Room 821900 (55 NSF), Room 840401 (159 NSF), Room 851200 (118 NSF), Room 810091 (75 NSF), Room 820800 (528 NSF), Room 821600 (902 NSF), Room 840100 (993 NSF), Room 850900 (666 NSF), Room 860601 (87 NSF), Room 810092 (74 NSF), Room 820900 (976 NSF), Room 840002 (337 NSF), Room 850200 (515 NSF), Room 860104 (138 NSF), Room 8M0600 (297 NSF), Room 811400 (316 NSF), Room 830092 (74 NSF), Room 840004 (414 NSF), Room 850302 (27 NSF), Room 860300 (190 NSF), Room 8M0800 (523 NSF), Room 830091 (75 NSF), Room 841300 (2046 NSF), Room 84000C (1622 NSF), Room 85030A (1484 NSF), Room 860400 (146 NSF), Room 8M0900 (452 NSF), Room 85000S (1590 NSF), Room 860091 (75 NSF), Room 841400 (2895 NSF), Room 852200 (111 NSF), Room 861601 (156 NSF), Room 811300 (175 NSF), Room 860004 (355 NSF), Room 8M0091 (75 NSF), Room 852100 (111 NSF), Room 861600 (71 NSF), Room 820092 (74 NSF), Room 831600 (950 NSF), Room 870400 (46 NSF), Room 820093 (92 NSF), Room 8M0100 (49 NSF), Room 82000C (2944 NSF), Room 831300 (1015 NSF), Room 850003 (361 NSF), Room	1,551,854
-------	---	-----------

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

820004 (312 NSF), Room 831200 (1021 NSF), Room 812100 (711 NSF), Room 830700 (139 NSF), Room 842100 (225 NSF), Room 852700 (49 NSF), Room 831000 (907 NSF), Room 842400 (1316 NSF), Room 831700 (46 NSF), Room 850091 (75 NSF), Room 860092 (74 NSF), Room 8M0101 (174 NSF), Room 831801 (159 NSF), Room 850093 (56 NSF), Room 850002 (338 NSF), Room 860002 (338 NSF), Room 8M000N (863 NSF), Room 820002 (337 NSF), Room 840900 (385 NSF), Room 851700 (111 NSF), Room 852900 (54 NSF), Room 8M0002 (337 NSF), Room 810002 (337 NSF), Room 820200 (1300 NSF), Room 850800 (140 NSF), Room 860600 (86 NSF), Room 860100 (7206 NSF), Room 8M0300 (180 NSF), Room 810900 (1044 NSF), Room 830003 (361 NSF), Room 870200 (75 NSF), Room 811701 (66 NSF), Room 861300 (1374 NSF), Room 810500 (286 NSF), Room 821500 (890 NSF), Room 840093 (56 NSF), Room 820001 (568 NSF), Room 830900 (977 NSF), Room 811900 (480 NSF), Room 830500 (102 NSF), Room 851900 (141 NSF), Room 852501 (153 NSF), Room 830093 (92 NSF), Room 841401 (80 NSF), Room 830300 (1229 NSF), Room 841700 (102 NSF), Room 852402 (209 NSF), Room 870009 (98 NSF), Room 842000 (528 NSF), Room 852600 (2622 NSF), Room 842300 (441 NSF), Room 852801 (159 NSF), Room 8M0001 (512 NSF), Room 811500 (1424 NSF), Room 852000 (111 NSF), Room 861500 (100 NSF), Room 852300 (157 NSF), Room 861700 (56 NSF), Room 812000 (185 NSF), Room 830600 (141 NSF), Room 860603 (136 NSF), Room 811600 (366 NSF), Room 870300 (91 NSF), Room 811200 (250 NSF), Room 83000N (815 NSF), Room 841200 (174 NSF), Room 811000 (876 NSF), Room 830004 (355 NSF), Room 810701 (64 NSF), Room 821800 (53 NSF), Room 840300 (46 NSF), Room 851001 (124 NSF), Room 83000C (2837 NSF), Room 841100 (179 NSF), Room 830100 (1290 NSF), Room 841500 (161 NSF), Room 852400 (444 NSF), Room 861701 (154 NSF), Room 842500 (458 NSF), Room 852901 (151 NSF), Room 841000 (231 NSF), Room 851800 (84 NSF), Room 861400 (1032 NSF), Room 811100 (294 NSF), Room 851000 (914 NSF), Room 860602 (216 NSF), Room 851900 (74 NSF), Room 861401 (164 NSF), Room 820003 (361 NSF), Room 831100 (1006 NSF), Room 8M0093 (92 NSF), Room 810400 (153 NSF), Room 8M0004 (590 NSF), Room 810700 (242 NSF), Room 821700 (47 NSF), Room 840200 (388 NSF), Room 8M1400 (62 NSF), Room 81000E (1302 NSF), Room 820091 (75 NSF), Room 831500 (898 NSF), Room 85000N (669 NSF), Room 86000S (205 NSF), Room 8M0500 (227 NSF), Room 810800 (921 NSF), Room 821400 (879 NSF), Room 840092 (74 NSF), Room 850700 (135 NSF), Room 860504 (210 NSF), Room 810093 (92 NSF), Room 821000 (866 NSF), Room 820500 (102 NSF), Room 832000 (245 NSF), Room 850102 (153 NSF), Room 860103 (63 NSF), Room 811700 (566 NSF), Room 830200 (1300 NSF), Room 822000 (246 NSF), Room 840501 (156 NSF), Room 851400 (173 NSF), Room 861000 (38 NSF), Room 830002 (337 NSF), Room 840800 (239 NSF), Room 84000E (184 NSF), Room 85030B (1692 NSF), Room 860500 (78 NSF), Room 8M1000 (119 NSF), Room 831900 (56 NSF), Room 850100 (764 NSF), Room 841600 (51 NSF), Room 852401 (107 NSF), Room 870002 (373 NSF), Room 810802 (225 NSF), Room 840600 (685 NSF), Room 851500 (111 NSF), Room 851600 (111 NSF), Room 861200 (502 NSF), Room 810003 (236 NSF), Room 820300 (1235 NSF), Room 850600 (102 NSF), Room 860503 (144 NSF), Room 860101 (473 NSF), Room 8M0400 (982 NSF), Room 810801 (2172 NSF), Room 830001 (571 NSF), Room 851300 (117 NSF), Room 860800 (153 NSF), Room 861100 (150 NSF), Room 810300 (77 NSF), Room 821300 (948 NSF), Room 840091 (75 NSF), Room 860093 (92 NSF), Room 8M0201 (33 NSF), Room 8M1300 (383 NSF), Room 810704 (66 NSF), Room 821901 (156 NSF), Room 840500 (56 NSF), Room 870500 (67 NSF), Room 82000N (773 NSF), Room 810001 (679 NSF), Room 820100 (1291 NSF), Room 831800 (54 NSF), Room 850092 (74 NSF), Room 810200 (80 NSF), Room 821200 (1001 NSF), Room 812200 (113 NSF), Room 830800 (528 NSF), Room 842200 (968 NSF), Room 852800 (57 NSF), Room 81000W (343 NSF), Room 820700 (136 NSF), Room 831400 (956 NSF), Room 850004 (372 NSF), Room 86000N (884 NSF), Room 8M0092 (74 NSF), Room 810702 (54 NSF), Room 821801 (158 NSF), Room 84000S (784 NSF), Room 850500 (50 NSF), Room 860502 (356 NSF), Room 8M1200 (405 NSF), Room 830400 (51 NSF), Room 841800 (142 NSF), Room 840003 (361 NSF), Room 850301 (22 NSF), Room 860200 (151 NSF), Room 8M0700 (229 NSF), Room 852500 (1653 NSF), Room 870100 (63 NSF), Room 840400 (54 NSF), Room 851100 (125 NSF), Room 860604 (396 NSF), Room 811800 (132 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$42,882 in deficiencies (Year 1) and \$1,508,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

Facilities condition assessment performed February 2020 identified \$42,882 in deficiencies (Year 1) and \$1,508,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
3.025	<p>Renovating Building Number - 9, Building Name - CULINARY ARTS INSTIT (82 SS), (32022 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 911201 (59 NSF), Room 940093 (105 NSF), Room 960901 (63 NSF), Room 911300 (55 NSF), Room 940100 (897 NSF), Room 961000 (78 NSF), Room 940200 (805 NSF), Room 970001 (214 NSF), Room 911500 (120 NSF), Room 940300 (227 NSF), Room 970002 (214 NSF), Room 940500 (22 NSF), Room 97000E (62 NSF), Room 92000C (656 NSF), Room 940600 (63 NSF), Room 970091 (77 NSF), Room 911400 (37 NSF), Room 940700 (108 NSF), Room 95000C (798 NSF), Room 970092 (75 NSF), Room 920091 (77 NSF), Room 940800 (51 NSF), Room 970093 (105 NSF), Room 920002 (248 NSF), Room 940901 (57 NSF), Room 970100 (1627 NSF), Room 920100 (117 NSF), Room 941000 (78 NSF), Room 970101 (61 NSF), Room 92000E (63 NSF), Room 950001 (214 NSF), Room 970200 (227 NSF), Room 920103 (225 NSF), Room 95000C (798 NSF), Room 970400 (22 NSF), Room 920093 (110 NSF), Room 950002 (214 NSF), Room 970300 (28 NSF), Room 920200 (853 NSF), Room 95000E (62 NSF), Room 970500 (63 NSF), Room 920101 (163 NSF), Room 950091 (77 NSF), Room 970600 (58 NSF), Room 920092 (75 NSF), Room 940900 (70 NSF), Room 970094 (16 NSF), Room 920102 (129 NSF), Room 950092 (75 NSF), Room 970700 (70 NSF), Room 920500 (108 NSF), Room 950093 (105 NSF), Room 970701 (63 NSF), Room 920300 (226 NSF), Room 950100 (920 NSF), Room 970800 (108 NSF), Room 920600 (65 NSF), Room 950200 (226 NSF), Room 970900 (78 NSF), Room 920400 (113 NSF), Room 950300 (204 NSF), Room 98000C (375 NSF), Room 920900 (85 NSF), Room 950301 (82 NSF), Room 98001E (183 NSF), Room 920501 (48 NSF), Room 950302 (66 NSF), Room 98002E (63 NSF), Room 930002 (214 NSF), Room 950303 (46 NSF), Room 980091 (77 NSF), Room 920800 (47 NSF), Room 950500 (28 NSF), Room 980093 (98 NSF), Room 93000C (842 NSF), Room 950400 (226 NSF), Room 980092 (75 NSF), Room 930001 (214 NSF), Room 930091 (77 NSF), Room 950600 (22 NSF), Room 980094 (16 NSF), Room 910002 (213 NSF), Room 930092 (75 NSF), Room 93000E (61 NSF), Room 980100 (1430 NSF), Room 91000C (95 NSF), Room 930093 (105 NSF), Room 950800 (387 NSF), Room 980200 (143 NSF), Room 910001 (226 NSF), Room 930100 (1641 NSF), Room 960001 (214 NSF), Room 980300 (355 NSF), Room 910091 (76 NSF), Room 930200 (226 NSF), Room 950700 (63 NSF), Room 980400 (227 NSF), Room 910092 (75 NSF), Room 930300 (29 NSF), Room 96000C (815 NSF), Room 980500 (28 NSF), Room 91000E (218 NSF), Room 930400 (22 NSF), Room 96000E (61 NSF), Room 980600 (22 NSF), Room 910100 (438 NSF), Room 930500 (63 NSF), Room 960002 (214 NSF), Room 980700 (68 NSF), Room 910200 (720 NSF), Room 930600 (35 NSF), Room 960092 (75 NSF), Room 980800 (35 NSF), Room 910093 (98 NSF), Room 930601 (151 NSF), Room 960093 (105 NSF), Room 980801 (247 NSF), Room 910400 (107 NSF), Room 930700 (39 NSF), Room 960091 (77 NSF), Room 980802 (47 NSF), Room 910500 (237 NSF), Room 930800 (34 NSF), Room 960200 (805 NSF), Room 980803 (19 NSF), Room 910300 (128 NSF), Room 930801 (151 NSF), Room 960300 (227 NSF), Room 980804 (22 NSF), Room 910700 (242 NSF), Room 940001 (214 NSF), Room 960100 (897 NSF), Room 990001 (206 NSF), Room 910800 (120 NSF), Room 940002 (214 NSF), Room 960500 (22 NSF), Room 990100 (95 NSF), Room 910600 (119 NSF), Room 94000C (816 NSF), Room 960600 (63 NSF), Room 990200 (182 NSF), Room 911000 (63 NSF), Room 94000E (60 NSF), Room 960400 (29 NSF), Room 990300 (166 NSF), Room 911100 (98 NSF), Room 940091 (77 NSF), Room 960800 (58 NSF), Room 911200 (46 NSF), Room 910900 (172 NSF), Room 960900 (70 NSF), Room 920700 (58 NSF), Room 950202 (66 NSF), Room 980002 (214 NSF), Room 920601 (63 NSF), Room 960700 (108 NSF), Room 950201 (82 NSF), Room 980001 (214 NSF), Room 920001 (254 NSF), Room 940400 (29 NSF), Room 97000C (811 NSF), Room 940092 (75 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$83,541 in deficiencies (Year 1) and \$1,832,049 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$83,541 in deficiencies (Year 1) and \$1,832,049 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p>	1,915,590

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

3.026	Renovating Building Number - 10, Building Name - FREEDOM TOWER (0 SS), (85435 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room A0002W (355 NSF), Room A10400 (356 NSF), Room A21001 (75 NSF), Room A50500 (154 NSF), Room AA1002 (61 NSF), Room A00300 (255 NSF), Room A60100 (154 NSF), Room AA1104 (288 NSF), Room A00500 (42 NSF), Room A10M93 (87 NSF), Room AA1106 (10 NSF), Room A00092 (52 NSF), Room A10500 (11261 NSF), Room A21200 (247 NSF), Room A10901 (19 NSF), Room A3001E (39 NSF), Room A00601 (222 NSF), Room A1100M (1177 NSF), Room A30092 (51 NSF), Room A60500 (129 NSF), Room A3002E (51 NSF), Room A60300 (45 NSF), Room A10700 (59 NSF), Room A21400 (48 NSF), Room A60003 (107 NSF), Room AA1101 (179 NSF), Room A50700 (10 NSF), Room AA1091 (49 NSF), Room A21100 (445 NSF), Room A50600 (304 NSF), Room AA1003 (107 NSF), Room A01000 (59 NSF), Room AA1191 (49 NSF), Room A00094 (52 NSF), Room A60900 (74 NSF), Room AA1202 (173 NSF), Room A00093 (88 NSF), Room A10600 (251 NSF), Room A00091 (51 NSF), Room A10401 (76 NSF), Room AA1092 (49 NSF), Room A00400 (62 NSF), Room A109M0 (255 NSF), Room A3001W (56 NSF), Room A113M0 (59 NSF), Room A30300 (165 NSF), Room A10001 (137 NSF), Room A20091 (51 NSF), Room A40100 (173 NSF), Room A80091 (49 NSF), Room AA1300 (301 NSF), Room A50800 (63 NSF), Room A2001E (348 NSF), Room A40003 (107 NSF), Room A70800 (10 NSF), Room AA140E (183 NSF), Room A60200 (132 NSF), Room AA1105 (258 NSF), Room A40800 (11 NSF), Room A90003 (107 NSF), Room AA1602 (668 NSF), Room A00005 (278 NSF), Room AA140W (178 NSF), Room A01900 (292 NSF), Room A50100 (282 NSF), Room A90600 (305 NSF), Room A02100 (466 NSF), Room A2002W (797 NSF), Room A1003W (146 NSF), Room A2021W (186 NSF), Room AA140S (181 NSF), Room A10005 (205 NSF), Room A20100 (312 NSF), Room A40500 (1644 NSF), Room A10100 (1037 NSF), Room A20701 (75 NSF), Room A02000 (155 NSF), Room A2001W (739 NSF), Room A40091 (48 NSF), Room A70900 (63 NSF), Room A40092 (50 NSF), Room A80003 (107 NSF), Room A2011W (215 NSF), Room A40600 (146 NSF), Room A80400 (10 NSF), Room AA1508 (39 NSF), Room A80300 (198 NSF), Room AA1507 (89 NSF), Room A30200 (811 NSF), Room A60800 (10 NSF), Room AA1201 (188 NSF), Room A00004 (122 NSF), Room AA140N (181 NSF), Room A1001W (277 NSF), Room A50092 (49 NSF), Room A90500 (284 NSF), Room A00003 (125 NSF), Room A100M4 (186 NSF), Room A00900 (342 NSF), Room A112M0 (47 NSF), Room A90400 (194 NSF), Room A01700 (94 NSF), Room A20004 (171 NSF), Room A31300 (74 NSF), Room A100M5 (257 NSF), Room A20700 (278 NSF), Room A00100 (11446 NSF), Room A10800 (19 NSF), Room A30003 (239 NSF), Room A60091 (49 NSF), Room A20602 (366 NSF), Room A50091 (49 NSF), Room A20200 (350 NSF), Room A40700 (66 NSF), Room A80500 (63 NSF), Room AA1601 (255 NSF), Room A70600 (154 NSF), Room AA1401 (649 NSF), Room A20600 (7909 NSF), Room A41200 (60 NSF), Room A90200 (134 NSF), Room A00600 (164 NSF), Room AA1102 (285 NSF), Room A1002W (146 NSF), Room A60400 (193 NSF), Room AA1107 (122 NSF), Room A01500 (1175 NSF), Room A118M0 (343 NSF), Room A00001 (287 NSF), Room A10093 (88 NSF), Room AA1207 (75 NSF), Room A01800 (177 NSF), Room A20005 (237 NSF), Room A31400 (198 NSF), Room A10M94 (51 NSF), Room A30091 (49 NSF), Room A01502 (30 NSF), Room A120M0 (172 NSF), Room A31100 (83 NSF), Room A70400 (194 NSF), Room A30800 (1614 NSF), Room A70200 (132 NSF), Room A20402 (79 NSF), Room A41100 (491 NSF), Room A90100 (151 NSF), Room A00006 (50 NSF), Room A70700 (303 NSF), Room AA1407 (85 NSF), Room A50200 (51 NSF), Room A90700 (10 NSF), Room A01400 (408 NSF), Room A117M0 (42 NSF), Room AA1209 (84 NSF), Room A10092 (51 NSF), Room AA1206 (224 NSF), Room A10002 (138 NSF), Room A20092 (54 NSF), Room A40200 (112 NSF), Room A10200 (1291 NSF), Room A20800 (2666 NSF), Room A00002 (218 NSF), Room A10094 (51 NSF), Room A20601 (260 NSF), Room A50003 (107 NSF), Room A30700 (184 NSF), Room A70100 (154 NSF), Room A119M0 (38 NSF), Room A30900 (1290 NSF), Room A70300 (45 NSF), Room AA1208 (143 NSF), Room A80092 (49 NSF), Room AA1495 (46 NSF), Room A40900 (131 NSF), Room A90091 (49 NSF), Room AA1608 (46 NSF), Room A01200 (598 NSF), Room A90300 (46 NSF), Room A01501 (30 NSF), Room A70091 (49 NSF), Room AA1204 (91 NSF), Room A0001N (230 NSF), Room A10201 (1502 NSF), Room A1004W (325 NSF), Room A20400 (1130 NSF), Room A90800 (63 NSF), Room A01600 (94 NSF), Room A20003 (145 NSF), Room A31200 (246 NSF), Room A115M0 (186 NSF), Room A30500 (246 NSF), Room A00800 (500 NSF), Room A111M0 (1033 NSF), Room A30100 (164 NSF), Room A60700 (303 NSF), Room A20900 (297 NSF), Room A50300 (206 NSF), Room A108M0 (1032 NSF), Room A30005 (182 NSF), Room A60092 (49 NSF), Room AA1103 (108 NSF), Room A70500 (134 NSF), Room AA1295 (46 NSF), Room A21000 (347 NSF), Room A50400 (129 NSF), Room AA1001 (1121 NSF), Room A10091 (51 NSF), Room AA1195 (46 NSF), Room A00200 (255 NSF), Room A90092 (49 NSF), Room A00700 (52 NSF), Room A110M1 (309 NSF), Room A30093 (102 NSF), Room A0001W (355 NSF), Room A10300 (487 NSF), Room A01100 (259 NSF), Room A114M0 (24 NSF), Room A30400 (97 NSF), Room A70003 (108 NSF), Room A20401 (81 NSF), Room A41000 (154 NSF), Room A116M0 (127 NSF), Room A30600 (142 NSF), Room A70092 (49 NSF), Room AA1205 (86 NSF), Room A60600 (154 NSF), Room AA1192 (49 NSF), Room A40300 (90 NSF), Room A80100 (790 NSF), Room AA1501 (550 NSF), Room A10004 (148 NSF), Room AA1203 (89 NSF), Room A01300 (122 NSF), Room A20094 (49 NSF), Room A40400 (382 NSF), Room A80200 (51 NSF), Room AA1502 (79 NSF), Room A10003 (115 NSF), Room A20093 (90 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$273,085 in deficiencies (Year 1) and \$2,534,087 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	2,807,172
-------	---	-----------

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
	Facilities condition assessment performed February 2020 identified \$273,085 in deficiencies (Year 1) and \$2,534,087 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	
3.027	Renovating Building Number - 11, Building Name - WOLFSON CAMPUS 11 (0 SS), (211256 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Other to Room B701S (223 NSF), Room B101S1 (223 NSF), Room B102EL (103 NSF), Room B102S2 (223 NSF), Room B702EL (103 NSF), Room B103EL (103 NSF), Room B10300 (258 NSF), Room B10000 (26908 NSF), Room B702S (193 NSF), Room B10400 (196 NSF), Room B10500 (175 NSF), Room B101EL (103 NSF), Room B10600 (4695 NSF), Room B10800 (234 NSF), Room B10900 (52 NSF), Room B20000 (32859 NSF), Room B302S (191 NSF), Room B203EL (103 NSF), Room B202S (191 NSF), Room B502S (191 NSF), Room B501S (223 NSF), Room B60000 (32787 NSF), Room B11000 (70 NSF), Room B601S (223 NSF), Room B301S (223 NSF), Room B201EL (103 NSF), Room B11300 (123 NSF), Room B50000 (32859 NSF), Room B40000 (32859 NSF), Room B602S (191 NSF), Room B501EL (103 NSF), Room B601EL (103 NSF), Room B401EL (103 NSF), Room B502EL (103 NSF), Room B701EL (103 NSF), Room B602EL (103 NSF), Room B302EL (103 NSF), Room B70000 (9580 NSF), Room B401S (223 NSF), Room B201S (223 NSF), Room B60500 (72 NSF), Room B402EL (103 NSF), Room B402S (191 NSF), Room B30000 (32859 NSF), Room B301EL (103 NSF), Room B10700 (90 NSF), Room B202EL (103 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$70,799 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$70,799 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	70,799
WOLFSON CAMPUS		Total : 401,383,343

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 4
Site Name: MEDICAL CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
4.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	64,613
4.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	1,249,240
4.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	945,564
4.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	2,000,000
MEDICAL CAMPUS		Total : 4,259,417

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
4.005	New Construction: Adding Vocational Labs (720 SS), (52350 NSF), (74358 GSF); Massage Therapy (3150 NSF), Diagnostic Medical Sonography (6000 NSF), Emergency Medical Tech. (10050 NSF), Dental Assisting (11550 NSF), Nursing (21600 NSF)	29,668,443

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
4.006	New Construction: Adding Student Services (4425 NSF), Physical Education (20950 NSF), Mechanical / Sanitation (4237 NSF), Library / Study (9177 NSF), Custodial (466 NSF), Circulation (43121 NSF), Auditorium / Exhibition (10570 NSF), Audiovisual (5190 NSF), Audiovisual (327 NSF)	55,802,544
4.007	Remodeling Building Number - 3, Building Name - CLIS : Adding AudioVisual (1500 NSF), (2131 GSF); Office (5600 NSF), (7954 GSF); Circulation (500 NSF), (710 GSF); Mechanical/Sanitation (500 NSF), (710 GSF); Office (5600 NSF), Circulation (500 NSF), Mechanical / Sanitation (500 NSF), Audiovisual (1500 NSF) and Removing (12 SS), (3986 NSF) Room 33070D (194 NSF), Room 33070C (271 NSF), Room 33070Y (124 NSF), Room 3307DA (354 NSF), Room 33070B (111 NSF), Room 33070X (127 NSF), Room 33070A (207 NSF), Room 33070E (272 NSF), Room 33070F (144 NSF), Room 33070H (301 NSF), Room 33070W (275 NSF), Room 33070Z (257 NSF), Room 330700 (1060 NSF), Room 33070G (289 NSF)	1,615,950
4.008	Renovating Building Number - 2, Building Name - MEDICAL CT BLDG 2 (55 SS), (1366 NSF) Apply Painting to Room 210100 (1366 NSF) Renovation Description:	181,678
4.009	Renovating Building Number - 1, Building Name - MEYERS HALL (320 SS), (127655 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 11003N (276 NSF), Room 112300 (198 NSF), Room 115105 (11 NSF), Room 119800 (108 NSF), Room 123204 (215 NSF), Room 13002C (766 NSF), Room 112301 (33 NSF), Room 115106 (96 NSF), Room 119900 (345 NSF), Room 140003 (274 NSF), Room 11004W (305 NSF), Room 112400 (107 NSF), Room 133301 (209 NSF), Room 136100 (102 NSF), Room 11003W (887 NSF), Room 13002W (570 NSF), Room 133500 (263 NSF), Room 140004 (278 NSF), Room 123205 (208 NSF), Room 13002E (285 NSF), Room 120003 (587 NSF), Room 120001 (231 NSF), Room 123400 (857 NSF), Room 13003W (1142 NSF), Room 115200 (85 NSF), Room 120000 (2428 NSF), Room 123300 (1182 NSF), Room 112600 (103 NSF), Room 115301 (106 NSF), Room 120002 (275 NSF), Room 110091 (104 NSF), Room 112500 (58 NSF), Room 115300 (436 NSF), Room 142500 (1410 NSF), Room 110100 (193 NSF), Room 112601 (86 NSF), Room 133501 (276 NSF), Room 140005 (259 NSF), Room 110092 (104 NSF), Room 130092 (106 NSF), Room 133503 (314 NSF), Room 142501 (633 NSF), Room 123401 (66 NSF), Room 130091 (106 NSF), Room 133502 (348 NSF), Room 120004 (259 NSF), Room 123600 (841 NSF), Room 130204 (478 NSF), Room 115302 (107 NSF), Room 120003 (264 NSF), Room 123500 (1356 NSF), Room 112800 (83 NSF), Room 115400 (212 NSF), Room 12001E (525 NSF), Room 110101 (174 NSF), Room 112700 (88 NSF), Room 115303 (157 NSF), Room 142600 (165 NSF), Room 110200 (142 NSF), Room 112900 (86 NSF), Room 133504 (105 NSF), Room 142502 (459 NSF), Room 110102 (147 NSF), Room 130215 (109 NSF), Room 133601 (99 NSF), Room 142700 (367 NSF), Room 123601 (121 NSF), Room 130213 (200 NSF), Room 133600 (269 NSF), Room 12002E (357 NSF), Room 123700 (442 NSF), Room 130217 (82 NSF), Room 115401 (45 NSF), Room 12001N (454 NSF), Room 123602 (110 NSF), Room 115500 (337 NSF), Room 12001W (968 NSF), Room 123603 (114 NSF), Room 110400 (491 NSF), Room 113100 (139 NSF), Room 115600 (343 NSF), Room 110500 (663 NSF), Room 113101 (72 NSF), Room 115700 (290 NSF), Room 133603 (328 NSF), Room 110300 (391 NSF), Room 113000 (84 NSF), Room 133604 (321 NSF), Room 110501 (16 NSF), Room 1132A (891 NSF), Room 130216 (136 NSF), Room 133602 (237 NSF), Room 145000 (2294 NSF), Room 130301 (106 NSF), Room 133700 (30 NSF), Room 110800 (200 NSF), Room 12002N (404 NSF), Room 123800 (340 NSF), Room 130300 (1829 NSF), Room 123804 (115 NSF), Room 130304 (144 NSF), Room 133703 (426 NSF), Room 115800 (73 NSF), Room 12002W (485 NSF), Room 123801 (82 NSF), Room 120091 (106 NSF), Room 123803 (106 NSF), Room 130303 (107 NSF), Room 1132D (897 NSF), Room 116001 (574 NSF), Room 120092 (106 NSF), Room 116002 (86 NSF), Room 120100 (927 NSF), Room 123805 (106 NSF), Room 110700 (191 NSF), Room 1132C (883 NSF), Room 116000 (450 NSF), Room 1132B (880 NSF), Room 115900 (410 NSF), Room 12003W (1100 NSF), Room 133702 (67 NSF), Room 110900 (106 NSF), Room 1132E (853 NSF), Room 111000 (208 NSF), Room 1132F (853 NSF), Room 116100 (496 NSF), Room 130305 (108 NSF), Room 133800 (709 NSF), Room 110600 (154 NSF), Room 133900 (435 NSF), Room 111100 (63 NSF), Room 1132G (888 NSF), Room 123802 (83 NSF), Room 130302 (220 NSF), Room 133701 (441 NSF), Room 130307 (108 NSF), Room 133901 (238 NSF), Room 111200 (197 NSF), Room 120101 (109 NSF), Room 123806 (97 NSF), Room 130306 (108 NSF), Room 123808 (88 NSF), Room 130308 (103 NSF), Room 135000 (59 NSF), Room 116200 (363 NSF), Room 120102 (108 NSF), Room 123807 (98 NSF), Room 120104 (83 NSF), Room 123809 (93 NSF), Room 130309 (1108 NSF), Room 113300 (79 NSF), Room 116300 (814 NSF), Room 120103 (144 NSF), Room 116601 (24 NSF), Room 120108 (145 NSF), Room 124101 (148 NSF), Room 111201 (173 NSF), Room 113400 (79 NSF), Room 116301 (28 NSF), Room 113800 (447 NSF), Room 116700 (94 NSF), Room 120109 (100 NSF), Room 135100 (221 NSF), Room 111303 (201 NSF), Room 113700 (64 NSF), Room 111302 (176 NSF), Room 113600 (184 NSF), Room 116600 (112 NSF), Room 130313 (109 NSF), Room 135300 (110 NSF), Room 111400 (96 NSF), Room 135201 (59 NSF), Room 111500 (662	16,978,115

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NSF), Room 113900 (1845 NSF), Room 125000 (61 NSF), Room 130314 (109 NSF), Room 135400 (1223 NSF), Room 130315 (212 NSF), Room 135500 (531 NSF), Room 111501 (168 NSF), Room 120107 (122 NSF), Room 124100 (973 NSF), Room 130312 (109 NSF), Room 125101 (45 NSF), Room 130400 (992 NSF), Room 135501 (132 NSF), Room 116800 (98 NSF), Room 120200 (4452 NSF), Room 125100 (189 NSF), Room 120202 (165 NSF), Room 125200 (196 NSF), Room 130401 (140 NSF), Room 114000 (310 NSF), Room 116900 (899 NSF), Room 120201 (162 NSF), Room 117101 (109 NSF), Room 120204 (178 NSF), Room 125300 (118 NSF), Room 111502 (112 NSF), Room 114100 (176 NSF), Room 117000 (107 NSF), Room 114202 (95 NSF), Room 117102 (122 NSF), Room 120300 (323 NSF), Room 135502 (151 NSF), Room 111504 (158 NSF), Room 114201 (95 NSF), Room 111503 (90 NSF), Room 114200 (390 NSF), Room 117100 (157 NSF), Room 132600 (65 NSF), Room 135504 (250 NSF), Room 111505 (88 NSF), Room 135503 (213 NSF), Room 111506 (87 NSF), Room 114203 (161 NSF), Room 125400 (1967 NSF), Room 132700 (224 NSF), Room 135505 (132 NSF), Room 132701 (41 NSF), Room 135506 (41 NSF), Room 111507 (165 NSF), Room 120203 (165 NSF), Room 125201 (46 NSF), Room 130405 (406 NSF), Room 125501 (100 NSF), Room 132800 (249 NSF), Room 135507 (166 NSF), Room 117103 (122 NSF), Room 120301 (162 NSF), Room 125500 (856 NSF), Room 117108 (149 NSF), Room 122800 (222 NSF), Room 125700 (1011 NSF), Room 114300 (122 NSF), Room 117104 (172 NSF), Room 120302 (198 NSF), Room 111513 (95 NSF), Room 114700 (56 NSF), Room 117500 (2581 NSF), Room 110000 (6664 NSF), Room 111511 (96 NSF), Room 114501 (34 NSF), Room 135704 (136 NSF), Room 111508 (208 NSF), Room 114400 (197 NSF), Room 133001 (77 NSF), Room 135702 (117 NSF), Room 110002 (275 NSF), Room 132801 (43 NSF), Room 135600 (316 NSF), Room 110003 (262 NSF), Room 122900 (99 NSF), Room 125900 (403 NSF), Room 133100 (492 NSF), Room 123000 (1537 NSF), Room 126000 (102 NSF), Room 133101 (31 NSF), Room 117105 (36 NSF), Room 122600 (60 NSF), Room 125502 (64 NSF), Room 115001 (24 NSF), Room 117502 (111 NSF), Room 123001 (136 NSF), Room 111514 (95 NSF), Room 115000 (156 NSF), Room 117501 (111 NSF), Room 11000E (486 NSF), Room 111516 (464 NSF), Room 115002 (123 NSF), Room 135800 (550 NSF), Room 110004 (259 NSF), Room 111515 (161 NSF), Room 133200 (2246 NSF), Room 136000 (449 NSF), Room 11001N (522 NSF), Room 130000 (2576 NSF), Room 133102 (122 NSF), Room 135900 (391 NSF), Room 123200 (370 NSF), Room 130004 (278 NSF), Room 133202 (102 NSF), Room 117503 (121 NSF), Room 123002 (144 NSF), Room 130001 (232 NSF), Room 115100 (255 NSF), Room 117504 (535 NSF), Room 123100 (838 NSF), Room 112000 (45 NSF), Room 115101 (18 NSF), Room 118000 (1496 NSF), Room 11001W (426 NSF), Room 112100 (62 NSF), Room 115102 (110 NSF), Room 136002 (193 NSF), Room 11000S (2589 NSF), Room 111517 (106 NSF), Room 133203 (240 NSF), Room 136003 (142 NSF), Room 11002N (133 NSF), Room 130003 (274 NSF), Room 133201 (225 NSF), Room 136001 (283 NSF), Room 123202 (454 NSF), Room 13001E (500 NSF), Room 133204 (190 NSF), Room 118001 (200 NSF), Room 123201 (84 NSF), Room 130005 (259 NSF), Room 114600 (122 NSF), Room 117109 (118 NSF), Room 122801 (42 NSF), Room 112200 (197 NSF), Room 115103 (106 NSF), Room 118002 (187 NSF), Room 11002W (531 NSF), Room 112201 (32 NSF), Room 115104 (50 NSF), Room 136004 (49 NSF), Room 110001 (228 NSF), Room 111512 (93 NSF), Room 133300 (783 NSF), Room 136005 (46 NSF), Room 111509 (157 NSF), Room 125800 (472 NSF), Room 133002 (861 NSF), Room 135703 (190 NSF), Room 125600 (1435 NSF), Room 132900 (109 NSF), Room 135700 (510 NSF), Room 118003 (26 NSF), Room 123203 (109 NSF), Room 13001W (829 NSF), Room 120105 (113 NSF), Room 123810 (82 NSF), Room 130310 (1190 NSF), Room 114401 (34 NSF), Room 117106 (127 NSF), Room 122700 (219 NSF), Room 117107 (244 NSF), Room 122701 (39 NSF), Room 125601 (112 NSF), Room 111300 (114 NSF), Room 113500 (742 NSF), Room 116400 (42 NSF), Room 113501 (195 NSF), Room 116500 (105 NSF), Room 120106 (83 NSF), Room 135101 (60 NSF), Room 111510 (97 NSF), Room 114500 (197 NSF), Room 123811 (105 NSF), Room 130311 (104 NSF), Room 135200 (228 NSF), Room 133000 (899 NSF), Room 135701 (214 NSF), Room 111301 (542 NSF) Renovation Description:

4.010 Renovating Building Number - 2, Building Name - MEDICAL CT BLDG 2 (0 SS), (497 NSF) Apply Electrical to Room 21002N (497 NSF) Renovation Description: 66,101

MEDICAL CAMPUS Total : 104,312,831

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 5
Site Name: HOMESTEAD CAMPUS

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
5.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	2,945,059
5.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	10,632,161
5.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	1,323,789
5.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	2,800,000
HOMESTEAD CAMPUS Total :		17,701,009

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
5.005	New Construction: Adding Non-Vocational Labs (325 SS), (17375 NSF), (24679 GSF); Vocational Labs (12 SS), (2525 NSF), (3587 GSF); Vocational Preparatory (7375 NSF), Agriculture Business (5000 NSF), Nursing (Four Year Programs) (5000 NSF), Aircraft Piloting & Navigation (2525 NSF)	11,277,735
5.006	New Construction: Adding Custodial (1969 NSF), Auditorium / Exhibition (1194 NSF), Audiovisual (2143 NSF), Audiovisual (2107 NSF)	4,201,071
5.007	New Construction: Adding Library / Study (13386 NSF)	7,586,187
5.008	New Construction: Adding Physical Education (17540 NSF)	9,940,287
5.009	New Construction: Adding Student Services (2747 NSF)	1,556,499
5.010	New Construction: Adding Support Services (4158 NSF), Support Services (2212 NSF)	3,609,753
5.011	New Construction: Adding Auditorium / Exhibition (10000 NSF), Library / Study (5500 NSF), Student Services (9300 NSF)	14,054,775
5.012	Remodeling Building Number - 4, Building Name - TECHNOLOGY/INFO CT : Adding Classrooms (12 SS), (315 NSF), (447 GSF); Classroom (315 NSF, 12 SSC) and Removing (0 SS), (30 NSF) Room D30101 (30 NSF)	62,842
5.013	Remodeling Building Number - 7, Building Name - CLASSROOM/LAB BLDG : Adding Classrooms (31 SS), (925 NSF), (1314 GSF); Classroom (925 NSF, 31 SSC) and Removing (19 SS), (2941 NSF) Room G11500 (2941 NSF)	586,729
5.014	Renovating Building Number - 7, Building Name - CLASSROOM/LAB BLDG (0 SS), (198 NSF) Apply HVAC Systems to Room G1000N (198 NSF) Renovation Description: Deferred Maintenance project HDM19001 HVAC upgrades in Lab Spaces Deferred Maintenance project HDM19001 HVAC upgrades in Lab Spaces	26,334
5.015	Renovating Building Number - 8, Building Name - PHYSICAL PLANT BLDG (0 SS), (105 NSF) Apply Other to Room H1000S (105 NSF) Renovation Description: Deferred Maintenance project HDM17003 that will replace and upgrade HVAC systems Deferred Maintenance project HDM17003 that will replace and upgrade HVAC systems	1

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
5.016	<p>Renovating Building Number - 8, Building Name - PHYSICAL PLANT BLDG (30 SS), (18495 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room H10601 (134 NSF), Room H11000 (333 NSF), Room H10900 (1446 NSF), Room H11300 (2530 NSF), Room H10701 (39 NSF), Room H11301 (52 NSF), Room H10800 (337 NSF), Room H2000C (775 NSF), Room H20201 (106 NSF), Room H20300 (883 NSF), Room H20202 (205 NSF), Room H20100 (80 NSF), Room H20700 (876 NSF), Room H10600 (919 NSF), Room H10200 (52 NSF), Room H20800 (2037 NSF), Room H10002 (184 NSF), Room H10500 (228 NSF), Room H20601 (39 NSF), Room H10300 (1203 NSF), Room H10100 (80 NSF), Room 05G RO (1 NSF), Room H10004 (78 NSF), Room H20203 (157 NSF), Room H10091 (96 NSF), Room H2000N (620 NSF), Room H11100 (214 NSF), Room H20600 (184 NSF), Room H1002C (586 NSF), Room H20003 (75 NSF), Room H10003 (43 NSF), Room H1000N (474 NSF), Room H20204 (130 NSF), Room H20091 (96 NSF), Room H10602 (298 NSF), Room H20001 (202 NSF), Room H10400 (118 NSF), Room H11200 (91 NSF), Room H20302 (38 NSF), Room H1001C (947 NSF), Room H10700 (184 NSF), Room H10001 (202 NSF), Room H2000S (227 NSF), Room H20200 (187 NSF), Room H20400 (118 NSF), Room H20500 (228 NSF), Room H20301 (363 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$281,406 in deficiencies (Year 1) and \$ in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$281,406 in deficiencies (Year 1) and \$ in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p>	4,566,838
5.017	<p>Renovating Building Number - 7, Building Name - CLASSROOM/LAB BLDG (786 SS), (49889 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room G10002 (228 NSF), Room G20800 (348 NSF), Room G10003 (228 NSF), Room G20801 (68 NSF), Room G10300 (835 NSF), Room G21500 (999 NSF), Room G11301 (67 NSF), Room G30091 (81 NSF), Room G10100 (176 NSF), Room G21400 (1394 NSF), Room G1000N (198 NSF), Room G20900 (275 NSF), Room G10091 (81 NSF), Room G21300 (348 NSF), Room G11800 (59 NSF), Room G30800 (348 NSF), Room G11300 (348 NSF), Room G3003S (224 NSF), Room G20500 (835 NSF), Room G31601 (330 NSF), Room G2001S (3750 NSF), Room G31200 (73 NSF), Room G11900 (650 NSF), Room G30801 (68 NSF), Room G20091 (81 NSF), Room G31400 (1251 NSF), Room G11200 (73 NSF), Room G3002S (226 NSF), Room G2003S (224 NSF), Room G31301 (69 NSF), Room G11502 (445 NSF), Room G30300 (835 NSF), Room G10900 (275 NSF), Room G30003 (202 NSF), Room G11700 (81 NSF), Room G30700 (835 NSF), Room G20002 (210 NSF), Room G30900 (275 NSF), Room G2000N (110 NSF), Room G31100 (72 NSF), Room G11000 (41 NSF), Room G3000N (61 NSF), Room G11100 (72 NSF), Room G3000S (3713 NSF), Room G11400 (172 NSF), Room G30092 (63 NSF), Room G11501 (302 NSF), Room G30200 (829 NSF), Room G11600 (66 NSF), Room G30600 (835 NSF), Room G31700 (66 NSF), Room G10001 (261 NSF), Room G1003S (224 NSF), Room G21200 (73 NSF), Room G10600 (835 NSF), Room G21601 (330 NSF), Room G20200 (829 NSF), Room G31501 (294 NSF), Room G20003 (202 NSF), Room G31000 (41 NSF), Room 05G AR (1 NSF), Room G20600 (835 NSF), Room G1002S (229 NSF), Room G21100 (72 NSF), Room G20700 (835 NSF), Room G31800 (81 NSF), Room G11500 (2941 NSF), Room G30100 (169 NSF), Room G10092 (62 NSF), Room G21301 (69 NSF), Room G2002S (226 NSF), Room G31300 (348 NSF), Room G11503 (336 NSF), Room G30400 (835 NSF), Room G20092 (63 NSF), Room G31401 (326 NSF), Room G10200 (841 NSF), Room G21401 (330 NSF), Room G10500 (835 NSF), Room G21600 (1393 NSF), Room G10801 (67 NSF), Room G30002 (202 NSF), Room G20100 (176 NSF), Room G31500 (1308 NSF), Room G10400 (835 NSF), Room G21501 (585 NSF), Room G10700 (835 NSF), Room G21700 (66 NSF), Room G20300 (835 NSF), Room G31502 (252 NSF), Room G10800 (348 NSF), Room G21800 (81 NSF), Room G20400 (835 NSF), Room G31600 (1248 NSF), Room G1001S (3595 NSF), Room G21000 (41 NSF), Room G11504 (334 NSF), Room G30500 (835 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$1,000,256 in deficiencies (Year 1) and \$4,995,737 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$1,000,256 in deficiencies (Year 1) and \$4,995,737 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p>	5,995,993

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
5.018	Renovating Building Number - 6, Building Name - AVIATION TRAINING (265 SS), (42421 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room F11500 (84 NSF), Room F20000 (628 NSF), Room F11700 (263 NSF), Room F11301 (564 NSF), Room F11302 (567 NSF), Room F20002 (288 NSF), Room F10002 (106 NSF), Room F20400 (935 NSF), Room F20001 (251 NSF), Room F1001N (597 NSF), Room F21000 (401 NSF), Room F20800 (260 NSF), Room F10100 (313 NSF), Room F21400 (360 NSF), Room F2003E (563 NSF), Room F10004 (66 NSF), Room F20091 (106 NSF), Room F10201 (105 NSF), Room F21600 (379 NSF), Room F10301 (139 NSF), Room F21900 (727 NSF), Room F10303 (56 NSF), Room F1000W (2685 NSF), Room F11000 (1059 NSF), Room F10700 (350 NSF), Room F1001E (1848 NSF), Room F20900 (26 NSF), Room F1002E (1882 NSF), Room F20600 (2101 NSF), Room F11100 (248 NSF), Room F10900 (840 NSF), Room F1000S (3204 NSF), Room F20700 (261 NSF), Room F10500 (27 NSF), Room F22100 (379 NSF), Room F20003 (170 NSF), Room 05F (1 NSF), Room F20100 (953 NSF), Room F10800 (376 NSF), Room F10001 (251 NSF), Room F21100 (350 NSF), Room F10304 (57 NSF), Room F22200 (1259 NSF), Room F10202 (184 NSF), Room F21700 (397 NSF), Room F11300 (1994 NSF), Room F11200 (116 NSF), Room F21500 (569 NSF), Room F10600 (376 NSF), Room F11800 (263 NSF), Room F10000 (557 NSF), Room F20200 (938 NSF), Room F20300 (937 NSF), Room F1003E (490 NSF), Room F21200 (416 NSF), Room F10091 (105 NSF), Room F21300 (400 NSF), Room F10400 (124 NSF), Room F10200 (993 NSF), Room F10302 (519 NSF), Room F22000 (171 NSF), Room F10300 (1096 NSF), Room F21800 (890 NSF), Room F11600 (74 NSF), Room F20004 (238 NSF), Room F2001E (1227 NSF), Room F11400 (263 NSF), Room F2002E (514 NSF), Room F10003 (130 NSF), Room F20500 (945 NSF), Room F22300 (1410 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$568,449 in deficiencies (Year 1) and \$5,300,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovate over next 5 years. Facilities condition assessment performed February 2020 identified \$568,449 in deficiencies (Year 1) and \$5,300,972 in life cycle renewal (Years 2-5) to repair, replace and/or renovate over next 5 years.	5,869,421
5.019	Renovating Building Number - 1, Building Name - ADMINISTRATION BLDG (81 SS), (25793 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room A11602 (138 NSF), Room A23200 (360 NSF), Room A11601 (76 NSF), Room A23100 (125 NSF), Room A1000E (280 NSF), Room A11900 (968 NSF), Room A23306 (126 NSF), Room A21000 (522 NSF), Room A23305 (129 NSF), Room A1002W (288 NSF), Room A20000 (178 NSF), Room A1000R (1 NSF), Room A12000 (149 NSF), Room A20601 (99 NSF), Room A10401 (58 NSF), Room A2000W (467 NSF), Room A10200 (47 NSF), Room A2000E (555 NSF), Room A10607 (85 NSF), Room A20600 (456 NSF), Room A10608 (88 NSF), Room A21100 (126 NSF), Room A10610 (96 NSF), Room A21201 (38 NSF), Room A10605 (148 NSF), Room A21900 (126 NSF), Room A11000 (131 NSF), Room A21700 (126 NSF), Room A11202 (156 NSF), Room A22400 (156 NSF), Room A10604 (269 NSF), Room A22300 (375 NSF), Room A11001 (59 NSF), Room A21800 (127 NSF), Room A10602 (115 NSF), Room A20400 (360 NSF), Room A11002 (53 NSF), Room A22600 (186 NSF), Room A10901 (35 NSF), Room A21600 (491 NSF), Room A10700 (122 NSF), Room A21400 (118 NSF), Room A11201 (127 NSF), Room A2000S (382 NSF), Room A11603 (60 NSF), Room A23300 (561 NSF), Room A10606 (127 NSF), Room A20800 (914 NSF), Room A11203 (170 NSF), Room A23000 (465 NSF), Room A10603 (65 NSF), Room A20500 (131 NSF), Room A11300 (98 NSF), Room A22700 (130 NSF), Room A10400 (203 NSF), Room A11501 (45 NSF), Room A10101 (47 NSF), Room A2000C (196 NSF), Room A10800 (228 NSF), Room A21401 (45 NSF), Room A11402 (61 NSF), Room A1000C (587 NSF), Room A10000 (2261 NSF), Room A11700 (103 NSF), Room A23301 (510 NSF), Room A10900 (179 NSF), Room A21402 (74 NSF), Room A20001 (189 NSF), Room A23002 (302 NSF), Room A11600 (595 NSF), Room A23003 (221 NSF), Room A10500 (70 NSF), Room A20091 (57 NSF), Room A22900 (131 NSF), Room A11802 (78 NSF), Room A23304 (125 NSF), Room A11400 (1465 NSF), Room A22800 (165 NSF), Room A10091 (47 NSF), Room A10300 (74 NSF), Room A10609 (97 NSF), Room A21200 (113 NSF), Room A11200 (265 NSF), Room A22200 (739 NSF), Room A11401 (145 NSF), Room A22100 (125 NSF), Room A10100 (178 NSF), Room A20002 (177 NSF), Room A1001W (234 NSF), Room A12100 (159 NSF), Room A23307 (130 NSF), Room A11801 (127 NSF), Room A2000N (327 NSF), Room A10001 (155 NSF), Room A11800 (721 NSF), Room A23302 (129 NSF), Room A11100 (112 NSF), Room A23303 (129 NSF), Room A10600 (1136 NSF), Room A20200 (323 NSF), Room A11500 (183 NSF), Room A23001 (64 NSF), Room A10002 (129 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$995,499 in deficiencies (Year 1) and \$1,315,361 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$995,499 in deficiencies (Year 1) and \$1,315,361 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	2,310,860

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
5.020	<p>Renovating Building Number - 2, Building Name - FACULTY/ADMIN BLDG (0 SS), (25118 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room B1004C (109 NSF), Room B14100 (122 NSF), Room B21600 (120 NSF), Room B1005E (102 NSF), Room B14300 (117 NSF), Room B21800 (113 NSF), Room B10200 (103 NSF), Room B14500 (97 NSF), Room B22000 (97 NSF), Room B12100 (526 NSF), Room B2003C (89 NSF), Room B11700 (346 NSF), Room B10300 (115 NSF), Room B14600 (40 NSF), Room B22100 (43 NSF), Room B22400 (110 NSF), Room B1003C (119 NSF), Room B13900 (117 NSF), Room B10100 (380 NSF), Room B14401 (42 NSF), Room B21901 (42 NSF), Room B20800 (217 NSF), Room B10003 (237 NSF), Room B12900 (50 NSF), Room B2002C (142 NSF), Room B10700 (124 NSF), Room B14900 (228 NSF), Room B23100 (116 NSF), Room B12600 (119 NSF), Room B20300 (112 NSF), Room B21402 (94 NSF), Room B1001C (898 NSF), Room B13100 (116 NSF), Room B2002S (191 NSF), Room B10001 (200 NSF), Room B12700 (117 NSF), Room B20600 (218 NSF), Room B11300 (156 NSF), Room B2000R (1 NSF), Room B21100 (332 NSF), Room B1002S (309 NSF), Room B13700 (50 NSF), Room B12400 (87 NSF), Room B20091 (76 NSF), Room B11900 (117 NSF), Room B1002E (149 NSF), Room B13600 (547 NSF), Room B21300 (294 NSF), Room B20400 (112 NSF), Room B1001W (141 NSF), Room B13400 (177 NSF), Room B2004E (48 NSF), Room B11000 (125 NSF), Room B20001 (195 NSF), Room B21400 (605 NSF), Room B12401 (91 NSF), Room B20100 (115 NSF), Room B21700 (145 NSF), Room B12000 (118 NSF), Room B2002W (187 NSF), Room B11800 (119 NSF), Room B2002E (135 NSF), Room B12300 (117 NSF), Room B14800 (172 NSF), Room B22300 (170 NSF), Room B1000N (277 NSF), Room B22700 (114 NSF), Room B1004E (136 NSF), Room B14200 (121 NSF), Room B13500 (174 NSF), Room B21200 (421 NSF), Room B11100 (113 NSF), Room B12500 (178 NSF), Room B20200 (327 NSF), Room B10500 (112 NSF), Room B15001 (150 NSF), Room B22600 (145 NSF), Room B10600 (111 NSF), Room B13000 (468 NSF), Room B20700 (287 NSF), Room B1002C (169 NSF), Room B2001E (137 NSF), Room B11600 (213 NSF), Room B2001W (202 NSF), Room B20002 (230 NSF), Room B22800 (227 NSF), Room B10900 (114 NSF), Room B12101 (140 NSF), Room B2003E (101 NSF), Room B10002 (229 NSF), Room B14801 (43 NSF), Room B22301 (43 NSF), Room B11401 (94 NSF), Room B13200 (117 NSF), Room B20900 (415 NSF), Room B12200 (109 NSF), Room B1001S (857 NSF), Room B13300 (119 NSF), Room B21000 (222 NSF), Room B21900 (207 NSF), Room B11200 (531 NSF), Room B20003 (237 NSF), Room B12800 (116 NSF), Room B20500 (239 NSF), Room B1001E (112 NSF), Room B22500 (141 NSF), Room B11500 (480 NSF), Room B2001S (782 NSF), Room B2004C (86 NSF), Room B10091 (78 NSF), Room B14400 (178 NSF), Room B10400 (224 NSF), Room B14700 (65 NSF), Room B22200 (65 NSF), Room B22900 (113 NSF), Room B10800 (115 NSF), Room B15000 (245 NSF), Room B11201 (125 NSF), Room B2000N (687 NSF), Room B23000 (145 NSF), Room B1003E (137 NSF), Room B14000 (120 NSF), Room B21500 (319 NSF), Room B1002W (152 NSF), Room B13800 (116 NSF), Room B21401 (145 NSF), Room B11400 (83 NSF), Room B2001C (1032 NSF), Room B23200 (110 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$245,572 in deficiencies (Year 1) and \$2,024,303 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p> <p>Facilities condition assessment performed February 2020 identified \$245,572 in deficiencies (Year 1) and \$2,024,303 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.</p>	2,269,875

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
5.021	Renovating Building Number - 4, Building Name - TECHNOLOGY/INFO CT (396 SS), (58457 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room D11305 (147 NSF), Room D20706 (102 NSF), Room D11306 (140 NSF), Room D20800 (409 NSF), Room D10003 (95 NSF), Room D11310 (141 NSF), Room D1000C (1853 NSF), Room D11403 (194 NSF), Room D30004 (309 NSF), Room D11302 (216 NSF), Room D20703 (112 NSF), Room D20004 (296 NSF), Room D3030C (127 NSF), Room D10503 (47 NSF), Room D2000N (480 NSF), Room D30500 (113 NSF), Room D30300 (304 NSF), Room D21100 (256 NSF), Room D20302 (107 NSF), Room D31301 (39 NSF), Room D10510 (502 NSF), Room D2001C (354 NSF), Room D30700 (1028 NSF), Room D10501 (145 NSF), Room D11900 (82 NSF), Room D30101 (30 NSF), Room D10600 (110 NSF), Room D20101 (30 NSF), Room D31100 (231 NSF), Room D11000 (76 NSF), Room D20001 (1602 NSF), Room D30300 (304 NSF), Room D10502 (174 NSF), Room D2000C (2342 NSF), Room D30400 (109 NSF), Room D10102 (37 NSF), Room D20500 (116 NSF), Room D4000R (1 NSF), Room D11102 (385 NSF), Room D20602 (461 NSF), Room D10100 (5147 NSF), Room D10200 (77 NSF), Room D30092 (87 NSF), Room D10702 (98 NSF), Room D20301 (203 NSF), Room D31300 (256 NSF), Room D11100 (133 NSF), Room D11003 (152 NSF), Room D11001 (551 NSF), Room D20303 (207 NSF), Room D31400 (82 NSF), Room D11103 (457 NSF), Room D206A (1655 NSF), Room D11800 (230 NSF), Room D20700 (762 NSF), Room D11300 (853 NSF), Room D20701 (404 NSF), Room D10522 (219 NSF), Room D20100 (463 NSF), Room D20600 (789 NSF), Room D10701 (108 NSF), Room D20300 (2352 NSF), Room D31200 (53 NSF), Room D10520 (979 NSF), Room D20091 (84 NSF), Room D11201 (341 NSF), Room D10005 (36 NSF), Room D11401 (155 NSF), Room D21200 (82 NSF), Room D10521 (140 NSF), Room D20092 (87 NSF), Room D31000 (409 NSF), Room D11002 (149 NSF), Room D20400 (102 NSF), Room D31500 (738 NSF), Room D10300 (77 NSF), Room D20002 (305 NSF), Room D30800 (1021 NSF), Room D11200 (1160 NSF), Room D206B (2378 NSF), Room D10006 (44 NSF), Room D11402 (95 NSF), Room D30002 (305 NSF), Room D30900 (819 NSF), Room D11307 (140 NSF), Room D20900 (231 NSF), Room D10004 (255 NSF), Room D11400 (372 NSF), Room D21101 (39 NSF), Room D30301 (1004 NSF), Room D11500 (390 NSF), Room D3000C (2312 NSF), Room D10505 (173 NSF), Room D2000S (523 NSF), Room D30600 (1531 NSF), Room D10000 (1404 NSF), Room D11601 (38 NSF), Room D3000S (560 NSF), Room D11101 (119 NSF), Room D20601 (121 NSF), Room D1000S (484 NSF), Room D1000N (684 NSF), Room D3000N (669 NSF), Room D10700 (102 NSF), Room D20200 (329 NSF), Room D31101 (38 NSF), Room D10103 (1221 NSF), Room D10091 (63 NSF), Room D30200 (329 NSF), Room D11301 (230 NSF), Room D20702 (214 NSF), Room D10001 (2171 NSF), Room D11308 (147 NSF), Room D11600 (246 NSF), Room D11303 (238 NSF), Room D20704 (113 NSF), Room D10002 (257 NSF), Room D11309 (139 NSF), Room D21000 (53 NSF), Room D12000 (124 NSF), Room D11700 (53 NSF), Room D30091 (84 NSF), Room D11304 (227 NSF), Room D20705 (116 NSF), Room D10400 (310 NSF), Room D20901 (38 NSF), Room D20003 (308 NSF), Room D30302 (630 NSF), Room D10101 (926 NSF), Room D11801 (34 NSF), Room D30100 (463 NSF), Room D10092 (59 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$552,014 in deficiencies (Year 1) and \$1,561,576 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$552,014 in deficiencies (Year 1) and \$1,561,576 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	2,113,590
HOMESTEAD CAMPUS Total :		76,028,790

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 6
Site Name: PADRON CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
6.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	232,849

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
6.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	5,069,537
6.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	1,891,127
6.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems	4,000,000
PADRON CAMPUS		Total : 11,193,513

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
6.005	New Construction: Adding Audiovisual (2422 NSF), Audiovisual (1020 NSF)	1,950,711
6.006	New Construction: Adding Auditorium / Exhibition (6773 NSF)	3,838,380
6.007	New Construction: Adding Custodial (2814 NSF)	1,594,803
6.008	New Construction: Adding Library / Study (28518 NSF)	16,161,894
6.009	New Construction: Adding Physical Education (28305 NSF)	16,041,396
6.010	New Construction: Adding Student Services (1187 NSF)	672,714
6.011	Remodeling Building Number - 6, Building Name - INTERAMERICAN PLAZA : Adding Auditorium/Exhibition (4000 NSF), (5682 GSF); Auditorium / Exhibition (4000 NSF) and Removing (0 SS), (2273 NSF) Room 610100 (2007 NSF), Room 610C01 (266 NSF)	798,000
6.012	Remodeling Building Number - 6, Building Name - INTERAMERICAN PLAZA : Adding Classrooms (80 SS), (1900 NSF), (2699 GSF); Non-Vocational Labs (100 SS), (4800 NSF), (6818 GSF); Vocational Labs (30 SS), (2515 NSF), (3572 GSF); Student Services (150 NSF), (213 GSF); Office (9795 NSF), (13913 GSF); Computer & Information Systems (4800 NSF, 100 SSC), Business Data Processing (2515 NSF, 30 SSC), Classroom (1900 NSF, 80 SSC), Office (9795 NSF), Student Services (150 NSF) and Removing (0 SS), (45434 NSF) Room 615A00 (11363 NSF), Room 611A00 (11345 NSF), Room 612A00 (11363 NSF), Room 614A00 (11363 NSF)	9,064,083
6.013	Remodeling Building Number - 1, Building Name - ACADEMIC BUILDING : Adding Non-Vocational Labs (286 SS), (15730 NSF), (22342 GSF); Student Services (11507 NSF), (16345 GSF); Biology, General (5610 NSF, 102 SSC), Chemistry, General (5610 NSF, 102 SSC), Physics, General (4510 NSF, 82 SSC), Student Services (11507 NSF) and Removing (0 SS), (16660 NSF) Room 110400 (363 NSF), Room 110300 (368 NSF), Room 110093 (75 NSF), Room 110200 (126 NSF), Room 113400 (255 NSF), Room 110502 (170 NSF), Room 113200 (475 NSF), Room 110094 (91 NSF), Room 110100 (127 NSF), Room 110501 (37 NSF), Room 11001C (574 NSF), Room 113500 (69 NSF), Room 11003C (1357 NSF), Room 111800 (187 NSF), Room 110091 (75 NSF), Room 110003 (471 NSF), Room 11001W (638 NSF), Room 113700 (534 NSF), Room 11008C (1785 NSF), Room 11002S (374 NSF), Room 113600 (37 NSF), Room 11002W (402 NSF), Room 110001 (499 NSF), Room 11006C (1054 NSF), Room 113800 (76 NSF), Room 11000E (104 NSF), Room 11002C (383 NSF), Room 110700 (610 NSF), Room 111500 (35 NSF), Room 11000N (1201 NSF), Room 11007C (974 NSF), Room 11005C (1568 NSF), Room 11004C (939 NSF), Room 110002 (540 NSF), Room 110500 (61 NSF), Room 113302 (26 NSF)	5,433,781
6.014	Renovating Building Number - 23, Building Name - KOUBEK GAZEBO (0 SS), (113 NSF) Apply Other to Room G10000 (113 NSF) Renovation Description:	354

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
6.015	<p>Renovating Building Number - 22, Building Name - KOUBEK AUDITORIUM (0 SS), (15 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room T10108 (15 NSF) Renovation Description: Facilities Condition Assessment performed February 2020 identified 87,340 in deficiencies and \$347,894 in life cycle renewal repairs, replacement and renovations for Padron Facility</p> <p>Facilities Condition Assessment performed February 2020 identified 87,340 in deficiencies and \$347,894 in life cycle renewal repairs, replacement and renovations for Padron Facility</p>	435,234
6.016	<p>Renovating Building Number - 21, Building Name - KOUBEK CLASSROOM (0 SS), (180 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room K20001 (180 NSF) Renovation Description: Facilities Condition Assessment performed February 2020 identified \$16,560 in deficiencies and \$86,177 in life cycle renewal repairs, replacements, and renovation for Padron Facility 21</p> <p>Facilities Condition Assessment performed February 2020 identified \$16,560 in deficiencies and \$86,177 in life cycle renewal repairs, replacements, and renovation for Padron Facility 21</p>	102,737
6.017	<p>Renovating Building Number - 20, Building Name - KOUBEK MANSION (0 SS), (175 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room M1002E (175 NSF) Renovation Description: Facilities Condition Assessment performed April 2020 identified \$6,426 in deficiencies and \$357,822 in life cycle renewal repairs, replacements, and renovation in Padron Facility 6</p> <p>Facilities Condition Assessment performed April 2020 identified \$6,426 in deficiencies and \$357,822 in life cycle renewal repairs, replacements, and renovation in Padron Facility 6</p>	364,248
6.018	<p>Renovating Building Number - 5, Building Name - SERVICE BUILDING (0 SS), (675 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 050300 (216 NSF), Room 05001C (238 NSF), Room 050200 (221 NSF) Renovation Description: Facilities Condition Assessment performed April 2020 identified \$1,281,083 in deficiencies and \$1,387,105 in life cycle renewal repairs, replacements, and renovation in Padron Facility 5</p> <p>Facilities Condition Assessment performed April 2020 identified \$1,281,083 in deficiencies and \$1,387,105 in life cycle renewal repairs, replacements, and renovation in Padron Facility 5</p>	1,855,878
6.019	<p>Renovating Building Number - 6, Building Name - INTERAMERICAN PLAZA (0 SS), (956 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 601500 (956 NSF) Renovation Description: Facilities Condition Assessment performed February 2020 identified \$43,479 in deficiencies plus another \$7,998,160 in life cycle renewal plan for repairs/replacement/renovations</p> <p>Facilities Condition Assessment performed February 2020 identified \$43,479 in deficiencies plus another \$7,998,160 in life cycle renewal plan for repairs/replacement/renovations</p>	8,041,639
6.020	<p>Renovating Building Number - 4, Building Name - PARKING STRUCTURE (0 SS), (623 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 41000S (623 NSF) Renovation Description: Facilities Condition Assessment performed in February 2020, identified \$764,720 in deficiencies and \$1,387,105 in life cycle renewal repairs/replacement over the next 5 years.</p> <p>Facilities Condition Assessment performed in February 2020, identified \$764,720 in deficiencies and \$1,387,105 in life cycle renewal repairs/replacement over the next 5 years.</p>	2,151,825
6.021	<p>Renovating Building Number - 3, Building Name - INTERAMERICAN (0 SS), (738 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 340000 (738 NSF) Renovation Description: Facilities Condition Assessment performed in February 2020, identified \$911,527 in deficiencies and \$4,166,225 in life cycle renewal repairs/replacement over the next 5 years.</p> <p>Facilities Condition Assessment performed in February 2020, identified \$911,527 in deficiencies and \$4,166,225 in life cycle renewal repairs/replacement over the next 5 years.</p>	5,077,752
6.022	<p>Renovating Building Number - 2, Building Name - CLASSROOM BUILDING (0 SS), (304 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 02000S (304 NSF) Renovation Description: Facilities Condition Assessment performed in February 2020, identified \$18,356 in deficiencies and \$314,205 in life cycle renewal repairs/repalcement over the next 5 years.</p> <p>Facilities Condition Assessment performed in February 2020, identified \$18,356 in deficiencies and \$314,205 in life cycle renewal repairs/repalcement over the next 5 years.</p>	332,561

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
6.023	Renovating Building Number - 1, Building Name - ACADEMIC BUILDING (0 SS), (773 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 130803 (773 NSF) Renovation Description: Facilities Condition Assessment performed in February 2020, identified \$164,474 in deficiencies and \$11,206,927 in life cycle renewal repairs/repalcement over the next 5 years. Facilities Condition Assessment performed in February 2020, identified \$164,474 in deficiencies and \$11,206,927 in life cycle renewal repairs/repalcement over the next 5 years.	11,371,407
PADRON CAMPUS		Total :
		85,289,397

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 7
Site Name: HIALEAH CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
7.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	7,800
7.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	3,122,910
7.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	567,338
7.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems	1,200,000
HIALEAH CAMPUS		Total :
		4,898,048

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
7.005	New Construction: Adding Auditorium / Exhibition (7348 NSF), Audiovisual (2280 NSF), Audiovisual (1677 NSF)	6,406,743
7.006	New Construction: Adding Office (2692 NSF), Mechanical / Sanitation (6130 NSF), Library / Study (7444 NSF), Custodial (2136 NSF), Circulation (16856 NSF)	19,981,920
7.007	New Construction: Adding Physical Education (27925 NSF)	15,825,936
7.008	New Construction: Adding Student Services (23766 NSF)	13,469,043
7.009	New Construction: Adding Classrooms (516 SS), (14475 NSF), (20560 GSF); Non-Vocational Labs (769 SS), (35905 NSF), (51000 GSF); Vocational Labs (17 SS), (884 NSF), (1256 GSF); Classroom (14475 NSF), Supervisory and Administrative Management (General Business, etc.) (884 NSF), General Liberal Arts and Sciences (7150 NSF), Education, General (9000 NSF), Business and Commerce, General (9900 NSF), Adult and Continuing Education, General (9855 NSF), Office (20000 NSF), Library / Study (20000 NSF)	51,722,769

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
7.010	Renovating Building Number - 2, Building Name - BLDG_2000 (0 SS), (99 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 21010N (99 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$143,430 in deficiencies (Year 1), and \$3,412,807 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$143,430 in deficiencies (Year 1), and \$3,412,807 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	3,556,237
7.011	Renovating Building Number - 3, Building Name - CENTRAL UTILITIES PL (0 SS), (1444 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 310000 (1444 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$16,184 in deficiencies (Year 1) and \$735,609 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$16,184 in deficiencies (Year 1) and \$735,609 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	751,793
7.012	Renovating Building Number - 5, Building Name - BUILDING 5000 (0 SS), (374697 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 520000 (42836 NSF), Room 570003 (249 NSF), Room 520002 (217 NSF), Room 570092 (62 NSF), Room 520500 (293 NSF), Room 520093 (64 NSF), Room 520003 (253 NSF), Room 570093 (62 NSF), Room 510093 (90 NSF), Room 530100 (293 NSF), Room 510003 (266 NSF), Room 530003 (294 NSF), Room 510400 (1573 NSF), Room 540100 (293 NSF), Room 510002 (233 NSF), Room 530002 (217 NSF), Room 510200 (146 NSF), Room 540091 (67 NSF), Room 510101 (232 NSF), Room 540001 (504 NSF), Room 510102 (1059 NSF), Room 540002 (217 NSF), Room 520092 (64 NSF), Room 510900 (387 NSF), Room 550092 (64 NSF), Room 510092 (64 NSF), Room 510300 (421 NSF), Room 540093 (64 NSF), Room 550100 (293 NSF), Room 511800 (1177 NSF), Room 560093 (64 NSF), Room 520091 (67 NSF), Room 510201 (52 NSF), Room 540092 (64 NSF), Room 510001 (475 NSF), Room 530001 (505 NSF), Room 510700 (415 NSF), Room 550003 (253 NSF), Room 530093 (64 NSF), Room 511100 (209 NSF), Room 511700 (109 NSF), Room 560092 (64 NSF), Room 511900 (98 NSF), Room 560100 (293 NSF), Room 510601 (117 NSF), Room 550002 (217 NSF), Room 510000 (30635 NSF), Room 530000 (55219 NSF), Room 510103 (7941 NSF), Room 540003 (253 NSF), Room 510500 (36 NSF), Room 550000 (54748 NSF), Room 511300 (190 NSF), Room 560001 (505 NSF), Room 511400 (250 NSF), Room 560002 (217 NSF), Room 511500 (162 NSF), Room 560003 (253 NSF), Room 510600 (411 NSF), Room 550001 (503 NSF), Room 520300 (224 NSF), Room 512000 (600 NSF), Room 510800 (99 NSF), Room 550091 (67 NSF), Room 530091 (67 NSF), Room 510091 (67 NSF), Room 530092 (64 NSF), Room 510100 (4131 NSF), Room 511200 (455 NSF), Room 560000 (54756 NSF), Room 560091 (67 NSF), Room 520200 (584 NSF), Room 520400 (292 NSF), Room 520100 (247 NSF), Room 570000 (49188 NSF), Room 510004 (94 NSF), Room 512001 (121 NSF), Room 570001 (503 NSF), Room 512100 (289 NSF), Room 570002 (217 NSF), Room 540000 (54757 NSF), Room 511600 (137 NSF), Room 511000 (195 NSF), Room 550093 (64 NSF), Room 520001 (500 NSF), Room 570091 (62 NSF), Room 520004 (130 NSF), Room 570100 (277 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$214,855 in deficiencies (Year 1) and \$441,807 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$214,855 in deficiencies (Year 1) and \$441,807 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	656,662

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
7.013	Renovating Building Number - 1, Building Name - ACADEMIC BLDG (590 SS), (54388 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 110801 (128 NSF), Room 122200 (137 NSF), Room 140092 (56 NSF), Room 110802 (162 NSF), Room 122300 (749 NSF), Room 140100 (167 NSF), Room 111400 (216 NSF), Room 13000N (646 NSF), Room 140500 (630 NSF), Room 120003 (137 NSF), Room 130100 (167 NSF), Room 140506 (72 NSF), Room 120001 (298 NSF), Room 130091 (58 NSF), Room 140504 (156 NSF), Room 111600 (129 NSF), Room 13001W (486 NSF), Room 140502 (127 NSF), Room 111200 (1362 NSF), Room 130001 (300 NSF), Room 140400 (168 NSF), Room 12000W (818 NSF), Room 130200 (31 NSF), Room 140800 (167 NSF), Room 111000 (101 NSF), Room 122500 (210 NSF), Room 140102 (45 NSF), Room 110003 (98 NSF), Room 120700 (87 NSF), Room 131100 (590 NSF), Room 120091 (58 NSF), Room 130200 (31 NSF), Room 140900 (179 NSF), Room 110001 (500 NSF), Room 120500 (291 NSF), Room 130902 (54 NSF), Room 120400 (168 NSF), Room 130800 (30 NSF), Room 120102 (45 NSF), Room 130500 (290 NSF), Room 120002 (130 NSF), Room 130092 (56 NSF), Room 140505 (166 NSF), Room 110002 (97 NSF), Room 120600 (129 NSF), Room 131000 (858 NSF), Room 110600 (256 NSF), Room 122001 (538 NSF), Room 140003 (137 NSF), Room 110004 (33 NSF), Room 120800 (31 NSF), Room 131200 (454 NSF), Room 0R (1 NSF), Room 120401 (40 NSF), Room 130900 (1458 NSF), Room 110300 (894 NSF), Room 121300 (584 NSF), Room 131900 (776 NSF), Room 110301 (235 NSF), Room 121400 (597 NSF), Room 132000 (574 NSF), Room 120101 (38 NSF), Room 130402 (45 NSF), Room 110092 (56 NSF), Room 121100 (526 NSF), Room 131700 (31 NSF), Room 110005 (39 NSF), Room 120900 (742 NSF), Room 131300 (1059 NSF), Room 110400 (48 NSF), Room 121600 (992 NSF), Room 140000 (9698 NSF), Room 111700 (291 NSF), Room 13002W (180 NSF), Room 140503 (181 NSF), Room 110501 (134 NSF), Room 121800 (592 NSF), Room 140002 (130 NSF), Room 110100 (960 NSF), Room 121101 (79 NSF), Room 131800 (724 NSF), Room 110900 (889 NSF), Room 122400 (1048 NSF), Room 140101 (38 NSF), Room 11000S (559 NSF), Room 120901 (166 NSF), Room 131400 (831 NSF), Room 111301 (44 NSF), Room 130003 (137 NSF), Room 140402 (45 NSF), Room 120100 (167 NSF), Room 130401 (38 NSF), Room 110500 (276 NSF), Room 121700 (594 NSF), Room 140001 (273 NSF), Room 111500 (189 NSF), Room 13000S (879 NSF), Room 140501 (127 NSF), Room 110700 (56 NSF), Room 122002 (115 NSF), Room 14000W (56 NSF), Room 110200 (195 NSF), Room 121200 (580 NSF), Room 131801 (38 NSF), Room 11001E (72 NSF), Room 121000 (690 NSF), Room 131500 (822 NSF), Room 110800 (805 NSF), Room 122100 (161 NSF), Room 140091 (58 NSF), Room 110000 (3863 NSF), Room 120402 (45 NSF), Room 130901 (213 NSF), Room 12000N (862 NSF), Room 130101 (38 NSF), Room 140600 (243 NSF), Room 111300 (488 NSF), Room 130002 (130 NSF), Room 140401 (38 NSF), Room 12000S (741 NSF), Room 130102 (45 NSF), Room 140700 (111 NSF), Room 120300 (32 NSF), Room 130700 (88 NSF), Room 120092 (56 NSF), Room 130400 (168 NSF), Room 141000 (560 NSF), Room 120200 (32 NSF), Room 130600 (129 NSF), Room 110302 (98 NSF), Room 121500 (26 NSF), Room 132200 (796 NSF), Room 111100 (97 NSF), Room 122501 (164 NSF), Room 140200 (53 NSF), Room 110091 (58 NSF), Room 121001 (58 NSF), Room 131600 (475 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$310,941 in deficiencies (Year 1) and \$3037633 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$310,941 in deficiencies (Year 1) and \$3037633 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	3,348,574
HIALEAH CAMPUS Total :		115,719,677

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 8
Site Name: WEST CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
8.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	359,101

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
8.002	Renovate site and facilities systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	1
8.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	567,338
8.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	1,200,000
WEST CAMPUS		
Total :		2,126,440

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
8.005	New Construction: Adding Audiovisual (1251 NSF), Custodial (1330 NSF), Library / Study (2454 NSF), Student Services (635 NSF), Auditorium / Exhibition (2212 NSF)	4,466,805
8.006	New Construction: Adding Physical Education (19171 NSF)	10,864,770
8.007	New Construction: Adding Non-Vocational Labs (183 SS), (8260 NSF), (11732 GSF); Vocational Labs (17 SS), (4507 NSF), (6402 GSF); Computer & Information Systems (4160 NSF), City, Community and Regional Planning (900 NSF), Other Arts (3200 NSF), Automotive Mechanics (4507 NSF), Auditorium / Exhibition (2500 NSF), Student Services (8213 NSF)	13,306,650
8.008	Remodeling Building Number - 1, Building Name - CENTRAL BUILDING : Adding Student Services (1000 NSF), (1420 GSF); Custodial (500 NSF), (710 GSF); Student Services (1000 NSF), Custodial (500 NSF) and Removing (0 SS), (30557 NSF) Room 121100 (339 NSF), Room 12001C (691 NSF), Room 12001W (364 NSF), Room 11002N (351 NSF), Room 12002N (1418 NSF), Room 12180A (172 NSF), Room 12001S (1605 NSF), Room 11001E (548 NSF), Room 12002S (971 NSF), Room 12001N (943 NSF), Room 12003E (350 NSF), Room 11000C (786 NSF), Room 110901 (207 NSF), Room 13000C (14742 NSF), Room 12001E (390 NSF), Room 11001S (975 NSF), Room 12002E (230 NSF), Room 122600 (335 NSF), Room 12002C (2867 NSF), Room 11003S (266 NSF), Room 11001W (693 NSF), Room 11001N (749 NSF), Room 11002S (565 NSF)	6,096,121
8.009	Remodeling Building Number - 2, Building Name - NORTH WAREHOUSE : Adding Non-Vocational Labs (313 SS), (17215 NSF), (24452 GSF); Library/Study (10000 NSF), (14204 GSF); General Liberal Arts and Sciences (17215 NSF, 313 SSC), Library / Study (10000 NSF) and Removing (0 SS), (30701 NSF) Room 210100 (21655 NSF), Room 212501 (542 NSF), Room 21001N (3059 NSF), Room 22000N (2629 NSF), Room 22000E (2250 NSF), Room 212105 (165 NSF), Room 210201 (101 NSF), Room 220001 (300 NSF)	6,124,849
8.010	Renovating Building Number - 2, Building Name - NORTH WAREHOUSE (0 SS), (411 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 210400 (411 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$728,375 in deficiencies (Year 1) and \$7,0389,36 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years. Facilities condition assessment performed February 2020 identified \$728,375 in deficiencies (Year 1) and \$7,0389,36 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years.	7,767,311
8.011	Renovating Building Number - 3, Building Name - PARKING GARAGE (0 SS), (94 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 310300 (94 NSF) Renovation Description: Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$9,583 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years for West Facility 3. Facilities condition assessment performed February 2020 identified \$0 in deficiencies (Year 1) and \$9,583 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years for West Facility 3.	9,583
8.012	Renovating Building Number - 1, Building Name - CENTRAL BUILDING (862 SS), (150917 NSF)	8,920,069

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

15-MIAMI DADE COLLEGE

Survey:

Survey : 3 Version : 1

Status:

Active Approved

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 110700 (433 NSF), Room 111708 (295 NSF), Room 120092 (37 NSF), Room 122200 (156 NSF), Room 126000 (651 NSF), Room 133400 (333 NSF), Room 120091 (37 NSF), Room 122100 (455 NSF), Room 125900 (660 NSF), Room 133300 (452 NSF), Room 120200 (393 NSF), Room 122400 (150 NSF), Room 126200 (865 NSF), Room 133600 (481 NSF), Room 110501 (87 NSF), Room 111707 (49 NSF), Room 112202 (158 NSF), Room 121101 (479 NSF), Room 123000 (436 NSF), Room 130092 (37 NSF), Room 110801 (118 NSF), Room 111900 (793 NSF), Room 111800 (459 NSF), Room 120093 (38 NSF), Room 122300 (160 NSF), Room 126100 (663 NSF), Room 11000W (877 NSF), Room 110903 (75 NSF), Room 110902 (2072 NSF), Room 112201 (788 NSF), Room 121100 (339 NSF), Room 122900 (149 NSF), Room 134400 (628 NSF), Room 110800 (821 NSF), Room 110200 (3974 NSF), Room 111002 (203 NSF), Room 113401 (11 NSF), Room 121805 (122 NSF), Room 133500 (91 NSF), Room 11000E (730 NSF), Room 110100 (287 NSF), Room 110914 (144 NSF), Room 112900 (105 NSF), Room 121800 (334 NSF), Room 130091 (37 NSF), Room 134300 (58 NSF), Room 135400 (1859 NSF), Room 110400 (315 NSF), Room 111500 (457 NSF), Room 12001C (691 NSF), Room 124600 (600 NSF), Room 131700 (271 NSF), Room 132300 (660 NSF), Room 110404 (366 NSF), Room 111700 (2611 NSF), Room 12001W (364 NSF), Room 124200 (972 NSF), Room 131100 (210 NSF), Room 132600 (86 NSF), Room 110093 (40 NSF), Room 110913 (42 NSF), Room 112800 (625 NSF), Room 121812 (134 NSF), Room 125102 (185 NSF), Room 131000 (242 NSF), Room 135300 (928 NSF), Room 11002N (351 NSF), Room 110908 (62 NSF), Room 121816 (133 NSF), Room 125500 (673 NSF), Room 123300 (217 NSF), Room 130500 (92 NSF), Room 134800 (81 NSF), Room 110104 (186 NSF), Room 121701 (40 NSF), Room 124100 (658 NSF), Room 121804 (139 NSF), Room 124501 (58 NSF), Room 131600 (223 NSF), Room 110407 (135 NSF), Room 112401 (90 NSF), Room 121300 (146 NSF), Room 121819 (174 NSF), Room 125800 (1486 NSF), Room 132900 (212 NSF), Room 110205 (1138 NSF), Room 111001 (88 NSF), Room 113400 (251 NSF), Room 12180A (172 NSF), Room 125000 (659 NSF), Room 132000 (541 NSF), Room 110203 (91 NSF), Room 111703 (204 NSF), Room 12002N (1418 NSF), Room 121808 (138 NSF), Room 124800 (891 NSF), Room 131801 (48 NSF), Room 110102 (131 NSF), Room 111203 (57 NSF), Room 120003 (206 NSF), Room 121802 (137 NSF), Room 124400 (970 NSF), Room 131300 (92 NSF), Room 135700 (2912 NSF), Room 111201 (123 NSF), Room 120001 (140 NSF), Room 113500 (45 NSF), Room 121806 (138 NSF), Room 124601 (85 NSF), Room 131701 (40 NSF), Room 110916 (6 NSF), Room 113100 (268 NSF), Room 12001S (1605 NSF), Room 121815 (171 NSF), Room 125400 (658 NSF), Room 132501 (62 NSF), Room 110201 (125 NSF), Room 111100 (896 NSF), Room 112203 (132 NSF), Room 121102 (322 NSF), Room 123100 (335 NSF), Room 130093 (37 NSF), Room 110403 (72 NSF), Room 111600 (96 NSF), Room 111704 (95 NSF), Room 12002S (971 NSF), Room 121820 (156 NSF), Room 125801 (54 NSF), Room 11001E (548 NSF), Room 110904 (62 NSF), Room 111502 (54 NSF), Room 12001N (943 NSF), Room 121814 (132 NSF), Room 125300 (640 NSF), Room 134500 (628 NSF), Room 110408 (134 NSF), Room 111202 (158 NSF), Room 120002 (203 NSF), Room 121809 (387 NSF), Room 124900 (900 NSF), Room 133000 (246 NSF), Room 110402 (181 NSF), Room 110915 (170 NSF), Room 113000 (219 NSF), Room 121801 (429 NSF), Room 124300 (640 NSF), Room 132500 (823 NSF), Room 110204 (239 NSF), Room 110500 (905 NSF), Room 111706 (407 NSF), Room 12003E (350 NSF), Room 122000 (87 NSF), Room 131900 (311 NSF), Room 110101 (147 NSF), Room 110091 (40 NSF), Room 110911 (173 NSF), Room 112600 (151 NSF), Room 121600 (226 NSF), Room 131200 (188 NSF), Room 135500 (2362 NSF), Room 135000 (1859 NSF), Room 11000C (786 NSF), Room 110901 (207 NSF), Room 112200 (29 NSF), Room 125803 (106 NSF), Room 133200 (210 NSF), Room 13000C (14742 NSF), Room 134200 (267 NSF), Room 110202 (224 NSF), Room 111200 (406 NSF), Room 123900 (93 NSF), Room 130800 (212 NSF), Room 124700 (892 NSF), Room 131800 (506 NSF), Room 110103 (138 NSF), Room 111000 (421 NSF), Room 121000 (302 NSF), Room 122800 (150 NSF), Room 124500 (628 NSF), Room 131400 (92 NSF), Room 140100 (2558 NSF), Room 110401 (399 NSF), Room 120000 (1611 NSF), Room 121807 (191 NSF), Room 121813 (231 NSF), Room 125200 (842 NSF), Room 132400 (713 NSF), Room 110301 (145 NSF), Room 113200 (254 NSF), Room 121803 (122 NSF), Room 121811 (131 NSF), Room 125101 (714 NSF), Room 132200 (1070 NSF), Room 110003 (203 NSF), Room 111501 (40 NSF), Room 12001E (390 NSF), Room 120700 (165 NSF), Room 122603 (213 NSF), Room 130003 (203 NSF), Room 133902 (46 NSF), Room 111401 (56 NSF), Room 120005 (203 NSF), Room 112700 (95 NSF), Room 121700 (270 NSF), Room 124000 (673 NSF), Room 130900 (215 NSF), Room 110806 (73 NSF), Room 112100 (21 NSF), Room 111901 (174 NSF), Room 120300 (390 NSF), Room 122500 (150 NSF), Room 126300 (873 NSF), Room 110092 (40 NSF), Room 110912 (38 NSF), Room 110804 (563 NSF), Room 112001 (173 NSF), Room 120500 (428 NSF), Room 122601 (352 NSF), Room 135200 (957 NSF), Room 110802 (118 NSF), Room 110409 (732 NSF), Room 111705 (298 NSF), Room 12002W (1061 NSF), Room 121900 (355 NSF), Room 133700 (449 NSF), Room 110000 (1378 NSF), Room 11001S (975 NSF), Room 110906 (274 NSF), Room 112300 (41 NSF), Room 121104 (389 NSF), Room 130000 (1489 NSF), Room 133900 (273 NSF), Room 134700 (1470 NSF), Room 110406 (144 NSF), Room 111702 (96 NSF), Room 12002E (230 NSF), Room 125802 (81 NSF), Room 133100 (208 NSF), Room 132800 (189 NSF), Room 110004 (165 NSF), Room 110807 (142 NSF), Room 112101 (1592 NSF), Room 123201 (13 NSF), Room 130300 (549 NSF), Room 130004 (203 NSF), Room 134000 (220 NSF), Room 110803 (149 NSF), Room 112000 (1702 NSF), Room 121818 (245 NSF), Room 125700 (663 NSF), Room 126400 (1002 NSF), Room 133800 (150 NSF), Room 110405 (277 NSF), Room 111701 (159 NSF), Room 120800 (151 NSF), Room 122604 (380 NSF), Room

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

125600 (651 NSF), Room 132700 (153 NSF), Room 11003S (266 NSF), Room 110910 (275 NSF), Room 120400 (369 NSF), Room 122600 (335 NSF), Room 123500 (263 NSF), Room 130700 (453 NSF), Room 134900 (4161 NSF), Room 11001W (693 NSF), Room 12002C (2867 NSF), Room 121817 (179 NSF), Room 121200 (152 NSF), Room 123202 (46 NSF), Room 130400 (621 NSF), Room 134701 (54 NSF), Room 112500 (4400 NSF), Room 121500 (92 NSF), Room 112204 (151 NSF), Room 121103 (214 NSF), Room 123200 (275 NSF), Room 130200 (416 NSF), Room 110907 (76 NSF), Room 112400 (2503 NSF), Room 110900 (321 NSF), Room 112102 (151 NSF), Room 120900 (151 NSF), Room 122700 (150 NSF), Room 11001N (749 NSF), Room 110905 (194 NSF), Room 110300 (835 NSF), Room 111400 (234 NSF), Room 120004 (203 NSF), Room 121810 (138 NSF), Room 134600 (58 NSF), Room 110005 (203 NSF), Room 110001 (90 NSF), Room 110805 (158 NSF), Room 112002 (226 NSF), Room 120600 (96 NSF), Room 130005 (204 NSF), Room 134100 (254 NSF), Room 133901 (13 NSF), Room 11002S (565 NSF), Room 110909 (190 NSF), Room 112402 (541 NSF), Room 125100 (105 NSF), Room 132100 (550 NSF), Room 121400 (182 NSF), Room 123400 (250 NSF), Room 130600 (333 NSF), Room 134801 (94 NSF), Room 122602 (145 NSF), Room 130002 (209 NSF)

Renovation Description: Facilities condition assessment performed February 2020 identified \$657,710 in deficiencies (Year 1) and \$8,262,359 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years for West Facility 1.

Facilities condition assessment performed February 2020 identified \$657,710 in deficiencies (Year 1) and \$8,262,359 in life cycle renewal (Years 2-5) to repair, replace and/or renovation over next 5 years for West Facility 1.

WEST CAMPUS Total : 57,556,158

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 10

Site Name: ENTREPRENEURIAL ED

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATE D COST
10.001	Renovate and/or remodel site facilities to include but not limited to existing parking facilities, roadways, walkways, plazas, site entrances, fencing.	81,752
10.002	Renovate site systems and utilities to include not limited to electrical distribution, chilled water distribution, water, sanitary drainage and sewer systems, data and telecom lines, fire safety systems, safety and security systems, storm water systems, lift & pump stations, irrigation controls and systems, lake fountain systems, transportation and wayfinding signage systems.	50,000
10.003	Identify and Implement guidelines and procedures to include but not limited to lighting studies and assessments, energy engineering and economics studies, signage and wayfinding assessments and recommendations	10,000
10.004	Maintain proper care and service of site utilities and building systems pursuant to definition in Section 1013.01(18), F.S., and provisions of State Requirements for Educational Facilities of the Florida Building Code; to include HVAC, mechanical, structural, electrical, plumbing, elevator and other building systems.	125,000
ENTREPRENEURIAL ED Total :		<u>266,752</u>

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
10.005	New Construction: Adding Physical Education (10000 NSF)	5,667,396
10.006	New Construction: Adding Support Services (1946 NSF)	1,102,836
10.007	New Construction: Adding Student Services (2865 NSF)	1,623,531
10.008	New Construction: Adding Auditorium / Exhibition (10000 NSF)	5,667,396
10.009	New Construction: Adding Non-Vocational Labs (62 SS), (2790 NSF), (3963 GSF); Education, General (2790 NSF), Audiovisual (494 NSF)	1,860,936

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
10.010	Remodeling Building Number - 1, Building Name - MEEK ENTRPREUNEUR CT: Adding Library/Study (1523 NSF), (2163 GSF); Library / Study (1523 NSF) and Removing (61 SS), (1523 NSF) Room 12030A (647 NSF), Room 12090A (876 NSF)	303,838
10.011	Renovating Building Number - 1, Building Name - MEEK ENTRPREUNEUR CT (337 SS), (30209 NSF) Apply HVAC Systems to Room 110900 (633 NSF), Room 111100 (80 NSF), Room 110701 (412 NSF), Room 121500 (152 NSF), Room 110902 (53 NSF), Room 110800 (142 NSF), Room 111600 (350 NSF), Room 111300 (585 NSF), Room 110103 (669 NSF), Room 110102 (217 NSF), Room 120103 (225 NSF), Room 111000 (50 NSF), Room 130100 (561 NSF), Room 110001 (415 NSF), Room 110002 (170 NSF), Room 120600 (36 NSF), Room 110301 (115 NSF), Room 120801 (32 NSF), Room 120200 (272 NSF), Room 110004 (60 NSF), Room 120002 (208 NSF), Room 12030A (647 NSF), Room 110104 (120 NSF), Room 120201 (34 NSF), Room 11001W (771 NSF), Room 120091 (50 NSF), Room 110203 (30 NSF), Room 12090A (876 NSF), Room 111200 (142 NSF), Room 11010B (319 NSF), Room 11001E (1404 NSF), Room 12000N (225 NSF), Room 11010C (90 NSF), Room 110600 (46 NSF), Room 121300 (645 NSF), Room 110204 (83 NSF), Room 110305 (60 NSF), Room 121000 (351 NSF), Room 110302 (100 NSF), Room 110202 (109 NSF), Room 120500 (48 NSF), Room 11000E (259 NSF), Room 120302 (44 NSF), Room 110303 (100 NSF), Room 12090B (770 NSF), Room 111400 (779 NSF), Room 110003 (85 NSF), Room 120001 (415 NSF), Room 120700 (158 NSF), Room 110400 (170 NSF), Room 121100 (475 NSF), Room 110101 (142 NSF), Room 120102 (230 NSF), Room 110700 (147 NSF), Room 12000E (788 NSF), Room 110201 (121 NSF), Room 120400 (624 NSF), Room 120301 (39 NSF), Room 110200 (590 NSF), Room 12030B (646 NSF), Room 110901 (153 NSF), Room 11002E (1406 NSF), Room 120100 (1494 NSF), Room 120701 (32 NSF), Room 110304 (50 NSF), Room 1209A1 (56 NSF), Room 121400 (708 NSF), Room 110000 (2917 NSF), Room 11010A (63 NSF), Room 12000W (64 NSF), Room 111500 (700 NSF), Room 110300 (1227 NSF), Room 110500 (170 NSF), Room 121200 (645 NSF), Room 110205 (97 NSF), Room 120800 (146 NSF), Room 110091 (50 NSF), Room 120101 (217 NSF), Room 11001N (614 NSF), Room 12000S (154 NSF), Room 11001S (1077 NSF) Renovation Description:	4,017,797
10.012	Renovating Building Number - 1, Building Name - MEEK ENTRPREUNEUR CT (337 SS), (30209 NSF) Apply Painting to Room 110900 (633 NSF), Room 111100 (80 NSF), Room 110701 (412 NSF), Room 121500 (152 NSF), Room 110902 (53 NSF), Room 110800 (142 NSF), Room 111600 (350 NSF), Room 111300 (585 NSF), Room 110103 (669 NSF), Room 110102 (217 NSF), Room 120103 (225 NSF), Room 111000 (50 NSF), Room 130100 (561 NSF), Room 110001 (415 NSF), Room 110002 (170 NSF), Room 120600 (36 NSF), Room 110301 (115 NSF), Room 120801 (32 NSF), Room 120200 (272 NSF), Room 110004 (60 NSF), Room 120002 (208 NSF), Room 12030A (647 NSF), Room 110104 (120 NSF), Room 120201 (34 NSF), Room 11001W (771 NSF), Room 120091 (50 NSF), Room 110203 (30 NSF), Room 12090A (876 NSF), Room 111200 (142 NSF), Room 11010B (319 NSF), Room 11001E (1404 NSF), Room 12000N (225 NSF), Room 11010C (90 NSF), Room 110600 (46 NSF), Room 121300 (645 NSF), Room 110204 (83 NSF), Room 110305 (60 NSF), Room 121000 (351 NSF), Room 110302 (100 NSF), Room 110202 (109 NSF), Room 120500 (48 NSF), Room 11000E (259 NSF), Room 120302 (44 NSF), Room 110303 (100 NSF), Room 12090B (770 NSF), Room 111400 (779 NSF), Room 110003 (85 NSF), Room 120001 (415 NSF), Room 120700 (158 NSF), Room 110400 (170 NSF), Room 121100 (475 NSF), Room 110101 (142 NSF), Room 120102 (230 NSF), Room 110700 (147 NSF), Room 12000E (788 NSF), Room 110201 (121 NSF), Room 120400 (624 NSF), Room 120301 (39 NSF), Room 110200 (590 NSF), Room 12030B (646 NSF), Room 110901 (153 NSF), Room 11002E (1406 NSF), Room 120100 (1494 NSF), Room 120701 (32 NSF), Room 110304 (50 NSF), Room 1209A1 (56 NSF), Room 121400 (708 NSF), Room 110000 (2917 NSF), Room 11010A (63 NSF), Room 12000W (64 NSF), Room 111500 (700 NSF), Room 110300 (1227 NSF), Room 110500 (170 NSF), Room 121200 (645 NSF), Room 110205 (97 NSF), Room 120800 (146 NSF), Room 110091 (50 NSF), Room 120101 (217 NSF), Room 11001N (614 NSF), Room 12000S (154 NSF), Room 11001S (1077 NSF) Renovation Description:	4,017,797
10.013	Renovating Building Number - 1, Building Name - MEEK ENTRPREUNEUR CT (0 SS), (4537 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 110900 (633 NSF), Room 111100 (80 NSF), Room 110001 (415 NSF), Room 110002 (170 NSF), Room 111600 (350 NSF), Room 120002 (208 NSF), Room 110203 (30 NSF), Room 120600 (36 NSF), Room 110301 (115 NSF), Room 11001E (1404 NSF), Room 120103 (225 NSF), Room 111000 (50 NSF), Room 11001W (771 NSF), Room 120091 (50 NSF) Renovation Description:	603,421

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:
15-MIAMI DADE COLLEGE

Survey:
Survey : 3 Version : 1

Status:
Active Approved

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
10.014	Renovating Building Number - 1, Building Name - MEEK ENTPREUNEUR CT (337 SS), (30209 NSF) Apply Painting, Floor Cover, Lighting, Restrooms, Retrofit for Technology to Room 110900 (633 NSF), Room 111100 (80 NSF), Room 110701 (412 NSF), Room 121500 (152 NSF), Room 110902 (53 NSF), Room 110800 (142 NSF), Room 120800 (146 NSF), Room 110091 (50 NSF), Room 120101 (217 NSF), Room 11001N (614 NSF), Room 12000S (154 NSF), Room 11001S (1077 NSF), Room 12000W (64 NSF), Room 111500 (700 NSF), Room 110300 (1227 NSF), Room 110500 (170 NSF), Room 121200 (645 NSF), Room 110205 (97 NSF), Room 120701 (32 NSF), Room 110304 (50 NSF), Room 1209A1 (56 NSF), Room 121400 (708 NSF), Room 110000 (2917 NSF), Room 11010A (63 NSF), Room 120301 (39 NSF), Room 110200 (590 NSF), Room 12030B (646 NSF), Room 110901 (153 NSF), Room 11002E (1406 NSF), Room 120100 (1494 NSF), Room 110101 (142 NSF), Room 120102 (230 NSF), Room 110700 (147 NSF), Room 12000E (788 NSF), Room 110201 (121 NSF), Room 120400 (624 NSF), Room 111400 (779 NSF), Room 110003 (85 NSF), Room 120001 (415 NSF), Room 120700 (158 NSF), Room 110400 (170 NSF), Room 121100 (475 NSF), Room 110202 (109 NSF), Room 120500 (48 NSF), Room 11000E (259 NSF), Room 120302 (44 NSF), Room 110303 (100 NSF), Room 12090B (770 NSF), Room 110600 (46 NSF), Room 121300 (645 NSF), Room 110204 (83 NSF), Room 110305 (60 NSF), Room 121000 (351 NSF), Room 110302 (100 NSF), Room 12090A (876 NSF), Room 111200 (142 NSF), Room 11010B (319 NSF), Room 11001E (1404 NSF), Room 12000N (225 NSF), Room 11010C (90 NSF), Room 12030A (647 NSF), Room 110104 (120 NSF), Room 120201 (34 NSF), Room 11001W (771 NSF), Room 120091 (50 NSF), Room 110203 (30 NSF), Room 120600 (36 NSF), Room 110301 (115 NSF), Room 120801 (32 NSF), Room 120200 (272 NSF), Room 110004 (60 NSF), Room 120002 (208 NSF), Room 110102 (217 NSF), Room 120103 (225 NSF), Room 111000 (50 NSF), Room 130100 (561 NSF), Room 110001 (415 NSF), Room 110002 (170 NSF), Room 111600 (350 NSF), Room 111300 (585 NSF), Room 110103 (669 NSF) Renovation Description:	4,017,797
ENTREPRENEURIAL ED Total :		28,882,745